

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 31859

USING DEPT NO: 507121	OPENED DATE: 01/07/2019 15:24:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/10/2019 08:32:21	METER 1 - M: 33548 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/10/2019 08:32:23	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$485.35	\$485.35

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **485.35** **485.35**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	259858	0046451	\$485.35
COMML					485.35

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 31859

Work Order Notes

(LISAPATE) Windshield has 2 cracks very close together, cannot be repaired. Glass DR will install a new windshield

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr came to the shop and installed a new windshield. PD by CC

Work Order Charge Detail

UNIT NO: 242800 2018 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 32110

USING DEPT NO:	507121	OPENED DATE:	02/04/2019 13:14:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/08/2019 06:34:55	METER 1 - M:	1734	METER 2 - H: 212
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/08/2019 06:34:57	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$0.00	\$23.03	\$0.00	\$23.03

JOB COUNT: 1 WORK ORDER TOTAL: 0.37 0.00 23.03 0.00 23.03

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/05/2019 07:28:25	02/05/2019 07:50:41	0.37	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	6	\$18.00
					PARTS	23.03

Work Order Charge Detail

UNIT NO: 242800 2018 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 32110

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH
Coolant -10'

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32351

USING DEPT NO: 507121	OPENED DATE: 03/06/2019 14:14:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/08/2019 10:46:46	METER 1 - M: 3078 METER 2 - H: 299
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/08/2019 10:46:48	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$0.00	\$22.85	\$0.00	\$22.85

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.33** **0.00** **22.85** **0.00** **22.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/07/2019 10:51:01	03/07/2019 11:11:03	0.33	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.97	6	\$17.82
					PARTS	22.85

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32351

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) Visit Reason Changed On 3/6/2019 2:15 PM By EKIMBREL

(EKIMBREL) Top: AG, Bot: AG

coolant -35

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32690

USING DEPT NO:	507121	OPENED DATE:	04/22/2019 07:49:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/25/2019 12:16:56	METER 1 - M:	4413	METER 2 - H: 727
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	04/25/2019 12:17:04	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.31	\$0.00	\$22.79	\$0.00	\$22.79

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.31** **0.00** **22.79** **0.00** **22.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/22/2019 09:31:13	04/22/2019 10:05:17	0.57	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/22/2019 08:15:25	04/22/2019 09:00:00	0.74	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	6	\$17.76
					PARTS	22.79

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32690

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) Visit Reason Changed On 4/22/2019 7:50 AM By IFALLS

(LISAPATE) PM by AG/SH

Coolant -35'

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33024

USING DEPT NO: 507121	OPENED DATE: 05/30/2019 07:01:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/05/2019 09:30:00	METER 1 - M: 5487 METER 2 - H: 997
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 06/05/2019 09:30:02	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.59	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.02	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.61** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	05/31/2019 09:32:32	05/31/2019 10:07:46	0.59	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/31/2019 08:01:46	05/31/2019 09:02:53	1.02	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33024

Work Order Notes

(LISAPATE) PM-Rotate tires
(LISAPATE) idle hours 720

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 5/30/2019 7:01 AM By LISAPATE
(LISAPATE) PM by SH
Coolant -20'

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33232

USING DEPT NO: 507121	OPENED DATE: 06/25/2019 07:39:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/11/2019 06:49:09	METER 1 - M: 64450 METER 2 - H: 997
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/11/2019 06:49:10	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-42-004	WARRANTY WATER PUMP	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	2.18	\$0.00	\$0.00	\$0.00	\$0.00
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.30	\$0.00	\$41.97	\$0.00	\$41.97
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.30	\$0.00	\$3.55	\$0.00	\$3.55

JOB COUNT: 5	WORK ORDER TOTAL:	4.28	0.00	45.52	0.00	45.52
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
15-42-004	WARRANTY WATER PUMP	11078175	61663	0048742	\$0.00	
					COMML	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-42	DIAGNOSE COOLING SYSTEM	11901357	07/10/2019 07:00:00	07/10/2019 07:30:00	0.50	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	07/10/2019 07:00:00	07/10/2019 07:18:00	0.30	\$0.00
16-42	TRANSPORT COOLING SYSTEM	10208562	06/27/2019 10:50:07	06/27/2019 13:00:40	2.18	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/25/2019 13:49:12	06/25/2019 15:07:25	1.30	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4068	FILTER- CABIN AIR	3.55	1	\$3.55
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	VC3B	FORD ORANGE ANTIFREEZE	19.24	1	\$19.24
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	45.52

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33232

Work Order Notes

(LISAPATE) PM

Job Notes

15-42-004 - WARRANTY WATER PUMP

(LISAPATE) Ford pressure test cooling system. found leaking at water pump weep hole in block behind alternator. Replaced water pump, reseal front cover. Replace and torque crank bolt. Replaced valve cover gaskets. Changed oil and filled coolant. Test drove and verified repair.

16-42 - TRANSPORT COOLING SYSTEM

(LISAPATE) Taken to Ford by EK

35-42 - DIAGNOSE COOLING SYSTEM

(LISAPATE) Found coolant leaking from front of engine and coolant reservoir was empty. Pressured up system found water pump leaking. Take to dealer still under warranty

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 6/25/2019 7:40 AM By LISAPATE

(LISAPATE) PM by AG/SH

Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33645

USING DEPT NO: 507121	OPENED DATE: 08/07/2019 07:04:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/09/2019 13:31:24	METER 1 - M: 7753 METER 2 - H: 1519
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 08/09/2019 13:31:25	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.29	\$0.00	\$76.98	\$0.00	\$76.98
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.70** **0.00** **99.71** **0.00** **99.71**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/07/2019 10:01:46	08/07/2019 10:26:19	0.41	\$0.00
03-32-002	REPLACE NEW BATTERY	12052187	08/08/2019 09:42:17	08/08/2019 09:59:27	0.29	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.64	2	\$1.28
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	75.70	1	\$75.70
					PARTS	99.71

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33645

Work Order Notes

(LISAPATE) PM
(LISAPATE) Check battery truck had to be jumped off

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Battery checked bad. Replaced battery added 2 corrosion washers

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW
Coolant -34'

66-PM-PTU - PERFORM Power Transfer Unit Service

(RWINTERS) not due until 12/12

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33866

USING DEPT NO: 507121	OPENED DATE: 08/27/2019 06:04:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/28/2019 11:34:49	METER 1 - M: 8550 METER 2 - H: 1724
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 08/28/2019 11:34:50	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.88	\$0.00	\$41.99	\$0.00	\$41.99

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.88** **0.00** **41.99** **0.00** **41.99**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/27/2019 06:11:24	08/27/2019 07:04:00	0.88	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	VC3B	FORD ORANGE ANTIFREEZE	19.26	1	\$19.26
					PARTS	41.99

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33866

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG

(AJONES) Coolant Temp -35

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34202

USING DEPT NO: 507121	OPENED DATE: 09/23/2019 08:06:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/24/2019 15:05:57	METER 1 - M: 9704 METER 2 - H: 1995
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/24/2019 15:05:59	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.30** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/23/2019 11:00:52	09/23/2019 11:11:15	0.17	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/23/2019 10:35:17	09/23/2019 10:43:10	0.13	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34202

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/JW
Coolant -35'

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34496

USING DEPT NO: 507121	OPENED DATE: 10/18/2019 07:11:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/21/2019 07:25:55	METER 1 - M: 10600 METER 2 - H: 1689
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 10/21/2019 07:26:08	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.24	\$0.00	\$27.02	\$0.00	\$27.02

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.24** **0.00** **27.02** **0.00** **27.02**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/18/2019 07:57:13	10/18/2019 09:11:40	1.24	\$0.00
LABOR						0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
PARTS						27.02

Work Order Charge Detail

UNIT NO: 242800 2018 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 34496

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG

Coolant -35'

Syn 6.11

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34893

USING DEPT NO:	507121	OPENED DATE:	11/18/2019 06:02:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/19/2019 10:26:16	METER 1 - M:	11267	METER 2 - H: 1895
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/19/2019 10:26:17	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.46	\$0.00	\$22.25	\$0.00	\$22.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.96** **0.00** **22.25** **0.00** **22.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11901357	11/18/2019 07:00:00	11/18/2019 07:30:00	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/18/2019 07:36:44	11/18/2019 08:04:06	0.46	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.87	6	\$17.22
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	22.25

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34893

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW,EK/AG
Coolant -35'

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35218

USING DEPT NO: 507121	OPENED DATE: 12/18/2019 07:33:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/20/2019 09:07:09	METER 1 - M: 11952 METER 2 - H: 2095
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/20/2019 09:07:11	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.10	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.90	\$0.00	\$22.25	\$0.00	\$22.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.99** **0.00** **22.25** **0.00** **22.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/18/2019 09:38:45	12/18/2019 10:32:37	0.90	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	12/18/2019 14:03:51	12/18/2019 14:09:33	0.10	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.87	6	\$17.22
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	22.25

Work Order Charge Detail

UNIT NO: 242800 2018 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 35218

Work Order Notes

(EKIMBREL) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(EKIMBREL) JW rotated tires.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/JW. Coolant -24

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35610

USING DEPT NO: 507121	OPENED DATE: 02/10/2020 06:59:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/13/2020 09:02:56	METER 1 - M: 12719 METER 2 - H: 2299
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/13/2020 09:02:57	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.25	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.46	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.71** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	02/10/2020 11:07:51	02/10/2020 11:22:59	0.25	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/10/2020 08:33:34	02/10/2020 09:01:10	0.46	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35610

Work Order Notes

(EKIMBREL) PM, rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(EKIMBREL) JW rotated tires.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/JW. Coolant -25

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36043

USING DEPT NO: 507121	OPENED DATE: 03/24/2020 07:15:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/24/2020 13:57:56	METER 1 - M: 13536 METER 2 - H: 2498
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 03/25/2020 15:24:27	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.48	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.50	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.98** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	03/24/2020 10:20:47	03/24/2020 10:49:27	0.48	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/24/2020 09:40:14	03/24/2020 10:25:18	0.75	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2020 09:39:27	03/24/2020 10:24:21	0.75	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36043

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires and torqued to spec. Relearned TPMS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW,SH/AG
Coolant -20'

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36178

USING DEPT NO: 507121	OPENED DATE: 04/20/2020 13:33:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/21/2020 10:45:43	METER 1 - M: 14065 METER 2 - H: 2498
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/21/2020 11:44:27	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.14	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$0.00	\$28.31	\$0.00	\$28.31
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.49	\$0.00	\$3.55	\$0.00	\$3.55

JOB COUNT: 3 **WORK ORDER TOTAL:** **1.00** **0.00** **31.86** **0.00** **31.86**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11901357	04/20/2020 15:09:24	04/20/2020 15:17:36	0.14	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	04/20/2020 14:40:05	04/20/2020 15:09:24	0.49	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/20/2020 14:30:00	04/20/2020 14:40:05	0.17	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/20/2020 14:02:21	04/20/2020 14:15:00	0.21	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	3.88	6	\$23.28
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4068	FILTER- CABIN AIR	3.55	1	\$3.55
					PARTS	31.86

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36178

Work Order Notes

(IFALLS) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(IFALLS) AG/SH rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AG performed pm

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(IFALLS) AG replaced cabin filter

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36628

USING DEPT NO: 507121	OPENED DATE: 06/01/2020 07:02:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/01/2020 09:48:12	METER 1 - M: 14982 METER 2 - H: 2834
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/02/2020 10:52:10	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-015	PERFORM TIRE ROTATION	DON	P	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.90	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.39** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-015	PERFORM TIRE ROTATION	11901357	06/01/2020 08:23:19	06/01/2020 08:53:15	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/01/2020 07:40:34	06/01/2020 08:25:38	(0.75)	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/01/2020 07:40:34	06/01/2020 08:25:38	0.75	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/01/2020 07:40:34	06/01/2020 07:58:34	0.30	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/01/2020 07:47:34	06/01/2020 08:23:19	0.60	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36628

Work Order Notes

(EKIMBREL) PM

Job Notes

66-17-015 - PERFORM TIRE ROTATION

(EKIMBREL) AG rotated tires and performed relearn on TPMS.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/JW performed pm. Coolant -35

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36793

USING DEPT NO: 507121	OPENED DATE: 06/12/2020 08:01:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/12/2020 09:27:44	METER 1 - M: 15303 METER 2 - H: 2891
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/15/2020 08:41:35	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PR-01-002	PROGRAM HEATING & VENTILATING	DON	O	N	GARAGE	0.51	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.51** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PR-01-002	PROGRAM HEATING & VENTILATING	11170580	06/12/2020 08:14:53	06/12/2020 08:45:46	0.51	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 242800 2018 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 36793

Work Order Notes

(EKIMBREL) Program for coronavirus

Job Notes

PR-01-002 - PROGRAM HEATING & VENTILATING

(ABLACK) AB reprogrammed PCM, BCM, and HVAC modules in order to activate coronavirus disinfectant mode.

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37031

USING DEPT NO: 507121	OPENED DATE: 07/06/2020 14:33:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/07/2020 11:29:00	METER 1 - M: 15779 METER 2 - H: 3058
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/08/2020 08:08:19	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.69	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.19** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	07/07/2020 06:00:00	07/07/2020 06:30:00	(0.50)	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	07/07/2020 06:00:00	07/07/2020 06:30:00	0.50	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11310047	07/07/2020 06:00:00	07/07/2020 06:30:00	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/06/2020 14:39:34	07/06/2020 15:21:06	0.69	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37031

Work Order Notes

(EKIMBREL) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires and relearned TPMS EH

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EH/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37245

USING DEPT NO: 507121	OPENED DATE: 08/03/2020 14:32:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/04/2020 07:28:51	METER 1 - M: 16617 METER 2 - H: 3255
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/04/2020 09:02:36	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.51	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.51** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/03/2020 14:54:46	08/03/2020 15:25:21	0.51	\$0.00
LABOR						0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
PARTS						22.73

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37245

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Did not rotate tires this time. possible will need tires next service. AG

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37577

USING DEPT NO: 507121	OPENED DATE: 09/14/2020 07:08:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/14/2020 09:44:34	METER 1 - M: 18189 METER 2 - H: 3565
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/14/2020 13:11:18	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.01	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$0.00	\$22.79	\$0.00	\$22.79

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.45** **0.00** **22.79** **0.00** **22.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/14/2020 07:28:28	09/14/2020 07:44:29	0.27	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	09/14/2020 07:38:39	09/14/2020 07:39:30	0.01	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/14/2020 07:28:07	09/14/2020 07:38:20	0.17	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	6	\$17.76
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	22.79

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37577

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(SHARBIN) Tires did not need to be rotated this PM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW PERFORMED PM.

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38330

USING DEPT NO: 507121	OPENED DATE: 11/09/2020 14:12:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/11/2020 09:25:33	METER 1 - M: 19816 METER 2 - H: 3881
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/11/2020 14:11:21	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.22	\$26.29	\$0.00	\$0.00	\$26.29
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.54	\$64.02	\$0.00	\$0.00	\$64.02
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.80	\$94.96	\$777.24	\$0.00	\$872.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.88	\$104.17	\$35.01	\$0.00	\$139.18
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.15	\$18.26	\$12.14	\$0.00	\$30.40

JOB COUNT: 5 **WORK ORDER TOTAL:** **2.61** **307.70** **824.39** **0.00** **1,132.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
09-15	ALIGN STEERING	11310047	11/10/2020 15:22:35	11/10/2020 15:55:08	0.54	\$64.02
06-15	INSPECT STEERING	11074414	11/10/2020 14:50:26	11/10/2020 15:03:48	0.22	\$26.29
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/10/2020 10:03:04	11/10/2020 10:37:40	0.58	\$68.05
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	11/10/2020 09:53:30	11/10/2020 10:02:47	0.15	\$18.26
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/10/2020 09:34:52	11/10/2020 09:53:14	0.31	\$36.12
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	11/10/2020 14:01:22	11/10/2020 14:49:39	0.80	\$94.96

LABOR **307.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1555395	TIRE 245/55R18 GEN GMAXPURSUIT	189.63	4	\$758.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.42	8	\$3.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.84	4	\$15.36
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	12.14	1	\$12.14
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64

PARTS **824.39**

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38330

Work Order Notes

(LISAPATE) PM

Job Notes

06-15 - INSPECT STEERING

(SHARBIN) SH/AB Checked front end found no issues.

06-17-028 - INSPECT MOUNT AND BALANCE TIRES

09-15 - ALIGN STEERING

(GARAGE) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) SH Mounted and AMG balanced 4 tires. Relearned tire positions.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 19816 Engine hours 4958 Idle hours 3881. SH/AMG Performed PM. Needs 4 tires due tread depth.

(SHARBIN) Washed vacuumed and filled with gas. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38671

USING DEPT NO: 507121	OPENED DATE: 12/16/2020 07:28:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/16/2020 13:28:42	METER 1 - M: 21262 METER 2 - H: 4113
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/17/2020 08:34:48	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>	
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.49	\$34.92	\$0.00	\$86.41	
JOB COUNT: 1						WORK ORDER TOTAL:	0.44	51.49	34.92	0.00	86.41

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/16/2020 11:11:41	12/16/2020 11:37:52	0.44	\$51.49
					LABOR	51.49

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	34.92

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38671

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. EK,RC/JAW

MILEAGE-21262

HRS-4113

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39000

USING DEPT NO: 507121	OPENED DATE: 02/02/2021 15:12:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/03/2021 14:23:14	METER 1 - M: 32556 METER 2 - H: 4113
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/04/2021 14:26:49	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.22	\$25.53	\$146.72	\$0.00	\$172.25

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.22** **25.53** **146.72** **0.00** **172.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12052187	02/02/2021 15:40:07	02/02/2021 15:53:06	0.22	\$25.53
					LABOR	25.53

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	146.72	1	\$146.72
					PARTS	146.72

Work Order Charge Detail

UNIT NO: 242800 2018 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 39000

Work Order Notes

(LISAPATE) Battery is smelling like sulfur

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced battery with new. MS resetting computer. JAW

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39158

USING DEPT NO: 507121	OPENED DATE: 02/22/2021 08:38:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/24/2021 10:30:46	METER 1 - M: 22622 METER 2 - H: 4425
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/24/2021 11:58:07	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.20	\$23.27	\$0.00	\$0.00	\$23.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$80.70	\$41.81	\$0.00	\$122.51

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.88** **103.97** **41.81** **0.00** **145.78**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/22/2021 11:15:21	02/22/2021 11:30:00	0.24	\$28.81
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	02/22/2021 13:04:11	02/22/2021 13:16:01	0.20	\$23.27
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/22/2021 10:36:03	02/22/2021 11:02:26	0.44	\$51.89
					LABOR	103.97

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5066517	WSWF RAIN-X -20DEG DEICER GAL	6.89	1	\$6.89
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	41.81

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39158

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes found no issues. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 22622 Engine hours 5669 Idle hours 4425. SH Performed PM. JW vacuumed.

(SHARBIN) SH Filled with gas wash bay was occupied.

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39926

USING DEPT NO: 507121	OPENED DATE: 05/11/2021 08:40:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/12/2021 09:07:14	METER 1 - M: 23823 METER 2 - H: 4723
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/12/2021 12:58:57	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$74.21	\$41.84	\$0.00	\$116.05

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.63** **74.21** **41.84** **0.00** **116.05**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/11/2021 10:59:52	05/11/2021 11:37:36	0.63	\$74.21
					LABOR	74.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
					PARTS	41.84

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39926

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 23823 Engine hours 6038 Idle hours 4723. SH Performed PM.

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40407

USING DEPT NO: 507121	OPENED DATE: 07/12/2021 10:46:46	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/14/2021 10:30:50	METER 1 - M: 24539 METER 2 - H: 4938
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/14/2021 12:33:07	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.92	\$30.32	\$0.00	\$35.24
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.63	\$74.77	\$194.57	\$0.00	\$269.34
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.55	\$65.16	\$0.00	\$0.00	\$65.16
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$43.76	\$47.13	\$0.00	\$90.89

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.60** **188.61** **272.02** **0.00** **460.63**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	07/12/2021 14:42:35	07/12/2021 15:20:36	0.63	\$74.77
03-51-038	REPLACE NEW WIPER BLADES	11901357	07/12/2021 13:22:55	07/12/2021 13:25:25	0.04	\$4.92
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/12/2021 13:00:18	07/12/2021 13:22:33	0.37	\$43.76
66-79-002	PERFORM SERVICE CALL	11074414	07/12/2021 10:55:24	07/12/2021 11:28:32	0.55	\$65.16
					LABOR	188.61

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	8.85	1	\$8.85
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	9.50	1	\$9.50
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	11.97	1	\$11.97
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.78	1	\$9.78
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1555395	TIRE 245/55R18 GEN GMAXPURSUIT	189.63	1	\$189.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.51	2	\$1.02
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.92	1	\$3.92
					PARTS	272.02

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40407

Work Order Notes

(LISAPATE) PM due-RR tire has a nail in it

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Andrew replaced wipers. AB

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) Replaced and balanced R/R tire. AMG

66-79-002 - PERFORM SERVICE CALL

(SHARBIN) Put air in the tire and drove the vehicle back to the shop. The tire can not be repaired the screw is to close to the sidewall of the tire. SH AB

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 24539 idle hours: 4938 Completed PM bottomside, Josh was topside. Completed checklist. JW/AMG

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40993

USING DEPT NO: 507121	OPENED DATE: 09/13/2021 07:58:04	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/16/2021 11:54:29	METER 1 - M: 26031 METER 2 - H: 5263
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/16/2021 12:24:25	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$6.92	\$31.82	\$0.00	\$38.74
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.11	\$12.55	\$0.00	\$0.00	\$12.55
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.30	\$35.37	\$0.00	\$0.00	\$35.37
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$71.72	\$69.76	\$0.00	\$141.48
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.04	\$4.92	\$11.67	\$0.00	\$16.59
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	P	N	GARAGE	0.46	\$53.89	\$12.75	\$0.00	\$66.64
66-PM-PTU	PERFORM Power Transfer Unit Service	DON	P	N	GARAGE	1.58	\$186.34	\$16.13	\$0.00	\$202.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 8 **WORK ORDER TOTAL:** **3.15** **371.71** **142.13** **2.00** **515.84**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PTU	PERFORM Power Transfer Unit Service	11170580	09/15/2021 08:08:40	09/15/2021 09:10:25	1.03	\$121.44
66-PM-PTU	PERFORM Power Transfer Unit Service	11170580	09/14/2021 15:19:12	09/14/2021 15:52:12	0.55	\$64.90
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11074414	09/13/2021 14:56:14	09/13/2021 15:23:38	0.46	\$53.89
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/13/2021 14:49:38	09/13/2021 14:56:01	0.11	\$12.55
66-79-003	PERFORM SAFETY INSPECTION	11074414	09/13/2021 14:30:00	09/13/2021 14:47:59	0.30	\$35.37
66-79-003	PERFORM SAFETY INSPECTION	11074414	09/13/2021 14:14:08	09/13/2021 14:14:08	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	09/13/2021 14:11:25	09/13/2021 14:13:55	0.04	\$4.92
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/13/2021 14:07:40	09/13/2021 14:11:11	0.06	\$6.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/13/2021 13:30:52	09/13/2021 14:07:20	0.61	\$71.72
LABOR					371.71	

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.13	1	\$5.13
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PTU	PERFORM Power Transfer Unit Service	VV982	75W-140 LS SYN GEAR OIL QT	15.66	1	\$15.66
66-PM-PMT	PERFORM TRANSMISSION SERVICE	VV324GAL	TRANS FLUID GALLON	12.75	1	\$12.75
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	11.67	1	\$11.67
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
66-PM-PTU	PERFORM Power Transfer Unit Service	4 CLAMP	HOSE CLAMPS	0.47	1	\$0.47
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	20.81	1	\$20.81
					PARTS	142.13

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40993

Work Order Notes

(LISAPATE) PM-Do annual SI-service PTU

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed safety inspection found no issues. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 26031 Engine hours 6719 Idle hours 5263. SH Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

66-PM-PMT - PERFORM TRANSMISSION SERVICE

(SHARBIN) Performed transmission service drained and refilled. SH

66-PM-PTU - PERFORM Power Transfer Unit Service

(ABLACK) AB performed PTU service

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41624

USING DEPT NO: 507121	OPENED DATE: 11/15/2021 08:21:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/19/2021 13:44:35	METER 1 - M: 27412 METER 2 - H: 5588
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/22/2021 08:17:38	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.46	\$31.82	\$0.00	\$38.28
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.07	\$7.67	\$0.00	\$0.00	\$7.67
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.31	\$36.68	\$0.00	\$0.00	\$36.68
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.38	\$163.14	\$785.73	\$0.00	\$948.87
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.04	\$46.34	\$0.00	\$81.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.11	248.99	863.89	2.00	1,114.88
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	11/18/2021 14:30:00	11/18/2021 14:47:36	0.29	\$34.61
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	11/18/2021 14:19:21	11/18/2021 14:19:21	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	11/17/2021 10:24:36	11/17/2021 11:29:57	1.09	\$128.52
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/15/2021 15:39:15	11/15/2021 15:42:32	0.05	\$6.46
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/15/2021 15:21:09	11/15/2021 15:38:58	0.30	\$35.04
06-15	INSPECT STEERING	11074414	11/18/2021 14:48:38	11/18/2021 14:52:32	0.07	\$7.67
66-17-013	PERFORM ALIGNMENT	11310047	11/18/2021 15:33:14	11/18/2021 15:51:53	0.31	\$36.68
					LABOR	248.98

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1555395	TIRE 245/55R18 GEN GMAXPURSUIT	189.63	2	\$379.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1555395	TIRE 245/55R18 GEN GMAXPURSUIT	194.13	2	\$388.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.18	1	\$0.18
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.41	1	\$0.41

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.55	3	\$1.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.66	1	\$0.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.83	4	\$15.30
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1555395	TIRE 245/55R18 GEN GMAXPURSUIT	194.13	(2)	(\$388.26)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1555395	TIRE 245/55R18 GEN GMAXPURSUIT	194.13	2	\$388.26
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.08	1	\$9.08
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
					PARTS	863.89

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41624

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) IF Replaced wipers.

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering found no issues. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Checked alignment and it was within spec. Did not make any adjustments. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

(SHARBIN) Needs 4 tires due to shoulder wear. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42121

USING DEPT NO: 507121	OPENED DATE: 01/20/2022 10:02:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/27/2022 10:30:27	METER 1 - M: 28414 METER 2 - H: 5820
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/28/2022 07:27:10	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-028	REPLACE NEW SEAT ADJUSTER	DON	O	N	GARAGE	0.14	\$16.32	\$0.00	\$0.00	\$16.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$17.08	\$46.80	\$0.00	\$63.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.28** **33.40** **46.80** **2.00** **82.20**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-028	REPLACE NEW SEAT ADJUSTER	11310047	01/24/2022 07:00:27	01/24/2022 07:08:45	0.14	\$16.32
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/26/2022 14:00:35	01/26/2022 14:09:16	0.14	\$17.08
LABOR						33.40

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.54	1	\$9.54
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						46.80

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42121

Work Order Notes

(LISAPATE) Passenger seat adjuster handle is broken

Job Notes

03-02-028 - REPLACE NEW SEAT ADJUSTER

(EHOWELL) The sliding function of the seat still functions. No repairs were made. EH/IF (IFALLS) reinstalled the seat adjustment handle driver need to be easy with handle

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) CW SH/SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42431

USING DEPT NO: 507121	OPENED DATE: 02/21/2022 13:56:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/22/2022 10:43:44	METER 1 - M: 28938 METER 2 - H: 5910
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/22/2022 14:46:11	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$46.32	\$0.00	\$0.00	\$46.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.39** **46.32** **0.00** **2.00** **48.32**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/22/2022 08:26:47	02/22/2022 08:50:20	0.39	\$46.32
LABOR						46.32

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42431

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 28938 hours: 7518 idle hours: 5910 Vehicle has been 524 miles and 90 idle hours, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change stickers and completed checklist. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43235

USING DEPT NO: 507121	OPENED DATE: 05/16/2022 07:27:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/17/2022 10:07:16	METER 1 - M: 30015 METER 2 - H: 6123
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/17/2022 15:20:43	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.52	\$31.82	\$0.00	\$36.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.99	\$54.08	\$0.00	\$106.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.48** **56.51** **85.90** **2.00** **144.41**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/16/2022 08:42:19	05/16/2022 08:44:37	0.04	\$4.52
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/16/2022 08:15:42	05/16/2022 08:42:08	0.44	\$51.99
LABOR					56.51	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.64	6	\$33.84
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.53	(6)	(\$57.15)
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.53	6	\$57.15
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.53	1	\$9.53
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
PARTS					85.90	

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43235

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43908

USING DEPT NO: 507121	OPENED DATE: 07/11/2022 11:23:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/14/2022 14:57:12	METER 1 - M: 31329 METER 2 - H: 6428
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/15/2022 09:12:50	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	1.38	\$163.14	\$424.69	\$0.00	\$587.83
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	0.39	\$46.38	\$335.94	\$0.00	\$382.32
03-50-100	REPLACE NEW BELT, SERPENTINE OR	DON	O	N	GARAGE	0.89	\$105.09	\$34.26	\$0.00	\$139.35
66-13-130	PERFORM Burnish Brakes	DON	O	N	GARAGE	0.32	\$37.33	\$0.00	\$0.00	\$37.33
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	1.07	\$126.72	\$0.00	\$0.00	\$126.72
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$61.49	\$80.55	\$0.00	\$142.04
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	1.11	\$130.46	\$30.32	\$0.00	\$160.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 8 **WORK ORDER TOTAL:** **5.68** **670.61** **905.76** **2.00** **1,578.37**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-13-130	PERFORM Burnish Brakes	11310047	07/13/2022 09:19:10	07/13/2022 09:19:10	0.00	\$0.00
66-13-130	PERFORM Burnish Brakes	11310047	07/13/2022 09:30:00	07/13/2022 09:48:59	0.32	\$37.33
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	07/13/2022 08:20:10	07/13/2022 09:15:00	0.91	\$107.84
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	07/12/2022 13:25:45	07/12/2022 13:53:52	0.47	\$55.30
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	07/12/2022 13:02:10	07/12/2022 13:25:45	0.39	\$46.38
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	11310047	07/12/2022 10:59:02	07/12/2022 11:52:28	0.89	\$105.09
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11310047	07/12/2022 10:44:17	07/12/2022 10:59:02	0.25	\$29.01
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11310047	07/11/2022 15:01:16	07/11/2022 15:50:57	0.83	\$97.71
66-PM-PMA	PERFORM OIL CHANGE	11310047	07/11/2022 14:30:00	07/11/2022 15:01:16	0.52	\$61.49
66-PM-PMA	PERFORM OIL CHANGE	11310047	07/11/2022 14:26:04	07/11/2022 14:26:04	0.00	\$0.00

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11310047	07/11/2022 13:08:40	07/11/2022 14:15:00	1.11	\$130.46
					LABOR	670.61

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	GATK060448	BELT	34.26	1	\$34.26
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABSP1611APPH	BRAKE PAD SET	100.97	1	\$100.97
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	GG1Z1125A	FRONT ROTORS	158.90	2	\$317.79
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RABSP1377PSH	REAR BRAKE PADS	65.01	1	\$65.01
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	20.91	1	\$20.91
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP68	CABIN FILTER	30.32	1	\$30.32
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.61	1	\$11.61
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.82	6	\$34.92
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RAB680983P	REAR ROTORS	135.47	2	\$270.93
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	1	\$5.93
					PARTS	905.76

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43908

Work Order Notes

(LISAPATE) PM

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(EHOWELL) Replaced front pads and rotors. Greased slide pins. EH

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(EHOWELL) Replaced rear pads and rotors. Greased slide pins. EH

03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.

(EHOWELL) The serpentine belt was cracked. Replaced serpentine belt. EH

66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made hard stops after brake job was performed. EH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(EHOWELL) Rotated tires. Front and rear brake pads were near 4mm. The spec for the brake pad minimum thickness is 3mm. EH

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) PM. Installed Seafoam.

EH-Top

SH-Bottom

Mileage-31329

Hours-8161

Idle Hours-6428

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EHOWELL) Replaced cabin filter. EH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44959

USING DEPT NO: 507121	OPENED DATE: 10/12/2022 07:41:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/13/2022 11:59:55	METER 1 - M: 31555 METER 2 - H: 6504
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/17/2022 09:19:54	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.28	\$32.91	\$0.00	\$0.00	\$32.91
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.19	\$0.00	\$0.00	\$30.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.53	63.10	0.00	5.00	68.10
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-32-002	INSPECT BATTERY	11074414	10/12/2022 09:46:02	10/12/2022 10:02:46	0.28	\$32.91
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/12/2022 09:30:28	10/12/2022 09:45:49	0.26	\$30.19
LABOR					63.10	

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44959

Work Order Notes

(CWIGLEY) PM. Check battery, they said its had to be jumped off a few times.

Job Notes

06-32-002 - INSPECT BATTERY

(SHARBIN) Battery tested good. ALT is charging at 14 volts. Started vehicle several times did not have any issues cranking. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 229 miles and has idled 76 hours since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 45822

USING DEPT NO: 507121	OPENED DATE: 01/18/2023 09:54:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/20/2023 11:10:40	METER 1 - M: 32382 METER 2 - H: 6822
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/20/2023 14:13:36	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.15	\$18.19	\$113.55	\$0.00	\$131.74
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.90	\$56.72	\$0.00	\$72.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.29** **152.09** **170.27** **5.00** **327.36**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	01/20/2023 07:00:00	01/20/2023 08:00:00	1.00	\$118.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/18/2023 13:18:54	01/18/2023 13:20:43	0.03	\$3.57
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/18/2023 12:56:48	01/18/2023 13:03:04	0.10	\$12.32
03-32-002	REPLACE NEW BATTERY	12052187	01/18/2023 12:47:19	01/18/2023 12:56:34	0.15	\$18.19
					LABOR 152.08	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.08	1	\$6.08
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
					PARTS 170.27	

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 45822

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced battery. JAW
EH will reset charging system

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) performed pm service coolant -34° JAW/GC
MILEAGE-32382
IDLE HRS-6822
ENG HRS-8611

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) EH reset with a scan tool

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46527

USING DEPT NO: 507121	OPENED DATE: 03/24/2023 10:41:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/24/2023 14:37:02	METER 1 - M: 32990 METER 2 - H: 6822
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/17/2023 10:14:33	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.30	\$35.40	\$113.55	\$0.00	\$148.95
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.80** **94.40** **113.55** **5.00** **212.95**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11399745	03/24/2023 11:45:50	03/24/2023 12:03:50	0.30	\$35.40
66-79-002	PERFORM SERVICE CALL	11399745	03/24/2023 11:15:50	03/24/2023 11:15:50	0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	11399745	03/24/2023 11:15:50	03/24/2023 11:15:50	0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	11399745	03/24/2023 11:15:50	03/24/2023 11:45:50	0.50	\$59.00
LABOR					94.40	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
PARTS					113.55	

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46527

Work Order Notes

(EKIMBREL) SERVICE CALL DEAD BATTERY

Job Notes

03-32-002 - REPLACE NEW BATTERY

(EKIMBREL) CW REPLACED BATTERY

66-79-002 - PERFORM SERVICE CALL

(GARAGE) swapped batteries so that we could charge the original battery

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46573

USING DEPT NO: 507121	OPENED DATE: 03/31/2023 09:21:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/14/2023 15:16:54	METER 1 - M: 32990 METER 2 - H: 6822
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/17/2023 10:00:25	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-31-001	REPLACE NEW ALTERNATOR	DON	O	N	GARAGE	1.32	\$155.69	\$364.31	\$0.00	\$520.00
03-35-006	REPLACE NEW FUSE(S)	DON	O	N	GARAGE	0.51	\$60.64	\$115.90	\$0.00	\$176.54
06-31	INSPECT CHARGING SYSTEM	DON	O	N	GARAGE	4.13	\$487.64	\$0.00	\$0.00	\$487.64
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.10	\$11.93	\$0.00	\$0.00	\$11.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-31	SCAN OUT CHARGING SYSTEM	DON	O	N	GARAGE	3.56	\$420.38	\$0.00	\$0.00	\$420.38

JOB COUNT: 6	WORK ORDER TOTAL:	9.63	1,136.28	480.21	5.00	1,621.49
---------------------	--------------------------	-------------	-----------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11310047	04/13/2023 14:40:32	04/13/2023 14:46:36	0.10	\$11.93
03-35-006	REPLACE NEW FUSE(S)	11310047	04/13/2023 14:03:40	04/13/2023 14:34:30	0.51	\$60.64
03-31-001	REPLACE NEW ALTERNATOR	11310047	04/13/2023 10:00:20	04/13/2023 11:19:30	1.32	\$155.69
SO-31	SCAN OUT CHARGING SYSTEM	11310047	04/03/2023 09:30:00	04/03/2023 11:49:05	2.32	\$273.53
SO-31	SCAN OUT CHARGING SYSTEM	11310047	04/03/2023 08:00:37	04/03/2023 09:15:00	1.24	\$146.29
06-31	INSPECT CHARGING SYSTEM	11310047	03/31/2023 14:42:38	03/31/2023 15:53:12	1.18	\$138.78
06-31	INSPECT CHARGING SYSTEM	11310047	03/31/2023 10:04:26	03/31/2023 10:36:51	0.54	\$63.75
06-31	INSPECT CHARGING SYSTEM	11310047	04/03/2023 07:22:47	04/03/2023 08:00:37	0.63	\$74.41
06-31	INSPECT CHARGING SYSTEM	11310047	04/10/2023 13:01:08	04/10/2023 14:47:56	1.78	\$210.04
06-31	INSPECT CHARGING SYSTEM	11310047	04/13/2023 14:34:30	04/13/2023 14:34:50	0.01	\$0.66
SO-31	SCAN OUT CHARGING SYSTEM	11310047	04/13/2023 14:34:50	04/13/2023 14:35:07	0.00	\$0.56
					LABOR	1136.28

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-31-001	REPLACE NEW ALTERNATOR	REM23006	ALTERNATOR	364.31	1	\$364.31
03-31-001	REPLACE NEW ALTERNATOR	REM23006	ALTERNATOR	364.31	(1)	(\$364.31)
03-31-001	REPLACE NEW ALTERNATOR	REM23006	ALTERNATOR	364.31	1	\$364.31
03-35-006	REPLACE NEW FUSE(S)	KU5Z14526A	MEGA FUSE CIRCUIT BREAKER	104.23	1	\$104.23
03-35-006	REPLACE NEW FUSE(S)	LITMIC2020VP	MICRO FUSE	5.22	1	\$5.22
03-35-006	REPLACE NEW FUSE(S)	LITMIC3005VP	FUSE- MICRO3 32V	6.45	1	\$6.45
					PARTS	480.21

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46573

Work Order Notes

(EKIMBREL) CHECK FOR CHARGE

Job Notes

03-31-001 - REPLACE NEW ALTERNATOR

(EHOWELL) Replaced alternator. Verified vehicle was charging after repair. EH

03-35-006 - REPLACE NEW FUSE(S)

(EHOWELL) Replaced mega fuse in under hood fuse block. Also, replaced two fuses in the Body Control Module. The alternator is now charging, the radio is working, and the HVAC controls are working properly. EH .3 HR

06-31 - INSPECT CHARGING SYSTEM

(EHOWELL) The alternator was not charging. The mega fuse for the alternator was blown. The alternator is at fault. 1.0 HR EH

CH-32-002 - CHARGE BATTERY

(EHOWELL) Charged battery in battery room. Battery tested good after charging. Reset the Battery Monitoring System using the Ford Scan tool. EH

CH-SP - CHARGE Shop Supplies

SO-31 - SCAN OUT CHARGING SYSTEM

(EHOWELL) Found DTC related to the front control interface module. Also, the radio was inoperative. There were two blown fuses in the Body Control Module. EH

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46957

USING DEPT NO: 507121	OPENED DATE: 05/05/2023 07:15:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/05/2023 13:39:19	METER 1 - M: 33366 METER 2 - H: 7079
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/05/2023 15:41:48	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-010	REPLACE NEW TAG LIGHT	DON	O	N	GARAGE	0.03	\$2.98	\$0.39	\$0.00	\$3.37
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.58	\$56.40	\$0.00	\$84.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.27** **31.56** **56.79** **5.00** **93.35**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-010	REPLACE NEW TAG LIGHT	11074414	05/05/2023 07:43:50	05/05/2023 07:45:21	0.03	\$2.98
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/05/2023 07:29:04	05/05/2023 07:43:36	0.24	\$28.58
LABOR					31.56	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-010	REPLACE NEW TAG LIGHT	194	BULB-TAG/MARKER	0.39	1	\$0.39
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
PARTS					56.79	

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46957

Work Order Notes

(CWIGLEY) PM. Driver says a tag light is out.

Job Notes

03-34-010 - REPLACE NEW TAG LIGHT

(SHARBIN) JW Replaced the right side tag light. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH JW/EH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48839

USING DEPT NO: 507121	OPENED DATE: 11/06/2023 09:05:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/06/2023 14:51:08	METER 1 - M: 33948 METER 2 - H: 7079
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/07/2023 08:37:51	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.49	\$64.16	\$0.00	\$82.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.16** **18.49** **64.16** **5.00** **87.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/06/2023 10:14:40	11/06/2023 10:24:04	0.16	\$18.49
LABOR					18.49	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
PARTS					64.16	

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48839

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49727

USING DEPT NO: 507121	OPENED DATE: 02/07/2024 08:08:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/09/2024 13:14:25	METER 1 - M: 33970 METER 2 - H: 7200
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/12/2024 07:57:58	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.81	\$18.83	\$0.00	\$41.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.19** **22.81** **18.83** **5.00** **46.64**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/07/2024 13:00:00	02/07/2024 13:11:36	0.19	\$22.81
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/07/2024 12:59:11	02/07/2024 12:59:11	0.00	\$0.00
LABOR					22.81	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	800151C	CABIN AIR FILTER REPL 4068	18.83	1	\$18.83
PARTS					18.83	

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49727

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform fluid check FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50403

USING DEPT NO: 507121	OPENED DATE: 04/03/2024 08:36:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/26/2024 13:15:26	METER 1 - M: 33970 METER 2 - H: 7200
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/30/2024 10:17:34	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR4JGC29281

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$42.27	\$0.00	\$42.27
RY-02-058	REKEY DOOR LOCK	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$115.00	\$115.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.00** **0.00** **42.27** **120.00** **162.27**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
RY-02-058	REKEY DOOR LOCK	11111231	2311951		\$115.00
COMML					120.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	04/18/2024 12:22:19	04/18/2024 12:22:19	0.00	\$0.00
LABOR					0.00	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.14	2	\$0.27
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	08984	ADHESIVE REMOVER	42.00	1	\$42.00
PARTS					42.27	

Work Order Charge Detail

UNIT NO: 242800 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50403

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Removed wordmarks and tag. CW/RC

(EHOWELL) Removed all four lock cylinders. Reinstalled all four lock cylinders after they were rekeyed. EH

RY-02-058 - REKEY DOOR LOCK

(EKIMBREL) a1 locksmith rekeyed door locks and ignition

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Aug 05 2024 12:14:00 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '1FM5K8AR4JGC29281') //Q=