

# Work Order Charge Detail

**UNIT NO:** 243607      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 35091

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 12/06/2019 14:42:37	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/10/2019 07:21:42	<b>METER 1 - M:</b> 53 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/10/2019 07:21:44	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.50**      **0.00**      **0.00**      **0.00**      **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11901357	12/06/2019 14:43:17	12/06/2019 15:13:17	0.50	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 35091

---

**Work Order Notes**

(LISAPATE) New unit do PDI

---

**Job Notes**

**PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION**

(LISAPATE) PDI completed

---

# Work Order Charge Detail

**UNIT NO:** 243607      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 35402

<b>USING DEPT NO:</b>	507121	<b>OPENED DATE:</b>	01/15/2020 07:44:15	<b>LOCATION:</b>	GARAGE - University Automotive Services		
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	01/22/2020 06:44:55	<b>METER 1 - M:</b>	53	<b>METER 2 - H:</b>	0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	01/22/2020 06:44:56	<b>IN-SERVICE DATE:</b>	12/06/2019		
<b>TECH SPEC NO:</b>	20TOYOTACAMRY	2020 Toyota Camry		<b>UNIT SERIAL NO:</b>	4T1C11AK7LU860938		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$210.00	\$210.00
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **1.00**      **0.00**      **0.00**      **210.00**      **210.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
14-78-028	INSTALL WINDOW TINT	5564144	32040		\$210.00
				<b>COMML</b>	<b>210.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	11268671	01/16/2020 07:00:00	01/16/2020 08:00:00	1.00	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 35402

---

**Work Order Notes**

(LISAPATE) Tint windows per Josh Kelley. Take to Bama Trim

---

**Job Notes**

**14-78-028 - INSTALL WINDOW TINT**

(LISAPATE) All windows were tinted including a windshield strip. Pd by CC

**16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE**

(LISAPATE) Taken to Bama Trim by IF

---

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY WORK ORDER NO: 36918

USING DEPT NO:	507121	OPENED DATE:	06/23/2020 07:31:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/23/2020 09:59:56	METER 1 - M:	2874	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/24/2020 09:30:17	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$0.00	\$28.12	\$0.00	\$28.12

JOB COUNT: 1 WORK ORDER TOTAL: 0.40 0.00 28.12 0.00 28.12

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/23/2020 09:16:30	06/23/2020 09:40:20	0.40	\$0.00

LABOR 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.90	5	\$19.50
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29

PARTS 28.12

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 36918

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by RC/AG  
Coolant -34'

---

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 38009

USING DEPT NO:	507121	OPENED DATE:	10/15/2020 07:16:35	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	10/16/2020 08:54:42	METER 1 - M:	5907	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/16/2020 09:25:29	IN-SERVICE DATE:	12/06/2019		
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK7LU860938		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	0.48	\$56.97	\$0.00	\$0.00	\$56.97
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.51	\$60.38	\$4.28	\$0.00	\$64.66
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.69	\$81.78	\$35.68	\$0.00	\$117.46

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.69</b>	<b>199.13</b>	<b>39.96</b>	<b>0.00</b>	<b>239.09</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-32	DIAGNOSE CRANKING SYSTEM	11213180	10/15/2020 15:01:12	10/15/2020 15:30:10	0.48	\$56.97
66-17-030	PERFORM TIRE PATCH	12052187	10/15/2020 09:19:22	10/15/2020 09:50:04	0.51	\$60.38
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/15/2020 08:30:01	10/15/2020 09:11:36	0.69	\$81.78
					<b>LABOR</b>	<b>199.13</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.50	1	\$3.50
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	6	\$0.36
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.42	1	\$0.42
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					<b>PARTS</b>	<b>39.96</b>

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 38009

---

## Work Order Notes

(LISAPATE) PM-LF tire has a nail in it-Check battery after sitting over weekend has to be jumped off possible draw from lights

---

## Job Notes

### **35-32 - DIAGNOSE CRANKING SYSTEM**

(MSIDES) With all upfitted and outlet accessories unplugged found the vehicle to only have a 4 milli-amp draw. Upon further inspection found positive battery cable to be loose where upfitter installed eyelet connector for lights to be loose, also found a radio battery charger in center console plug into the 12v constant outlet meaning the charger stays on at all times. The combination of these two issues could be the cause of the battery drain. MS

### **66-17-030 - PERFORM TIRE PATCH**

(IFALLS) Repaired rf tire. Aired and balanced. Torqued to spec. Rotated tires also. JAW

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34 ° JAW/JAW

---



# Work Order Charge Detail

**UNIT NO:** 243607      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 39587

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 04/07/2021 10:43:39	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/08/2021 10:49:18	<b>METER 1 - M:</b> 9965 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/09/2021 10:31:46	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$63.85	\$42.24	\$0.00	\$106.09

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.54**      **63.85**      **42.24**      **0.00**      **106.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/07/2021 13:00:00	04/07/2021 13:32:28	0.54	\$63.85
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/07/2021 12:49:37	04/07/2021 12:49:37	0.00	\$0.00
					<b>LABOR</b>	<b>63.85</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
					<b>PARTS</b>	<b>42.24</b>

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 39587

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

03-51-042 - REPLACE NEW KEY FOB BATTERY

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 9965 Completed PM top side, Josh was bottom side. AMG/JW Completed checklist. AMG

(AGUERRA) Left rear tire has a groove worn into the sidewall. Inspected by Isaac and determined tire was still usable. AMG IF

---

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 40650

USING DEPT NO:	507121	OPENED DATE:	08/05/2021 10:27:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/10/2021 10:42:41	METER 1 - M:	12991	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/11/2021 09:42:18	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.93	\$17.89	\$0.00	\$23.82
16-44	TRANSPORT FUEL SYSTEM	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
17-44-003	RECALL FUEL PUMP	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.98	\$115.12	\$50.56	\$0.00	\$165.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>2.03</b>	<b>239.05</b>	<b>68.45</b>	<b>2.00</b>	<b>309.50</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-44-003	RECALL FUEL PUMP	11076422	6126907		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11310047	08/06/2021 14:54:21	08/06/2021 15:50:26	0.93	\$110.30
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/06/2021 14:36:42	08/06/2021 14:39:09	0.04	\$4.82
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/06/2021 08:40:22	08/06/2021 08:43:23	0.05	\$5.93
16-44	TRANSPORT FUEL SYSTEM	11915538	08/09/2021 07:00:00	08/09/2021 08:00:00	1.00	\$118.00
<b>LABOR</b>					<b>2.03</b>	<b>239.05</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.08	5	\$30.38
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.47	1	\$9.47
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.58	1	\$7.58
<b>PARTS</b>					<b>68.45</b>	<b>68.45</b>

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 40650

---

## Work Order Notes

(LISAPATE) PM-Wipers-Recall from Toyota NHTSA recall # 20V-682 a low pressure fuel pump may stop operating

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

### **16-44 - TRANSPORT FUEL SYSTEM**

(LISAPATE) Taken to Toyota by RC

### **17-44-003 - RECALL FUEL PUMP**

(LISAPATE) Toyota completed recall installed new fuel pump

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by EH/AG

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 41458

USING DEPT NO:	507121	OPENED DATE:	10/29/2021 12:48:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2021 07:49:37	METER 1 - M:	14816	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	11/04/2021 07:49:40	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK7LU860938	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.79	\$93.52	\$10.64	\$0.00	\$104.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.79 93.52 10.64 2.00 106.16

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML 2.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11074414	10/29/2021 13:02:41	10/29/2021 13:50:14	0.79	\$93.52
					<b>LABOR</b>	<b>93.52</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
66-17-030	PERFORM TIRE PATCH	21372	HAMATON VALVE STEM TOYOTA	6.35	1	\$6.35
66-17-030	PERFORM TIRE PATCH	58122	.75 OZ WHEEL WEIGHT	0.43	1	\$0.43
					<b>PARTS</b>	<b>10.64</b>

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 41458

---

**Work Order Notes**

(CHANNELL) nail in right front tire

---

**Job Notes**

**66-17-030 - PERFORM TIRE PATCH**

(SHARBIN) Patched right front tire and adjusted all tire pressures. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 41620

USING DEPT NO:	507121	OPENED DATE:	11/15/2021 08:06:14	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	11/16/2021 10:15:47	METER 1 - M:	15478	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/16/2021 11:54:55	IN-SERVICE DATE:	12/06/2019		
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK7LU860938		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.46	\$53.72	\$11.18	\$0.00	\$64.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 2</b>	<b>WORK ORDER TOTAL:</b>					<b>0.46</b>	<b>53.72</b>	<b>11.18</b>	<b>2.00</b>	<b>66.90</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11074414	11/15/2021 08:47:41	11/15/2021 09:15:00	0.46	\$53.72
<b>LABOR</b>						<b>53.72</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	9	\$0.54
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
66-17-030	PERFORM TIRE PATCH	58121	.50 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-030	PERFORM TIRE PATCH	21372	HAMATON VALVE STEM TOYOTA	6.35	1	\$6.35
<b>PARTS</b>						<b>11.18</b>

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 41620

---

**Work Order Notes**

(LISAPATE) Nail in RR tire

---

**Job Notes**

**66-17-030 - PERFORM TIRE PATCH**

(SHARBIN) Patched right rear tire. SH

**CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 42043

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 01/11/2022 09:00:25	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/12/2022 08:21:12	<b>METER 1 - M:</b> 16420 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/12/2022 12:47:25	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.41	\$17.90	\$0.00	\$19.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.66	\$77.55	\$85.05	\$0.00	\$162.60
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.03	\$3.38	\$18.57	\$0.00	\$21.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>0.70</b>	<b>82.34</b>	<b>121.52</b>	<b>2.00</b>	<b>205.86</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML</b> <b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	01/11/2022 15:10:52	01/11/2022 15:12:35	0.03	\$3.38
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/11/2022 15:10:01	01/11/2022 15:10:44	0.01	\$1.41
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/11/2022 15:03:30	01/11/2022 15:09:48	0.11	\$12.39
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/11/2022 14:30:00	01/11/2022 15:03:08	0.55	\$65.16
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/11/2022 14:20:32	01/11/2022 14:20:32	0.00	\$0.00
					<b>LABOR</b>	<b>82.34</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.24	1	\$9.24
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	18.57	1	\$18.57
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	13.02	5	\$65.10
					<b>PARTS</b>	<b>121.52</b>

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 42043

---

**Work Order Notes**

(LISAPATE) PM

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Replaced wiper blades

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH  
MILEAGE-16420

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(JWRIGHT) Replaced cabin filter

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243607      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 43573

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 06/08/2022 10:47:56	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/10/2022 14:26:27	<b>METER 1 - M:</b> 20428 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/13/2022 09:00:33	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.09	\$10.13	\$0.00	\$0.00	\$10.13
09-17-013	ALIGN ALIGNMENT	DON	P	N	GARAGE	0.68	\$80.08	\$0.00	\$0.00	\$80.08
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	P	N	GARAGE	1.05	\$123.51	\$41.66	\$0.00	\$165.17
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.40	\$69.05	\$0.00	\$118.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 5**      **WORK ORDER TOTAL:**      **2.23**      **263.12**      **110.71**      **2.00**      **375.83**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-15	INSPECT STEERING	11074414	06/10/2022 07:44:51	06/10/2022 07:50:00	0.09	\$10.13
09-17-013	ALIGN ALIGNMENT	11310047	06/10/2022 09:51:51	06/10/2022 10:32:34	0.68	\$80.08
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	06/10/2022 07:07:30	06/10/2022 07:44:36	0.62	\$72.96
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	06/09/2022 14:36:31	06/09/2022 15:02:13	0.43	\$50.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/08/2022 14:30:00	06/08/2022 14:55:07	0.42	\$49.40
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/08/2022 14:28:17	06/08/2022 14:28:17	0.00	\$0.00
<b>LABOR</b>					<b>263.11</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21372	HAMATON VALVE STEM TOYOTA	9.63	4	\$38.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	19	\$3.14
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	25.53	1	\$25.53
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.17	1	\$6.17
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.47	5	\$37.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	B110772A	215/55R17 MICH SURVEY TIRES	0.00	4	\$0.00

# Work Order Charge Detail

---

**PARTS**

**110.71**

---

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 43573

---

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **06-15 - INSPECT STEERING**

(HHARBIN) Inspected steering found no issues at this time. SH

### **09-17-013 - ALIGN ALIGNMENT**

(EHOWELL) Performed Alignment. EH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(HHARBIN) SH Mounted JW balanced 4 tires.

LF 1

RF 2

RR 3

LR 4

(EKIMBREL) SURVEY TIRES

### **66-PM-PMA - PERFORM OIL CHANGE**

(HHARBIN) SH Performed PM. Needs 4 tires cut to outer shoulder wear.

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 45485

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 12/08/2022 08:45:02	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/09/2022 10:46:38	<b>METER 1 - M:</b> 23625 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/12/2022 07:53:24	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.05	\$18.41	\$0.00	\$21.46
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.35	\$41.66	\$0.00	\$0.00	\$41.66
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$41.45	\$0.00	\$80.39
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.07	\$8.52	\$20.52	\$0.00	\$29.04
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.78</b>	<b>92.17</b>	<b>80.38</b>	<b>5.00</b>	<b>177.55</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	12/08/2022 14:32:38	12/08/2022 14:36:58	0.07	\$8.52
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/08/2022 14:30:56	12/08/2022 14:32:29	0.03	\$3.05
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/08/2022 14:19:28	12/08/2022 14:19:28	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/08/2022 14:19:28	12/08/2022 14:19:28	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/08/2022 14:19:28	12/08/2022 14:39:16	0.33	\$38.94
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12201267	12/08/2022 14:41:02	12/08/2022 15:02:13	0.35	\$41.66
<b>LABOR</b>					<b>92.17</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.59	1	\$10.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	20.52	1	\$20.52
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.35	1	\$6.35
<b>PARTS</b>					<b>80.38</b>	

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 45485

---

**Work Order Notes**

(EHANNAH) pm- replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

**66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(GARAGE) Performed Tire Rotation and Brake Inspection-GC

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/GC Performed PM.

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(SHARBIN) Replaced the cabin air filter. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243607      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 46868

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 04/27/2023 10:04:54	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/28/2023 09:40:04	<b>METER 1 - M:</b> 24267 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/28/2023 13:24:38	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.28	\$33.17	\$0.00	\$0.00	\$33.17
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.85	\$0.00	\$0.00	\$24.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **0.49**      **58.02**      **0.00**      **5.00**      **63.02**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/27/2023 13:00:00	04/27/2023 13:16:52	0.28	\$33.17
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/27/2023 12:59:07	04/27/2023 12:59:07	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/27/2023 11:10:24	04/27/2023 11:16:18	0.10	\$11.60
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/27/2023 10:50:26	04/27/2023 10:57:10	0.11	\$13.24
<b>LABOR</b>					<b>58.01</b>	



# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 46868

---

## Work Order Notes

(EHANNAH) pm- replace wipers- do SI wash

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-79-003 - PERFORM SAFETY INSPECTION**

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front and rear brake pads measure 6MM. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has been driven 642 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

---

# Work Order Charge Detail

**UNIT NO:** 243607      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 47880

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 08/10/2023 13:41:26	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/11/2023 15:03:14	<b>METER 1 - M:</b> 24596 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/21/2023 08:36:35	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.48	\$56.84	\$24.08	\$0.00	\$80.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.48**      **56.84**      **24.08**      **5.00**      **85.92**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/10/2023 14:30:00	08/10/2023 14:42:18	0.21	\$24.19
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/10/2023 13:58:24	08/10/2023 14:15:00	0.28	\$32.65
<b>LABOR</b>					<b>56.84</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
<b>PARTS</b>					<b>24.08</b>	

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 47880

---

**Work Order Notes**

(EHANNAH) Replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced wipers. JAW

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243607      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 48191

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 09/13/2023 08:39:52	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/14/2023 09:43:45	<b>METER 1 - M:</b> 26175 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/14/2023 13:42:28	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$25.60	\$66.75	\$0.00	\$92.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **0.47**      **55.10**      **66.75**      **5.00**      **126.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/13/2023 09:46:18	09/13/2023 09:59:19	0.22	\$25.60
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	09/14/2023 07:00:00	09/14/2023 07:15:00	0.25	\$29.50
<b>LABOR</b>					<b>55.10</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.46	5	\$42.30
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.34	1	\$11.34
<b>PARTS</b>					<b>66.75</b>	

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 48191

---

## Work Order Notes

(EHANNAH) pm- wash

---

## Job Notes

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(LISAPATE) Rotated tires and inspect4ed brakes. FC rear brakes pad at 4mm needs brake job next PM

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/FC Performed PM.

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

---

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 49742

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 02/08/2024 09:26:41	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/08/2024 13:08:04	<b>METER 1 - M:</b> 28904 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/09/2024 07:27:22	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$32.81	\$57.74	\$0.00	\$90.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.28** **32.81** **57.74** **5.00** **95.55**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/08/2024 10:21:13	02/08/2024 10:37:54	0.28	\$32.81
<b>LABOR</b>						<b>32.81</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.44	5	\$37.20
<b>PARTS</b>						<b>57.74</b>

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 49742

---

**Work Order Notes**

(EHANNAH) pm

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Perform oil changes fc

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 50073

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 03/05/2024 09:12:17	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/06/2024 08:53:59	<b>METER 1 - M:</b> 29358 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/06/2024 10:35:25	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.18	\$21.54	\$0.00	\$0.00	\$21.54
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.18** **21.54** **0.00** **5.00** **26.54**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11074414	03/05/2024 13:00:00	03/05/2024 13:10:57	0.18	\$21.54
14-52-021	INSTALL GPS SYSTEM	11074414	03/05/2024 12:59:58	03/05/2024 12:59:58	0.00	\$0.00
14-52-021	INSTALL GPS SYSTEM	11074414	03/05/2024 13:00:00	03/05/2024 13:10:57	0.18	\$21.54
14-52-021	INSTALL GPS SYSTEM	11074414	03/05/2024 12:59:58	03/05/2024 12:59:58	0.00	\$0.00
14-52-021	INSTALL GPS SYSTEM	11074414	03/05/2024 13:00:00	03/05/2024 13:10:57	(0.18)	(\$21.54)
14-52-021	INSTALL GPS SYSTEM	11074414	03/05/2024 12:59:58	03/05/2024 12:59:58	0.00	\$0.00
<b>LABOR</b>					<b>21.54</b>	



# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 50073

---

**Work Order Notes**

(EHANNAH) install GPS

---

**Job Notes**

**14-52-021 - INSTALL GPS SYSTEM**

(GARAGE) Installed GPS# 87U030240186. SH

(IFALLS) Visit Reason Changed On 3/6/2024 10:35 AM By IFALLS

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 51254

USING DEPT NO:	507121	OPENED DATE:	06/21/2024 10:50:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/21/2024 14:47:17	METER 1 - M:	32146	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/21/2024 15:59:26	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$61.29	\$0.00	\$61.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>61.29</b>	<b>5.00</b>	<b>66.29</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.86	1	\$6.86
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.26	5	\$41.32
					<b>PARTS</b>	<b>61.29</b>

# Work Order Charge Detail

UNIT NO: 243607 2020 TOYOTA CAMRY

WORK ORDER NO: 51254

---

## Work Order Notes

(EHANNAH) DIANOSE mold smell in AC

---

## Job Notes

### **35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT**

(GARAGE) Inspected and could not smell anything in the a/c. Filter is clean. Sprayed deoderizer into evaporator drain and ran for 15 minutes. Found no issues. JAW

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(GARAGE) Rotated tires and inspected brakes-FC,SH, Brake pads are 7mm front and 7mm rear

### **66-PM-PMA - PERFORM OIL CHANGE**

(EKIMBREL) Cancelled from Work Order# 51254. By User ID EHANNAH on 6/21/2024 10:51 AM.

The job was restored for Work Order# 51254. By User ID EKIMBREL on 6/21/2024 1:07 PM.

(GARAGE) Performed PM-GC,FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

Miles, 32,146

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 51477

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 07/15/2024 09:43:50	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/18/2024 08:40:09	<b>METER 1 - M:</b> 32320 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/18/2024 10:46:26	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.00	\$0.00	\$22.88	\$0.00	\$22.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 2</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>22.88</b>	<b>5.00</b>	<b>27.88</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
03-51-038	REPLACE NEW WIPER BLADES	XC26	26" WIPER	12.00	1	\$12.00
<b>PARTS</b>						<b>22.88</b>

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 51477

---

**Work Order Notes**

(LRUSHING) Replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced wiper blades. JAW

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 51669

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 08/01/2024 11:52:21	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/12/2024 08:19:25	<b>METER 1 - M:</b> 32719 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/12/2024 10:32:43	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK7LU860938	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 2</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 243607 2020 TOYOTA CAMRY

**WORK ORDER NO:** 51669

---

**Work Order Notes**

(LRUSHING) prep for sale - remove gps from S2845C into S8260B

---

**Job Notes**

**25-52-021 - REMOVE GPS SYSTEM**

(GARAGE) Removed GPS SN: 87U030240186 out of unit 2845C-GC

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) removed wordmarks and tag\RC

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Tue Aug 13 2024 14:24:12 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.serial\_no} = '4T1C11AK7LU860938') //Q=