

# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 35092

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 12/06/2019 14:44:10	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/10/2019 07:20:42	<b>METER 1 - M:</b> 53 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/10/2019 07:20:43	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.50**      **0.00**      **0.00**      **0.00**      **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	12/06/2019 14:44:38	12/06/2019 15:14:38	0.50	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 35092

---

**Work Order Notes**

(LISAPATE) New unit do PDI

---

**Job Notes**

**PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION**

(LISAPATE) PDI completed

---

# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 35185

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 12/13/2019 09:17:33	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/19/2019 15:23:03	<b>METER 1 - M:</b> 53 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/19/2019 15:23:05	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$210.00	\$210.00
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	0.69	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.69**      **0.00**      **0.00**      **210.00**      **210.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
14-78-028	INSTALL WINDOW TINT	5564144	31967		\$210.00
					<b>COMML</b> <b>210.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	11915538	12/13/2019 11:13:12	12/13/2019 11:54:52	0.69	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 35185

---

**Work Order Notes**

(LISAPATE) Install window tint per driver

---

**Job Notes**

**14-78-028 - INSTALL WINDOW TINT**

(EKIMBREL) Bama Trim installed window tint.

**16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE**

(EKIMBREL) Transported vehicle to and from Bama Trim.

---

# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 36543

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 05/21/2020 13:03:01	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/21/2020 14:52:05	<b>METER 1 - M:</b> 2087 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/22/2020 09:41:45	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.84	\$0.00	\$24.03	\$0.00	\$24.03

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.84**      **0.00**      **24.03**      **0.00**      **24.03**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/21/2020 13:29:46	05/21/2020 13:58:17	0.48	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/21/2020 13:30:18	05/21/2020 13:52:18	0.37	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.94	5	\$19.70
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
					<b>PARTS</b>	<b>24.03</b>

# Work Order Charge Detail

UNIT NO: 243605 2020 TOYOTA CAMRY

WORK ORDER NO: 36543

---

**Work Order Notes**

(EKIMBREL) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(EKIMBREL) SH/JW performed pm. Coolant -20

---

# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 37984

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 10/13/2020 14:07:55	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/14/2020 08:25:46	<b>METER 1 - M:</b> 4271 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/14/2020 12:51:26	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.45	\$53.40	\$35.68	\$0.00	\$89.08

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.45**      **53.40**      **35.68**      **0.00**      **89.08**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/13/2020 14:11:38	10/13/2020 14:33:38	0.37	\$43.27
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/13/2020 14:25:46	10/13/2020 14:30:55	0.09	\$10.13
					<b>LABOR</b>	<b>53.40</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					<b>PARTS</b>	<b>35.68</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 37984

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH AMG/JW PERFORMED PM.

---



# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**

**WORK ORDER NO:** 39368

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 03/10/2021 13:32:41	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/11/2021 11:22:03	<b>METER 1 - M:</b> 6984 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/12/2021 10:38:52	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLAC	DON	O	N	GARAGE	0.10	\$11.80	\$11.06	\$0.00	\$22.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.49	\$57.56	\$53.28	\$0.00	\$110.84

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.59**      **69.36**      **64.34**      **0.00**      **133.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	12052187	03/12/2021 07:00:00	03/12/2021 07:06:00	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/10/2021 14:30:00	03/10/2021 14:59:16	0.49	\$57.56
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/10/2021 14:22:15	03/10/2021 14:22:15	0.00	\$0.00
					<b>LABOR</b>	<b>69.36</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	800208CTYC	CABIN AIR FILTER	11.06	1	\$11.06
66-PM-PMA	PERFORM OIL CHANGE	5066517	WSWF RAIN-X -20DEG DEICER GAL	6.89	1	\$6.89
					<b>PARTS</b>	<b>64.34</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 39368

---

**Work Order Notes**

(LISAPATE) PM

**Job Notes**

**03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT**

(EHOWELL) JAW replaced cabin filter.

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -35°. JAW,AMG/JAW  
MILEAGE-6984

---

# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 39465

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 03/22/2021 15:24:05	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/22/2021 15:25:54	<b>METER 1 - M:</b> 7070 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/24/2021 08:40:21	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$46.00	\$46.00

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.00**      **0.00**      **0.00**      **46.00**      **46.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-02-061	REPAIR WINDSHIELD	11078716	285814		\$46.00
				<b>COMML</b>	<b>46.00</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 39465

---

**Work Order Notes**

(LISAPATE) Sanford took car to Glass Dr and had windshield repaired.

---

**Job Notes**

**24-02-061 - REPAIR WINDSHIELD**

(LISAPATE) Glass Dr repaired ding in the windshield

---

# Work Order Charge Detail

UNIT NO: 243605 2020 TOYOTA CAMRY

WORK ORDER NO: 39872

USING DEPT NO:	507121	OPENED DATE:	05/04/2021 11:47:25	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	05/10/2021 12:29:44	METER 1 - M:	7884	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/10/2021 15:35:31	IN-SERVICE DATE:	12/06/2019		
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3LU861729		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.40	\$47.30	\$185.21	\$0.00	\$232.51
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.29	\$33.76	\$0.00	\$0.00	\$33.76
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.15	\$17.11	\$0.00	\$0.00	\$17.11

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>1.83</b>	<b>216.17</b>	<b>185.21</b>	<b>0.00</b>	<b>401.38</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
CH-32-002	CHARGE BATTERY	11901357	05/04/2021 13:18:01	05/04/2021 13:26:43	0.15	\$17.11
03-32-002	REPLACE NEW BATTERY	11213180	05/05/2021 08:50:57	05/05/2021 09:15:00	0.40	\$47.30
35-32	DIAGNOSE CRANKING SYSTEM	11213180	05/10/2021 07:00:00	05/10/2021 08:00:00	1.00	\$118.00
66-79-002	PERFORM SERVICE CALL	11901357	05/04/2021 13:00:00	05/04/2021 13:17:10	0.29	\$33.76
66-79-002	PERFORM SERVICE CALL	11901357	05/04/2021 12:00:45	05/04/2021 12:00:45	0.00	\$0.00
					<b>LABOR</b>	<b>216.17</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	H5AGM	BATTERY DIN H5 AGM 345 CCA	185.21	1	\$185.21
					<b>PARTS</b>	<b>185.21</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 39872

---

## Work Order Notes

(LISAPATE) Daniel Sanford requested a service call to the Campus Drive deck battery is dead on car

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) Replaced battery

### **35-32 - DIAGNOSE CRANKING SYSTEM**

(LISAPATE) Found battery voltage to be at 10.5 volts, which indicated a weak cell caused by charger for radio in rear floor going straight to the battery . Notified dept. MS

### **66-79-002 - PERFORM SERVICE CALL**

(AGUERRA) Jumped vehicle off and brought back to shop for repairs. AMG JW

### **CH-32-002 - CHARGE BATTERY**

(LISAPATE) Charged battery. Returned to Daniel. Battery was dead again that evening.

---

# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 40687

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 08/10/2021 08:48:09	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/12/2021 10:46:55	<b>METER 1 - M:</b> 9356 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/16/2021 08:06:56	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$22.62	\$0.00	\$34.42
16-44	TRANSPORT FUEL SYSTEM	DON	O	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80
17-44-003	RECALL FUEL PUMP	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.13	\$15.67	\$0.00	\$0.00	\$15.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$63.49	\$50.56	\$0.00	\$114.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT:</b> 6	<b>WORK ORDER TOTAL:</b>	<b>0.87</b>	<b>102.76</b>	<b>73.18</b>	<b>2.00</b>	<b>177.94</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-44-003	RECALL FUEL PUMP	11076422	6127384		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/10/2021 10:14:35	08/10/2021 10:20:35	0.10	\$11.80
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/10/2021 10:14:35	08/10/2021 10:14:47	0.00	\$0.39
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/10/2021 10:14:35	08/10/2021 10:14:47	0.00	(\$0.39)
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/10/2021 10:16:57	08/10/2021 10:31:55	0.25	\$29.43
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/10/2021 10:14:58	08/10/2021 10:32:17	0.29	\$34.06
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	08/10/2021 10:36:26	08/10/2021 10:44:24	0.13	\$15.67
16-44	TRANSPORT FUEL SYSTEM	11915538	08/12/2021 07:00:00	08/12/2021 07:06:00	0.10	\$11.80
<b>LABOR</b>					<b>102.76</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.08	5	\$30.38
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.47	1	\$9.47
					<b>PARTS</b>	<b>73.18</b>



# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 40687

---

**Work Order Notes**

(LISAPATE) PM-replace wipers-Take to Toyota for recall NHTSA 20V-682 vehicles equipped with a low pressure fuel pump may stop operating

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Installed new wiper blades

**16-44 - TRANSPORT FUEL SYSTEM**

(LISAPATE) Taken to Toyota by RC

**17-44-003 - RECALL FUEL PUMP**

(LISAPATE) Tuscaloosa Toyota completed recall installed fuel pump kit

**66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(JWRIGHT) Rotated tires. All pads are good. Torqued lugs to spec. JAW,SH

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH  
MILEAGE-9356

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 42579

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 03/07/2022 08:41:46	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/08/2022 10:59:33	<b>METER 1 - M:</b> 12890 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/08/2022 14:11:01	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.91	\$49.71	\$0.00	\$92.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** 0.36 42.91 49.71 2.00 94.62

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/07/2022 09:30:00	03/07/2022 09:46:43	0.28	\$32.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/07/2022 09:19:04	03/07/2022 09:19:04	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/07/2022 09:30:00	03/07/2022 09:35:06	0.09	\$10.03
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/07/2022 09:16:30	03/07/2022 09:16:30	0.00	\$0.00
<b>LABOR</b>					<b>42.91</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.40	1	\$5.40
<b>PARTS</b>					<b>49.71</b>	

# Work Order Charge Detail

UNIT NO: 243605 2020 TOYOTA CAMRY

WORK ORDER NO: 42579

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Cancelled from Work Order# 42337. By User ID EKIMBREL on 2/18/2022 2:53 PM.

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/JAW

MILEAGE-12890

### CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

UNIT NO: 243605 2020 TOYOTA CAMRY

WORK ORDER NO: 44207

USING DEPT NO:	507121	OPENED DATE:	08/08/2022 08:02:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/10/2022 11:39:15	METER 1 - M:	17096	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/12/2022 14:33:33	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK3LU861729	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.99	\$90.67	\$0.00	\$140.66
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$35.40	\$20.52	\$0.00	\$55.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.72</b>	<b>85.39</b>	<b>111.19</b>	<b>2.00</b>	<b>198.58</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	08/08/2022 12:11:47	08/08/2022 12:11:47	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	08/08/2022 12:11:47	08/08/2022 12:11:47	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	08/08/2022 12:11:47	08/08/2022 12:29:47	0.30	\$35.40
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/08/2022 10:56:30	08/08/2022 11:21:55	0.42	\$49.99
<b>LABOR</b>					<b>85.39</b>	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.01	5	\$35.03
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.41	1	\$9.41
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	20.52	1	\$20.52
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	33.12	1	\$33.12
<b>PARTS</b>					<b>111.19</b>	

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 44207

---

**Work Order Notes**

(LISAPATE) PM

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(HHARBIN) Performed PM. SH

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(AGUERRA) Replaced cabin filter. AMG

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 44724

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 09/20/2022 07:11:40	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/20/2022 15:26:19	<b>METER 1 - M:</b> 21236 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/20/2022 15:38:36	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$31.20	\$52.10	\$0.00	\$83.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.26** **31.20** **52.10** **5.00** **88.30**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/20/2022 07:21:10	09/20/2022 07:37:02	0.26	\$31.20
					<b>LABOR</b>	<b>31.20</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.81	5	\$34.05
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.77	1	\$7.77
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	10.28	1	\$10.28
					<b>PARTS</b>	<b>52.10</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 44724

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH EH/AMG Performed PM.

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 45280

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 11/16/2022 07:34:48	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/17/2022 10:26:54	<b>METER 1 - M:</b> 25554 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/17/2022 12:24:08	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.66	\$23.26	\$0.00	\$25.92
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.61	\$41.45	\$0.00	\$72.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.28</b>	<b>33.27</b>	<b>64.71</b>	<b>5.00</b>	<b>102.98</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/16/2022 07:59:01	11/16/2022 08:00:22	0.02	\$2.66
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/16/2022 07:43:27	11/16/2022 07:59:01	0.26	\$30.61
<b>LABOR</b>					<b>33.27</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.35	1	\$6.35
<b>PARTS</b>					<b>64.71</b>	



# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 45280

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced wipers. JAW

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) performed pm service. coolant -34. JAW/GC  
MILEAGE-25554

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 46721

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 04/14/2023 08:09:15	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/14/2023 15:13:12	<b>METER 1 - M:</b> 27268 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/17/2023 10:05:29	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.22	\$26.29	\$0.00	\$0.00	\$26.29
06-17-020	INSPECT MUD FLAPS	DON	O	N	GARAGE	0.11	\$12.82	\$0.00	\$0.00	\$12.82
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.31	\$36.97	\$0.00	\$0.00	\$36.97
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$25.44	\$0.00	\$0.00	\$25.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.86</b>	<b>101.52</b>	<b>0.00</b>	<b>5.00</b>	<b>106.52</b>
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/14/2023 09:45:37	04/14/2023 09:58:33	0.22	\$25.44
06-17-020	INSPECT MUD FLAPS	11074414	04/14/2023 10:00:18	04/14/2023 10:06:49	0.11	\$12.82
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/14/2023 10:07:04	04/14/2023 10:25:52	0.31	\$36.97
06-13	INSPECT BRAKES	11074414	04/14/2023 10:26:09	04/14/2023 10:39:31	0.22	\$26.29
<b>LABOR</b>					<b>101.52</b>	

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 46721

---

## Work Order Notes

(EHANNAH) pm- replace wipers - do SI- wash- brakes are squeaking- mud flap is loose.

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

**06-13 - INSPECT BRAKES**

(SHARBIN) Inspected the brakes front and rear pads measure 6MM. Test drove the vehicle making several stops. I did not experience the brakes squealing at this time. It's possible there was moisture on the rotors causing the squealing. SH

**06-17-020 - INSPECT MUD FLAPS**

(SHARBIN) The screw was missing from the mud flap. Installed a screw and washer rechecks good .15 labor. SH

**66-79-003 - PERFORM SAFETY INSPECTION**

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front and rear pads measure 6MM. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has been driven 1714 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(LISAPATE) UAPD

---

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 47960

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 08/23/2023 09:19:42	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/25/2023 09:41:00	<b>METER 1 - M:</b> 29540 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/25/2023 12:44:46	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.12	\$14.32	\$24.08	\$0.00	\$38.40
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.23	\$27.21	\$0.00	\$0.00	\$27.21
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.56	\$66.60	\$0.00	\$0.00	\$66.60
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.99	\$116.92	\$763.73	\$0.00	\$880.65
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$47.86	\$61.19	\$0.00	\$109.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT:</b> 6	<b>WORK ORDER TOTAL:</b>	<b>2.31</b>	<b>272.91</b>	<b>849.00</b>	<b>5.00</b>	<b>1,126.91</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/23/2023 10:01:18	08/23/2023 10:25:38	0.41	\$47.86
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/23/2023 10:25:50	08/23/2023 10:33:07	0.12	\$14.32
06-15	INSPECT STEERING	11074414	08/23/2023 10:33:16	08/23/2023 10:47:06	0.23	\$27.21
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/23/2023 10:56:55	08/23/2023 11:55:04	0.97	\$114.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/23/2023 13:10:32	08/23/2023 13:11:50	0.02	\$2.56
66-17-013	PERFORM ALIGNMENT	11310047	08/24/2023 07:58:22	08/24/2023 08:32:14	0.56	\$66.60
					<b>LABOR</b>	<b>272.91</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.46	5	\$42.30
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.78	1	\$5.78

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21372	HAMATON VALVE STEM TOYOTA	11.82	4	\$47.28
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.26	39	\$9.95
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1557627	TIRE 215/55R17 GEN ALTIMAX	176.63	4	\$706.50
					<b>PARTS</b>	<b>849.00</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 47960

---

## Work Order Notes

(EHANNAH) pm- wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) FC Replaced the wipers. SH

### **06-15 - INSPECT STEERING**

(SHARBIN) Inspected the steering. Found no issues at this time. SH

### **66-17-013 - PERFORM ALIGNMENT**

(EHOWELL) Performed 4 wheel alignment. EH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(SHARBIN) Mounted and balanced 4 tires. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/FC Performed PM. Vehicle needs 4 tires due to tread depth and shoulder wear. SH

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 49573

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 01/25/2024 07:58:06	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/29/2024 09:31:58	<b>METER 1 - M:</b> 31553 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/29/2024 11:33:41	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$2.33	\$57.74	\$0.00	\$60.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.02**      **2.33**      **57.74**      **5.00**      **65.07**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/25/2024 14:52:25	01/25/2024 14:53:36	0.02	\$2.33
						<b>LABOR</b> <b>2.33</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.44	5	\$37.20
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
						<b>PARTS</b> <b>57.74</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 49573

---

**Work Order Notes**

(EHANNAH) pm

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) perform oil changes fc -rc

**CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 50119

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 03/08/2024 08:45:30	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/21/2024 07:31:04	<b>METER 1 - M:</b> 32161 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/21/2024 08:43:43	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.15	\$17.67	\$0.00	\$0.00	\$17.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.15**      **17.67**      **0.00**      **5.00**      **22.67**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11074414	03/08/2024 08:51:35	03/08/2024 09:00:34	0.15	\$17.67
<b>LABOR</b>						<b>17.67</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 50119

---

**Work Order Notes**

(EHANNAH) install GPS

---

**Job Notes**

**14-52-021 - INSTALL GPS SYSTEM**

(GARAGE) Installed GPS# 87U030240142. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 51290

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 06/25/2024 08:23:51	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/26/2024 09:26:19	<b>METER 1 - M:</b> 33350 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/26/2024 12:15:51	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	N	N	GARAGE	0.00	\$0.00	\$168.38	\$0.00	\$168.38
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	N	N	GARAGE	0.00	\$0.00	\$131.33	\$0.00	\$131.33
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$181.85	\$0.00	\$181.85
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$0.95	\$0.00	\$0.00	\$0.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.01</b>	<b>0.95</b>	<b>481.56</b>	<b>5.00</b>	<b>487.51</b>
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/25/2024 08:44:37	06/25/2024 08:45:06	0.01	\$0.95
					<b>LABOR</b>	<b>0.95</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.23	5	\$1.13
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.33	1	\$3.33
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR172076	FRONT BRAKE PADS	68.69	1	\$68.69
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	FBR982292	FRONT ROTORS	49.85	2	\$99.69
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBR982285	REAR ROTORS	46.62	2	\$93.24
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWR171212	REAR PADS	38.09	1	\$38.09
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1557737	TIRE 215/55R17 GEN ALTIMAX	177.39	1	\$177.39
					<b>PARTS</b>	<b>481.56</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 51290

---

## Work Order Notes

(EHANNAH) pm- rear brakes are squeaking

---

## Job Notes

### **03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(GARAGE) Replaced front pads and rotors. JAW

### **03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS**

(GARAGE) Replaced rear pads and rotors. JAW  
Bedded brakes.

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(EKIMBREL) jw replaced 1 tire

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed fluid check. SH

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243605      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 51681

<b>USING DEPT NO:</b>	507121	<b>OPENED DATE:</b>	08/02/2024 09:29:16	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	08/05/2024 09:20:22	<b>METER 1 - M:</b>	33862	<b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	08/05/2024 10:10:24	<b>IN-SERVICE DATE:</b>	12/06/2019	
<b>TECH SPEC NO:</b>	20TOYOTACAMRY	2020 Toyota Camry		<b>UNIT SERIAL NO:</b>	4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
<b>JOB COUNT: 1</b>						<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>

# Work Order Charge Detail

UNIT NO: 243605 2020 TOYOTA CAMRY

WORK ORDER NO: 51681

---

**Work Order Notes**

(EHANNAH) remove GPS- 2907C

---

**Job Notes**

**25-52-021 - REMOVE GPS SYSTEM**

(EHOWELL) Removed GPS# 87U030240142. Reinstalled into unit S2907C.

(GARAGE) The customer left our facility in this vehicle after the GPS was removed. EH

---

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 51735

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 08/07/2024 12:46:01	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/13/2024 08:14:25	<b>METER 1 - M:</b> 33862 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/13/2024 11:20:37	<b>IN-SERVICE DATE:</b> 12/06/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK3LU861729	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.00	\$0.00	\$0.00	\$2.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.02** **2.00** **0.00** **2.00** **4.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML</b> <b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	08/12/2024 14:16:58	08/12/2024 14:17:59	0.02	\$2.00
					<b>LABOR</b>	<b>2.00</b>

# Work Order Charge Detail

**UNIT NO:** 243605 2020 TOYOTA CAMRY

**WORK ORDER NO:** 51735

---

**Work Order Notes**

(EHANNAH) prep for sale  
(EHOWELL) The GPS was previously removed from the vehicle. See work order #51681.

---

**Job Notes**

**CH-SP - CHARGE Shop Supplies**

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) No wordmarks. Removed tag 2849C. Checked inside of vehicle. CW

---



# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Wed Aug 21 2024 12:08:59 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '243605' //Q=