

Work Order Charge Detail

UNIT NO: 243608 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 35090

USING DEPT NO: 507121	OPENED DATE: 12/06/2019 14:41:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/10/2019 07:22:43	METER 1 - M: 54 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/10/2019 07:22:44	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	12/06/2019 14:41:39	12/06/2019 15:11:39	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 35090

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 243608 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 35403

USING DEPT NO: 507121	OPENED DATE: 01/15/2020 07:46:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/22/2020 06:46:22	METER 1 - M: 667 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/22/2020 06:46:25	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$210.00	\$210.00
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **0.00** **0.00** **210.00** **210.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
14-78-028	INSTALL WINDOW TINT	5564144	32039		\$210.00
					COMML 210.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	11268671	01/16/2020 07:00:00	01/16/2020 08:00:00	1.00	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 35403

Work Order Notes

(LISAPATE) Tint windows per Josh Kelley- Take to Bama Trim

Job Notes

14-78-028 - INSTALL WINDOW TINT

(LISAPATE) All windows were tinted and strip across windshield. PD by CC

16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(LISAPATE) Taken to Bama Trim by IF

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY WORK ORDER NO: 36438

USING DEPT NO:	507121	OPENED DATE:	05/14/2020 13:48:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/15/2020 10:15:21	METER 1 - M:	1063	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/15/2020 10:15:26	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.86	\$0.00	\$24.03	\$0.00	\$24.03

JOB COUNT: 1 WORK ORDER TOTAL: 0.86 0.00 24.03 0.00 24.03

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/15/2020 07:07:29	05/15/2020 07:58:57	0.86	\$0.00

LABOR 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.94	5	\$19.70

PARTS 24.03

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 36438

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/JW performed pm. Coolant -34
Put lightbar back up on windshield

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 38208

USING DEPT NO: 507121	OPENED DATE: 10/29/2020 10:26:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/30/2020 09:27:55	METER 1 - M: 2836 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/30/2020 09:56:07	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.63	\$0.00	\$0.00	\$35.63

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.30** **35.63** **0.00** **0.00** **35.63**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/29/2020 12:21:07	10/29/2020 12:38:33	0.29	\$34.29
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/29/2020 12:27:50	10/29/2020 12:28:31	0.01	\$1.34
					LABOR	35.63

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 38208

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1773 miles since pm. Updated sticker and checked all fluids. Coolant -34 JAW,AMG

Work Order Charge Detail

UNIT NO: 243608 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 39594

USING DEPT NO: 507121	OPENED DATE: 04/07/2021 15:43:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/08/2021 10:36:39	METER 1 - M: 5593 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/09/2021 10:34:05	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.17	\$35.68	\$0.00	\$68.85

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.28** **33.17** **35.68** **0.00** **68.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/08/2021 09:30:14	04/08/2021 09:47:06	0.28	\$33.17
					LABOR	33.17

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
					PARTS	35.68

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 39594

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/JAW
MILEAGE-5593

Work Order Charge Detail

UNIT NO: 243608 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 40163

USING DEPT NO: 507121	OPENED DATE: 06/14/2021 08:44:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/18/2021 13:37:33	METER 1 - M: 6232 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/18/2021 13:37:44	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **57.50** **57.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-02-061	REPAIR WINDSHIELD	11078716	2-89425		\$57.50
				COMML	57.50

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 40163

Work Order Notes

(CHANNELL) crack in windshield

Job Notes

24-02-061 - REPAIR WINDSHIELD

(CHANNELL) Glass Dr. came to shop and repaired chip in windshield.

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY WORK ORDER NO: 40229

USING DEPT NO:	507121	OPENED DATE:	06/22/2021 12:36:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/23/2021 13:48:28	METER 1 - M:	6549	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/23/2021 13:48:32	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50

JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 0.00 57.50 57.50

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-02-061	REPAIR WINDSHIELD	11078716	2-89816		\$57.50
				COMML	57.50

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 40229

Work Order Notes

(CHANNELL) rock crack in windshield\ glass doctor

Job Notes

24-02-061 - REPAIR WINDSHIELD

(IFALLS) glass doctor repaired windshield at our shop.

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 40621

USING DEPT NO: 507121	OPENED DATE: 08/03/2021 13:17:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/09/2021 13:54:33	METER 1 - M: 7617 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/09/2021 14:52:03	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.54	\$17.89	\$0.00	\$21.43
16-44	TRANSPORT FUEL SYSTEM	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
17-44-003	RECALL FUEL PUMP	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$62.41	\$39.83	\$0.00	\$102.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.56	183.95	57.72	2.00	243.67
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-44-003	RECALL FUEL PUMP	11076422	6126626		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/05/2021 07:46:34	08/05/2021 07:48:22	0.03	\$3.54
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/05/2021 07:14:38	08/05/2021 07:46:22	0.53	\$62.41
16-44	TRANSPORT FUEL SYSTEM	11915538	08/09/2021 07:00:00	08/09/2021 08:00:00	1.00	\$118.00
LABOR					183.95	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	7.46	1	\$7.46
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.08	5	\$30.38
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.45	1	\$9.45
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	7.46	(1)	(\$7.46)
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.58	1	\$7.58
PARTS					57.72	

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 40621

Work Order Notes

(LISAPATE) Take to Tuscaloosa Toyota for recall 20V-682 low pressure fuel pump may stop operating-PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades. JAW,RC

16-44 - TRANSPORT FUEL SYSTEM

(LISAPATE) Taken to Toyota by RC

17-44-003 - RECALL FUEL PUMP

(LISAPATE) Tuscaloosa Toyota completed recall installed new fuel pump

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,RC/JAW
MILEAGE-7617

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 41966

USING DEPT NO: 507121	OPENED DATE: 01/05/2022 07:56:28	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/06/2022 08:21:21	METER 1 - M: 9614 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/06/2022 11:05:30	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$17.90	\$0.00	\$35.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.01	\$0.00	\$0.00	\$21.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	38.71	17.90	2.00	58.61
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/06/2022 07:00:00	01/06/2022 07:09:00	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/05/2022 09:47:39	01/05/2022 09:58:20	0.18	\$21.01
LABOR					38.71	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
PARTS					17.90	

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 41966

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1900 miles. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-9614

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 42795

USING DEPT NO: 507121	OPENED DATE: 04/01/2022 11:40:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/18/2022 15:12:14	METER 1 - M: 9863 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/20/2022 08:56:04	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$730.25	\$730.25
03-78-028	REPLACE NEW WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$23.00	\$23.00
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** 0.50 59.00 0.00 755.25 814.25

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	297600		\$730.25
03-78-028	REPLACE NEW WINDOW TINT	8616313	1501		\$23.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					755.25

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	11399745	04/18/2022 07:00:00	04/18/2022 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 42795

Work Order Notes

(LISAPATE) Windshield has a large crack running down.

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield and recalibrated. Pd by CC

(LISAPATE) No transport needed driver took and picked up from Glass DR

03-78-028 - REPLACE NEW WINDOW TINT

(LISAPATE) Custom Films installed new tint strip on the windshield after replaced. Pd by CC

16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(LISAPATE) CW took car to Custom Films

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 43572

USING DEPT NO: 507121	OPENED DATE: 06/08/2022 10:47:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/09/2022 09:58:33	METER 1 - M: 11973 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/10/2022 10:16:16	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.13	\$15.41	\$0.00	\$0.00	\$15.41
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$62.93	\$43.52	\$0.00	\$106.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.66	78.34	43.52	2.00	123.86
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	06/08/2022 14:07:10	06/08/2022 14:15:00	0.13	\$15.41
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/08/2022 13:31:23	06/08/2022 14:03:23	0.53	\$62.93
LABOR					78.34	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.17	1	\$6.17
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.47	5	\$37.35
PARTS					43.52	

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 43572

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(HHARBIN) Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 43701

USING DEPT NO: 507121	OPENED DATE: 06/21/2022 12:19:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/23/2022 09:18:33	METER 1 - M: 11980 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/27/2022 13:49:59	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **118.00** **0.00** **2.00** **120.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11213180	06/23/2022 07:00:00	06/23/2022 07:09:00	(0.15)	(\$17.70)
CH-32-002	CHARGE BATTERY	11213180	06/23/2022 07:00:00	06/23/2022 07:09:00	0.15	\$17.70
CH-32-002	CHARGE BATTERY	11213180	06/23/2022 07:00:00	06/23/2022 08:00:00	1.00	\$118.00
LABOR						118.00

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 43701

Work Order Notes

(LISAPATE) Check battery had to jump off

Job Notes

CH-32-002 - CHARGE BATTERY

(MSIDES) Charged battery and found radio behind center console to be causing drain. MS

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 45478

USING DEPT NO: 507121	OPENED DATE: 12/07/2022 14:01:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/08/2022 11:11:47	METER 1 - M: 15426 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/08/2022 14:12:29	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.24	\$18.41	\$0.00	\$23.65
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.45	\$171.62	\$41.45	\$0.00	\$213.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.50	176.86	59.86	5.00	241.72
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/08/2022 08:23:45	12/08/2022 08:25:49	0.03	\$4.06
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/08/2022 07:48:02	12/08/2022 08:23:26	0.59	\$69.62
66-PM-PMA	PERFORM OIL CHANGE	12201267	12/08/2022 07:29:13	12/08/2022 08:19:01	0.83	\$97.94
03-51-038	REPLACE NEW WIPER BLADES	12201267	12/07/2022 15:33:55	12/07/2022 15:36:35	0.04	\$5.24
LABOR					176.86	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.59	1	\$10.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.35	1	\$6.35
PARTS					59.86	

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 45478

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 15426 Completed PM topside, Greg was bottomside. AMG/GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 46883

USING DEPT NO: 507121	OPENED DATE: 04/27/2023 13:01:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/02/2023 11:32:22	METER 1 - M: 17500 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/04/2023 11:56:24	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$661.25	\$661.25
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$46.00	\$46.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.11	\$13.08	\$0.00	\$0.00	\$13.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$47.82	\$41.36	\$0.00	\$89.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7 **WORK ORDER TOTAL:** **1.52** **178.90** **41.36** **712.25** **932.51**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	2108190		\$661.25
14-78-028	INSTALL WINDOW TINT	8616313	2056		\$46.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					712.25

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	11915538	05/02/2023 07:00:00	05/02/2023 07:30:00	0.50	\$59.00
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	11915538	05/02/2023 07:30:00	05/02/2023 08:00:00	0.50	\$59.00
66-79-003	PERFORM SAFETY INSPECTION	12052187	04/27/2023 14:10:15	04/27/2023 14:16:54	0.11	\$13.08
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/27/2023 13:42:56	04/27/2023 14:07:15	0.41	\$47.82
LABOR					178.90	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.81	1	\$5.81
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.11	5	\$35.55
PARTS					41.36	

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 46883

Work Order Notes

(EHANNAH) pm- replace wiper- wash

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield. PD by CC

(LISAPATE) Install new RFID sticker

14-78-028 - INSTALL WINDOW TINT

(LISAPATE) Custom Films installed new windshield tint strip on windshield after windshield was replaced. PD by CC

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by RC/CW

16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(LISAPATE) Taken to Custom Films by RC/CW

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. Found Crack in left lower corner of windshield, needs replaced. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-17844

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) do not wash uapd

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 48251

USING DEPT NO: 507121	OPENED DATE: 09/19/2023 08:14:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/20/2023 13:38:05	METER 1 - M: 22773 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/22/2023 09:42:21	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.31	\$86.63	\$0.00	\$109.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.20** **23.31** **86.63** **5.00** **114.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/19/2023 10:47:56	09/19/2023 10:59:47	0.20	\$23.31
					LABOR	23.31

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	35.61	1	\$35.61
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.07	1	\$7.07
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.79	5	\$43.95
					PARTS	86.63

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 48251

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 49326

USING DEPT NO: 507121	OPENED DATE: 01/03/2024 09:44:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/04/2024 08:58:56	METER 1 - M: 29379 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/04/2024 11:55:58	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$2.13	\$62.56	\$0.00	\$64.69
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.02** **2.13** **62.56** **5.00** **69.69**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/03/2024 11:34:45	01/03/2024 11:35:50	0.02	\$2.13
LABOR						2.13

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	11.03	5	\$55.13
PARTS						62.56

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 49326

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 49800

USING DEPT NO: 507121	OPENED DATE: 02/14/2024 11:46:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/01/2024 14:07:56	METER 1 - M: 31681 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/01/2024 15:14:34	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.31	\$36.22	\$225.15	\$0.00	\$261.37
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.81	95.22	225.15	5.00	325.37
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	12201267	03/01/2024 07:00:00	03/01/2024 07:30:00	0.50	\$59.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	02/16/2024 14:40:15	02/16/2024 14:58:40	0.31	\$36.22
LABOR					95.22	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.62	1	\$3.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.23	7	\$1.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000067	TIRE 215/55R17 BSTONE TURANZA	219.95	1	\$219.95
PARTS					225.15	

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 49800

Work Order Notes

(LRUSHING) service call and needs a new tire
(LISAPATE)

Job Notes

14-17 - INSTALL TIRES, TUBES, LINERS & VALVES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GRCOOK) Mounted and Balanced 1 new tire for unit 2841C, unit had small hole in center of tire that couldn't be patched, put tire back on unit and put spare tire back in trunk.-GC

Miles, 31,681

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) cancel not due

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 50349

USING DEPT NO: 507121	OPENED DATE: 03/28/2024 14:42:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/02/2024 08:28:42	METER 1 - M: 33965 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/02/2024 12:31:55	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry		UNIT SERIAL NO: 4T1C11AK6LU864902

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.42	\$49.43	\$0.00	\$0.00	\$49.43
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.42 49.43 0.00 5.00 54.43

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	12201267	03/28/2024 15:11:55	03/28/2024 15:37:03	0.42	\$49.43
					LABOR	49.43

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 50349

Work Order Notes

(EHANNAH) install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GRCOOK) Installed GPS SN: 87U030240196 in unit 2841C -GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 51148

USING DEPT NO:	507121	OPENED DATE:	06/11/2024 12:23:39	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	06/11/2024 14:52:51	METER 1 - M:	35662	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/12/2024 09:06:07	IN-SERVICE DATE:	12/06/2019		
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK6LU864902		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.96	\$24.11	\$0.00	\$34.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.21	\$43.89	\$0.00	\$45.10
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.11	\$22.73	\$0.00	\$23.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.10	12.28	90.73	5.00	108.01
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12395904	06/11/2024 14:38:16	06/11/2024 14:43:20	0.08	\$9.96
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	06/11/2024 14:37:17	06/11/2024 14:37:51	0.01	\$1.11
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/11/2024 14:36:15	06/11/2024 14:36:52	0.01	\$1.21
					LABOR	12.28

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.38	5	\$36.90
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.99	1	\$6.99
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
					PARTS	90.73

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 51148

Work Order Notes

(EHANNAH) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replace new wipers FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replace cabin filter fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 51678

USING DEPT NO: 507121	OPENED DATE: 08/02/2024 08:29:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/12/2024 15:08:25	METER 1 - M: 36844 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/13/2024 11:21:35	IN-SERVICE DATE: 12/06/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK6LU864902	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.90	\$1.90
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$1.90	\$0.00	\$0.00	\$1.90

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.02** **1.90** **0.00** **1.90** **3.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$1.90
					COMML 1.90

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	08/09/2024 10:45:12	08/09/2024 10:46:10	0.02	\$1.90
					LABOR	1.90

Work Order Charge Detail

UNIT NO: 243608 2020 TOYOTA CAMRY

WORK ORDER NO: 51678

Work Order Notes

(EHOWELL) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Removed tag, and cleaned out inside. CW

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Aug 21 2024 12:00:47 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243608') //Q=