

Work Order Charge Detail

UNIT NO: 243558 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 34870

USING DEPT NO: 507121	OPENED DATE: 11/14/2019 11:25:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/18/2019 10:31:50	METER 1 - M: 54 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/18/2019 10:31:50	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **36.25** **0.00** **0.00** **36.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	12052187	11/14/2019 11:25:59	11/14/2019 11:55:59	0.50	\$36.25
					LABOR	36.25

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 34870

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 243558 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 35636

USING DEPT NO: 507121	OPENED DATE: 02/12/2020 08:31:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/18/2020 07:34:31	METER 1 - M: 4645 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/18/2020 07:34:32	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$23.14	\$39.58	\$0.00	\$62.72

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.32** **23.14** **39.58** **0.00** **62.72**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/12/2020 09:48:43	02/12/2020 10:07:52	0.32	\$23.14
					LABOR	23.14

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.62	5	\$33.08
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					PARTS	39.58

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 35636

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/JW. Coolant -34

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 36344

USING DEPT NO:	507121	OPENED DATE:	05/07/2020 10:33:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/08/2020 08:31:52	METER 1 - M:	6710	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/08/2020 09:02:07	IN-SERVICE DATE:	11/13/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.14	\$82.73	\$42.49	\$0.00	\$125.22

JOB COUNT: 1 WORK ORDER TOTAL: 1.14 82.73 42.49 0.00 125.22

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/07/2020 14:28:32	05/07/2020 15:10:05	0.69	\$50.21
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/07/2020 14:32:11	05/07/2020 14:59:06	0.45	\$32.52
					LABOR	82.73

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.91	5	\$29.55
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44
					PARTS	42.49

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 36344

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) SH/AG performed pm. Coolant -35

Work Order Charge Detail

UNIT NO: 243558 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 37875

USING DEPT NO: 507121	OPENED DATE: 10/05/2020 14:44:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/06/2020 09:32:27	METER 1 - M: 7377 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/06/2020 12:45:00	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.15** **17.70** **0.00** **0.00** **17.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/06/2020 07:17:38	10/06/2020 07:26:38	0.15	\$17.70
					LABOR	17.70

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 37875

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Vehicle has been 667 milese. Checked fluids, battery and tires, updated oil change sticker. Completed checklist. AMG

Work Order Charge Detail

UNIT NO: 243558 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 38223

USING DEPT NO: 507121	OPENED DATE: 11/02/2020 07:17:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/03/2020 07:54:50	METER 1 - M: 7596 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/03/2020 10:06:17	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-71-045	INSPECT Undercarriage	DON	O	N	GARAGE	0.20	\$24.06	\$0.00	\$0.00	\$24.06

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.20** **24.06** **0.00** **0.00** **24.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-71-045	INSPECT Undercarriage	11074414	11/02/2020 07:40:08	11/02/2020 07:52:22	0.20	\$24.06
					LABOR	24.06

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 38223

Work Order Notes

(LISAPATE) Per Fleet someone ran over something in the road. Advised please check undercarriage for damage

Job Notes

06-71-045 - INSPECT Undercarriage

(SHARBIN) Mileage 7596. Inspected underside of vehicle did not see any damage. SH

Work Order Charge Detail

UNIT NO: 243558 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 38945

USING DEPT NO: 507121	OPENED DATE: 01/29/2021 07:24:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/01/2021 11:03:00	METER 1 - M: 10462 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/02/2021 09:07:16	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$632.50	\$632.50
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.50** **59.00** **0.00** **632.50** **691.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	284246		\$632.50
					COMML 632.50

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	10208562	02/01/2021 07:00:00	02/01/2021 07:30:00	0.50	\$59.00
					LABOR 59.00	

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 38945

Work Order Notes

(LISAPATE) Take to Glass Dr to have new windshield installed and calibrated per the quote.

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Took to Glass Dr to have new windshield installed and calibrated per estimate. Pd by CC

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by EK

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 39130

USING DEPT NO:	507121	OPENED DATE:	02/18/2021 11:16:38	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	02/22/2021 08:31:00	METER 1 - M:	10662	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2021 11:34:51	IN-SERVICE DATE:	11/13/2019		
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU880113		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	0.05	\$5.41	\$0.00	\$0.00	\$5.41
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.05	\$5.57	\$0.00	\$0.00	\$5.57
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.47	\$55.07	\$0.00	\$0.00	\$55.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.45	\$53.56	\$35.68	\$0.00	\$89.24

JOB COUNT: 4	WORK ORDER TOTAL:	1.01	119.61	35.68	0.00	155.29
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	11074414	02/19/2021 08:47:00	02/19/2021 09:15:00	0.47	\$55.07
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	02/19/2021 09:25:46	02/19/2021 09:25:46	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	02/19/2021 09:30:00	02/19/2021 09:32:50	0.05	\$5.57
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11915538	02/22/2021 07:06:26	02/22/2021 07:09:11	0.05	\$5.41
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/19/2021 08:11:13	02/19/2021 08:11:56	0.01	\$1.41
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/19/2021 07:05:49	02/19/2021 07:32:20	0.44	\$52.15
					LABOR	119.61

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					PARTS	35.68

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 39130

Work Order Notes

(LISAPATE) PM-Do annual safety inspection

(LISAPATE) Remove all wordmarks car is going to another Dept

Job Notes

25-53-006 - REMOVE WORDMARKS/IDENTIFIERS

(GARAGE) Removed all wordmarks RC

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires due to shoulder wear on front tires and inspected brakes. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) SH Performed safety inspection found no issues.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. SH,JAW/JAW
MILEAGE-10662

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 39989

USING DEPT NO:	507121	OPENED DATE:	05/19/2021 08:23:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/10/2021 08:06:02	METER 1 - M:	10666	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/10/2021 11:51:23	IN-SERVICE DATE:	11/13/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$724.50	\$724.50
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$264.50	\$264.50
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
19-01	WIRE/REWIRE AIR CONDITIONING, HE/	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$511.52	\$511.52

JOB COUNT: 6	WORK ORDER TOTAL:	1.50	177.00	0.00	1,500.52	1,677.52
---------------------	--------------------------	-------------	---------------	-------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	288442		\$437.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	289053		\$287.50
14-78-028	INSTALL WINDOW TINT	5564144	33469		\$264.50
19-01	WIRE/REWIRE AIR CONDITIONING, HEAT, VENT	11076422	6117594		\$511.52
COMML					1500.52

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	11915538	06/10/2021 07:00:00	06/10/2021 07:30:00	0.50	\$59.00
16-02	TRANSPORT CAB & SHEET METAL	11915538	06/10/2021 07:30:00	06/10/2021 08:00:00	0.50	\$59.00
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11915538	06/10/2021 07:00:00	06/10/2021 07:30:00	0.50	\$59.00
LABOR					177.00	

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 39989

Work Order Notes

(LISAPATE) Windshield has a large crack running down-send to have windows tinted. A/C is not working

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield would not calibrate. sent to Toyota for repairs then car was brought back to Glass Dr and recalibrated. Pd by CC

14-78-028 - INSTALL WINDOW TINT

(LISAPATE) Bama Trim Installed tint on all windows including a windshield strip. Pd by CC

16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Taken to Tuscaloosa Toyota by drivers

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by drivers

16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(LISAPATE) Taken to Bama Trim by drivers

19-01 - WIRE/REWIRE AIR CONDITIONING, HEAT, VENT

(LISAPATE) Tuscaloosa Toyota repaired wires to A/C control panel that was cut into by UAPD radio installer. PD by CC

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 40428

USING DEPT NO: 507121	OPENED DATE: 07/14/2021 09:39:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/15/2021 13:55:04	METER 1 - M: 10899 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/16/2021 11:40:24	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.32	\$37.86	\$17.17	\$0.00	\$55.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$46.38	\$0.00	\$0.00	\$46.38

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.71** **84.24** **17.17** **0.00** **101.41**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	07/14/2021 10:31:47	07/14/2021 10:51:02	0.32	\$37.86
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/14/2021 10:01:40	07/14/2021 10:25:15	0.39	\$46.38
					LABOR	84.24

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	9.84	1	\$9.84
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.33	1	\$7.33
					PARTS	17.17

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 40428

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 10899 Vehicle has been 237 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

Work Order Charge Detail

UNIT NO: 243558 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 42257

USING DEPT NO: 507121	OPENED DATE: 02/02/2022 12:46:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/03/2022 11:26:46	METER 1 - M: 13026 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/03/2022 14:28:27	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.36	\$17.90	\$0.00	\$22.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.56	\$44.70	\$0.00	\$80.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.34** **39.92** **62.60** **2.00** **104.52**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/02/2022 13:17:50	02/02/2022 13:35:55	0.30	\$35.56
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/02/2022 13:36:06	02/02/2022 13:38:19	0.04	\$4.36
LABOR					39.92	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.10	1	\$11.10
PARTS					62.60	

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 42257

Work Order Notes

(CHANNELL) pm\ replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 44155

USING DEPT NO: 507121	OPENED DATE: 08/03/2022 07:53:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/09/2022 09:20:02	METER 1 - M: 15520 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/09/2022 12:53:30	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry		UNIT SERIAL NO: 4T1C11AK4LU880113

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$43.33	\$46.84	\$0.00	\$90.17
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.37 43.33 46.84 2.00 92.17

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/03/2022 08:11:01	08/03/2022 08:33:03	0.37	\$43.33
					LABOR	43.33

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.49	5	\$37.43
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.41	1	\$9.41
					PARTS	46.84

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 44155

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-15520

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 45671

USING DEPT NO:	507121	OPENED DATE:	01/04/2023 13:06:23	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	01/06/2023 13:03:37	METER 1 - M:	18492	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/06/2023 13:03:42	IN-SERVICE DATE:	11/13/2019		
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU880113		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$23.25	\$0.00	\$40.95
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.33	\$38.61	\$0.00	\$0.00	\$38.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.54	\$43.49	\$0.00	\$63.03
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.64	75.85	66.74	5.00	147.59
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/04/2023 14:32:25	01/04/2023 14:42:21	0.17	\$19.54
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	01/04/2023 14:42:33	01/04/2023 15:02:11	0.33	\$38.61
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/06/2023 07:00:00	01/06/2023 07:09:00	0.15	\$17.70
					LABOR	75.85

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.78	1	\$12.78
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.39	1	\$8.39
					PARTS	66.74

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 45671

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) sh replaced wipers

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Cross rotated tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243558 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 47088

USING DEPT NO: 507121	OPENED DATE: 05/17/2023 07:46:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/17/2023 15:44:04	METER 1 - M: 20906 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/18/2023 07:05:35	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.95	\$24.06	\$0.00	\$29.01
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$16.59	\$74.46	\$0.00	\$91.05
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.74	\$22.73	\$0.00	\$24.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.20** **23.28** **121.25** **5.00** **149.53**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/17/2023 11:24:00	05/17/2023 11:24:53	0.01	\$1.74
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/17/2023 11:21:18	05/17/2023 11:23:49	0.04	\$4.95
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/17/2023 11:12:41	05/17/2023 11:21:07	0.14	\$16.59
LABOR					23.28	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	33.12	1	\$33.12
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.11	5	\$35.55
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.83	1	\$10.83
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.79	1	\$5.79
PARTS					121.25	

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 47088

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) RC Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 48623

USING DEPT NO: 507121	OPENED DATE: 10/19/2023 07:42:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/19/2023 14:26:54	METER 1 - M: 23402 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/20/2023 08:59:02	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.91	\$107.77	\$0.00	\$0.00	\$107.77
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$16.85	\$65.01	\$0.00	\$81.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.06	124.62	65.01	5.00	194.63
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12395904	10/19/2023 09:39:06	10/19/2023 10:33:54	0.91	\$107.77
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/19/2023 09:30:00	10/19/2023 09:38:34	0.14	\$16.85
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/19/2023 09:27:25	10/19/2023 09:27:25	0.00	\$0.00
LABOR					124.62	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.07	5	\$40.35
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.55	1	\$11.55
PARTS					65.01	

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 48623

Work Order Notes

(EHANNAH) pm-do SI

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(FCONTRER) Safety inspection good fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil change fluid check fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 49517

USING DEPT NO: 507121	OPENED DATE: 01/22/2024 11:16:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/23/2024 15:08:23	METER 1 - M: 25240 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/24/2024 07:42:57	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.08	\$9.47	\$4.99	\$0.00	\$14.46
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.09	\$10.42	\$0.00	\$0.00	\$10.42
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.17	19.89	4.99	5.00	29.88
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	01/22/2024 13:09:40	01/22/2024 13:14:29	0.08	\$9.47
66-79-002	PERFORM SERVICE CALL	12201267	01/22/2024 13:04:10	01/22/2024 13:09:28	0.09	\$10.42
LABOR					19.89	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.20	7	\$1.37
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.62	1	\$3.62
PARTS					4.99	

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 49517

Work Order Notes

(LRUSHING) flat tire on drivers rear side - located in back parking lot of UAPD building

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(IFALLS) Unit 2798C, had service call for flat tire, tire had screw in center of tire, however tire had a knot on the side wall of the tire. Eric had a used Bridgestone tire for unit. Mounted and Balanced 1 left rear used tire. -GC
Miles, 25,240

66-79-002 - PERFORM SERVICE CALL

(IFALLS) Performed service call for flat tire on left rear of unit 2798C, aired up tire on unit and brought back to shop to fix flat tire. -GC

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 1/26/2024 3:07 PM By LRUSHING

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 50334

USING DEPT NO: 507121	OPENED DATE: 03/28/2024 07:50:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/29/2024 08:57:17	METER 1 - M: 26953 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/29/2024 10:01:19	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK4LU880113	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.15	\$17.27	\$0.00	\$0.00	\$17.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.70	\$61.42	\$0.00	\$81.12
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.31	36.97	61.42	5.00	103.39
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11074414	03/28/2024 08:01:39	03/28/2024 08:10:26	0.15	\$17.27
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/28/2024 08:10:26	03/28/2024 08:20:27	0.17	\$19.70
LABOR					36.97	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.18	5	\$40.88
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
PARTS					61.42	

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 50334

Work Order Notes

(EHANNAH) pm- install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240182. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH FC/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 51760

USING DEPT NO: 507121	OPENED DATE: 08/09/2024 10:44:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: COMPLETED	COMPLETED DATE: 08/15/2024 17:25:31	METER 1 - M: 29914 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE:	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry		UNIT SERIAL NO: 4T1C11AK4LU880113

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.88	\$0.00	\$0.00	\$2.88

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.02** **2.88** **0.00** **0.00** **2.88**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	08/13/2024 12:42:06	08/13/2024 12:43:34	0.02	\$2.88
					LABOR	2.88

Work Order Charge Detail

UNIT NO: 243558 2020 TOYOTA CAMRY

WORK ORDER NO: 51760

Work Order Notes

(LRUSHING) remove gps and install in 0883c
(EHANNAH) prep for sale

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(GARAGE) Removed GPS SN: 87U030240182out of unit 2798C and installed it into unit 0883C-GC

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) No wordmarks. Removed tag 2798C. Checked inside of vehicle. CW

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Aug 16 2024 11:41:24 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '4T1C11AK4LU880113') //Q=