

Work Order Charge Detail

UNIT NO: 243553 **2019 TOYOTA CAMRY** **WORK ORDER NO:** 34875

USING DEPT NO: 507121	OPENED DATE: 11/14/2019 11:36:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/18/2019 10:36:06	METER 1 - M: 120 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/18/2019 10:36:07	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **36.25** **0.00** **0.00** **36.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	11/14/2019 11:36:53	11/14/2019 12:06:53	0.50	\$36.25
					LABOR	36.25

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 34875

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY WORK ORDER NO: 35586

USING DEPT NO:	507121	OPENED DATE:	02/06/2020 08:12:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/14/2020 09:21:21	METER 1 - M:	4360	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	02/14/2020 09:21:22	IN-SERVICE DATE:	11/13/2019	
TECH SPEC NO:	19TOYCAMRY	2019 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.22	\$88.21	\$39.59	\$0.00	\$127.80

JOB COUNT: 1 WORK ORDER TOTAL: 1.22 88.21 39.59 0.00 127.80

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/06/2020 08:23:16	02/06/2020 09:36:16	1.22	\$88.21
					LABOR	88.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.62	5	\$33.08
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.51	1	\$6.51
					PARTS	39.59

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 35586

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 36048

USING DEPT NO: 507121	OPENED DATE: 03/24/2020 09:59:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/25/2020 08:04:58	METER 1 - M: 8045 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/25/2020 16:47:48	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY	2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$57.68	\$36.57	\$0.00	\$94.25

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.80** **57.68** **36.57** **0.00** **94.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2020 14:15:00	03/24/2020 14:19:04	0.07	\$4.91
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2020 13:28:15	03/24/2020 14:00:00	0.53	\$38.36
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/24/2020 13:24:05	03/24/2020 13:36:00	0.20	\$14.40
					LABOR	57.67

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.01	5	\$30.07
					PARTS	36.57

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 36048

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH,AG/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 243553 **2019 TOYOTA CAMRY** **WORK ORDER NO:** 37103

USING DEPT NO: 507121	OPENED DATE: 07/13/2020 15:39:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/14/2020 09:39:05	METER 1 - M: 8074 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/14/2020 13:28:27	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$18.45	\$0.00	\$0.00	\$18.45

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.25** **18.45** **0.00** **0.00** **18.45**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/14/2020 08:54:21	07/14/2020 09:09:37	0.25	\$18.45
					LABOR	18.45

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 37103

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Did not change oil at this time unit has only been 29 miles since last oil change. Checked fluids, battery and tire pressures. Updated sticker
Coolant -35'
AG

Work Order Charge Detail

UNIT NO: 243553 **2019 TOYOTA CAMRY** **WORK ORDER NO:** 38487

USING DEPT NO: 507121	OPENED DATE: 11/30/2020 10:40:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/01/2020 14:48:15	METER 1 - M: 10161 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/02/2020 07:43:25	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$37.89	\$35.68	\$0.00	\$73.57

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.32** **37.89** **35.68** **0.00** **73.57**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/30/2020 11:01:39	11/30/2020 11:20:55	0.32	\$37.89
					LABOR	37.89

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
					PARTS	35.68

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 38487

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) AB/SH Performed PM.

Work Order Charge Detail

UNIT NO: 243553 **2019 TOYOTA CAMRY** **WORK ORDER NO:** 39145

USING DEPT NO: 507121	OPENED DATE: 02/19/2021 10:43:46	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/22/2021 08:32:43	METER 1 - M: 11009 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/22/2021 11:24:42	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	0.03	\$3.70	\$0.00	\$0.00	\$3.70

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.03** **3.70** **0.00** **0.00** **3.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11915538	02/22/2021 07:09:11	02/22/2021 07:11:04	0.03	\$3.70
					LABOR	3.70

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 39145

Work Order Notes

(LISAPATE) Remove all wordmarks car is going to another Dept

Job Notes

25-53-006 - REMOVE WORDMARKS/IDENTIFIERS

(LISAPATE) RC removed wordmarks

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 40044

USING DEPT NO:	507121	OPENED DATE:	05/27/2021 07:32:59	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	05/28/2021 14:47:28	METER 1 - M:	12090	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/02/2021 08:00:24	IN-SERVICE DATE:	11/13/2019		
TECH SPEC NO:	19TOYCAMRY	2019 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9KU285774		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$333.50	\$333.50
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.09	\$128.75	\$35.61	\$0.00	\$164.36

JOB COUNT: 3	WORK ORDER TOTAL:	1.59	187.75	35.61	333.50	556.86
---------------------	--------------------------	-------------	---------------	--------------	---------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
14-78-028	INSTALL WINDOW TINT	5564144	33445		\$333.50
COMML					333.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	11915538	05/28/2021 07:00:00	05/28/2021 07:30:00	0.50	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/28/2021 07:16:04	05/28/2021 07:46:38	0.51	\$60.11
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/28/2021 07:12:21	05/28/2021 07:43:16	0.52	\$60.80
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/28/2021 07:12:22	05/28/2021 07:16:21	0.07	\$7.83
LABOR					187.74	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.51	1	\$6.51
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.82	5	\$29.10
PARTS					35.61	

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 40044

Work Order Notes

(LISAPATE) PM-Take to Bama Trim to have window tint installed all windows and front strip

Job Notes

14-78-028 - INSTALL WINDOW TINT

(LISAPATE) Bama Trim removed tint and installed darker tint. All windows and rear. including a windshield strip. PD by CC

16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(LISAPATE) Taken to Bama Trim by RC

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 12090 Completed PM topside, Josh was bottomsides. Completed checklist. AMG/JW

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 40418

USING DEPT NO: 507121	OPENED DATE: 07/13/2021 10:21:56	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/09/2021 14:20:29	METER 1 - M: 13541 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/09/2021 14:43:57	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-44	TRANSPORT FUEL SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
17-44-003	RECALL FUEL PUMP	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	0.00	59.00
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-44-003	RECALL FUEL PUMP	11076422	6127176		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-44	TRANSPORT FUEL SYSTEM	11915538	08/09/2021 07:00:00	08/09/2021 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 40418

Work Order Notes

(LISAPATE) Take to Tuscaloosa Toyota for NHTSA Recall no 20V-682 low pressure fuel pump may stop operating

Job Notes

16-44 - TRANSPORT FUEL SYSTEM

(LISAPATE) Taken to Toyota by RC

17-44-003 - RECALL FUEL PUMP

(LISAPATE) Toyota completed recall installed new fuel pump

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243553 **2019 TOYOTA CAMRY** **WORK ORDER NO:** 41542

USING DEPT NO: 507121	OPENED DATE: 11/08/2021 08:33:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/09/2021 10:21:39	METER 1 - M: 15867 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/10/2021 07:44:03	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.39	\$22.62	\$0.00	\$31.01
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.46	\$54.38	\$0.00	\$0.00	\$54.38
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.43	\$51.26	\$0.00	\$0.00	\$51.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$79.19	\$38.79	\$0.00	\$117.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.64	193.22	61.41	2.00	256.63
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	11/08/2021 12:43:48	11/08/2021 13:11:27	0.46	\$54.38
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/08/2021 09:38:38	11/08/2021 10:18:54	0.67	\$79.19
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/08/2021 09:32:59	11/08/2021 09:37:15	0.07	\$8.39
66-79-003	PERFORM SAFETY INSPECTION	11901357	11/08/2021 13:11:41	11/08/2021 13:35:47	0.40	\$47.40
66-79-003	PERFORM SAFETY INSPECTION	11901357	11/08/2021 15:40:10	11/08/2021 15:42:08	0.03	\$3.87
LABOR					193.23	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.91	5	\$29.55
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.24	1	\$9.24
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
PARTS					61.41	

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 41542

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) rotated tires and checked brakes, no issues found. AMG

66-79-003 - PERFORM SAFETY INSPECTION

(AGUERRA) miles: 15867 Completed safety inspection, no issues found. Completed safety inspection checklist. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 15867 Completed PM top and bottom side. Completed checklist. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243553 **2019 TOYOTA CAMRY** **WORK ORDER NO:** 42895

USING DEPT NO: 507121	OPENED DATE: 04/12/2022 09:43:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/13/2022 10:18:51	METER 1 - M: 20658 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/14/2022 07:52:06	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.41	\$22.62	\$0.00	\$30.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$54.90	\$39.00	\$0.00	\$93.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.53	62.31	61.62	2.00	125.93
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/12/2022 12:13:39	04/12/2022 12:41:34	0.47	\$54.90
03-51-038	REPLACE NEW WIPER BLADES	11901357	04/12/2022 12:09:37	04/12/2022 12:13:23	0.06	\$7.41
LABOR					62.31	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.40	1	\$5.40
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
PARTS					61.62	

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 42895

Work Order Notes

(CHANNELL) pm\ replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 20658 Completed PM top and bottom side. Completed checklist. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 44922

USING DEPT NO:	507121	OPENED DATE:	10/10/2022 07:54:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/13/2022 12:01:25	METER 1 - M:	25406	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2022 09:18:38	IN-SERVICE DATE:	11/13/2019	
TECH SPEC NO:	19TOYCAMRY	2019 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.28	\$33.40	\$0.00	\$0.00	\$33.40
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$31.83	\$47.27	\$0.00	\$79.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.55	65.23	47.27	5.00	117.50
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	10/10/2022 09:30:00	10/10/2022 09:46:59	0.28	\$33.40
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	10/10/2022 09:29:23	10/10/2022 09:29:23	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/10/2022 08:58:49	10/10/2022 09:15:00	0.27	\$31.83
LABOR					65.23	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.29	1	\$7.29
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.81	5	\$34.05
03-32-002	REPLACE NEW BATTERY	47H5	BATTERY	146.72	1	\$146.72
03-32-002	REPLACE NEW BATTERY	47H5	BATTERY	146.72	(1)	(\$146.72)
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	5.93	1	\$5.93
PARTS					47.27	

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 44922

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Cross rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243553 **2019 TOYOTA CAMRY** **WORK ORDER NO:** 46536

USING DEPT NO: 507121	OPENED DATE: 03/27/2023 10:01:56	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/27/2023 14:42:26	METER 1 - M: 29012 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/03/2023 14:03:04	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.23	\$23.26	\$0.00	\$27.49
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$47.33	\$41.40	\$0.00	\$88.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.44	51.56	64.66	5.00	121.22
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/27/2023 12:41:35	03/27/2023 13:05:39	0.40	\$47.33
03-51-038	REPLACE NEW WIPER BLADES	12052187	03/27/2023 12:39:13	03/27/2023 12:41:22	0.04	\$4.23
LABOR					51.56	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.85	1	\$5.85
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.11	5	\$35.55
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
PARTS					64.66	

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 46536

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-29012

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243553 **2019 TOYOTA CAMRY** **WORK ORDER NO:** 47991

USING DEPT NO: 507121	OPENED DATE: 08/25/2023 08:57:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/25/2023 14:53:00	METER 1 - M: 32485 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/28/2023 07:25:41	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.70	\$24.08	\$0.00	\$25.78
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.24	\$28.06	\$0.00	\$0.00	\$28.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$58.61	\$79.00	\$0.00	\$137.61
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.14	\$16.45	\$22.73	\$0.00	\$39.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.89	104.82	125.81	5.00	235.63
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/25/2023 11:40:40	08/25/2023 11:54:56	0.24	\$28.06
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/25/2023 11:39:48	08/25/2023 11:40:40	0.01	\$1.70
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	08/25/2023 11:31:17	08/25/2023 11:39:39	0.14	\$16.45
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/25/2023 10:56:22	08/25/2023 11:26:10	0.50	\$58.61
					LABOR	104.82

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.46	5	\$42.30
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.78	1	\$5.78
66-PM-PMA	PERFORM OIL CHANGE	PC99237C	CABIN FILTER 2020 CAMRY	22.73	(1)	(\$22.73)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
66-PM-PMA	PERFORM OIL CHANGE	PA6116F	DODGE DURANGO AIR FILTER	30.92	1	\$30.92

Work Order Charge Detail

PARTS

125.81

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 47991

Work Order Notes

(LRUSHING) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires and inspected the brakes. Found no issues at this time. FC SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 49484

USING DEPT NO: 507121	OPENED DATE: 01/18/2024 08:14:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/22/2024 15:12:23	METER 1 - M: 36222 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/23/2024 07:50:17	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY	2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.35	\$75.67	\$0.00	\$110.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.29** **34.35** **75.67** **5.00** **115.02**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/18/2024 08:33:07	01/18/2024 08:50:35	0.29	\$34.35
					LABOR	34.35

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	11.03	5	\$55.13
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
					PARTS	75.67

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 49484

Work Order Notes

(EHANNAH) pm- wipers- check tire pressure

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-17-001 - INSPECT TIRE - ADD AIR

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 50114

USING DEPT NO: 507121	OPENED DATE: 03/08/2024 07:57:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/21/2024 07:59:11	METER 1 - M: 37739 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/21/2024 08:43:09	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry		UNIT SERIAL NO: 4T1B11HK9KU285774

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.29	\$33.66	\$0.00	\$0.00	\$33.66
CH-SP	CHARGE Shop Supplies	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.29** **33.66** **0.00** **5.00** **38.66**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11074414	03/08/2024 08:34:28	03/08/2024 08:51:35	0.29	\$33.66
LABOR						33.66

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 50114

Work Order Notes

(EHANNAH) install GPS - Please check and replace her window sticker

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240181. SH

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 3/27/2024 9:29 AM By LRUSHING

Work Order Charge Detail

UNIT NO: 243553 **2019 TOYOTA CAMRY** **WORK ORDER NO:** 51667

USING DEPT NO: 507121	OPENED DATE: 08/01/2024 10:18:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/12/2024 08:14:17	METER 1 - M: 39112 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/12/2024 10:31:12	IN-SERVICE DATE: 11/13/2019
TECH SPEC NO: 19TOYCAMRY 2019 Toyota Camry	UNIT SERIAL NO: 4T1B11HK9KU285774	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 243553 2019 TOYOTA CAMRY

WORK ORDER NO: 51667

Work Order Notes

(EHOWELL) remove GPS and install in Red F150 -246406

Job Notes

25-34-006 - REMOVE SPECIAL APPL WARNING LIGHTS

25-52-021 - REMOVE GPS SYSTEM

(GARAGE) Removed GPS SN: 87U030240181 out of unit 2799C-GC
(EHOWELL) Visit Reason Changed On 8/12/2024 8:12 AM By EHOWELL
(EHOWELL) Visit Reason Changed On 8/12/2024 8:20 AM By EHOWELL

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag\RC

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Aug 13 2024 16:11:05 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '4T1B11HK9KU285774') //Q=