

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 34529

USING DEPT NO: 507121	OPENED DATE: 10/21/2019 10:19:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/25/2019 20:00:00	METER 1 - M: 17 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/25/2019 20:00:00	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-35-006	REPLACE NEW FUSE(S)	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.85	\$0.00	\$0.00	\$0.00	\$0.00
17-02-028	RECALL SEAT ADJUSTER	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-13-033	RECALL ABS MODULATOR	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.85	0.00	0.00	0.00	0.00
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
17-02-028	RECALL SEAT ADJUSTER	4910000	588175		\$0.00	
					COMML	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	10208562	10/22/2019 09:30:00	10/22/2019 09:45:14	0.25	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	10208562	10/22/2019 08:39:03	10/22/2019 09:15:00	0.60	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 34529

Work Order Notes

(LISAPATE) Take to Town and Country Ford for recalls- Anti lock brake module software update- mechanical seat recliner

Job Notes

03-35-006 - REPLACE NEW FUSE(S)

(LISAPATE) Verified concern. Replaced fuse for window switch covered by Town and Country

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Town and Country by AG

17-02-028 - RECALL SEAT ADJUSTER

(LISAPATE) Town and Country Performed recall 19C07. Using force meter inspected both front seats in all positions. Both front seats pass inspection

17-13-033 - RECALL ABS MODULATOR

(LISAPATE) Town and Country performed recall 19B12 Reprogrammed ABS module to latest calibration recall complete.

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 34945

USING DEPT NO: 507121	OPENED DATE: 11/21/2019 15:43:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/25/2019 09:51:55	METER 1 - M: 569 METER 2 - H: 31
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/25/2019 09:51:56	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	1.04	\$0.00	\$0.00	\$0.00	\$0.00
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL: 1.54 0.00 0.00 0.00 0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11901357	11/25/2019 07:00:00	11/25/2019 07:30:00	0.50	\$0.00
35-32	DIAGNOSE CRANKING SYSTEM	11901357	11/22/2019 14:30:00	11/22/2019 15:03:11	0.55	\$0.00
35-32	DIAGNOSE CRANKING SYSTEM	11901357	11/22/2019 14:12:33	11/22/2019 14:15:00	0.04	\$0.00
35-32	DIAGNOSE CRANKING SYSTEM	11901357	11/22/2019 06:15:51	11/22/2019 06:42:52	0.45	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 34945

Work Order Notes

(LISAPATE) Per driver battery is dead had to be jumped off

Job Notes

35-32 - DIAGNOSE CRANKING SYSTEM

(LISAPATE) Checked battery is dead needs to be charged

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery for 7 hours. Battery tested good, Checked charging system is good charging at 14.8 volts

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 35333

USING DEPT NO: 507121	OPENED DATE: 01/08/2020 07:16:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/15/2020 09:27:09	METER 1 - M: 1904 METER 2 - H: 247
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/15/2020 09:27:10	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.27	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.90	\$0.00	\$22.25	\$0.00	\$22.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **2.17** **0.00** **22.25** **0.00** **22.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/08/2020 08:29:49	01/08/2020 10:23:48	1.90	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	01/08/2020 10:23:48	01/08/2020 10:40:12	0.27	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.87	6	\$17.22
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	22.25

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 35333

Work Order Notes

(EKIMBREL) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(EKIMBREL) JW rotated tires.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/JW. Coolant -34

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 35611

USING DEPT NO: 507121	OPENED DATE: 02/10/2020 07:03:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/12/2020 07:17:35	METER 1 - M: 2973 METER 2 - H: 468
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/12/2020 07:17:45	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.33	\$0.00	\$19.31	\$0.00	\$19.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.01	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL: 1.35 0.00 42.04 0.00 42.04**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11915538	02/10/2020 07:45:00	02/10/2020 08:05:03	0.33	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/10/2020 07:34:48	02/10/2020 08:04:51	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/10/2020 07:33:52	02/10/2020 08:04:33	0.51	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	10.29	1	\$10.29
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	9.02	1	\$9.02
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	42.04

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 35611

Work Order Notes

(EKIMBREL) pm; tire rotation; replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) RC replaced wiper blades.

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/JW. coolant -35. Unit was a waiter, spoke with Randall and decided to hold off on tire rotation at this time due to no tire wear found.

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 36044

USING DEPT NO: 507121	OPENED DATE: 03/24/2020 07:16:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/24/2020 14:00:56	METER 1 - M: 4599 METER 2 - H: 687
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 03/25/2020 15:31:54	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.59	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.81** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	03/24/2020 10:37:14	03/24/2020 11:12:53	0.59	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2020 10:24:21	03/24/2020 10:37:14	0.21	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 36044

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires an relearned tire positions

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/AG
Coolant -20'

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 36460

USING DEPT NO: 507121	OPENED DATE: 05/18/2020 06:57:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/18/2020 13:46:05	METER 1 - M: 5876 METER 2 - H: 882
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/18/2020 13:46:09	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-015	PERFORM TIRE ROTATION	DON	P	N	GARAGE	0.70	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.95** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-015	PERFORM TIRE ROTATION	11901357	05/18/2020 08:27:19	05/18/2020 09:09:32	0.70	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/18/2020 07:25:53	05/18/2020 07:40:37	0.25	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 36460

Work Order Notes

(IFALLS) PM

Job Notes

66-17-015 - PERFORM TIRE ROTATION

(IFALLS) AG rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH performed pm

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 36796

USING DEPT NO: 507121	OPENED DATE: 06/12/2020 10:18:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/12/2020 14:35:32	METER 1 - M: 6754 METER 2 - H: 1368
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/15/2020 08:14:07	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PR-01-002	PROGRAM HEATING & VENTILATING	DON	P	N	GARAGE	2.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **2.00** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PR-01-002	PROGRAM HEATING & VENTILATING	11170580	06/12/2020 14:34:05	06/12/2020 16:34:05	2.00	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 36796

Work Order Notes

(EKIMBREL) Program for Covid19

Job Notes

PR-01-002 - PROGRAM HEATING & VENTILATING

(EKIMBREL) AB reprogrammed PCM, BCM, and HVAC modules in order to activate coronavirus disinfectant mode.

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 36967

USING DEPT NO: 507121	OPENED DATE: 06/29/2020 10:03:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/29/2020 15:07:31	METER 1 - M: 7198 METER 2 - H: 1085
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/30/2020 14:09:50	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>	
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00	
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.28	\$0.00	\$27.02	\$0.00	\$27.02	
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.25	\$0.00	\$3.55	\$0.00	\$3.55	
JOB COUNT: 3						WORK ORDER TOTAL:	2.03	0.00	30.57	0.00	30.57

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	06/29/2020 10:45:40	06/29/2020 11:00:45	0.25	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	06/29/2020 15:06:45	06/29/2020 15:36:45	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/29/2020 10:08:51	06/29/2020 10:48:20	0.66	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/29/2020 10:09:21	06/29/2020 10:28:23	0.32	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/29/2020 10:08:47	06/29/2020 10:27:00	0.30	\$0.00
LABOR						0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4068	FILTER- CABIN AIR	3.55	1	\$3.55
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
PARTS						30.57

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 36967

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) SH/JW Rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) performed pm service (JAW,SH/AMG) coolant -35°

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(JWRIGHT) replaced cabin filter. JAW

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 37463

USING DEPT NO: 507121	OPENED DATE: 08/31/2020 07:20:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/31/2020 14:31:39	METER 1 - M: 9097 METER 2 - H: 1494
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/31/2020 14:31:40	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$0.00	\$19.27	\$0.00	\$19.27

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.33** **0.00** **19.27** **0.00** **19.27**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10208562	08/31/2020 11:56:54	08/31/2020 12:16:42	0.33	\$0.00
LABOR						0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	VC3B	FORD ORANGE ANTIFREEZE	19.27	1	\$19.27
PARTS						19.27

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 37463

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Did not rotate tires at this time

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Did not drop oil at this time

(EKIMBREL) Checked fluids, tire pressures, battery, and updated sticker.

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 37524

USING DEPT NO: 507121	OPENED DATE: 09/08/2020 08:34:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/08/2020 15:25:37	METER 1 - M: 9308 METER 2 - H: 1557
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/09/2020 09:46:29	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$0.00	\$22.79	\$0.00	\$22.79

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.23** **0.00** **22.79** **0.00** **22.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	09/08/2020 09:30:00	09/08/2020 09:43:47	0.23	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11170580	09/08/2020 09:20:41	09/08/2020 09:20:41	0.00	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	6	\$17.76
					PARTS	22.79

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 37524

Work Order Notes

(LISAPATE) PM-Rotate tires
(ABLACK) AB/SH PERFORMED PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) AB Did not rotate tires at this time

66-PM-PMA - PERFORM OIL CHANGE

(ABLACK) AB worked top, SH worked bottom
(ABLACK) Used 5.91 quarts of 5W-20 oil AB

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 38126

USING DEPT NO: 507121	OPENED DATE: 10/26/2020 07:35:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/27/2020 08:09:36	METER 1 - M: 9308 METER 2 - H: 1557
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/27/2020 12:24:38	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.76	\$89.71	\$34.92	\$0.00	\$124.63

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.76** **89.71** **34.92** **0.00** **124.63**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/26/2020 07:58:52	10/26/2020 08:22:58	0.40	\$47.40
66-PM-PMA	PERFORM OIL CHANGE	11170580	10/26/2020 08:01:15	10/26/2020 08:22:46	0.36	\$42.32
					LABOR	89.72

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	34.92

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 38126

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(RTUNAITI) 5w20BT (6.0)

(ABLACK) AB SH performed pm

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 38675

USING DEPT NO: 507121	OPENED DATE: 12/16/2020 09:34:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/16/2020 13:26:09	METER 1 - M: 11542 METER 2 - H: 2155
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/17/2020 08:36:32	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$31.11	\$34.92	\$0.00	\$66.03

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.26** **31.11** **34.92** **0.00** **66.03**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/16/2020 11:38:10	12/16/2020 11:53:59	0.26	\$31.11
					LABOR	31.11

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	34.92

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 38675

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. RC/JAW

MILEAGE-11542

HRS-2155

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 39332

USING DEPT NO: 507121	OPENED DATE: 03/08/2021 09:42:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/09/2021 15:21:43	METER 1 - M: 12844 METER 2 - H: 2493
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/10/2021 07:58:22	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.61	\$71.55	\$0.00	\$0.00	\$71.55
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$73.52	\$49.69	\$0.00	\$123.21

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.23** **145.07** **49.69** **0.00** **194.76**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	03/09/2021 10:12:01	03/09/2021 10:48:24	0.61	\$71.55
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/09/2021 08:00:25	03/09/2021 08:37:48	0.62	\$73.52
					LABOR	145.07

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5066517	WSWF RAIN-X -20DEG DEICER GAL	6.89	1	\$6.89
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.45	1	\$5.45
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
					PARTS	49.69

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 39332

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires and checked brakes. All pads are 10mm. Torqued all lugs to 105ft lbs. JAW

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 12844 Engine hours 3204 Idle hours 2493. SH/AMG Performed PM and added 1 can of Sea Foam to the gas.

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 39720

USING DEPT NO: 507121	OPENED DATE: 04/19/2021 07:16:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/20/2021 14:43:47	METER 1 - M: 13435 METER 2 - H: 2646
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/21/2021 08:17:17	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.14	\$16.82	\$115.49	\$0.00	\$132.31
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.23	\$27.30	\$0.00	\$0.00	\$27.30

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.37** **44.12** **115.49** **0.00** **159.61**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	04/19/2021 08:41:08	04/19/2021 08:55:01	0.23	\$27.30
03-32-002	REPLACE NEW BATTERY	11170580	04/19/2021 08:29:33	04/19/2021 08:38:06	0.14	\$16.82
					LABOR	44.12

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	01253	BATT TERM PROTECTOR, PAIR PK	1.94	1	\$1.94
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
					PARTS	115.49

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 39720

Work Order Notes

(LISAPATE) Per Sgt Rice unit was dropped off at show due to sulfur smell and leaking battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(ABLACK) AB found battery was dead and leaking acid. Installed a new battery. Performed battery monitor reset. Rechecked ok.

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(ABLACK) AB scanned out and found all codes were related to the battery going dead. No overcharging codes were found. Alternator is charging at 14.7

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 39793

USING DEPT NO: 507121	OPENED DATE: 04/23/2021 14:13:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/29/2021 09:42:33	METER 1 - M: 13435 METER 2 - H: 2646
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/29/2021 11:42:21	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-32-002	DIAGNOSE BATTERY	DON	O	N	GARAGE	1.41	\$165.92	\$0.00	\$0.00	\$165.92
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.56** **183.62** **0.00** **0.00** **183.62**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-32-002	DIAGNOSE BATTERY	11310047	04/23/2021 14:30:00	04/23/2021 15:54:22	1.41	\$165.92
35-32-002	DIAGNOSE BATTERY	11310047	04/23/2021 14:17:13	04/23/2021 14:17:13	0.00	\$0.00
CH-32-002	CHARGE BATTERY	11310047	04/29/2021 07:00:00	04/29/2021 07:09:00	0.15	\$17.70
					LABOR	183.62

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 39793

Work Order Notes

(EKIMBREL) Customer came to pick up vehicle and the battery was dead. Battery was just replaced

Job Notes

35-32-002 - DIAGNOSE BATTERY

(LISAPATE) There was a 1 amp parasitic draw coming from the police accessories in the back of the vehicle. This is an extremely high amount. The police department will be informed that this condition needs to be addressed.

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery and battery tested good.
Reset battery monitoring system using the Ford scan tool. EH

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 40201

USING DEPT NO: 507121	OPENED DATE: 06/18/2021 07:16:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/22/2021 07:36:42	METER 1 - M: 13435 METER 2 - H: 2646
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 06/22/2021 07:36:45	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.71	\$84.01	\$46.94	\$0.00	\$130.95
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.02	\$2.23	\$7.20	\$0.00	\$9.43

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.73** **86.24** **54.14** **0.00** **140.38**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/18/2021 08:13:51	06/18/2021 08:37:23	0.39	\$46.28
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/18/2021 08:21:33	06/18/2021 08:40:44	0.32	\$37.73
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	06/18/2021 08:40:58	06/18/2021 08:42:06	0.02	\$2.23
					LABOR	86.24

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PF63	FILTER-OIL	9.68	1	\$9.68
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	7.20	1	\$7.20
					PARTS	54.14

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 40201

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 13629 Engine hours 3454 Idle hours 2700. SH/AMG Performed PM

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 40918

USING DEPT NO: 507121	OPENED DATE: 09/02/2021 09:32:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/08/2021 11:29:15	METER 1 - M: 14990 METER 2 - H: 3020
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/09/2021 07:34:39	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.38	\$31.82	\$0.00	\$39.20
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.08	\$9.90	\$0.00	\$0.00	\$9.90
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.32	\$42.39	\$0.00	\$72.71
66-PM-PTU	PERFORM Power Transfer Unit Service	DON	P	N	GARAGE	1.79	\$211.22	\$15.66	\$0.00	\$226.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.19	258.82	89.87	2.00	350.69
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/02/2021 13:38:01	09/02/2021 13:53:26	0.26	\$30.32
03-51-038	REPLACE NEW WIPER BLADES	12052187	09/02/2021 13:53:37	09/02/2021 13:57:22	0.06	\$7.38
66-79-003	PERFORM SAFETY INSPECTION	12052187	09/02/2021 13:57:32	09/02/2021 14:02:34	0.08	\$9.90
66-PM-PTU	PERFORM Power Transfer Unit Service	11170580	09/03/2021 07:22:54	09/03/2021 09:10:18	1.79	\$211.22
					LABOR	258.82

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.13	1	\$5.13
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PTU	PERFORM Power Transfer Unit Service	VV982	75W-140 LS SYN GEAR OIL QT	15.66	1	\$15.66
					PARTS	89.87

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 40918

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI-Service PTU

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed SI. Found no issues. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -35°. JAW,SH/JAW

MILEAGE-14990

ENG HRS-3846

IDLE HRS-3020

66-PM-PTU - PERFORM Power Transfer Unit Service

(ABLACK) AB performed PTU service

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 41548

USING DEPT NO: 507121	OPENED DATE: 11/08/2021 15:25:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/09/2021 10:20:35	METER 1 - M: 15854 METER 2 - H: 3327
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/10/2021 07:44:35	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.56	\$46.22	\$0.00	\$79.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.28** **33.56** **46.22** **2.00** **81.78**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/09/2021 07:31:57	11/09/2021 07:49:01	0.28	\$33.56
LABOR					33.56	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.96	1	\$8.96
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS					46.22	

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 41548

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE-15854
ENG HRS-4199
IDLE HRS-3327

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 42243

USING DEPT NO: 507121	OPENED DATE: 02/01/2022 09:54:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/02/2022 10:45:57	METER 1 - M: 16820 METER 2 - H: 3626
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/02/2022 12:44:14	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$22.62	\$0.00	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$72.37	\$47.84	\$0.00	\$120.21
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.76	90.07	70.46	2.00	162.53
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/01/2022 13:02:05	02/01/2022 13:02:20	0.00	(\$0.49)
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/01/2022 13:02:05	02/01/2022 13:02:20	0.00	\$0.49
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/01/2022 13:02:05	02/01/2022 13:11:05	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/01/2022 12:25:04	02/01/2022 13:01:52	0.61	\$72.37
LABOR					90.07	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	10.58	1	\$10.58
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
PARTS					70.46	

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 42243

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE-16820

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 42964

USING DEPT NO: 507121	OPENED DATE: 04/19/2022 11:06:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/21/2022 08:51:43	METER 1 - M: 17711 METER 2 - H: 3857
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/21/2022 10:33:27	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.55	\$65.42	\$8.82	\$0.00	\$74.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.55** **65.42** **8.82** **2.00** **76.24**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	04/19/2022 11:10:05	04/19/2022 11:43:21	0.55	\$65.42
					LABOR	65.42

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.82	1	\$3.82
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.57	2	\$1.14
					PARTS	8.82

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 42964

Work Order Notes

(LISAPATE) Nail in RR tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(SHARBIN) Patched right rear tire. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 43107

USING DEPT NO:	507121	OPENED DATE:	05/02/2022 13:11:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/05/2022 08:19:22	METER 1 - M:	17895	METER 2 - H: 3900
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/05/2022 09:34:45	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR3KGB28055	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$20.36	\$53.96	\$0.00	\$74.32
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.18	\$21.08	\$24.75	\$0.00	\$45.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.35	41.44	78.71	2.00	122.15
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/03/2022 07:13:28	05/03/2022 07:24:11	0.18	\$21.08
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/02/2022 14:30:00	05/02/2022 14:40:21	0.17	\$20.36
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/02/2022 14:21:14	05/02/2022 14:21:14	0.00	\$0.00
LABOR					41.44	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.63	6	\$33.75
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.50	1	\$9.50
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.50	1	\$9.50
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	24.75	1	\$24.75
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.50	(1)	(\$9.50)
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS					78.71	

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 43107

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 17895 Completed PM topside, Scott was bottomsides. Completed checklist. AMG/SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(HHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 43217

USING DEPT NO: 507121	OPENED DATE: 05/13/2022 07:45:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/13/2022 14:05:38	METER 1 - M: 18208 METER 2 - H: 3983
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/18/2022 10:40:43	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	1.04	\$122.13	\$13.00	\$0.00	\$135.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.04** **122.13** **13.00** **2.00** **137.13**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	05/13/2022 07:53:27	05/13/2022 08:55:33	1.04	\$122.13
					LABOR	122.13

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.82	1	\$3.82
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	4.31	2	\$8.61
66-17-030	PERFORM TIRE PATCH	58104	1.25 OZ WHEEL WEIGHT	0.57	1	\$0.57
					PARTS	13.00

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 43217

Work Order Notes

(LISAPATE) Nail in RF tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) miles: 18208 hours: 4976 idle hours: 3983 Repaired and balanced R/F tire X2 nails. Rechecked for leaks, all good. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 44222

USING DEPT NO: 507121	OPENED DATE: 08/09/2022 10:53:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/17/2022 11:33:58	METER 1 - M: 18675 METER 2 - H: 4092
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 08/18/2022 13:40:51	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$46.61	\$66.48	\$0.00	\$113.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.40** **46.61** **66.48** **2.00** **115.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/09/2022 13:16:56	08/09/2022 13:40:38	0.40	\$46.61
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/09/2022 12:19:52	08/09/2022 12:19:52	0.00	\$0.00
LABOR					46.61	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.57	1	\$9.57
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	6	\$36.54
PARTS					66.48	

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 44222

Work Order Notes

(LRUSHING) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 18675 Completed PM top and bottom side. Completed checklist. AMG SH/ AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 45271

USING DEPT NO: 507121	OPENED DATE: 11/15/2022 09:18:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/17/2022 10:42:46	METER 1 - M: 19341 METER 2 - H: 4273
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/17/2022 12:20:38	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	1.00	\$118.00	\$113.55	\$0.00	\$231.55
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$6.69	\$58.40	\$0.00	\$65.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.06	124.69	171.95	5.00	301.64
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12052187	11/15/2022 15:03:04	11/15/2022 16:03:04	1.00	\$118.00
03-32-002	REPLACE NEW BATTERY	12052187	11/15/2022 15:03:04	11/15/2022 15:04:22	(0.02)	(\$2.56)
03-32-002	REPLACE NEW BATTERY	12052187	11/15/2022 15:03:04	11/15/2022 15:04:22	0.02	\$2.56
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/15/2022 14:59:40	11/15/2022 15:03:04	0.06	\$6.69
LABOR					124.69	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.76	1	\$7.76
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
PARTS					171.95	

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 45271

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) GC replaced battery. JAW and IF reset charging system. alternator charging at 14.8 volts
(IFALLS) ADDED additional time to reset charge pids with scan tool.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm service. Coolant -34. GC,SH/GC

Mileage-19341

Idle-4273

Engine-5329

(LISAPATE) removed skid plate

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 46614

USING DEPT NO: 507121	OPENED DATE: 04/04/2023 13:49:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/11/2023 08:00:48	METER 1 - M: 21037 METER 2 - H: 4702
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/11/2023 15:45:29	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.42	\$19.59	\$0.00	\$38.01
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$35.40	\$30.32	\$0.00	\$65.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.46	53.82	49.91	5.00	108.73
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/11/2023 07:00:00	04/11/2023 07:09:00	(0.15)	(\$17.70)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	04/11/2023 07:09:00	04/11/2023 07:27:00	0.30	\$35.40
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/11/2023 07:00:00	04/11/2023 07:09:00	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/10/2023 07:21:42	04/10/2023 07:31:04	0.16	\$18.42
LABOR					53.82	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP68	CABIN FILTER	30.32	1	\$30.32
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	19.59	1	\$19.59
PARTS					49.91	

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 46614

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) cancel

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 531 miles and 129 idle hrs. Checked fluids and tires. Coolant -34°. JAW,GC,CW
MILEAGE-21037
ENG HRS-5851
IDLE HRS-4702

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter. JW

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 47461

USING DEPT NO: 507121	OPENED DATE: 06/28/2023 13:46:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/30/2023 09:25:56	METER 1 - M: 21688 METER 2 - H: 5039
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/05/2023 09:29:22	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.55	\$64.54	\$61.82	\$0.00	\$126.36
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.55** **64.54** **61.82** **5.00** **131.36**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/28/2023 14:30:00	06/28/2023 15:02:49	0.55	\$64.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/28/2023 14:23:31	06/28/2023 14:23:31	0.00	\$0.00
LABOR					64.54	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
PARTS					61.82	

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 47461

Work Order Notes

(EHANNAH) pm - replace wipers
(EKIMBREL) did not need wipers yet

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 48369

USING DEPT NO: 507121	OPENED DATE: 10/02/2023 08:23:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/02/2023 15:01:09	METER 1 - M: 23409 METER 2 - H: 5558
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/02/2023 15:41:14	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-010	REPLACE NEW TAG LIGHT	DON	P	N	GARAGE	0.10	\$11.80	\$0.39	\$0.00	\$12.19
15-32-002	WARRANTY BATTERY	DON	W	J	GARAGE	0.45	\$53.46	\$0.00	\$0.00	\$53.46
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$64.34	\$0.00	\$103.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.88** **104.20** **64.73** **5.00** **173.93**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/02/2023 14:58:44	10/02/2023 15:18:32	0.33	\$38.94
03-34-010	REPLACE NEW TAG LIGHT	12395904	10/02/2023 14:18:32	10/02/2023 14:24:32	0.10	\$11.80
15-32-002	WARRANTY BATTERY	11310047	10/02/2023 09:50:28	10/02/2023 10:17:39	0.45	\$53.46
					LABOR 104.20	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
03-34-010	REPLACE NEW TAG LIGHT	194	BULB-TAG/MARKER	0.39	1	\$0.39
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
15-32-002	WARRANTY BATTERY	650	BATTERY BCI 65 650 CCA	0.00	1	\$0.00
					PARTS 64.73	

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 48369

Work Order Notes

(EHANNAH) pm

Job Notes

03-34-010 - REPLACE NEW TAG LIGHT

(LISAPATE) Replaced tag light

15-32-002 - WARRANTY BATTERY

(EHOWELL) The customer was complaining of a sulfur smell. Performed a road test to smell for possible catalytic converter failure, but this didn't seem to be the cause. Examined battery under the hood and found a small amount of leakage from the battery between the posts. Replaced the battery under warranty and relearned the Battery Monitoring System with a scan tool.

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 49048

USING DEPT NO: 507121	OPENED DATE: 11/27/2023 07:53:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/14/2023 08:06:35	METER 1 - M: 24437 METER 2 - H: 5558
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/14/2023 14:34:39	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-15-034	REPLACE NEW CONTROL ARM ASSY	DON	N	N	GARAGE	1.12	\$132.36	\$207.75	\$0.00	\$340.11
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.93	\$109.54	\$0.00	\$0.00	\$109.54
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	N	N	GARAGE	0.20	\$24.16	\$0.00	\$0.00	\$24.16
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.06	\$7.64	\$0.00	\$0.00	\$7.64
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	1.52	\$178.77	\$0.00	\$0.00	\$178.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	3.83	452.47	207.75	5.00	665.22
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	12052187	12/11/2023 07:41:45	12/11/2023 07:42:02	0.00	\$0.56
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	12052187	12/14/2023 07:00:00	12/14/2023 07:12:00	0.20	\$23.60
14-52-021	INSTALL GPS SYSTEM	12052187	12/11/2023 07:37:52	12/11/2023 07:41:45	0.06	\$7.64
66-17-013	PERFORM ALIGNMENT	12052187	12/11/2023 07:36:30	12/11/2023 07:37:38	0.02	\$2.23
66-17-013	PERFORM ALIGNMENT	12052187	12/07/2023 09:22:57	12/07/2023 10:52:43	1.50	\$176.54
03-15-034	REPLACE NEW CONTROL ARM ASSY	12052187	12/07/2023 08:15:19	12/07/2023 09:22:37	1.12	\$132.36
06-15	INSPECT STEERING	12052187	11/27/2023 09:46:23	11/27/2023 10:42:05	0.93	\$109.54
					LABOR	452.47

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-15-034	REPLACE NEW CONTROL ARM ASSY	W707516S439	BOLT LCA BUSHING 1REQ	6.30	1	\$6.30
03-15-034	REPLACE NEW CONTROL ARM ASSY	W708848S439	BOLT LCA BRACKET 2REQ	7.86	1	\$7.86
03-15-034	REPLACE NEW CONTROL ARM ASSY	W708848S439	BOLT LCA BRACKET 2REQ	7.86	(1)	(\$7.86)
03-15-034	REPLACE NEW CONTROL ARM ASSY	W708848S439	BOLT LCA BRACKET 2REQ	3.93	2	\$7.86

Work Order Charge Detail

The University of Alabama

Report Printed: 12/03/2024 11:19:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-15-034	REPLACE NEW CONTROL ARM ASSY	TRWJTC2568	CONTROL ARM	193.59	1	\$193.59
PARTS						207.75

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 49048

Work Order Notes

(EHANNAH) inspect tires- inspect steering
(EHANNAH) install GPS- 87x032360270

Job Notes

03-15-034 - REPLACE NEW CONTROL ARM ASSY

(JWRIGHT) Replaced right front lower control arm assembly. Torqued rear arm bolts to 73 ft lbs. Front arm bolt to 195 ft lbs. Ball joint to 155 ft lbs. Hub bolts to 122 ft lbs and hub nut to 258 ft lbs. Test drove and found no issues. JAW

06-15 - INSPECT STEERING

(JWRIGHT) Inspected and found left front cv axle popping and needs replaced. JAW
(GARAGE) Further inspected and found bushing on right lower control arm is busted. JAW

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) Found no issues with tires. JAW

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed gps JAW
(LISAPATE) install GPS- 87x032360270

66-17-013 - PERFORM ALIGNMENT

(JWRIGHT) performed alignment. Adjusted right toe. Test drove and found no other issues. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 49273

USING DEPT NO: 507121	OPENED DATE: 12/15/2023 10:05:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/20/2023 15:38:47	METER 1 - M: 24589 METER 2 - H: 5811
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/21/2023 07:45:40	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.33	\$38.45	\$0.00	\$0.00	\$38.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.33** **38.45** **0.00** **5.00** **43.45**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-15	INSPECT STEERING	11310047	12/15/2023 13:27:37	12/15/2023 13:47:10	0.33	\$38.45
					LABOR	38.45

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 49273

Work Order Notes

(EHANNAH) making a popping noise when turning

Job Notes

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. Also, did not see any loose bolts, sway bar end links, or left lower control arm bushings. Made multiple sharp turns and listened for a noise. We are releasing the vehicle back to the customer. EH/GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 49706

USING DEPT NO: 507121	OPENED DATE: 02/06/2024 08:11:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/06/2024 15:45:19	METER 1 - M: 25129 METER 2 - H: 5923
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/07/2024 15:32:38	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$61.72	\$60.56	\$0.00	\$122.28
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.15	\$17.70	\$18.83	\$0.00	\$36.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.67	79.42	79.39	5.00	163.81
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/06/2024 08:43:37	02/06/2024 09:15:00	0.52	\$61.72
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	02/06/2024 09:15:00	02/06/2024 09:24:00	0.15	\$17.70
LABOR					79.42	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	18.83	1	\$18.83
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
PARTS					79.39	

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 49706

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 50796

USING DEPT NO: 507121	OPENED DATE: 05/09/2024 13:33:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/10/2024 09:35:15	METER 1 - M: 27141 METER 2 - H: 6321
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/13/2024 12:09:20	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.02	\$1.80	\$0.00	\$0.00	\$1.80
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$60.65	\$0.00	\$60.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.02	1.80	84.73	5.00	91.53
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/09/2024 14:17:04	05/09/2024 14:17:04	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/09/2024 14:18:25	05/09/2024 14:18:25	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	05/09/2024 14:52:26	05/09/2024 14:53:21	0.02	\$1.80
					LABOR	1.80

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.67	6	\$34.02
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
					PARTS	84.73

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 50796

Work Order Notes

(EHANNAH) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Rotated the tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 51057

USING DEPT NO: 507121	OPENED DATE: 06/05/2024 16:41:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/06/2024 08:10:38	METER 1 - M: 27702 METER 2 - H: 6321
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/06/2024 09:05:08	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-05	RECALL ELECTRONIC ENGINE EEC SY	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 51057

Work Order Notes

(EHANNAH) prep and schedule- RECALL for powertrain control

Job Notes

17-05 - RECALL ELECTRONIC ENGINE EEC SYSTEM

(EHANNAH) LL Ford came to our shop for Recall for powertrain control

17-GA-005 - RECALL Scheduling and Preparation

(EHANNAH) prep and scheduling by Denise

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 52101

USING DEPT NO: 507121	OPENED DATE: 09/11/2024 14:28:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/28/2024 08:25:30	METER 1 - M: 28495 METER 2 - H: 6321
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/28/2024 08:25:33	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$4.06	\$4.06
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.03	\$4.06	\$0.00	\$0.00	\$4.06

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.03** **4.06** **0.00** **4.06** **8.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$4.06
COMML					4.06

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	09/25/2024 09:39:25	09/25/2024 09:41:29	0.03	\$4.06
LABOR						4.06

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 52101

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Removed wordmarks. Removed tag 2479C. Removed GPS 87X032360270. Checked inside of vehicle. CW/RC

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 52352

USING DEPT NO: 507121	OPENED DATE: 10/02/2024 13:50:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/08/2024 07:46:32	METER 1 - M: 28495 METER 2 - H: 6321
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 10/08/2024 10:29:53	IN-SERVICE DATE: 03/01/2019
TECH SPEC NO: 19FORDEXPINTR	2019 Ford Explorer Police Interceptor	UNIT SERIAL NO: 1FM5K8AR3KGB28055

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-33-006	REMOVE IGNITION LOCK CYLINDER	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$42.30	\$0.00	\$42.30
RY-33-006	REKEY IGNITION LOCK CYLINDER	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$95.22	\$95.22

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	42.30	100.22	142.52
---------------------	--------------------------	-------------	-------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2315034		\$95.22
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					100.22

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.15	2	\$0.30
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	08984	ADHESIVE REMOVER	42.00	1	\$42.00
PARTS						42.30

Work Order Charge Detail

UNIT NO: 243197 2019 FORD INTERCEPTOR

WORK ORDER NO: 52352

Work Order Notes

(EHOWELL) The previous work order was closed due to year end. The GPS has already been removed, but we need to charge labor for it on this work order. We've already charged for the prep for sale.

Lock cylinders need to be removed and rekeyed.

Job Notes

25-33-006 - REMOVE IGNITION LOCK CYLINDER

(EHOWELL) REMOVED LOCK CYLINDERS TO BE REKEYED REINSTALLED KEY CYLINDERS CM

25-52-021 - REMOVE GPS SYSTEM

(EHOWELL) GPS # 87X032360270 was removed. Work order number 52101.

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) LABOR BILLED ON WO#52101

(EHOWELL) Removed wordmarks. Removed tag 2479C. Removed GPS 87X032360270. Checked inside of vehicle. CW/RC

RY-33-006 - REKEY IGNITION LOCK CYLINDER

(EHOWELL) A1 rekeyed lock cylinders.

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Dec 03 2024 11:19:12 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243197') //Q=