

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32205

USING DEPT NO: 507121	OPENED DATE: 02/18/2019 07:34:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/20/2019 09:41:03	METER 1 - M: 1166 METER 2 - H: 222
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/20/2019 09:41:05	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$0.00	\$23.03	\$0.00	\$23.03

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.00** **0.00** **23.03** **0.00** **23.03**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/18/2019 09:22:07	02/18/2019 10:22:10	1.00	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	6	\$18.00
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	23.03

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32205

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH
Coolant -20'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32549

USING DEPT NO:	507121	OPENED DATE:	04/08/2019 07:31:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/11/2019 08:04:09	METER 1 - M:	2654	METER 2 - H: 521
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/11/2019 08:04:11	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.71	\$0.00	\$22.85	\$0.00	\$22.85

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.71** **0.00** **22.85** **0.00** **22.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/08/2019 09:22:10	04/08/2019 10:04:28	0.71	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.97	6	\$17.82
					PARTS	22.85

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32549

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH
Coolant -20'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33081

USING DEPT NO:	507121	OPENED DATE:	06/06/2019 07:05:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/07/2019 09:54:49	METER 1 - M:	4275	METER 2 - H: 802
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/07/2019 09:54:51	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.39** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/06/2019 07:44:12	06/06/2019 08:07:45	0.39	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33081

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by RC/AG
Coolant -35'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33180

USING DEPT NO:	507121	OPENED DATE:	06/19/2019 07:03:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/21/2019 07:05:52	METER 1 - M:	4809	METER 2 - H: 921
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/21/2019 07:05:54	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$0.00	\$22.79	\$0.00	\$22.79

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.85** **0.00** **22.79** **0.00** **22.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/19/2019 07:34:02	06/19/2019 08:24:46	0.85	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	6	\$17.76
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	22.79

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33180

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 6/19/2019 7:04 AM By LISAPATE

(LISAPATE) PM by EK/AG

Coolant -35'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33255

USING DEPT NO: 507121	OPENED DATE: 06/27/2019 07:11:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/28/2019 06:48:01	METER 1 - M: 5025 METER 2 - H: 971
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/28/2019 06:48:03	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.98	\$0.00	\$22.79	\$0.00	\$22.79

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.98** **0.00** **22.79** **0.00** **22.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/27/2019 10:02:04	06/27/2019 11:00:48	0.98	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	1	\$2.96
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	(1)	(\$2.96)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	6	\$17.76
					PARTS	22.79

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33255

Work Order Notes

(LISAPATE) PM
(LISAPATE) idle hours 697

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 6/27/2019 7:12 AM By LISAPATE
(LISAPATE) PM by SH
Coolant -20'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33486

USING DEPT NO: 507121	OPENED DATE: 07/19/2019 07:10:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/22/2019 14:56:05	METER 1 - M: 58975 METER 2 - H: 971
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 07/22/2019 14:56:07	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/22/2019 06:00:00	07/22/2019 06:18:36	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33486

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS) SH performed pm coolant good to -35 deg

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33683

USING DEPT NO: 507121	OPENED DATE: 08/12/2019 07:27:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/13/2019 09:07:45	METER 1 - M: 7397 METER 2 - H: 1519
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 08/13/2019 09:07:47	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$0.00	\$26.94	\$0.00	\$26.94

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.32** **0.00** **26.94** **0.00** **26.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/12/2019 09:20:27	08/12/2019 09:39:43	0.32	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	26.94

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33683

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK,RC/SH
Coolant -15'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34033

USING DEPT NO: 507121	OPENED DATE: 09/10/2019 07:06:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/16/2019 13:55:18	METER 1 - M: 8531 METER 2 - H: 1519
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/16/2019 13:55:19	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-42-004	WARRANTY WATER PUMP	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	1.61	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$0.00	\$22.79	\$0.00	\$22.79

JOB COUNT: 3	WORK ORDER TOTAL:	1.97	0.00	22.79	0.00	22.79
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-42-004	WARRANTY WATER PUMP	4910000	585846		\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-42	TRANSPORT COOLING SYSTEM	10208562	09/10/2019 10:13:43	09/10/2019 11:50:24	1.61	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/10/2019 09:40:24	09/10/2019 09:57:58	0.29	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/10/2019 09:54:18	09/10/2019 09:58:12	0.07	\$0.00
LABOR					0.00	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	6	\$17.76
PARTS					22.79	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34033

Work Order Notes

(LISAPATE) PM

Job Notes

15-42-004 - WARRANTY WATER PUMP

(LISAPATE) Sent to Town and Country, Tuscaloosa Ford could not get vehicle in . Town and Country verified waterpump was leaking. Replaced water pump and adjusted coolant level. Verified repair

16-42 - TRANSPORT COOLING SYSTEM

(LISAPATE) Taken to Town and Country by EK/RC

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK,JW/SH
Coolant -35'

** Found coolant low and leaking around the water pump. Sent to dealer for warranty repair

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34170

USING DEPT NO: 507121	OPENED DATE: 09/20/2019 07:09:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/23/2019 13:36:33	METER 1 - M: 9344 METER 2 - H: 1872
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/23/2019 13:36:34	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$0.00	\$22.79	\$0.00	\$22.79

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.29** **0.00** **22.79** **0.00** **22.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/20/2019 08:37:45	09/20/2019 08:55:18	0.29	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	6	\$17.76
					PARTS	22.79

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34170

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,JW/AG
Coolant -35'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34214

USING DEPT NO: 507121	OPENED DATE: 09/23/2019 13:36:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/26/2019 06:31:01	METER 1 - M: 9661 METER 2 - H: 1872
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 09/26/2019 06:31:02	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-22	INSPECT AXLES - DRIVEN, REAR	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.23	\$0.00	\$5.16	\$0.00	\$5.16

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.73** **0.00** **5.16** **0.00** **5.16**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	12052187	09/25/2019 07:39:30	09/25/2019 07:53:26	0.23	\$0.00
06-22	INSPECT AXLES - DRIVEN, REAR	11268671	09/24/2019 07:00:00	09/24/2019 07:30:00	0.50	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.29	1	\$0.29
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.53	1	\$2.53
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	2.34	1	\$2.34
					PARTS	5.16

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34214

Work Order Notes

(LISAPATE) Per Matt Foster unit is making a banging noise in the rear end when accelerating from a stop
(LISAPATE) Nail in LR tire

Job Notes

06-22 - INSPECT AXLES - DRIVEN, REAR

(EKIMBREL) IF found that noise was caused by a bottle of water of water rolling around in back.

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) Patched LR tire from the inside. Rechecked ok

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34345

USING DEPT NO: 507121	OPENED DATE: 10/07/2019 07:18:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/08/2019 08:18:51	METER 1 - M: 10262 METER 2 - H: 1511
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 10/08/2019 08:18:53	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.79	\$0.00	\$22.73	\$0.00	\$22.73
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.11	\$0.00	\$3.55	\$0.00	\$3.55

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.89** **0.00** **26.28** **0.00** **26.28**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	10/07/2019 09:30:00	10/07/2019 09:33:02	0.05	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	10/07/2019 09:11:44	10/07/2019 09:15:00	0.05	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/07/2019 08:32:19	10/07/2019 09:00:16	0.47	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/07/2019 08:13:18	10/07/2019 08:18:54	0.09	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/07/2019 07:39:09	10/07/2019 07:52:46	0.23	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4068	FILTER- CABIN AIR	3.55	1	\$3.55
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	26.28

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34345

Work Order Notes

(LISAPATE) PM
(LISAPATE) engine idle hours 1511
(RWINTERS) engine hrs 2069

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by RC/AG
Coolant -20'
Syn 0.5

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34799

USING DEPT NO: 507121	OPENED DATE: 11/11/2019 07:07:46	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/12/2019 13:20:26	METER 1 - M: 11192 METER 2 - H: 1708
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/12/2019 13:20:27	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.52	\$0.00	\$19.27	\$0.00	\$19.27
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.12	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$0.00	\$22.25	\$0.00	\$22.25

JOB COUNT: 3	WORK ORDER TOTAL:	1.25	0.00	41.52	0.00	41.52
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	11/11/2019 07:47:41	11/11/2019 07:55:02	0.12	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	10208562	11/11/2019 08:27:56	11/11/2019 08:59:07	0.52	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/11/2019 07:11:28	11/11/2019 07:47:41	0.60	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	10.25	1	\$10.25
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	9.02	1	\$9.02
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.87	6	\$17.22
					PARTS	41.52

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34799

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH

Coolant -35'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35100

USING DEPT NO: 507121	OPENED DATE: 12/09/2019 07:25:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/10/2019 08:05:14	METER 1 - M: 12421 METER 2 - H: 1912
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/10/2019 08:05:15	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.10	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$0.00	\$22.31	\$0.00	\$22.31

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.63** **0.00** **22.31** **0.00** **22.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	12/09/2019 08:13:47	12/09/2019 08:19:44	0.10	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/09/2019 07:41:41	12/09/2019 08:13:47	0.54	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.88	6	\$17.28
					PARTS	22.31

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35100

Work Order Notes

(LISAPATE) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires, torqued to spec

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK,JW/JW
Coolant -35'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35255

USING DEPT NO:	507121	OPENED DATE:	01/02/2020 07:08:51	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	01/06/2020 06:52:25	METER 1 - M:	13622	METER 2 - H:	2117
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/06/2020 06:52:27	IN-SERVICE DATE:	08/06/2018		
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR6JGC29279		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.44	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.84	\$0.00	\$22.25	\$0.00	\$22.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.28** **0.00** **22.25** **0.00** **22.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	01/02/2020 08:31:15	01/02/2020 08:57:50	0.44	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/02/2020 07:41:04	01/02/2020 08:31:15	0.84	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.87	6	\$17.22
					PARTS	22.25

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35255

Work Order Notes

(EKIMBREL) PM; Rotate tires

Job Notes

15-40-408 - WARRANTY ENGINE MOUNT(S)

(RWINTERS) cancel job

16-40 - TRANSPORT ENGINE / MOTOR SYSTEMS

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(EKIMBREL) JW rotated tires and relearned TPMS.

66-17-015 - PERFORM TIRE ROTATION

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/JW. coolant -35

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35463

USING DEPT NO: 507121	OPENED DATE: 01/22/2020 07:02:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/30/2020 08:33:41	METER 1 - M: 16397 METER 2 - H: 2317
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 01/30/2020 08:33:42	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	1.05	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.74	\$0.00	\$27.02	\$0.00	\$27.02

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.80** **0.00** **27.02** **0.00** **27.02**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	01/23/2020 10:39:57	01/23/2020 11:43:04	1.05	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/22/2020 08:37:26	01/22/2020 08:58:00	0.34	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/22/2020 08:33:10	01/22/2020 08:57:14	0.40	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	27.02

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35463

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires. Relearned TPMS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/JW
Coolant -20'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35555

USING DEPT NO: 507121	OPENED DATE: 02/03/2020 08:36:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/12/2020 11:26:58	METER 1 - M: 15356 METER 2 - H: 2396
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 02/12/2020 11:26:59	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
SO-00	SCAN OUT COMPLETE VEHICLE	DON	O	N	GARAGE	0.86	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.86** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	02/04/2020 09:03:26	02/04/2020 09:55:15	0.86	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-33-004	REPLACE NEW SPARK PLUGS	MS97214	PLENUM GASKET	7.90	(1)	(\$7.90)
03-33-004	REPLACE NEW SPARK PLUGS	MS97214	PLENUM GASKET	7.90	1	\$7.90
03-33-004	REPLACE NEW SPARK PLUGS	MOTSP520	SPARK PLUGS	5.53	6	\$33.18
03-33-004	REPLACE NEW SPARK PLUGS	MOTSP520	SPARK PLUGS	5.53	(6)	(\$33.18)
03-33-003	REPLACE NEW COIL	702522	COP IGNITION COIL BOOT	3.09	5	\$15.45
03-33-003	REPLACE NEW COIL	702522	COP IGNITION COIL BOOT	3.09	(5)	(\$15.45)
03-33-003	REPLACE NEW COIL	IC930	IGNITION COIL COP	14.24	1	\$14.24
03-33-003	REPLACE NEW COIL	IC930	IGNITION COIL COP	14.24	(1)	(\$14.24)
					PARTS	0.00

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35555

Work Order Notes

(EKIMBREL) Check engine light on

Job Notes

03-33-003 - REPLACE NEW COIL

03-33-004 - REPLACE NEW SPARK PLUGS

SO-00 - SCAN OUT COMPLETE VEHICLE

(EKIMBREL) EH scanned out with Ford IDS. Codes: P0306, Cylinder 6 misfire detected. Performed multiple road tests and allowed vehicle to idle for an extended period of time. Viewed misfire data using scan tool, but the vehicle is not misfiring at this time. Swapped #6 coil with #5 coil to see if the location of the misfire changes. EH Cleared code and check engine light is off. JW Drove a total of 215 miles on interstate checking for misfiring and had no issues at all. Drove through stormy weather conditions with stopping/going and quick accelerating with no issues. If check engine light comes on vehicle will need to come back.

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35802

USING DEPT NO: 507121	OPENED DATE: 02/27/2020 07:02:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/02/2020 07:44:55	METER 1 - M: 16465 METER 2 - H: 2517
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/02/2020 07:44:58	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.92	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.75	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.67** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11310047	02/27/2020 10:59:15	02/27/2020 11:54:17	0.92	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/27/2020 10:03:25	02/27/2020 10:20:10	0.28	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/27/2020 09:45:28	02/27/2020 10:13:54	0.47	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35802

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires, relearned TPMS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/AG
Coolant -20'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36179

USING DEPT NO:	507121	OPENED DATE:	04/20/2020 13:48:51	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2020 07:37:06	METER 1 - M:	17944	METER 2 - H:	2517
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/22/2020 10:36:13	IN-SERVICE DATE:	08/06/2018		
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR6JGC29279		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.62	\$0.00	\$98.65	\$0.00	\$98.65
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.34	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$0.00	\$28.31	\$0.00	\$28.31
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.08	\$0.00	\$3.55	\$0.00	\$3.55

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.17** **0.00** **130.51** **0.00** **130.51**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11901357	04/21/2020 15:16:09	04/21/2020 15:36:15	0.34	\$0.00
03-32-002	REPLACE NEW BATTERY	11901357	04/21/2020 14:39:13	04/21/2020 15:16:09	0.62	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	04/21/2020 14:34:13	04/21/2020 14:39:13	0.08	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/21/2020 14:30:00	04/21/2020 14:34:13	0.07	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/21/2020 14:11:18	04/21/2020 14:15:00	0.06	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	3.88	6	\$23.28
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.42	2	\$0.84
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	97.81	1	\$97.81
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4068	FILTER- CABIN AIR	3.55	1	\$3.55
					PARTS	130.51

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36179

Work Order Notes

(IFALLS) pm

Job Notes

03-32-002 - REPLACE NEW BATTERY

(IFALLS) AG replaced battery

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(IFALLS) AG/EH rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) EH performed pm

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(IFALLS) EH replaced cabin filter

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36735

USING DEPT NO: 507121	OPENED DATE: 06/08/2020 13:08:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/11/2020 11:28:27	METER 1 - M: 19109 METER 2 - H: 2927
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/15/2020 09:15:53	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.18	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.76	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.15	\$0.00	\$520.05	\$0.00	\$520.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$0.00	\$22.73	\$0.00	\$22.73
PR-01-002	PROGRAM HEATING & VENTILATING	DON	O	N	GARAGE	0.35	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.79	0.00	542.78	0.00	542.78
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	06/09/2020 10:39:24	06/09/2020 11:48:10	1.15	\$0.00
09-15	ALIGN STEERING	11213180	06/10/2020 08:39:04	06/10/2020 09:24:44	0.76	\$0.00
PR-01-002	PROGRAM HEATING & VENTILATING	11170580	06/10/2020 11:37:14	06/10/2020 11:58:02	0.35	\$0.00
06-15	INSPECT STEERING	12052187	06/09/2020 10:28:03	06/09/2020 10:39:08	0.18	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/08/2020 14:20:48	06/08/2020 14:41:58	0.35	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000177	TIRE P245/55R18 FIREHAWK PURSU	126.98	4	\$507.92
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	7	\$1.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.56	4	\$10.24
					PARTS	542.78

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36735

Work Order Notes

(LISAPATE) PM-Program A/C for Covid

Job Notes

06-15 - INSPECT STEERING

(JWRIGHT) Inspected front end. Found no issues

09-15 - ALIGN STEERING

(MSIDES) Performed alignment. MS

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced and balanced all 4 tires. Aired to spec and torqued to spec. Relearned tpms.

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Needs a set of tires.

PM by RC/AG

Coolant -34'

PR-01-002 - PROGRAM HEATING & VENTILATING

(ABLACK) AB reprogrammed PCM, BCM, and HVAC modules in order to active coronavirus disinfectant mode.

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37179

USING DEPT NO: 507121	OPENED DATE: 07/27/2020 07:16:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/27/2020 15:27:45	METER 1 - M: 20537 METER 2 - H: 3125
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/28/2020 10:45:24	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.24	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.54** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	07/27/2020 08:13:28	07/27/2020 08:27:35	0.24	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/27/2020 07:47:33	07/27/2020 07:53:27	0.10	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/27/2020 07:40:55	07/27/2020 07:53:10	0.20	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37179

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires and relearned tire positions

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/EH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37277

USING DEPT NO: 507121	OPENED DATE: 08/06/2020 14:19:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/10/2020 14:21:47	METER 1 - M: 20934 METER 2 - H: 3198
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/11/2020 13:48:18	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-01	INSPECT AIR CONDITIONING, HEAT, VE	DON	O	N	GARAGE	0.19	\$0.00	\$0.00	\$0.00	\$0.00
06-34-002	INSPECT LAMPS-REAR,TAIL,STOP,TUR	DON	O	N	GARAGE	0.25	\$0.00	\$0.00	\$0.00	\$0.00
15-35-007	WARRANTY MULTI-FUNCTION SWITCH	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-35	TRANSPORT MULTI-FUNC ELECTRON/I	DON	O	N	GARAGE	1.75	\$0.00	\$0.00	\$0.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREI	DON	O	N	GARAGE	1.00	\$0.00	\$3.27	\$0.00	\$3.27

JOB COUNT: 5	WORK ORDER TOTAL:	3.19	0.00	3.27	0.00	3.27
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-35-007	WARRANTY MULTI-FUNCTION SWITCH	4910000	603073		\$0.00
					COMML
					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11170580	08/07/2020 07:42:06	08/07/2020 07:53:23	0.19	\$0.00
16-35	TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS	11915538	08/07/2020 08:24:52	08/07/2020 10:10:03	1.75	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	08/10/2020 07:00:00	08/10/2020 08:00:00	1.00	\$0.00
06-34-002	INSPECT LAMPS-REAR,TAIL,STOP,TURN,ETC	11170580	08/11/2020 07:00:00	08/11/2020 07:15:00	0.25	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.19	2	\$0.38
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	0.73	1	\$0.73
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.09	24	\$2.16
					PARTS	3.27

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37277

Work Order Notes

(EKIMBREL) Left turn signal will not cut off after turning. AC not blowing very cool

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Checked A/C found freon was low

06-34-002 - INSPECT LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) Found turn signal wasn't turning off after the wheel was being turned send to dealer for a warranty repair

15-35-007 - WARRANTY MULTI-FUNCTION SWITCH

(LISAPATE) Town and Country Ford verified concern found faulty clockspring. Removed and replaced clockspring. Verified repair

16-35 - TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS

(LISAPATE) Taken to T&C by RC

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(LISAPATE) AB Evacuated system. Pulled out 1lb 8oz . Found it was 2oz low. Vacuumed and recharged to 1lb 10oz used 1oz of ester oil with dye. Rechecked ok

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37308

USING DEPT NO: 507121	OPENED DATE: 08/11/2020 13:48:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/14/2020 13:33:19	METER 1 - M: 20934 METER 2 - H: 3198
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/14/2020 13:33:26	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-35-007	WARRANTY MULTI-FUNCTION SWITCH	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-35	TRANSPORT MULTI-FUNC ELECTRON/I	DON	O	N	GARAGE	2.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **2.00** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-35-007	WARRANTY MULTI-FUNCTION SWITCH	4910000	603248		\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-35	TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS	10208562	08/13/2020 07:00:00	08/13/2020 09:00:00	2.00	\$0.00
LABOR						0.00

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37308

Work Order Notes

(LISAPATE) Left turn signal still will not turn off by itself. Sent back to Town and Country

Job Notes

15-35-007 - WARRANTY MULTI-FUNCTION SWITCH

(LISAPATE) Town and Country replaced multi function switch. see attached

16-35 - TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS

(LISAPATE) Taken to T&C by EK

(IFALLS) No charge for transport

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37373

USING DEPT NO: 507121	OPENED DATE: 08/18/2020 09:31:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/21/2020 08:07:27	METER 1 - M: 21227 METER 2 - H: 3218
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/21/2020 10:13:49	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	DON	O	N	GARAGE	1.37	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.37** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11213180	08/21/2020 07:01:49	08/21/2020 07:06:04	0.07	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11213180	08/18/2020 09:39:31	08/18/2020 10:57:41	1.30	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37373

Work Order Notes

(LISAPATE) A/C is blowing hot

Job Notes

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(MSIDES) Let vehicle run about 14 hrs and A/C worked well the entire time, also test drove vehicle several times and issue never reoccurred. Decided to return vehicle to customer and informed them if issue happens again to open the hood and look to see if lines are frozen over and return vehicle to shop. MS

(MSIDES) Could not duplicate issue. Returned vehicle to customer. MS

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37526

USING DEPT NO:	507121	OPENED DATE:	09/08/2020 08:39:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/08/2020 15:22:04	METER 1 - M:	21651	METER 2 - H: 3336
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/09/2020 09:51:00	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$0.00	\$22.79	\$0.00	\$22.79

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.13** **0.00** **22.79** **0.00** **22.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11310047	09/09/2020 07:00:00	09/09/2020 07:30:00	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/08/2020 09:19:12	09/08/2020 09:56:46	0.63	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	6	\$17.76
					PARTS	22.79

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37526

Work Order Notes

(LISAPATE) PM-Rotate tires
(EHOWELL) Rotated tires and relearned tire positions. EH

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(IFALLS) Rotated tires and relearned tire positions. EH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) EH/SH Performed PM

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38225

USING DEPT NO: 507121	OPENED DATE: 11/02/2020 07:47:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/03/2020 07:52:15	METER 1 - M: 23151 METER 2 - H: 3642
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/03/2020 10:16:58	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$45.04	\$34.92	\$0.00	\$79.96
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.10	\$11.80	\$5.33	\$0.00	\$17.13

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.48** **56.84** **40.25** **0.00** **97.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	11/03/2020 06:00:00	11/03/2020 06:06:00	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2020 09:15:00	11/02/2020 09:24:54	0.17	\$19.47
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2020 08:47:00	11/02/2020 09:00:00	0.22	\$25.57
					LABOR	56.84

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4068	FILTER- CABIN AIR	5.33	1	\$5.33
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	40.25

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38225

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) SH PERFORMED PM
(SHARBIN) SH Vacuumed and RC washed vehicle.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter SH

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38492

USING DEPT NO: 507121	OPENED DATE: 12/01/2020 07:37:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/02/2020 10:22:23	METER 1 - M: 23780 METER 2 - H: 3766
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/03/2020 15:30:37	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-33-003	REPLACE NEW COIL	DON	O	N	GARAGE	0.06	\$6.52	\$21.36	\$0.00	\$27.88
03-33-004	REPLACE NEW SPARK PLUGS	DON	O	N	GARAGE	0.44	\$51.76	\$241.87	\$0.00	\$293.63
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.05	\$6.20	\$0.00	\$0.00	\$6.20

JOB COUNT: 3	WORK ORDER TOTAL:	0.55	64.48	263.23	0.00	327.71
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	12/01/2020 14:07:59	12/01/2020 14:11:08	0.05	\$6.20
03-33-003	REPLACE NEW COIL	11170580	12/01/2020 14:04:31	12/01/2020 14:07:50	0.06	\$6.52
03-33-004	REPLACE NEW SPARK PLUGS	11170580	12/01/2020 13:38:02	12/01/2020 14:04:21	0.44	\$51.76
					LABOR	64.48

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-33-004	REPLACE NEW SPARK PLUGS	7651674	ANTI-SEIZE LUBRICANT ALMN	10.28	1	\$10.28
03-33-004	REPLACE NEW SPARK PLUGS	DEN6716291	COP BOOT	165.05	1	\$165.05
03-33-003	REPLACE NEW COIL	IC930	IGNITION COIL COP	21.36	1	\$21.36
03-33-004	REPLACE NEW SPARK PLUGS	MOTSP520	SPARK PLUGS	8.64	6	\$51.84
03-33-004	REPLACE NEW SPARK PLUGS	MAHMS19928	PLENUM GASKET	14.70	1	\$14.70
					PARTS	263.23

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38492

Work Order Notes

(LISAPATE) PM not due

Job Notes

03-33-003 - REPLACE NEW COIL

(ABLACK) AB Found cylinder 5 ignition coil was bad. Installed a new coil on cylinder 5. Rechecked ok.

03-33-004 - REPLACE NEW SPARK PLUGS

(ABLACK) AB scanned out and found P0305 cylinder 5 misfire. Suspect coil to be breaking down. Installed all new spark plugs. Test drove monitored misfire graph rechecked ok.

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM not done

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(ABLACK) AB scanned out and found code P0305 Cylinder 5 misfire. Vehicle needs new spark plugs, one new coil and new ignition boots.

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38749

USING DEPT NO:	507121	OPENED DATE:	01/11/2021 13:42:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/12/2021 07:55:42	METER 1 - M:	25061	METER 2 - H: 3965
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/12/2021 13:07:27	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$70.24	\$34.92	\$0.00	\$105.16

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.60** **70.24** **34.92** **0.00** **105.16**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/11/2021 15:09:49	01/11/2021 15:45:32	0.60	\$70.24
					LABOR	70.24

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	34.92

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38749

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 25061 Idle hours 3965. SH Performed PM.

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39082

USING DEPT NO: 507121	OPENED DATE: 02/10/2021 14:16:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/25/2021 09:03:18	METER 1 - M: 25513 METER 2 - H: 3965
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/01/2021 15:07:35	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71-024	REPAIR BUMPER(S)	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,375.18	\$2,375.18

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.50** **59.00** **0.00** **2,375.18** **2,434.18**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-71-024	REPAIR BUMPER(S)	11150605	1690462		\$2,375.18
COMML					2375.18

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-71	TRANSPORT BODY	10208562	02/25/2021 07:00:00	02/25/2021 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39082

Work Order Notes

(LISAPATE) Replace taillight assy was broken when someone backed into a pole.

Job Notes

03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by EK

24-71-024 - REPAIR BUMPER(S)

(LISAPATE) Visit Reason Changed On 2/25/2021 8:57 AM By LISAPATE

(LISAPATE) Andrews repaired rear bumper damage per the estimate. Pd by CC

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39294

USING DEPT NO: 507121	OPENED DATE: 03/04/2021 10:47:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/10/2021 10:09:24	METER 1 - M: 25658 METER 2 - H: 3965
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/12/2021 14:07:33	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-52-024	INSPECT BACK UP CAMERA	DON	O	N	GARAGE	0.38	\$45.40	\$0.00	\$0.00	\$45.40

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.38** **45.40** **0.00** **0.00** **45.40**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-52-024	INSPECT BACK UP CAMERA	11170580	03/05/2021 07:48:51	03/05/2021 08:11:56	0.38	\$45.40
					LABOR	45.40

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39294

Work Order Notes

(LISAPATE) Back up camera has a short will not work at times

Job Notes

06-52-024 - INSPECT BACK UP CAMERA

(ABLACK) AB found camera to not be working. Scanned out and found codes C1001:01 camera failure, and B115E:08-0A camera module failure. Swapped camera with a known good camera and verified the camera was bad. Installed old camera back into vehicle and it started working again. Returned vehicle to customer until it stops working again.

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39532

USING DEPT NO: 507121	OPENED DATE: 03/31/2021 08:34:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/03/2021 11:50:13	METER 1 - M: 25824 METER 2 - H: 4132
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/04/2021 14:35:58	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.01	\$0.66	\$8.45	\$0.00	\$9.11
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.01	\$0.79	\$0.00	\$0.00	\$0.79
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.34	\$39.76	\$0.00	\$0.00	\$39.76
15-01-005	WARRANTY COMPRESSOR	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
17-05-020	RECALL PCM/PROCESSOR ASSEMBLY	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	1.10	\$130.10	\$0.00	\$0.00	\$130.10
66-01-058	PERFORM EVAC AND RECHARGE FREI	DON	O	N	GARAGE	1.00	\$118.00	\$35.02	\$0.00	\$153.02
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.53	\$62.70	\$390.45	\$0.00	\$453.15
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.15	\$135.11	\$0.00	\$0.00	\$135.11
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.99	\$117.15	\$41.84	\$0.00	\$158.99
66-PM-PTU	PERFORM Power Transfer Unit Service	DON	P	N	GARAGE	1.31	\$154.91	\$22.22	\$0.00	\$177.13

JOB COUNT: 12 **WORK ORDER TOTAL:** **7.43** **877.18** **497.98** **0.00** **1,375.16**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-01-005	WARRANTY COMPRESSOR	4910000	616729		\$0.00
					COMML
					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11915538	05/03/2021 07:00:00	05/03/2021 08:00:00	1.00	\$118.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	05/03/2021 07:00:00	05/03/2021 08:00:00	1.00	\$118.00
66-PM-PTU	PERFORM Power Transfer Unit Service	11310047	03/31/2021 14:34:04	03/31/2021 15:52:50	1.31	\$154.91
06-15	INSPECT STEERING	11310047	03/31/2021 14:33:40	03/31/2021 14:34:04	0.01	\$0.79
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/31/2021 09:23:34	03/31/2021 09:57:50	0.57	\$67.39
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/31/2021 10:13:41	03/31/2021 10:38:59	0.42	\$49.76

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11310047	03/31/2021 13:24:58	03/31/2021 14:33:40	1.15	\$135.11
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	04/01/2021 09:42:37	04/01/2021 10:14:30	0.53	\$62.70
03-51-038	REPLACE NEW WIPER BLADES	11310047	04/01/2021 12:16:56	04/01/2021 12:17:16	0.01	\$0.66
09-15	ALIGN STEERING	11310047	04/01/2021 12:56:16	04/01/2021 13:16:29	0.34	\$39.76
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	04/07/2021 13:14:26	04/07/2021 14:15:00	1.01	\$119.11
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	04/07/2021 14:30:00	04/07/2021 14:35:35	0.09	\$10.98
					LABOR	877.17

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PTU	PERFORM Power Transfer Unit Service	VV982	75W-140 LS SYN GEAR OIL QT	15.66	1	\$15.66
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	(1)	(\$6.56)
66-PM-PTU	PERFORM Power Transfer Unit Service	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	8.45	1	\$8.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000177	TIRE P245/55R18 FIREHAWK PURSU	190.43	2	\$380.85
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	4	\$1.92
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.84	2	\$7.68
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	801802	A/C SERVICE VALVE KIT	28.62	1	\$28.62
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	801802	A/C SERVICE VALVE KIT	28.62	(1)	(\$28.62)
66-01-058	PERFORM EVAC AND RECHARGE FREON	801802	A/C SERVICE VALVE KIT	28.62	1	\$28.62
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.29	11	\$3.14
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.10	1	\$1.10
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	16	\$2.16
					PARTS	497.98

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39532

Work Order Notes

(LISAPATE) PM-Do SI-Service PTU- replace tires and align as needed
(LISAPATE) Per John Brown A/C is blowing hot

Job Notes

Work Order Charge Detail

03-51-038 - REPLACE NEW WIPER BLADES

(EHOWELL) Replaced rear wiper. EH

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. EH

09-15 - ALIGN STEERING

(EHOWELL) Performed Alignment. EH

15-01-005 - WARRANTY COMPRESSOR

(LISAPATE) Per Town and Country invoice. Verified concern no codes. Performed symptom test for a/c not cooling found compressor operating but pressures not changing and out of spec checked charge found correct charge per ppt replace a/c compressor per Ford warranty states to replace dryer expansion valve and any hose with a baffle if replacing compressor evac system removed belt and removed a/c compressor installed new compressor removed front bumper removed cooling fans and radiator removed and replaced condenser for the dryer non serviceable removed lines at firewall removed and replaced expansion valve. reinstalled all parts charge system to correct specs retest performed test drive cooling as designed at this time (no hoses on vehicle had a baffle no lines replaced) all parts turned in

16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Taken to Town and Country by RC

17-05-020 - RECALL PCM/PROCESSOR ASSEMBLY

(LISAPATE) Town and Country completed recall 19E02 Powertrain control module program
Updated PCM

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(LISAPATE) A/c under warranty found leaking sent to dealer

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(LISAPATE) Evac system pulled out 16oz of freon. installed new high and low side schrader valves. vacuumed and recharged used 11oz of freon rechecked ok

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EHOWELL) Mounted and balanced 2 tires put new tires on the front relearned tire positions. SH Old tires are in the back seat.

66-79-003 - PERFORM SAFETY INSPECTION

(EHOWELL) Performed Safety Inspection. Found front tires in need of replacement and rear wiper torn. Front wipers are good. EH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 25824 Engine hours 5584 Idle hours 4132. SH/AMG Performed PM.

66-PM-PTU - PERFORM Power Transfer Unit Service

(EHOWELL) Drained transfer case oil and installed 75W-140 oil. EH

PR-05-020 - PROGRAM PCM/PROCESSOR ASSEMBLY

Work Order Charge Detail

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40410

USING DEPT NO: 507121	OPENED DATE: 07/12/2021 13:10:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/13/2021 15:29:54	METER 1 - M: 26442 METER 2 - H: 4281
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/14/2021 12:16:42	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$21.80	\$0.00	\$33.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.27	\$47.13	\$0.00	\$70.40

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.30** **35.07** **68.93** **0.00** **104.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/12/2021 14:40:22	07/12/2021 14:52:12	0.20	\$23.27
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/12/2021 14:39:13	07/12/2021 14:39:26	0.00	(\$0.43)
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/12/2021 14:39:13	07/12/2021 14:39:26	0.00	\$0.43
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/12/2021 14:39:13	07/12/2021 14:45:13	0.10	\$11.80
					LABOR	35.07

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.78	1	\$9.78
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	9.83	1	\$9.83
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	11.97	1	\$11.97
					PARTS	68.93

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40410

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 26442 Engine hours 5767 Idle hours 4281. JW SH/JW performed PM.

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41064

USING DEPT NO:	507121	OPENED DATE:	09/20/2021 07:24:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/21/2021 12:51:20	METER 1 - M:	27629	METER 2 - H: 4583
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2021 07:30:50	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-003	REPLACE NEW SIGNAL,PARKING, & BA	DON	O	N	GARAGE	0.10	\$11.80	\$1.86	\$0.00	\$13.66
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$31.82	\$0.00	\$43.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$7.54	\$42.21	\$0.00	\$49.75
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.12	\$13.67	\$11.67	\$0.00	\$25.34
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.38	44.81	87.56	2.00	134.37
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00	
					COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	09/20/2021 13:04:55	09/20/2021 13:11:52	0.12	\$13.67
03-34-003	REPLACE NEW SIGNAL,PARKING, & BACKUP LAMPS	11901357	09/20/2021 12:24:59	09/20/2021 12:30:59	0.10	\$11.80
03-34-003	REPLACE NEW SIGNAL,PARKING, & BACKUP LAMPS	11901357	09/20/2021 12:24:59	09/20/2021 12:24:59	0.00	\$0.00
03-34-003	REPLACE NEW SIGNAL,PARKING, & BACKUP LAMPS	11901357	09/20/2021 12:24:59	09/20/2021 12:24:59	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/20/2021 12:29:51	09/20/2021 12:35:51	0.10	\$11.80
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/20/2021 12:29:51	09/20/2021 12:29:51	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/20/2021 12:29:51	09/20/2021 12:29:51	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/20/2021 12:35:50	09/20/2021 12:35:50	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/20/2021 13:00:00	09/20/2021 13:03:50	0.06	\$7.54
					LABOR	44.81

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.86	1	\$4.86
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-34-003	REPLACE NEW SIGNAL,PARKING, & BACKUP LAMPS	7440N	BULB	1.86	1	\$1.86
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	11.67	1	\$11.67
					PARTS	87.56

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41064

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-34-003 - REPLACE NEW SIGNAL,PARKING, & BACKUP LAMPS

(AGUERRA) Replaced left backup light bulb and checked for proper operation, all good. AMG

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced front and rear wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 27629 hours: 6140 idle hours: 4583 Completed PM top and bottom side. Completed checklist. AMG/AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41536

USING DEPT NO: 507121	OPENED DATE: 11/05/2021 15:11:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/09/2021 10:43:12	METER 1 - M: 28302 METER 2 - H: 4769
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/10/2021 07:18:14	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.10	\$11.90	\$113.55	\$0.00	\$125.45
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.24	\$28.32	\$0.00	\$0.00	\$28.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-31-001	SCAN OUT ALTERNATOR	DON	P	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.34** **158.22** **113.55** **2.00** **273.77**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-31-001	SCAN OUT ALTERNATOR	11170580	11/10/2021 07:00:00	11/10/2021 08:00:00	1.00	\$118.00
06-32-002	INSPECT BATTERY	11170580	11/08/2021 07:20:01	11/08/2021 07:34:25	0.24	\$28.32
03-32-002	REPLACE NEW BATTERY	11170580	11/08/2021 07:13:42	11/08/2021 07:19:45	0.10	\$11.90
					LABOR 158.22	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
					PARTS 113.55	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41536

Work Order Notes

(IFALLS) Check battery and alternator

Job Notes

03-32-002 - REPLACE NEW BATTERY

(ABLACK) AB installed a new battery. Old battery was smoking. Reset the bms on the vehicle and found vehicle was charging at 15v. Told the office to keep an eye on it over the weekend to see if he smelled the battery cooking. May need the alternator replaced if its still overcharging.

06-32-002 - INSPECT BATTERY

(ABLACK) AB inspected battery and found it was smoking. Needs a new battery

CH-SP - CHARGE Shop Supplies

SO-31-001 - SCAN OUT ALTERNATOR

(IFALLS) AB used scan tool to reset bms / alternator charging output.

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41763

USING DEPT NO: 507121	OPENED DATE: 12/02/2021 08:08:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/07/2021 11:46:05	METER 1 - M: 28693 METER 2 - H: 4897
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/07/2021 14:13:38	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.46	\$31.82	\$0.00	\$38.28
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.18	\$20.65	\$0.00	\$0.00	\$20.65
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.87	\$102.30	\$0.00	\$0.00	\$102.30
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.07	\$126.00	\$389.81	\$0.00	\$515.81
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$56.57	\$67.55	\$0.00	\$124.12
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.64	311.98	489.18	2.00	803.16
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11310047	12/06/2021 08:00:49	12/06/2021 08:52:50	0.87	\$102.30
06-15	INSPECT STEERING	11074414	12/02/2021 11:54:16	12/02/2021 11:55:46	0.03	\$2.95
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/02/2021 10:25:35	12/02/2021 10:28:52	0.05	\$6.46
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/02/2021 09:55:29	12/02/2021 10:24:15	0.48	\$56.57
06-15	INSPECT STEERING	11074414	12/02/2021 12:59:44	12/02/2021 12:59:44	0.00	\$0.00
06-15	INSPECT STEERING	11074414	12/02/2021 13:00:00	12/02/2021 13:09:00	0.15	\$17.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	12/03/2021 07:32:24	12/03/2021 08:36:28	1.07	\$126.00
					LABOR	311.98

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.48	1	\$9.48
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	20.81	1	\$20.81
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000177	TIRE P245/55R18 FIREHAWK PURSU	190.43	1	\$190.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.83	2	\$7.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.18	1	\$0.18
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.41	1	\$0.41
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.47	1	\$0.47
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000177	TIRE P245/55R18 FIREHAWK PURSU	190.41	1	\$190.41
					PARTS	489.18

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41763

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

06-15 - INSPECT STEERING

(SHARBIN) Inspected front end and brakes found no issues. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Checked alignment. No adjustments were necessary. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 2 tires. Put new tires on the front and relearned tire positions. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

(SHARBIN) Needs 2 rear tires. Tread depths are 2/32 and 3/32. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42487

USING DEPT NO: 507121	OPENED DATE: 02/28/2022 07:29:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/28/2022 15:00:44	METER 1 - M: 30565 METER 2 - H: 5244
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/01/2022 07:26:10	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.73	\$85.88	\$52.30	\$0.00	\$138.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.73** **85.88** **52.30** **2.00** **140.18**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/28/2022 08:04:34	02/28/2022 08:48:14	0.73	\$85.88
LABOR						85.88

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.48	1	\$8.48
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						52.30

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42487

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-30565

ENG HRS-6967

IDLE HRS-5244

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42771

USING DEPT NO: 507121	OPENED DATE: 03/31/2022 08:44:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/01/2022 09:31:03	METER 1 - M: 32137 METER 2 - H: 5548
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/15/2022 09:52:36	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.77	\$31.82	\$0.00	\$37.59
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$12.16	\$32.03	\$0.00	\$44.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.15	17.93	63.85	2.00	83.78
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	03/31/2022 12:24:55	03/31/2022 12:27:51	0.05	\$5.77
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/31/2022 12:18:35	03/31/2022 12:24:46	0.10	\$12.16
LABOR					17.93	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.39	1	\$5.39
PARTS					63.85	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42771

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/SH
MILEAGE-32137
HRS-5548

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43130

USING DEPT NO: 507121	OPENED DATE: 05/04/2022 08:19:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/05/2022 09:56:02	METER 1 - M: 33609 METER 2 - H: 5823
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/05/2022 12:52:26	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.51	\$60.25	\$54.03	\$0.00	\$114.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.51** **60.25** **54.03** **2.00** **116.28**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/04/2022 10:15:24	05/04/2022 10:46:02	0.51	\$60.25
					LABOR	60.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.63	6	\$33.75
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.57	1	\$9.57
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
					PARTS	54.03

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43130

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/JAW
MILEAGE-33609
IDLE HRS-5823
ENG HRS-7706

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43497

USING DEPT NO: 507121	OPENED DATE: 06/02/2022 15:23:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/03/2022 09:58:09	METER 1 - M: 34621 METER 2 - H: 6072
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/06/2022 10:41:03	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-010	REPLACE NEW TAG LIGHT	DON	O	N	GARAGE	0.04	\$4.46	\$0.38	\$0.00	\$4.84
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$72.90	\$55.70	\$0.00	\$128.60
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.11	\$12.82	\$18.83	\$0.00	\$31.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.76** **90.18** **74.91** **2.00** **167.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/03/2022 08:30:55	06/03/2022 09:07:59	0.62	\$72.90
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	06/03/2022 09:08:29	06/03/2022 09:15:00	0.11	\$12.82
03-34-010	REPLACE NEW TAG LIGHT	11901357	06/03/2022 09:46:17	06/03/2022 09:48:33	0.04	\$4.46
					LABOR 90.18	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.64	6	\$33.84
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.15	1	\$11.15
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	18.83	1	\$18.83
03-34-010	REPLACE NEW TAG LIGHT	194	BULB-TAG/MARKER	0.38	1	\$0.38
					PARTS 74.91	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43497

Work Order Notes

(LISAPATE) PM

Job Notes

03-34-010 - REPLACE NEW TAG LIGHT

(AGUERRA) Replaced right tag light. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 34621 hours: 8008 idle hours: 6072 Completed PM topside, Scott was bottomsides. Completed checklist. AMG/SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43512

USING DEPT NO: 507121	OPENED DATE: 06/03/2022 09:58:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/27/2022 10:52:05	METER 1 - M: 34634 METER 2 - H: 6072
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/28/2022 07:40:04	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	1.62	\$191.68	\$424.69	\$0.00	\$616.37
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.57	\$67.42	\$0.00	\$0.00	\$67.42
35-31	DIAGNOSE CHARGING SYSTEM	DON	O	N	GARAGE	0.48	\$56.48	\$0.00	\$0.00	\$56.48
66-13-130	PERFORM Burnish Brakes	DON	O	N	GARAGE	0.60	\$71.32	\$0.00	\$0.00	\$71.32
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.52	\$61.43	\$0.00	\$0.00	\$61.43
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.23	\$145.34	\$775.95	\$0.00	\$921.29
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 8	WORK ORDER TOTAL:	5.18	611.37	1,200.64	2.00	1,814.01
---------------------	--------------------------	-------------	---------------	-----------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11310047	06/27/2022 07:00:00	06/27/2022 07:09:00	0.15	\$17.70
35-31	DIAGNOSE CHARGING SYSTEM	11310047	06/23/2022 09:31:40	06/23/2022 10:00:23	0.48	\$56.48
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	06/15/2022 11:31:04	06/15/2022 11:57:00	0.43	\$51.00
06-15	INSPECT STEERING	11901357	06/03/2022 10:04:04	06/03/2022 10:38:21	0.57	\$67.42
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	06/15/2022 07:56:28	06/15/2022 09:10:22	1.23	\$145.34
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	06/15/2022 13:00:39	06/15/2022 14:12:11	1.19	\$140.68
66-13-130	PERFORM Burnish Brakes	11310047	06/15/2022 14:13:17	06/15/2022 14:15:00	0.03	\$3.38
66-17-013	PERFORM ALIGNMENT	11310047	06/16/2022 09:38:29	06/16/2022 10:09:43	0.52	\$61.43
66-13-130	PERFORM Burnish Brakes	11310047	06/16/2022 10:09:43	06/16/2022 10:44:16	0.58	\$67.95
LABOR					611.38	

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	1	\$5.93
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	GG1Z1125A	FRONT ROTORS	158.90	2	\$317.79
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABSP1611APPH	BRAKE PAD SET	100.97	1	\$100.97
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.61	4	\$10.44
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.44	2	\$0.87
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	4	\$2.28
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	2	\$1.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000702	TIRE 245/55R18 FSTONE PURSUIT	190.28	4	\$761.10
PARTS						1200.64

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43512

Work Order Notes

(EKIMBREL) needs 4 tires and an alignment

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(EHOWELL) Replaced front brake pads and rotors. EH

06-15 - INSPECT STEERING

(AGUERRA) Checked steering and front end, no issues with steering. Found vehicle needs front brake pads and rotors. AMG SH

35-31 - DIAGNOSE CHARGING SYSTEM

(EHOWELL) The customer had to jump the vehicle off at some point before the vehicle was brought to our shop. The vehicle would not start while the vehicle was in our shop due to a discharged battery. Installed a new battery and reset the battery monitoring system. The alternator charged at 15 volts with the new battery and with the old battery. Charged old battery and it tested good. Installed old battery back into the vehicle. Observed the alternator desired voltage with the scan tool and compared it to the battery voltage. It was within spec. Also, checked DTCs.

Performed a parasitic draw test on the vehicle's electrical system over night. The average draw was 207 mA with the radio in maintenance mode. Observed the live reading on the meter and turned the radio off. The draw went away almost completely. The radio needs to be turned off if the vehicle isn't running. EH 1.0 HR

66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made hard stops after brake job was performed. EH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) Mounted and balanced 4 tires. AMG SH

CH-32-002 - CHARGE BATTERY

(LISAPATE) The customer had to jump the vehicle off at some point before the vehicle was brought to our shop. The vehicle would not start while the vehicle was in our shop due to a discharged battery. Installed a new battery and reset the battery monitoring system. The alternator charged at 15 volts with the new battery and with the old battery. Charged old battery and it tested good. Installed old battery back into the vehicle. Observed the alternator desired voltage with the scan tool and compared it to the battery voltage. It was within spec. Also, checked DTCs.

Performed a parasitic draw test on the vehicle's electrical system over night. The average draw was 207 mA with the radio in maintenance mode. Observed the live reading on the meter and turned the radio off. The draw went away almost completely. The radio needs to be turned off if the vehicle isn't running. EH 1.0 HR

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44645

USING DEPT NO: 507121	OPENED DATE: 09/12/2022 06:59:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/14/2022 13:35:14	METER 1 - M: 34641 METER 2 - H: 6075
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/15/2022 09:38:42	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.33	\$38.55	\$113.55	\$0.00	\$152.10
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.24	\$28.09	\$0.00	\$0.00	\$28.09
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$72.24	\$0.00	\$0.00	\$72.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.18** **138.88** **113.55** **5.00** **257.43**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML
					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-32-002	INSPECT BATTERY	11901357	09/13/2022 14:13:53	09/13/2022 14:15:30	0.03	\$3.18
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/13/2022 14:53:18	09/13/2022 15:30:02	0.61	\$72.24
03-32-002	REPLACE NEW BATTERY	11901357	09/13/2022 14:15:46	09/13/2022 14:35:22	0.33	\$38.55
06-32-002	INSPECT BATTERY	11901357	09/13/2022 07:21:00	09/13/2022 07:33:40	0.21	\$24.91
					LABOR	138.88

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
					PARTS	113.55

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44645

Work Order Notes

(CWIGLEY) Per driver. The car has not been consistently driven and the battery will not stay charged. It has been jumped a couple times but needs to be jumped each time upon returning to shift.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(AGUERRA) Replaced battery and checked charging system, good at 14.5 volts. AMG

06-32-002 - INSPECT BATTERY

(AGUERRA) Removed battery and charged. Tested bad after charge, needs replacing. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 34641 hours: 8010 idle hours: 6075 Vehicle has been 20 miles and 3 idle hours. Oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 45552

USING DEPT NO: 507121	OPENED DATE: 12/13/2022 07:28:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/16/2022 07:23:42	METER 1 - M: 35283 METER 2 - H: 6305
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/16/2022 15:26:54	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	0.12	\$14.49	\$0.00	\$0.00	\$14.49
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.55	\$65.26	\$58.80	\$0.00	\$124.06
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.20	\$23.83	\$0.00	\$0.00	\$23.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.88	221.58	58.80	5.00	285.38
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/14/2022 13:29:08	12/14/2022 13:59:54	0.51	\$60.51
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/15/2022 07:29:15	12/15/2022 07:31:40	0.04	\$4.75
35-32	DIAGNOSE CRANKING SYSTEM	11901357	12/15/2022 07:32:35	12/15/2022 07:39:57	0.12	\$14.49
CH-32-002	CHARGE BATTERY	11901357	12/15/2022 07:40:32	12/15/2022 07:52:39	0.20	\$23.83
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	12/16/2022 07:00:00	12/16/2022 08:00:00	1.00	\$118.00
					LABOR	221.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.25	1	\$8.25
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
					PARTS	58.80

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 45552

Work Order Notes

(LISAPATE) PM due-Per driver unit keeps dying check the battery

Job Notes

35-32 - DIAGNOSE CRANKING SYSTEM

(AGUERRA) Charging system good, battery needs charging from vehicle not being driven. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 35283 Completed PM topside, Scott was bottomside. AMG/SH

CH-32-002 - CHARGE BATTERY

(AGUERRA) Removed battery and charged overnight. Battery tested good, reinstalled battery. AMG

(IFALLS) Reset battery monitoring system with scan tool. EH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Reset battery monitoring system. EH

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46524

USING DEPT NO: 507121	OPENED DATE: 03/24/2023 09:42:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/24/2023 15:08:56	METER 1 - M: 36240 METER 2 - H: 6604
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/03/2023 13:54:47	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$23.26	\$0.00	\$35.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$14.26	\$56.40	\$0.00	\$70.66
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.22	26.06	79.66	5.00	110.72
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2023 13:56:17	03/24/2023 14:03:32	0.12	\$14.26
03-51-038	REPLACE NEW WIPER BLADES	12201267	03/24/2023 15:08:18	03/24/2023 15:14:18	0.10	\$11.80
LABOR					26.06	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.47	1	\$10.47
PARTS					79.66	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46524

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) GC changed wipers

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47244

USING DEPT NO: 507121	OPENED DATE: 06/02/2023 07:15:56	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/02/2023 15:33:37	METER 1 - M: 37262 METER 2 - H: 6848
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/05/2023 10:47:41	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.18	\$34.15	\$0.00	\$39.33
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$61.91	\$0.00	\$100.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.37** **44.12** **96.06** **5.00** **145.18**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12201267	06/02/2023 13:00:54	06/02/2023 13:03:32	0.04	\$5.18
66-PM-PMA	PERFORM OIL CHANGE	12201267	06/02/2023 12:49:09	06/02/2023 12:49:09	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	06/02/2023 12:49:09	06/02/2023 12:49:09	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	06/02/2023 12:49:09	06/02/2023 13:08:57	0.33	\$38.94
LABOR					44.12	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
PARTS					96.06	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47244

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-CW

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

Miles, 37,262

Idle Hours, 6,848

Total Hours, 8,946

(LISAPATE) .5 skid plate removal

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47766

USING DEPT NO: 507121	OPENED DATE: 07/28/2023 07:13:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/01/2023 08:32:54	METER 1 - M: 38301 METER 2 - H: 7104
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/01/2023 11:14:30	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.90	\$24.08	\$0.00	\$29.98
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.42	\$49.46	\$0.00	\$0.00	\$49.46
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$31.07	\$64.20	\$0.00	\$95.27
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.73** **86.43** **88.28** **5.00** **179.71**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	07/28/2023 08:19:36	07/28/2023 08:44:45	0.42	\$49.46
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/28/2023 08:03:29	07/28/2023 08:06:29	0.05	\$5.90
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/28/2023 07:47:41	07/28/2023 08:03:29	0.26	\$31.07
					LABOR 86.43	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.38	1	\$13.38
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS 88.28	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47766

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Rotated the tires relearned the tire positions and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48311

USING DEPT NO: 507121	OPENED DATE: 09/25/2023 07:18:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/28/2023 15:58:53	METER 1 - M: 39601 METER 2 - H: 7104
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/28/2023 16:06:08	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	N	N	GARAGE	0.67	\$78.70	\$349.37	\$0.00	\$428.07
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.03	\$3.18	\$0.00	\$0.00	\$3.18
06-52-024	INSPECT BACK UP CAMERA	DON	O	N	GARAGE	2.41	\$284.05	\$0.00	\$0.00	\$284.05
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.43	\$50.48	\$0.00	\$0.00	\$50.48
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$64.34	\$0.00	\$103.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6 **WORK ORDER TOTAL:** **3.86** **455.35** **413.71** **5.00** **874.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	12052187	09/25/2023 14:32:31	09/25/2023 15:12:32	0.67	\$78.70
66-13-130	PERFORM Burnish Brakes	12052187	09/25/2023 15:12:32	09/25/2023 15:36:10	0.39	\$46.48
06-52-024	INSPECT BACK UP CAMERA	11310047	09/26/2023 09:29:42	09/26/2023 11:54:08	2.41	\$284.05
06-13	INSPECT BRAKES	12052187	09/28/2023 13:49:49	09/28/2023 13:51:26	0.03	\$3.18
66-13-130	PERFORM Burnish Brakes	12052187	09/28/2023 13:51:26	09/28/2023 13:53:28	0.03	\$4.00
66-PM-PMA	PERFORM OIL CHANGE	12395904	09/28/2023 07:00:00	09/28/2023 07:19:48	0.33	\$38.94
					LABOR 455.35	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWRZ371377	BRAKE PADS-POLICE	78.44	1	\$78.44
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RAB680983P	REAR ROTORS	135.47	2	\$270.93

Work Order Charge Detail

PARTS

413.71

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48311

Work Order Notes

(EHANNAH) PM- WASH- CHECK BRAKES- BACKUP CAMERA NOT WORKING

(EHOWELL) The battery is going dead approximately over night. Charged the battery two different times. Spoke with Kevin Battle and he informed me that this vehicle does not have "Charge Guard" on it. Charge guard has a relay that times out and prevents the Motorola device from draining the battery. The device never cuts off and draws 750 milliamps. This is a take home vehicle that does not get driven every day, so Kevin knows that it needs charge guard installed. EH

Job Notes

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(GARAGE) Replaced rear pads and rotors. Torqued bracket bolts to spec with loc-tite. Greased slide pins. JAW

06-13 - INSPECT BRAKES

(GARAGE) inspected brakes needs rear pads and rotors. JAW

06-52-024 - INSPECT BACK UP CAMERA

(EHOWELL) Found DTCS related to the camera. Performed multiple steps of the pinpoint test and the camera wiring proved good. Removed backup camera from another vehicle and installed it on this vehicle. The camera functioned. This vehicle will need a new backup camera installed. EH 1.0 HR

(LISAPATE) Closed for fiscal year end will replace camera next week Oct 1

66-13-130 - PERFORM Burnish Brakes

(GARAGE) Burnished brakes found no issues. JAW

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC

CH-SP - CHARGE Shop Supplies

CU-13-002 - CUT REAR BRAKES & DRUMS/ROTORS

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48409

USING DEPT NO: 507121	OPENED DATE: 10/04/2023 14:30:04	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/06/2023 07:20:47	METER 1 - M: 39601 METER 2 - H: 7104
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/06/2023 08:42:24	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-52-024	REPLACE NEW BACK UP CAMERA	DON	N	N	GARAGE	0.20	\$23.44	\$433.02	\$0.00	\$456.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.20** **23.44** **433.02** **5.00** **461.46**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-52-024	REPLACE NEW BACK UP CAMERA	12052187	10/05/2023 08:58:02	10/05/2023 09:00:09	0.04	\$4.16
03-52-024	REPLACE NEW BACK UP CAMERA	12052187	10/04/2023 14:32:36	10/04/2023 14:42:24	0.16	\$19.27
LABOR					23.43	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-52-024	REPLACE NEW BACK UP CAMERA	GB5Z19G490C	BACK UP CAMERA	433.02	1	\$433.02
PARTS					433.02	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48409

Work Order Notes

(IFALLS) back up camera inop

Job Notes

03-52-024 - REPLACE NEW BACK UP CAMERA

(JWRIGHT) Replaced reverse camera. Tested and found no other issues. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49288

USING DEPT NO: 507121	OPENED DATE: 12/18/2023 07:18:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/20/2023 15:41:26	METER 1 - M: 41423 METER 2 - H: 7104
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/21/2023 07:46:20	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.13	\$15.08	\$24.08	\$0.00	\$39.16
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$48.31	\$64.16	\$0.00	\$112.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.54** **63.39** **88.24** **5.00** **156.63**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12395904	12/18/2023 08:05:48	12/18/2023 08:13:28	0.13	\$15.08
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/18/2023 07:40:41	12/18/2023 08:05:15	0.41	\$48.31
LABOR					63.39	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
PARTS					88.24	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49288

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replace new wipers FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50096

USING DEPT NO: 507121	OPENED DATE: 03/07/2024 08:12:50	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/08/2024 08:22:32	METER 1 - M: 43407 METER 2 - H: 8201
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/08/2024 10:26:52	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.28	\$32.65	\$0.00	\$0.00	\$32.65
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.44	\$67.04	\$0.00	\$94.48
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$35.40	\$32.21	\$0.00	\$67.61
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.81** **95.49** **99.25** **5.00** **199.74**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11074414	03/07/2024 10:18:06	03/07/2024 10:34:42	0.28	\$32.65
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/07/2024 10:04:09	03/07/2024 10:18:06	0.23	\$27.44
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	03/08/2024 07:00:00	03/08/2024 07:18:00	0.30	\$35.40
					LABOR 95.49	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP68	CABIN FILTER	32.21	1	\$32.21
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	19.59	1	\$19.59
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
					PARTS 99.25	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50096

Work Order Notes

(EHANNAH) pm- install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240162. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) SH replaced cabin filter

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51462

USING DEPT NO: 507121	OPENED DATE: 07/12/2024 09:06:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/16/2024 08:59:32	METER 1 - M: 46775 METER 2 - H: 8201
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/17/2024 09:29:07	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.74	\$68.66	\$0.00	\$70.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.01** **1.74** **68.66** **5.00** **75.40**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/12/2024 10:27:52	07/12/2024 10:28:45	0.01	\$1.74
LABOR					1.74	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
PARTS					68.66	

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51462

Work Order Notes

(EHANNAH) Pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 52353

USING DEPT NO: 507121	OPENED DATE: 10/02/2024 14:45:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/28/2024 11:52:39	METER 1 - M: 46775 METER 2 - H: 8201
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 10/28/2024 13:50:04	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR6JGC29279	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-33-006	TRANSPORT IGNITION LOCK CYLINDEI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-33-006	REMOVE IGNITION LOCK CYLINDER	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
RY-33-006	REKEY IGNITION LOCK CYLINDER	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$119.03	\$119.03

JOB COUNT: 6 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **124.03** **124.03**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>				
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2315197		\$119.03				
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2315197		\$115.00				
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2315197		(\$115.00)				
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00				
COMML									124.03

Work Order Charge Detail

UNIT NO: 242798 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 52353

Work Order Notes

(EHOWELL) Prep for Sale. Remove lock cylinders and send to A1 locksmith to be rekeyed. Haynes Emergency Lighting needs to remove the radio, etc.

Job Notes

16-33-006 - TRANSPORT IGNITION LOCK CYLINDER

(GARAGE) took locks to a1 RC

25-33-006 - REMOVE IGNITION LOCK CYLINDER

(EHOWELL) CM removed/installed 4 lock cylinders.

25-52-003 - REMOVE RADIO

25-52-021 - REMOVE GPS SYSTEM

(EHOWELL) GPS# 87U030240162 was removed.

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) remove university wordmarks and tag RC

RY-33-006 - REKEY IGNITION LOCK CYLINDER

(GARAGE) a1 rekeyed

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Dec 03 2024 09:22:38 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242798') //Q=