

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 34530

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 10/21/2019 10:24:54 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 10/25/2019 20:00:00 | METER 1 - M: 17 METER 2 - H: 0 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 10/25/2019 20:00:00 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|-----------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 16-02 | TRANSPORT CAB & SHEET METAL | DON | O | N | GARAGE | 2.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 17-02-028 | RECALL SEAT ADJUSTER | DON | R | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 17-13-033 | RECALL ABS MODULATOR | DON | R | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|-------------|-------------|-------------|-------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 2.00 | 0.00 | 0.00 | 0.00 | 0.00 |
|---------------------|--------------------------|-------------|-------------|-------------|-------------|-------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| 17-02-028 | RECALL SEAT ADJUSTER | 4910000 | 588173 | | \$0.00 |
| | | | | COMML | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|-----------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 16-02 | TRANSPORT CAB & SHEET METAL | 11074414 | 10/23/2019 06:00:00 | 10/23/2019 08:00:00 | 2.00 | \$0.00 |
| | | | | | LABOR | 0.00 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 34530

Work Order Notes

(LISAPATE) Take to Town and Country Ford for recalls- Anti lock brake module software update- mechanical seat recliner

Job Notes

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Town and Country by SH

17-02-028 - RECALL SEAT ADJUSTER

(LISAPATE) Town and Country Tech stated Performed Recall 19C07. Vehicle is up fitted for police and has a divider between front and rear seats, removed divider to access front 2 seats. Using force meter inspected both front seats in all positions. both front seats pass inspection

17-13-033 - RECALL ABS MODULATOR

(LISAPATE) Town and Country Tech performed recall 19B12 Reprogrammed ABS module to latest calibration to complete recall

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 35143

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 12/11/2019 10:30:22 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 12/17/2019 11:47:37 | METER 1 - M: 1848 METER 2 - H: 0 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 12/17/2019 11:47:40 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALV | DON | P | N | GARAGE | 0.64 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.31 | \$0.00 | \$22.31 | \$0.00 | \$22.31 |

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.95** **0.00** **22.31** **0.00** **22.31**

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 12/13/2019 06:00:00 | 12/13/2019 06:18:36 | 0.31 | \$0.00 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 11074414 | 12/12/2019 07:33:17 | 12/12/2019 07:52:20 | 0.32 | \$0.00 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 12052187 | 12/12/2019 07:32:44 | 12/12/2019 07:51:57 | 0.32 | \$0.00 |
| | | | | | LABOR | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.88 | 6 | \$17.28 |
| | | | | | PARTS | 22.31 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 35143

Work Order Notes

(LISAPATE) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW,EK/SH

Coolat -35'

Syn 6.0

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 35520

| | | |
|--|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 01/29/2020 07:03:26 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 02/05/2020 11:28:05 | METER 1 - M: 2925 METER 2 - H: 440 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 02/05/2020 11:28:07 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 03-32-002 | REPLACE NEW BATTERY | DON | O | N | GARAGE | 0.50 | \$0.00 | \$98.65 | \$0.00 | \$98.65 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALV | DON | P | N | GARAGE | 0.40 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.42 | \$0.00 | \$22.73 | \$0.00 | \$22.73 |

| | | | | | | |
|---------------------|--------------------------|-------------|-------------|---------------|-------------|---------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 1.32 | 0.00 | 121.38 | 0.00 | 121.38 |
|---------------------|--------------------------|-------------|-------------|---------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 03-32-002 | REPLACE NEW BATTERY | 11074414 | 01/30/2020 06:00:00 | 01/30/2020 06:30:00 | 0.50 | \$0.00 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 11074414 | 01/29/2020 10:54:34 | 01/29/2020 11:18:43 | 0.40 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 01/29/2020 10:29:38 | 01/29/2020 10:54:34 | 0.42 | \$0.00 |
| | | | | | LABOR | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 03-32-002 | REPLACE NEW BATTERY | 740245 | BATTERY TERM PROTECTOR WASHER | 0.42 | 2 | \$0.84 |
| 03-32-002 | REPLACE NEW BATTERY | 652 | BATTERY BCI 65 850 CCA | 97.81 | 1 | \$97.81 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.95 | 6 | \$17.70 |
| | | | | | PARTS | 121.38 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 35520

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Battery failed, charged, still failed. installed a new battery rechecked charging at 14.5 volts

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH

Coolant -35'

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 36082

| | | |
|--|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 04/01/2020 09:18:58 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 04/02/2020 10:09:51 | METER 1 - M: 2925 METER 2 - H: 440 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 04/02/2020 14:12:09 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALV | DON | P | N | GARAGE | 0.50 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 1.09 | \$0.00 | \$22.73 | \$0.00 | \$22.73 |

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.59** **0.00** **22.73** **0.00** **22.73**

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 11901357 | 04/01/2020 10:46:53 | 04/01/2020 11:01:46 | 0.25 | \$0.00 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 11074414 | 04/01/2020 10:46:34 | 04/01/2020 11:01:27 | 0.25 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 04/01/2020 10:14:19 | 04/01/2020 10:46:53 | 0.54 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 04/01/2020 10:13:29 | 04/01/2020 10:46:34 | 0.55 | \$0.00 |
| | | | | | LABOR | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.95 | 6 | \$17.70 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| | | | | | PARTS | 22.73 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 36082

Work Order Notes

(IFALLS) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(IFALLS) SH/AG rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH/AG performed pm

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 36134

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 04/13/2020 07:14:36 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 04/15/2020 09:57:15 | METER 1 - M: 2925 METER 2 - H: 440 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 04/15/2020 15:16:53 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-17-030 | PERFORM TIRE PATCH | DON | O | N | GARAGE | 1.39 | \$0.00 | \$5.43 | \$0.00 | \$5.43 |
| 66-79-002 | PERFORM SERVICE CALL | DON | P | N | GARAGE | 1.09 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

JOB COUNT: 2 **WORK ORDER TOTAL: 2.48 0.00 5.43 0.00 5.43**

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-17-030 | PERFORM TIRE PATCH | 11074414 | 04/13/2020 08:50:01 | 04/13/2020 10:13:30 | 1.39 | \$0.00 |
| 66-79-002 | PERFORM SERVICE CALL | 11074414 | 04/13/2020 07:44:40 | 04/13/2020 08:50:01 | 1.09 | \$0.00 |
| | | | | | LABOR | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------------|-------------------|-----------------|-------------------|
| 66-17-030 | PERFORM TIRE PATCH | 14041 | PATCH 1/4 PILOT WIRE | 2.33 | 1 | \$2.33 |
| 66-17-030 | PERFORM TIRE PATCH | 23131 | TPMS SNAP IN VALVE 21060 | 2.56 | 1 | \$2.56 |
| 66-17-030 | PERFORM TIRE PATCH | WHEEL WEIGHT | WHEEL WEIGHT KNOCK ON | 0.27 | 2 | \$0.54 |
| | | | | | PARTS | 5.43 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 36134

Work Order Notes

(IFALLS) Service call requested for flat tire inside Capstone parking deck left front

Job Notes

66-17-030 - PERFORM TIRE PATCH

(IFALLS) SH patched left front tire

66-79-002 - PERFORM SERVICE CALL

(IFALLS) SH performed service call aired tire up

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 36362

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 05/08/2020 13:04:02 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 05/27/2020 14:11:56 | METER 1 - M: 5476 METER 2 - H: 806 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 05/27/2020 14:12:01 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|----------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 14-02-028 | INSTALL SEAT ADJUSTER | DON | W | J | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 16-00 | TRANSPORT COMPLETE VEHICLE | DON | O | N | GARAGE | 1.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-17-015 | PERFORM TIRE ROTATION | DON | P | N | GARAGE | 0.56 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 1.49 | \$0.00 | \$22.73 | \$0.00 | \$22.73 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | DON | O | N | GARAGE | 0.16 | \$0.00 | \$3.55 | \$0.00 | \$3.55 |
| CH-32-002 | CHARGE BATTERY | DON | O | N | GARAGE | 0.23 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|-------------|--------------|-------------|--------------|
| JOB COUNT: 6 | WORK ORDER TOTAL: | 3.43 | 0.00 | 26.28 | 0.00 | 26.28 |
|---------------------|--------------------------|-------------|-------------|--------------|-------------|--------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| 14-02-028 | INSTALL SEAT ADJUSTER | 4910000 | 598163 | | \$0.00 |
| COMML | | | | | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|----------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 16-00 | TRANSPORT COMPLETE VEHICLE | 11915538 | 05/22/2020 07:00:00 | 05/22/2020 08:00:00 | 1.00 | \$0.00 |
| 66-17-015 | PERFORM TIRE ROTATION | 11901357 | 05/13/2020 07:33:43 | 05/13/2020 08:01:54 | 0.47 | \$0.00 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 11901357 | 05/13/2020 07:24:01 | 05/13/2020 07:33:43 | 0.16 | \$0.00 |
| CH-32-002 | CHARGE BATTERY | 11901357 | 05/13/2020 07:10:26 | 05/13/2020 07:24:01 | 0.23 | \$0.00 |
| 66-17-015 | PERFORM TIRE ROTATION | 11901357 | 05/12/2020 08:51:20 | 05/12/2020 08:56:45 | 0.09 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 05/12/2020 07:15:55 | 05/12/2020 08:45:06 | 1.49 | \$0.00 |
| LABOR | | | | | 0.00 | |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|----------------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 4068 | FILTER- CABIN AIR | 3.55 | 1 | \$3.55 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.95 | 6 | \$17.70 |
| PARTS | | | | | 26.28 | |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 36362

Work Order Notes

(EKIMBREL) Take vehicle to town & country to get drivers seat handle looked at(warranty)
(GARAGE) pm; CHARGE BATTERY

Job Notes

14-02-028 - INSTALL SEAT ADJUSTER

(EKIMBREL) Town & Country Ford performed warranty on seat back adjuster handle. Part# DB5Z*7861199 and *W790163*S900 Clip

16-00 - TRANSPORT COMPLETE VEHICLE

(EKIMBREL) RC transported vehicle to Town & Country

66-17-015 - PERFORM TIRE ROTATION

(EKIMBREL) AG performed tire rotation. Relearned tire positions.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/AG performed pm. Coolant -35

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) AG replaced cabin filter.

CH-32-002 - CHARGE BATTERY

(EKIMBREL) AG charged battery overnight, rechecked good.

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 36817

| | | |
|--|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 06/15/2020 11:03:12 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 06/16/2020 08:49:39 | METER 1 - M: 6046 METER 2 - H: 913 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 06/16/2020 09:16:41 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|-------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| PR-01-002 | PROGRAM HEATING & VENTILATING | DON | O | N | GARAGE | 1.37 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

JOB COUNT: 1 **WORK ORDER TOTAL: 1.37 0.00 0.00 0.00 0.00**

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|-------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| PR-01-002 | PROGRAM HEATING & VENTILATING | 11170580 | 06/15/2020 14:27:06 | 06/15/2020 14:27:06 | 0.00 | \$0.00 |
| PR-01-002 | PROGRAM HEATING & VENTILATING | 11170580 | 06/15/2020 14:27:06 | 06/15/2020 14:27:06 | 0.00 | \$0.00 |
| PR-01-002 | PROGRAM HEATING & VENTILATING | 11170580 | 06/15/2020 14:30:00 | 06/15/2020 14:52:29 | 0.37 | \$0.00 |
| PR-01-002 | PROGRAM HEATING & VENTILATING | 11170580 | 06/15/2020 14:27:06 | 06/15/2020 15:27:06 | 1.00 | \$0.00 |
| | | | | | LABOR | 0.00 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 36817

Work Order Notes

(LISAPATE) Program unit for Covid 19 update

Job Notes

PR-01-002 - PROGRAM HEATING & VENTILATING

(ABLACK) AB re programmed PCM, BCM, and HVAC modules in order to activate coronavirus disinfectant mode.

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 37017

| | | |
|-------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 07/06/2020 07:34:16 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 07/07/2020 13:59:07 | METER 1 - M: 6395 METER 2 - H: 1002 |
| WO VISIT REASON: UNSCHEDULED | CLOSED DATE: 07/08/2020 07:54:29 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-79-002 | PERFORM SERVICE CALL | DON | B | N | GARAGE | 1.91 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.61 | \$0.00 | \$22.73 | \$0.00 | \$22.73 |
| CH-32-002 | CHARGE BATTERY | DON | O | N | GARAGE | 0.50 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|-------------|--------------|-------------|--------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 3.02 | 0.00 | 22.73 | 0.00 | 22.73 |
|---------------------|--------------------------|-------------|-------------|--------------|-------------|--------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| CH-32-002 | CHARGE BATTERY | 11074414 | 07/07/2020 06:00:00 | 07/07/2020 06:30:00 | 0.50 | \$0.00 |
| 66-79-002 | PERFORM SERVICE CALL | 10208562 | 07/06/2020 08:22:04 | 07/06/2020 10:16:34 | 1.91 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 07/06/2020 08:48:02 | 07/06/2020 09:14:10 | 0.44 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 07/06/2020 08:50:53 | 07/06/2020 09:01:13 | 0.17 | \$0.00 |
| | | | | | LABOR | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-79-002 | PERFORM SERVICE CALL | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| 66-79-002 | PERFORM SERVICE CALL | FL500S | FILTER-OIL FORD | 5.03 | (1) | (\$5.03) |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.95 | 6 | \$17.70 |
| | | | | | PARTS | 22.73 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 37017

Work Order Notes

(LISAPATE) UAPD requested a service call for a dead battery
(IFALLS) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed jumped off and drove to the shop

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/SH
(IFALLS) Tires didn't need rotated at this time

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery, rechecked good

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 37139

| | | |
|--|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 07/20/2020 07:10:04 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 07/21/2020 11:04:58 | METER 1 - M: 6543 METER 2 - H: 1019 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 07/21/2020 13:23:41 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|--------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-79-002 | PERFORM SERVICE CALL | DON | B | N | GARAGE | 2.02 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| CH-32-002 | CHARGE BATTERY | DON | O | N | GARAGE | 0.50 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC | DON | O | N | GARAGE | 2.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|-------------|-------------|-------------|-------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 4.52 | 0.00 | 0.00 | 0.00 | 0.00 |
|---------------------|--------------------------|-------------|-------------|-------------|-------------|-------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|---------------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC SYSTEM | 11213180 | 07/21/2020 07:00:00 | 07/21/2020 09:00:00 | 2.00 | \$0.00 |
| CH-32-002 | CHARGE BATTERY | 11213180 | 07/21/2020 07:00:00 | 07/21/2020 07:30:00 | 0.50 | \$0.00 |
| 66-79-002 | PERFORM SERVICE CALL | 11213180 | 07/20/2020 07:16:34 | 07/20/2020 08:21:45 | 1.09 | \$0.00 |
| 66-79-002 | PERFORM SERVICE CALL | 11074414 | 07/20/2020 07:18:10 | 07/20/2020 08:14:20 | 0.94 | \$0.00 |
| | | | | | LABOR | 0.00 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 37139

Work Order Notes

(LISAPATE) Rachel reported unit has a dead battery at UAPD lot

Job Notes

66-79-002 - PERFORM SERVICE CALL

(MSIDES) Jumped vehicle off and drove back to shop. MS

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery rechecked ok

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Used scan tool to rest battery monitoring system. Rechecked ok

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 37228

| | | |
|-------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 08/03/2020 07:07:40 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 08/04/2020 11:01:00 | METER 1 - M: 6587 METER 2 - H: 1026 |
| WO VISIT REASON: UNSCHEDULED | CLOSED DATE: 08/06/2020 07:28:28 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-79-002 | PERFORM SERVICE CALL | DON | B | N | GARAGE | 0.17 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| CH-32-002 | CHARGE BATTERY | DON | O | N | GARAGE | 0.50 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.67** **0.00** **0.00** **0.00** **0.00**

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| CH-32-002 | CHARGE BATTERY | 11915538 | 08/04/2020 07:00:00 | 08/04/2020 07:30:00 | 0.50 | \$0.00 |
| 66-79-002 | PERFORM SERVICE CALL | 10208562 | 08/03/2020 08:56:08 | 08/03/2020 09:06:04 | 0.17 | \$0.00 |
| LABOR | | | | | | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|-------------------------------|-------------------|-----------------|-------------------|
| 66-79-002 | PERFORM SERVICE CALL | 740245 | BATTERY TERM PROTECTOR WASHER | 0.42 | 2 | \$0.84 |
| 66-79-002 | PERFORM SERVICE CALL | 652 | BATTERY BCI 65 850 CCA | 97.81 | 1 | \$97.81 |
| 66-79-002 | PERFORM SERVICE CALL | 740245 | BATTERY TERM PROTECTOR WASHER | 0.42 | (2) | (\$0.84) |
| 66-79-002 | PERFORM SERVICE CALL | 652 | BATTERY BCI 65 850 CCA | 97.81 | (1) | (\$97.81) |
| PARTS | | | | | | 0.00 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 37228

Work Order Notes

(LISAPATE) UAPD requested a service call for a dead battery

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed jumped off and drove to the shop.

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery and rechecked good charging at 14 volts

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 37716

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 09/24/2020 07:24:09 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 09/24/2020 15:22:09 | METER 1 - M: 6764 METER 2 - H: 1073 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 09/25/2020 08:54:17 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.36 | \$0.00 | \$23.26 | \$0.00 | \$23.26 |
| CH-32-002 | CHARGE BATTERY | DON | O | N | GARAGE | 0.01 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.38** **0.00** **23.26** **0.00** **23.26**

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| CH-32-002 | CHARGE BATTERY | 12052187 | 09/24/2020 14:56:45 | 09/24/2020 14:57:37 | 0.01 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 09/24/2020 08:06:14 | 09/24/2020 08:28:03 | 0.36 | \$0.00 |
| | | | | | LABOR | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.50 | 1 | \$5.50 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.96 | 6 | \$17.76 |
| | | | | | PARTS | 23.26 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 37716

Work Order Notes

(LISAPATE) PM-Charge battery

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34° JAW

CH-32-002 - CHARGE BATTERY

(JWRIGHT) Charged battery

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 37795

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 09/28/2020 09:48:25 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 09/29/2020 16:31:16 | METER 1 - M: 6785 METER 2 - H: 1073 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 09/29/2020 16:33:38 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 15-32-002 | WARRANTY BATTERY | DON | W | J | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 35-32-002 | DIAGNOSE BATTERY | DON | O | N | GARAGE | 2.32 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

JOB COUNT: 2 **WORK ORDER TOTAL:** **2.32** **0.00** **0.00** **0.00** **0.00**

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 35-32-002 | DIAGNOSE BATTERY | 11170580 | 09/28/2020 13:06:52 | 09/28/2020 15:26:06 | 2.32 | \$0.00 |
| | | | | | LABOR | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|------------------------|-------------------|-----------------|-------------------|
| 15-32-002 | WARRANTY BATTERY | 652 | BATTERY BCI 65 850 CCA | 97.81 | (1) | (\$97.81) |
| 15-32-002 | WARRANTY BATTERY | 652 | BATTERY BCI 65 850 CCA | 97.81 | 1 | \$97.81 |
| 35-32-002 | DIAGNOSE BATTERY | 652 | BATTERY BCI 65 850 CCA | 97.81 | (1) | (\$97.81) |
| 35-32-002 | DIAGNOSE BATTERY | 652 | BATTERY BCI 65 850 CCA | 97.81 | 1 | \$97.81 |
| | | | | | PARTS | 0.00 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 37795

Work Order Notes

(LISAPATE) Battery is dead again just charged a few days ago. Kevin Battles says it not from the radio.

Job Notes

15-32-002 - WARRANTY BATTERY

(RTUNAITI) Replaced battery under warranty

WO 35520, 1/29/2020

(LISAPATE) Visit Reason Changed On 9/29/2020 4:28 PM By LISAPATE

35-32-002 - DIAGNOSE BATTERY

(LISAPATE) AB found a massive draw on the Ford side of the truck. Was blowing a 10amp fuse. Unplugged alt, PSCM and a starter and still blowing fuse. Installed a new battery still blowing fuse. Unplugged BCM connectors and plugged back in. Draw went away. Draw is showing to be 0.15 amps well under Ford specs.

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 38390

| | | |
|--|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 11/16/2020 10:16:50 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 11/18/2020 09:25:52 | METER 1 - M: 6785 METER 2 - H: 1073 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 11/18/2020 10:34:12 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|---------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 06-33-006 | INSPECT IGNITION LOCK CYLINDER | DON | O | N | GARAGE | 0.15 | \$17.70 | \$0.00 | \$0.00 | \$17.70 |
| 15-33-006 | WARRANTY IGNITION LOCK CYLINDER | DON | W | J | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 16-33 | TRANSPORT IGNITION SYSTEM | DON | O | N | GARAGE | 2.00 | \$236.00 | \$0.00 | \$0.00 | \$236.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|---------------|-------------|-------------|---------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 2.15 | 253.70 | 0.00 | 0.00 | 253.70 |
|---------------------|--------------------------|-------------|---------------|-------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|---------------------------------|-------------------|--------------------|---------------------------|-------------------|
| 15-33-006 | WARRANTY IGNITION LOCK CYLINDER | 4910000 | 608763 | | \$0.00 |
| COMML | | | | | 0.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 06-33-006 | INSPECT IGNITION LOCK CYLINDER | 11268671 | 11/18/2020 07:00:00 | 11/18/2020 07:09:00 | 0.15 | \$17.70 |
| 16-33 | TRANSPORT IGNITION SYSTEM | 11915538 | 11/18/2020 07:00:00 | 11/18/2020 08:00:00 | 1.00 | \$118.00 |
| 16-33 | TRANSPORT IGNITION SYSTEM | 10208562 | 11/18/2020 07:00:00 | 11/18/2020 08:00:00 | 1.00 | \$118.00 |
| LABOR | | | | | 2.15 | 253.70 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 38390

Work Order Notes

(LISAPATE) Per driver when pulling the key out the whole ignition cylinder is coming out.

Job Notes

06-33-006 - INSPECT IGNITION LOCK CYLINDER

(EKIMBREL) IF/AB inspected lock cylinder and found it popped out of place. Sent vehicle to Town & Country Ford for warranty repair.

15-33-006 - WARRANTY IGNITION LOCK CYLINDER

(EKIMBREL) Town & Country inspected ignition lock cylinder housing and switch. Properly installed lock cylinder housing and lock cylinder bezel. tested for proper operation .

16-33 - TRANSPORT IGNITION SYSTEM

(EKIMBREL) EK/RC transported vehicle to and from Town & Country Ford

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 38443

| | | |
|--|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 11/20/2020 07:58:58 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 11/23/2020 09:58:07 | METER 1 - M: 7563 METER 2 - H: 1188 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 11/24/2020 07:52:20 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|--------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 35-31 | DIAGNOSE CHARGING SYSTEM | DON | O | N | GARAGE | 0.25 | \$29.70 | \$0.00 | \$0.00 | \$29.70 |

| | | | | | | |
|---------------------|--------------------------|-------------|--------------|-------------|-------------|--------------|
| JOB COUNT: 1 | WORK ORDER TOTAL: | 0.25 | 29.70 | 0.00 | 0.00 | 29.70 |
|---------------------|--------------------------|-------------|--------------|-------------|-------------|--------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 35-31 | DIAGNOSE CHARGING SYSTEM | 11170580 | 11/20/2020 14:59:12 | 11/20/2020 15:14:18 | 0.25 | \$29.70 |
| | | | | | LABOR | 29.70 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 38443

Work Order Notes

(LISAPATE) Unit has a dead battery again. Battery was just replaced on 9/28/20 under warranty. Battery has been charged many times on this unit. Check for a draw

Job Notes

35-31 - DIAGNOSE CHARGING SYSTEM

(IFALLS) AB / vehicle sat in our lot for one day and battery was dead. Charged battery back up since it was only a month old. Checked vehicle for a draw. Found it had a .8 amp draw. Pinpointed draw coming from the police radio. Spoke with Kevin Battles about this issue and we agreed that the radio needs to be on a separate timer. If a timer is not installed on all the police cars with this specific radio then they will be having to buy a \$100 battery every month or so.

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 38819

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Found no issues. JAW/AMG

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 39498

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 03/29/2021 07:10:25 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 03/29/2021 14:28:17 | METER 1 - M: 9937 METER 2 - H: 1630 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 03/29/2021 15:01:45 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|----------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.36 | \$42.48 | \$41.84 | \$0.00 | \$84.32 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | DON | P | N | GARAGE | 0.10 | \$11.80 | \$7.20 | \$0.00 | \$19.00 |

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.46** **54.28** **49.04** **0.00** **103.32**

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|----------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 12052187 | 03/29/2021 07:56:38 | 03/29/2021 08:02:38 | 0.10 | \$11.80 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 03/29/2021 08:46:52 | 03/29/2021 09:05:27 | 0.31 | \$36.55 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 03/29/2021 07:53:37 | 03/29/2021 07:56:38 | 0.05 | \$5.93 |
| | | | | | LABOR | 54.28 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|----------------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 4.58 | 1 | \$4.58 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.43 | 6 | \$26.55 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 800151C | CABIN AIR FILTER REPL 4068 | 7.20 | 1 | \$7.20 |
| | | | | | PARTS | 49.04 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 39498

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm. Coolant -35°. SH,AMG,AB/JAW
MILEAGE-9937
HRS-1630

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 39951

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 05/14/2021 08:36:00 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 05/18/2021 13:12:02 | METER 1 - M: 11546 METER 2 - H: 1931 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 05/20/2021 11:53:28 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|---------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE | DON | P | N | GARAGE | 0.34 | \$39.56 | \$0.00 | \$0.00 | \$39.56 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.75 | \$88.37 | \$41.84 | \$0.00 | \$130.21 |

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.08** **127.93** **41.84** **0.00** **169.77**

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE INSPECTION | 11901357 | 05/14/2021 10:33:35 | 05/14/2021 10:53:42 | 0.34 | \$39.56 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 05/14/2021 09:43:33 | 05/14/2021 10:28:29 | 0.75 | \$88.37 |
| | | | | | LABOR | 127.93 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.43 | 6 | \$26.55 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 4.58 | 1 | \$4.58 |
| | | | | | PARTS | 41.84 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 39951

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Miles: 11546 idle hours: 1931 Completed PM topside, Josh was bottomsides. Completed checklist. AMG/JW

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 40619

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 08/03/2021 10:27:25 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 08/05/2021 11:36:40 | METER 1 - M: 13275 METER 2 - H: 2243 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 08/09/2021 09:08:57 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|--------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.43 | \$50.64 | \$21.80 | \$0.00 | \$72.44 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.53 | \$63.10 | \$43.10 | \$0.00 | \$106.20 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|---------------|--------------|-------------|---------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.96 | 113.74 | 64.90 | 2.00 | 180.64 |
|---------------------|--------------------------|-------------|---------------|--------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| COMML | | | | | 2.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 11901357 | 08/03/2021 13:36:28 | 08/03/2021 14:02:13 | 0.43 | \$50.64 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 08/03/2021 13:19:28 | 08/03/2021 13:41:32 | 0.37 | \$43.40 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 08/03/2021 12:58:37 | 08/03/2021 13:08:38 | 0.17 | \$19.70 |
| LABOR | | | | | 113.74 | |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 5.84 | 1 | \$5.84 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.43 | 6 | \$26.55 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 18-1 | WIPER BLADE 18" | 7.34 | 2 | \$14.67 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 18-1 | WIPER BLADE 18" | 7.34 | (2) | (\$14.67) |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19260 | WIPER BLADE 26 IN OE BEAM | 11.97 | 1 | \$11.97 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 9.83 | 1 | \$9.83 |
| PARTS | | | | | 64.90 | |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 40619

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 13275 Engine hours 2925 Idle hours 2243. SH AMG/SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 41258

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 10/08/2021 07:08:25 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 10/12/2021 07:26:28 | METER 1 - M: 14907 METER 2 - H: 2563 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 10/13/2021 11:10:10 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|--------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.04 | \$5.28 | \$31.82 | \$0.00 | \$37.10 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.42 | \$48.97 | \$42.20 | \$0.00 | \$91.17 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|--------------|--------------|-------------|---------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.46 | 54.25 | 74.02 | 2.00 | 130.27 |
|---------------------|--------------------------|-------------|--------------|--------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| COMML | | | | | 2.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 11074414 | 10/08/2021 11:21:10 | 10/08/2021 11:23:51 | 0.04 | \$5.28 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 10/08/2021 10:56:06 | 10/08/2021 11:21:00 | 0.42 | \$48.97 |
| LABOR | | | | | 54.25 | |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 60-011-G | WIPER-REAR FORD EXPLORER | 9.20 | 1 | \$9.20 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 4.85 | 1 | \$4.85 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.44 | 6 | \$26.64 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 10.19 | 1 | \$10.19 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19260 | WIPER BLADE 26 IN OE BEAM | 12.43 | 1 | \$12.43 |
| PARTS | | | | | 74.02 | |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 41258

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 14907 Engine hours 3333 Idle hours 2563. SH performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 42242

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 02/01/2022 09:48:42 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 02/04/2022 15:46:18 | METER 1 - M: 16369 METER 2 - H: 2826 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 02/08/2022 10:24:57 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|--------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 03-32-002 | REPLACE NEW BATTERY | DON | O | N | GARAGE | 0.12 | \$14.19 | \$113.55 | \$0.00 | \$127.74 |
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.11 | \$13.44 | \$22.62 | \$0.00 | \$36.06 |
| 06-15 | INSPECT STEERING | DON | O | N | GARAGE | 0.15 | \$17.70 | \$0.00 | \$0.00 | \$17.70 |
| 09-15 | ALIGN STEERING | DON | O | N | GARAGE | 1.00 | \$118.00 | \$0.00 | \$0.00 | \$118.00 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRE | DON | O | N | GARAGE | 1.28 | \$150.68 | \$796.65 | \$0.00 | \$947.33 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.04 | \$4.69 | \$47.49 | \$0.00 | \$52.18 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

JOB COUNT: 7 **WORK ORDER TOTAL:** **2.70** **318.70** **980.31** **2.00** **1,301.01**

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| | | | | COMML | 2.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|---------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 09-15 | ALIGN STEERING | 11310047 | 02/03/2022 15:19:02 | 02/03/2022 16:19:02 | 1.00 | \$118.00 |
| 09-15 | ALIGN STEERING | 11310047 | 02/03/2022 15:19:02 | 02/04/2022 07:24:55 | (16.10) | (\$1,899.57) |
| 09-15 | ALIGN STEERING | 11310047 | 02/03/2022 15:19:02 | 02/04/2022 07:24:55 | 16.10 | \$1,899.57 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 12052187 | 02/03/2022 08:04:42 | 02/03/2022 09:21:19 | 1.28 | \$150.68 |
| 06-15 | INSPECT STEERING | 12052187 | 02/03/2022 08:04:17 | 02/03/2022 08:13:17 | 0.15 | \$17.70 |
| 06-15 | INSPECT STEERING | 12052187 | 02/03/2022 08:04:17 | 02/03/2022 08:04:30 | 0.00 | (\$0.43) |
| 06-15 | INSPECT STEERING | 12052187 | 02/03/2022 08:04:17 | 02/03/2022 08:04:30 | 0.00 | \$0.43 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 02/01/2022 13:13:08 | 02/01/2022 13:15:31 | 0.04 | \$4.69 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 12052187 | 02/01/2022 13:06:04 | 02/01/2022 13:12:54 | 0.11 | \$13.44 |
| 03-32-002 | REPLACE NEW BATTERY | 11310047 | 02/04/2022 12:30:09 | 02/04/2022 12:37:22 | 0.12 | \$14.19 |
| | | | | | LABOR | 318.70 |

Work Order Charge Detail

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|---------------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE 21060 | 3.84 | 4 | \$15.36 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 10.23 | 1 | \$10.23 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19200 | WIPER BLADE OE BEAM STYLE 20IN | 10.19 | 1 | \$10.19 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.43 | 6 | \$26.55 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19260 | WIPER BLADE 26 IN OE BEAM | 12.43 | 1 | \$12.43 |
| 03-32-002 | REPLACE NEW BATTERY | 650 | BATTERY BCI 65 650 CCA | 113.55 | 1 | \$113.55 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 1555395 | TIRE 245/55R18 GEN GMAXPURSUIT | 194.13 | 4 | \$776.52 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 1555395 | TIRE 245/55R18 GEN GMAXPURSUIT | 194.13 | 4 | \$776.52 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 1555395 | TIRE 245/55R18 GEN GMAXPURSUIT | 194.13 | (4) | (\$776.52) |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58100 | .25 OZ WHEEL WEIGHT | 0.18 | 1 | \$0.18 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58102 | .75 OZ WHEEL WEIGHT | 0.36 | 1 | \$0.36 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58103 | 1.00 OZ WHEEL WEIGHT | 0.57 | 4 | \$2.28 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58104 | 1.25 OZ WHEEL WEIGHT | 0.57 | 2 | \$1.14 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58105 | 1.50 OZ WHEEL WEIGHT | 0.81 | 1 | \$0.81 |
| | | | | | PARTS | 980.31 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 42242

Work Order Notes

(LISAPATE) PM-replace wipers-Needs 4 tires and align

Job Notes

03-32-002 - REPLACE NEW BATTERY

(EHOWELL) Replaced battery and reset Battery Monitoring System. Alternator is charging. EH

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

06-15 - INSPECT STEERING

(JWRIGHT) Front end good

09-15 - ALIGN STEERING

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced and balanced all 4 tires. Torqued lug nuts to spec. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH

MILEAGE-16369

ENG HRS-3665

IDLE HRS-2826

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 43104

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 05/02/2022 09:24:00 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 05/05/2022 08:10:18 | METER 1 - M: 18081 METER 2 - H: 3118 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 05/05/2022 09:37:19 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|----------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-17-030 | PERFORM TIRE PATCH | DON | O | N | GARAGE | 0.45 | \$53.26 | \$8.82 | \$0.00 | \$62.08 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.41 | \$47.92 | \$53.96 | \$0.00 | \$101.88 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | DON | P | N | GARAGE | 0.09 | \$10.33 | \$24.75 | \$0.00 | \$35.08 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|---------------|--------------|-------------|---------------|
| JOB COUNT: 4 | WORK ORDER TOTAL: | 0.95 | 111.51 | 87.53 | 2.00 | 201.04 |
|---------------------|--------------------------|-------------|---------------|--------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|--------------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| | | | | | COMML 2.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|----------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-17-030 | PERFORM TIRE PATCH | 11074414 | 05/02/2022 11:00:29 | 05/02/2022 11:27:34 | 0.45 | \$53.26 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 05/02/2022 10:47:33 | 05/02/2022 10:49:45 | 0.04 | \$4.33 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 11901357 | 05/02/2022 10:41:56 | 05/02/2022 10:47:11 | 0.09 | \$10.33 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 05/02/2022 10:16:32 | 05/02/2022 10:38:42 | 0.37 | \$43.59 |
| | | | | | LABOR | 111.51 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|----------------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-17-030 | PERFORM TIRE PATCH | 58103 | 1.00 OZ WHEEL WEIGHT | 0.57 | 2 | \$1.14 |
| 66-17-030 | PERFORM TIRE PATCH | 14041 | PATCH 1/4 PILOT WIRE | 3.86 | 1 | \$3.86 |
| 66-17-030 | PERFORM TIRE PATCH | 23131 | TPMS SNAP IN VALVE 21060 | 3.82 | 1 | \$3.82 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 800151C | CABIN AIR FILTER REPL 4068 | 24.75 | 1 | \$24.75 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 9.50 | 1 | \$9.50 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 5.63 | 6 | \$33.75 |
| | | | | | PARTS | 87.53 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 43104

Work Order Notes

(LISAPATE) PM-replace wipers-nail in LF tire

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-030 - PERFORM TIRE PATCH

(SHARBIN) Patched left front tire. SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 18081 hours: 4040 idle hours: 3118 Completed PM topside, Scott was bottomsides. Completed checklist. AMG/SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 44335

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 08/16/2022 11:55:20 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 08/18/2022 11:41:18 | METER 1 - M: 19882 METER 2 - H: 3312 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 08/18/2022 12:19:32 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|---------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE | DON | O | N | GARAGE | 0.16 | \$18.32 | \$0.00 | \$0.00 | \$18.32 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.23 | \$27.34 | \$73.83 | \$0.00 | \$101.17 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|--------------|--------------|-------------|---------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.39 | 45.66 | 73.83 | 2.00 | 121.49 |
|---------------------|--------------------------|-------------|--------------|--------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| COMML | | | | | 2.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE INSPECTION | 11074414 | 08/16/2022 14:30:00 | 08/16/2022 14:36:42 | 0.11 | \$13.18 |
| 66-17-033 | PERFORM TIRE ROTATION AND BRAKE INSPECTION | 11074414 | 08/16/2022 14:12:23 | 08/16/2022 14:15:00 | 0.04 | \$5.15 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 08/16/2022 13:52:48 | 08/16/2022 14:06:42 | 0.23 | \$27.34 |
| LABOR | | | | | 45.67 | |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 46935 | AIR FILTER-SECURITY INTERCEP. | 26.37 | 1 | \$26.37 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 10.92 | 1 | \$10.92 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.09 | 6 | \$36.54 |
| PARTS | | | | | 73.83 | |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 44335

Work Order Notes

(CHANNELL) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Rotated tires relearned tire positions and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 45550

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 12/13/2022 07:13:28 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 12/13/2022 11:18:22 | METER 1 - M: 21546 METER 2 - H: 3577 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 12/13/2022 12:37:40 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.18 | \$21.70 | \$45.69 | \$0.00 | \$67.39 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.18 21.70 45.69 5.00 72.39

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | | COMML 5.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 12/13/2022 07:28:06 | 12/13/2022 07:39:08 | 0.18 | \$21.70 |
| | | | | | LABOR | 21.70 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 8.25 | 1 | \$8.25 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.24 | 6 | \$37.44 |
| | | | | | PARTS | 45.69 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 45550

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH

MILEAGE-21546

IDLE-3577

HRS-4642

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 46259

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 02/23/2023 14:34:36 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 02/24/2023 15:38:59 | METER 1 - M: 21546 METER 2 - H: 4573 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 02/27/2023 07:17:04 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|--------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 06-15 | INSPECT STEERING | DON | O | N | GARAGE | 0.14 | \$16.13 | \$0.00 | \$0.00 | \$16.13 |
| 66-17-013 | PERFORM ALIGNMENT | DON | O | N | GARAGE | 0.48 | \$56.97 | \$0.00 | \$0.00 | \$56.97 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRE | DON | O | N | GARAGE | 1.13 | \$133.44 | \$849.95 | \$0.00 | \$983.39 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.21 | \$24.45 | \$56.31 | \$0.00 | \$80.76 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|---------------|---------------|-------------|-----------------|
| JOB COUNT: 5 | WORK ORDER TOTAL: | 1.96 | 230.99 | 906.26 | 5.00 | 1,142.25 |
|---------------------|--------------------------|-------------|---------------|---------------|-------------|-----------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> | |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|-------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 | |
| | | | | | COMML | 5.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|---------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-17-013 | PERFORM ALIGNMENT | 11310047 | 02/24/2023 12:48:46 | 02/24/2023 13:17:44 | 0.48 | \$56.97 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11074414 | 02/24/2023 09:30:00 | 02/24/2023 09:42:44 | 0.21 | \$25.04 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11074414 | 02/24/2023 08:19:53 | 02/24/2023 09:15:00 | 0.92 | \$108.40 |
| 06-15 | INSPECT STEERING | 11074414 | 02/24/2023 08:11:29 | 02/24/2023 08:19:41 | 0.14 | \$16.13 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 02/23/2023 15:08:12 | 02/23/2023 15:20:38 | 0.21 | \$24.45 |
| | | | | | LABOR | 230.99 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|---------------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.24 | 6 | \$37.44 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 5.76 | 1 | \$5.76 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE 21060 | 2.16 | 4 | \$8.64 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58102 | .75 OZ WHEEL WEIGHT | 0.45 | 2 | \$0.90 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58104 | 1.25 OZ WHEEL WEIGHT | 0.65 | 3 | \$1.94 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58106 | 1.75 OZ WHEEL WEIGHT | 0.81 | 1 | \$0.81 |

Work Order Charge Detail

The University of Alabama

Report Printed: 02/25/2025 09:37:56 By User: GLOBETTI

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|---------------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58103 | 1.00 OZ WHEEL WEIGHT | 0.57 | 2 | \$1.14 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 732026500 | GDY EAGLE RS-A POLIC 245/55R18 | 209.13 | 4 | \$836.52 |
| | | | | | PARTS | 906.26 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 46259

Work Order Notes

(EHANNAH) pm

Job Notes

06-15 - INSPECT STEERING

(SHARBIN) Inspected the steering found no issues at this time. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed a 4 wheel alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires and relearned tire positions. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM. Right front tire is at 2/32 tread depth. Suggest a whole set. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 47118

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 05/19/2023 08:25:33 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 05/23/2023 12:12:43 | METER 1 - M: 23408 METER 2 - H: 4573 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 05/24/2023 09:18:16 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|--------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.14 | \$17.04 | \$24.08 | \$0.00 | \$41.12 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.23 | \$27.34 | \$61.82 | \$0.00 | \$89.16 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|--------------|--------------|-------------|---------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.38 | 44.38 | 85.90 | 5.00 | 135.28 |
|---------------------|--------------------------|-------------|--------------|--------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 12201267 | 05/19/2023 13:43:43 | 05/19/2023 13:52:23 | 0.14 | \$17.04 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12201267 | 05/19/2023 13:29:35 | 05/19/2023 13:43:29 | 0.23 | \$27.34 |
| LABOR | | | | | 44.38 | |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|--------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 10.85 | 1 | \$10.85 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19260 | WIPER BLADE 26 IN OE BEAM | 13.23 | 1 | \$13.23 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 11.27 | 1 | \$11.27 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.24 | 6 | \$37.44 |
| PARTS | | | | | 85.90 | |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 47118

Work Order Notes

(EHANNAH) pm- replace wipers- do SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- CW,SH, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 23,408 Idle Hours, 4,054

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 47830

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 08/04/2023 10:08:23 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 08/18/2023 09:39:53 | METER 1 - M: 24540 METER 2 - H: 4573 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 08/24/2023 07:34:31 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|--------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-17-013 | PERFORM ALIGNMENT | DON | N | N | GARAGE | 0.70 | \$82.14 | \$0.00 | \$0.00 | \$82.14 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRE | DON | N | N | GARAGE | 1.63 | \$192.27 | \$820.91 | \$0.00 | \$1,013.18 |
| 66-79-003 | PERFORM SAFETY INSPECTION | DON | Y | N | GARAGE | 0.42 | \$50.08 | \$0.00 | \$0.00 | \$50.08 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.33 | \$38.94 | \$64.31 | \$0.00 | \$103.25 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|---------------|---------------|-------------|-----------------|
| JOB COUNT: 5 | WORK ORDER TOTAL: | 3.08 | 363.43 | 885.22 | 5.00 | 1,253.65 |
|---------------------|--------------------------|-------------|---------------|---------------|-------------|-----------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | COMML | 5.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|---------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-17-013 | PERFORM ALIGNMENT | 12052187 | 08/08/2023 14:49:32 | 08/08/2023 15:31:18 | 0.70 | \$82.14 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11074414 | 08/08/2023 09:30:00 | 08/08/2023 10:55:41 | 1.43 | \$168.51 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11074414 | 08/08/2023 09:02:55 | 08/08/2023 09:15:00 | 0.20 | \$23.76 |
| 66-79-003 | PERFORM SAFETY INSPECTION | 11074414 | 08/04/2023 14:30:00 | 08/04/2023 14:41:16 | 0.19 | \$22.16 |
| 66-79-003 | PERFORM SAFETY INSPECTION | 11074414 | 08/04/2023 14:00:48 | 08/04/2023 14:15:00 | 0.24 | \$27.93 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12201267 | 08/04/2023 12:17:03 | 08/04/2023 12:17:03 | 0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12201267 | 08/04/2023 12:17:03 | 08/04/2023 12:17:03 | 0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12201267 | 08/04/2023 12:17:03 | 08/04/2023 12:36:51 | 0.33 | \$38.94 |
| | | | | | LABOR | 363.44 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|---------------------------------|-----------------|-------------------------------|-------------------|-----------------|-------------------|
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58107 | WHEEL WEIGHT PFE 2.00 | 1.31 | 1 | \$1.31 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 000702 | TIRE 245/55R18 FSTONE PURSUIT | 200.09 | 4 | \$800.34 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58104 | 1.25 OZ WHEEL WEIGHT | 0.90 | 2 | \$1.80 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58103 | 1.00 OZ WHEEL WEIGHT | 0.66 | 1 | \$0.66 |

Work Order Charge Detail

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|---------------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58102 | .75 OZ WHEEL WEIGHT | 0.63 | 1 | \$0.63 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58101 | .50 OZ WHEEL WEIGHT | 0.43 | 1 | \$0.43 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58100 | .25 OZ WHEEL WEIGHT | 0.26 | 1 | \$0.26 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE 21060 | 3.87 | 4 | \$15.48 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 13.49 | 1 | \$13.49 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.29 | 6 | \$37.71 |
| | | | | | PARTS | 885.22 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 47830

Work Order Notes

(EHANNAH) pm- replace wipers- do SI
(EKIMBREL) just got wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(IFALLS) canceled job

66-17-013 - PERFORM ALIGNMENT

(GARAGE) Performed alignment. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and balanced 4 tires and relearned the tire positions. SH

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed a safety inspection. Found the tires had excessive shoulder wear and need to be replaced. found no other issues at this time. Front and rear pads measure 6MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 24,540
Engine Hours, 5,557
Idle Hours, 4,339

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 49070

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 11/28/2023 12:35:39 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 11/29/2023 07:31:51 | METER 1 - M: 25389 METER 2 - H: 4573 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 11/29/2023 08:32:18 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 03-32-002 | REPLACE NEW BATTERY | DON | N | N | GARAGE | 0.20 | \$23.60 | \$199.98 | \$0.00 | \$223.58 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.33 | \$38.94 | \$64.16 | \$0.00 | \$103.10 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|--------------|---------------|-------------|---------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.53 | 62.54 | 264.14 | 5.00 | 331.68 |
|---------------------|--------------------------|-------------|--------------|---------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 03-32-002 | REPLACE NEW BATTERY | 12395904 | 11/29/2023 07:19:48 | 11/29/2023 07:31:48 | 0.20 | \$23.60 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12395904 | 11/29/2023 07:00:00 | 11/29/2023 07:19:48 | 0.33 | \$38.94 |
| LABOR | | | | | 62.54 | |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 03-32-002 | REPLACE NEW BATTERY | 651 | BATTERY BCI 65 750CCA | 199.98 | 1 | \$199.98 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 13.52 | 1 | \$13.52 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.26 | 6 | \$37.53 |
| PARTS | | | | | 264.14 | |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 49070

Work Order Notes

(EHANNAH) pm

Job Notes

03-32-002 - REPLACE NEW BATTERY

(EKIMBREL) FC REPLACED BATTERY

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) FC PERFORMED PM

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 49789

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 02/13/2024 14:25:08 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 02/16/2024 14:52:35 | METER 1 - M: 26161 METER 2 - H: 5086 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 02/19/2024 09:27:36 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|---------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.32 | \$37.92 | \$60.56 | \$0.00 | \$98.48 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMEI | DON | P | N | GARAGE | 0.01 | \$1.57 | \$32.21 | \$0.00 | \$33.78 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|--------------|--------------|-------------|---------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.33 | 39.49 | 92.77 | 5.00 | 137.26 |
|---------------------|--------------------------|-------------|--------------|--------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|----------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 12395904 | 02/14/2024 07:11:40 | 02/14/2024 07:30:57 | 0.32 | \$37.92 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 12395904 | 02/14/2024 07:10:27 | 02/14/2024 07:11:15 | 0.01 | \$1.57 |
| LABOR | | | | | 39.49 | |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|----------------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 13.52 | 1 | \$13.52 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | FP68 | CABIN FILTER | 32.21 | 1 | \$32.21 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 5.66 | 6 | \$33.93 |
| PARTS | | | | | 92.77 | |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 49789

Work Order Notes

(LRUSHING) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replaced new cabin filter fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 50016

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 02/29/2024 15:34:43 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 03/01/2024 14:16:08 | METER 1 - M: 26161 METER 2 - H: 5086 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 03/01/2024 15:12:15 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 14-52-021 | INSTALL GPS SYSTEM | DON | N | N | GARAGE | 0.20 | \$23.27 | \$0.00 | \$0.00 | \$23.27 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

JOB COUNT: 2 WORK ORDER TOTAL: 0.20 23.27 0.00 5.00 28.27

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|------------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | | COMML 5.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 14-52-021 | INSTALL GPS SYSTEM | 12201267 | 03/01/2024 09:45:36 | 03/01/2024 09:57:26 | 0.20 | \$23.27 |
| | | | | | LABOR | 23.27 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 50016

Work Order Notes

(EHANNAH) install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GRCOOK) Installed GPS SN:87U030240069 in unit 2478C. -GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 50496

| | | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|--------------|------|
| USING DEPT NO: | 507121 | OPENED DATE: | 04/09/2024 15:12:24 | LOCATION: | GARAGE - University Automotive Services | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 04/10/2024 12:23:11 | METER 1 - M: | 26161 | METER 2 - H: | 5086 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 04/10/2024 12:23:15 | IN-SERVICE DATE: | 03/01/2019 | | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR1KGB28054 | | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|-----------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 03-34-010 | REPLACE NEW TAG LIGHT | DON | O | N | GARAGE | 0.03 | \$3.77 | \$0.39 | \$0.00 | \$4.16 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$4.16 | \$4.16 |

JOB COUNT: 2 WORK ORDER TOTAL: 0.03 3.77 0.39 4.16 8.32

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost | |
|----------|----------------------|------------|-------------|--------------------|--------------|-------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$4.16 | |
| | | | | | COMML | 4.16 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|-----------------------|--------------|---------------------|---------------------|--------------|-------------|
| 03-34-010 | REPLACE NEW TAG LIGHT | 12201267 | 04/09/2024 15:39:06 | 04/09/2024 15:41:01 | 0.03 | \$3.77 |
| | | | | | LABOR | 3.77 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|-----------------------|----------|-----------------|------------|--------------|-------------|
| 03-34-010 | REPLACE NEW TAG LIGHT | 194 | BULB-TAG/MARKER | 0.39 | 1 | \$0.39 |
| | | | | | PARTS | 0.39 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 50496

Work Order Notes

(EHANNAH) replace tag light

Job Notes

03-34-010 - REPLACE NEW TAG LIGHT

(GRCOOK) Replaced tag light bulb in unit 2478C- GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 50836

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 05/14/2024 07:15:13 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 05/14/2024 10:40:44 | METER 1 - M: 28016 METER 2 - H: 5489 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 05/14/2024 13:00:38 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|----------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.01 | \$1.34 | \$78.74 | \$0.00 | \$80.08 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | DON | P | N | GARAGE | 0.01 | \$1.18 | \$32.21 | \$0.00 | \$33.39 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|---------------------|--------------------------|-------------|-------------|---------------|-------------|---------------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.02 | 2.52 | 110.95 | 5.00 | 118.47 |
|---------------------|--------------------------|-------------|-------------|---------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|----------------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 12395904 | 05/14/2024 08:34:19 | 05/14/2024 08:34:55 | 0.01 | \$1.18 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12395904 | 05/14/2024 08:33:16 | 05/14/2024 08:33:57 | 0.01 | \$1.34 |
| LABOR | | | | | 2.52 | |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|----------------------------------|-----------------|--------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20TQT | QUART CAM2 SYN 5W20 32OZ | 8.69 | 6 | \$52.11 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | FP68 | CABIN FILTER | 32.21 | 1 | \$32.21 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 13.52 | 1 | \$13.52 |
| PARTS | | | | | 110.95 | |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 50836

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replaced new cabin filter fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 52181

| | | |
|------------------------------------|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 09/20/2024 08:22:47 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 09/23/2024 13:46:46 | METER 1 - M: 30503 METER 2 - H: 5911 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 09/23/2024 14:35:37 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.00 | \$0.00 | \$68.61 | \$0.00 | \$68.61 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.00** **68.61** **5.00** **73.61**

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------|-------------------|--------------------|---------------------------|-------------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|--------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30BT | 5W30 BULK | 7.01 | 6 | \$42.03 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 13.47 | 1 | \$13.47 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| PARTS | | | | | | 68.61 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 52181

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm cm 30503 miles 5911 idle hours, 7488 total hours, changed motor oil and filter, checked all fluids cheked ok, checked tires checked ok, added seafo to gas

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 53182

| | | |
|--|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 12/17/2024 14:01:10 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 12/17/2024 14:38:08 | METER 1 - M: 30503 METER 2 - H: 5911 |
| WO VISIT REASON: SCHEDULED | CLOSED DATE: 12/17/2024 14:38:14 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|---------------------|------------------------|-------------|------------|-------------|----------------|--------------------------|--------------|-----------------|-------------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| JOB COUNT: 1 | | | | | | WORK ORDER TOTAL: | 0.00 | 0.00 | 0.00 | 0.00 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 53182

Work Order Notes

(EHANNAH) no labor- waiting to be sold and remove equipment

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 53689

| | | |
|--|--|--|
| USING DEPT NO: 507121 | OPENED DATE: 02/10/2025 11:30:50 | LOCATION: GARAGE - University Automotive Services |
| WO STATUS: CLOSED | COMPLETED DATE: 02/20/2025 14:31:05 | METER 1 - M: 30503 METER 2 - H: 5911 |
| WO VISIT REASON: UNSCHEDULED | CLOSED DATE: 02/21/2025 09:31:33 | IN-SERVICE DATE: 03/01/2019 |
| TECH SPEC NO: 19FORDEXPINTR 2019 Ford Explorer Police Interceptor | UNIT SERIAL NO: 1FM5K8AR1KGB28054 | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|----------------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 16-00 | TRANSPORT COMPLETE VEHICLE | DON | 5 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| PD-00-999 | PREP DISPOSE PREPARE UNIT FOR DI | DON | D | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| RY-33-006 | REKEY IGNITION LOCK CYLINDER | DON | 5 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$98.80 | \$98.80 |

JOB COUNT: 4 **WORK ORDER TOTAL:** 0.00 0.00 0.00 103.80 103.80

| <u>Job Code</u> | <u>Job Description</u> | <u>Vendor No.</u> | <u>Invoice No.</u> | <u>Purchase Order No.</u> | <u>Total Cost</u> |
|-----------------|------------------------------|-------------------|--------------------|---------------------------|-------------------|
| RY-33-006 | REKEY IGNITION LOCK CYLINDER | 11111231 | 2317336 | | \$98.80 |
| RY-33-006 | REKEY IGNITION LOCK CYLINDER | 11111231 | 2317336 | | \$95.45 |
| RY-33-006 | REKEY IGNITION LOCK CYLINDER | 11111231 | 2317336 | | (\$95.45) |
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 103.80 |

Work Order Charge Detail

UNIT NO: 243196 2019 FORD INTERCEPTOR

WORK ORDER NO: 53689

Work Order Notes

(EHOWELL) Prep for Sale

Job Notes

16-00 - TRANSPORT COMPLETE VEHICLE

(EKIMBREL) CM transported lock to and from A1 to get rekeyed.

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) CM performed prep for sale and removed GPS#87U030240069

RY-33-006 - REKEY IGNITION LOCK CYLINDER

(EKIMBREL) A-1 rekeyed locks

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Feb 25 2025 09:37:56 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243196') //Q=