

Work Order Charge Detail

UNIT NO: 242801 2018 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 32115

USING DEPT NO:	507121	OPENED DATE:	02/05/2019 07:33:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/08/2019 06:52:13	METER 1 - M:	996	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/08/2019 06:52:15	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$0.00	\$23.03	\$0.00	\$23.03

JOB COUNT: 1 WORK ORDER TOTAL: 0.39 0.00 23.03 0.00 23.03

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/05/2019 08:48:56	02/05/2019 09:12:29	0.39	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	6	\$18.00
					PARTS	23.03

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32115

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by RC/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32352

USING DEPT NO:	507121	OPENED DATE:	03/06/2019 14:40:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2019 10:34:59	METER 1 - M:	2102	METER 2 - H: 427
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2019 10:35:01	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.11	\$0.00	\$22.85	\$0.00	\$22.85

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.11** **0.00** **22.85** **0.00** **22.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/07/2019 07:36:56	03/07/2019 08:21:04	0.74	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/07/2019 07:37:45	03/07/2019 08:00:27	0.38	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.97	6	\$17.82
					PARTS	22.85

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32352

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) Visit Reason Changed On 3/6/2019 2:40 PM By EKIMBREL

(EKIMBREL) Top: AG, Bot: SH

coolant -35

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32560

USING DEPT NO:	507121	OPENED DATE:	04/09/2019 07:07:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/12/2019 09:32:16	METER 1 - M:	3150	METER 2 - H: 682
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/12/2019 09:32:18	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.87	\$0.00	\$22.85	\$0.00	\$22.85

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.87** **0.00** **22.85** **0.00** **22.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/09/2019 09:30:00	04/09/2019 10:03:59	0.57	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/09/2019 08:56:41	04/09/2019 09:15:00	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.97	6	\$17.82
					PARTS	22.85

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32560

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 4/9/2019 7:07 AM By LISAPATE

(LISAPATE) PM by EK/AG

Coolant -10'

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33033

USING DEPT NO: 507121	OPENED DATE: 05/30/2019 15:29:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/05/2019 09:27:07	METER 1 - M: 4429 METER 2 - H: 943
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 06/05/2019 09:27:09	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>	
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.90	\$0.00	\$26.94	\$0.00	\$26.94	
JOB COUNT: 1						WORK ORDER TOTAL:	0.90	0.00	26.94	0.00	26.94

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/31/2019 10:08:22	05/31/2019 13:02:20	2.90	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/31/2019 10:08:22	05/31/2019 13:02:20	(2.90)	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/31/2019 10:08:22	05/31/2019 11:02:22	0.90	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	26.94

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33033

Work Order Notes

(LISAPATE) PM
(LISAPATE) idle hours 710

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 5/30/2019 3:30 PM By LISAPATE
(LISAPATE) PM by SH
Coolant -20'

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33308

USING DEPT NO: 507121	OPENED DATE: 07/03/2019 07:19:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/08/2019 13:48:48	METER 1 - M: 5564 METER 2 - H: 1212
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 07/08/2019 13:48:51	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/03/2019 11:28:23	07/03/2019 11:46:59	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33308

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK,RC/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242801 2018 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 33484

USING DEPT NO:	507121	OPENED DATE:	07/19/2019 07:03:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2019 13:48:32	METER 1 - M:	6358	METER 2 - H: 1212
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/22/2019 13:48:34	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 0.00 22.73 0.00 22.73

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/22/2019 06:00:00	07/22/2019 06:18:36	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242801 2018 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 33484

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH performed pm coolant good to 35 deg

Work Order Charge Detail

UNIT NO: 242801 2018 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 33684

USING DEPT NO:	507121	OPENED DATE:	08/12/2019 07:28:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/13/2019 08:59:42	METER 1 - M:	7522	METER 2 - H: 1673
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	08/13/2019 08:59:45	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 WORK ORDER TOTAL: 0.61 0.00 22.73 0.00 22.73

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/12/2019 09:39:43	08/12/2019 10:16:17	0.61	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33684

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH
Coolant -20'

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34012

USING DEPT NO: 507121	OPENED DATE: 09/09/2019 07:15:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/10/2019 15:42:46	METER 1 - M: 8664 METER 2 - H: 1961
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 09/10/2019 15:42:48	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$0.00	\$22.79	\$0.00	\$22.79

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.68** **0.00** **22.79** **0.00** **22.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/09/2019 07:31:30	09/09/2019 07:52:12	0.35	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/09/2019 07:31:45	09/09/2019 07:52:00	0.34	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	6	\$17.76
					PARTS	22.79

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34012

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/JW
Coolant -20'

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34247

USING DEPT NO: 507121	OPENED DATE: 09/26/2019 07:54:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/26/2019 11:31:11	METER 1 - M: 9426 METER 2 - H: 2138
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/26/2019 11:31:13	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.05	\$0.00	\$19.24	\$0.00	\$19.24
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.63** **0.00** **41.97** **0.00** **41.97**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/26/2019 08:01:11	09/26/2019 08:26:43	0.43	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/26/2019 08:18:17	09/26/2019 08:21:16	0.05	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/26/2019 08:09:04	09/26/2019 08:18:17	0.15	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	10.23	1	\$10.23
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	9.01	1	\$9.01
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	41.97

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34247

Work Order Notes

(LISAPATE) PM-Replace wipers
(LISAPATE) Idle hours 1626

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

03-51-046 - REPLACE NEW KEY BLANK(S)

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW,AG/JW
Coolant -34'

Work Order Charge Detail

UNIT NO: 242801 2018 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 34536

USING DEPT NO:	507121	OPENED DATE:	10/22/2019 07:22:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2019 07:31:22	METER 1 - M:	10560	METER 2 - H: 1835
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/24/2019 07:31:23	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 WORK ORDER TOTAL: 0.43 0.00 22.73 0.00 22.73

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/22/2019 07:34:12	10/22/2019 08:00:11	0.43	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34536

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW,EK/SH

Coolant -35'

Syn 4.73

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34962

USING DEPT NO: 507121	OPENED DATE: 11/25/2019 06:49:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/27/2019 09:53:32	METER 1 - M: 11627 METER 2 - H: 2049
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 11/27/2019 09:53:33	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.04	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$0.00	\$22.25	\$0.00	\$22.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.64** **0.00** **22.25** **0.00** **22.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/25/2019 07:40:17	11/25/2019 07:46:32	0.10	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	11/25/2019 08:16:51	11/25/2019 08:19:05	0.04	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/25/2019 07:02:45	11/25/2019 07:32:40	0.50	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.87	6	\$17.22
					PARTS	22.25

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34962

Work Order Notes

(RWINTERS) pm and rotate tires
eng. hrs2689
idle 2049

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires and relearned TPMS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW/AG
Coolant -10'

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35380

USING DEPT NO: 507121	OPENED DATE: 01/14/2020 06:03:46	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/17/2020 09:23:33	METER 1 - M: 12852 METER 2 - H: 2249
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 01/17/2020 09:23:35	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.96	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.84	\$0.00	\$22.31	\$0.00	\$22.31

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.80** **0.00** **22.31** **0.00** **22.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	01/14/2020 13:17:18	01/14/2020 14:15:00	0.96	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/14/2020 07:35:11	01/14/2020 08:25:35	0.84	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.88	6	\$17.28
					PARTS	22.31

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35380

Work Order Notes

(IFALLS) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires and relearned TPMS. torqued to spec

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK,JW/JW
Coolant -34'

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35972

USING DEPT NO: 507121	OPENED DATE: 03/10/2020 14:40:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/11/2020 14:15:25	METER 1 - M: 14323 METER 2 - H: 2445
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/13/2020 14:54:56	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.26	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$0.00	\$28.37	\$0.00	\$28.37
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.14	\$0.00	\$3.55	\$0.00	\$3.55

JOB COUNT: 3	WORK ORDER TOTAL:	1.40	0.00	31.92	0.00	31.92
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11901357	03/11/2020 07:05:40	03/11/2020 07:10:05	0.07	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11901357	03/11/2020 09:30:55	03/11/2020 09:42:17	0.19	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	03/11/2020 09:42:17	03/11/2020 09:50:25	0.14	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/11/2020 06:05:24	03/11/2020 07:05:40	1.00	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4068	FILTER- CABIN AIR	3.55	1	\$3.55
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	3.89	6	\$23.34
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	31.92

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35972

Work Order Notes

(EKIMBREL) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires and relearned TPMS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG

Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36363

USING DEPT NO: 507121	OPENED DATE: 05/11/2020 06:56:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/11/2020 08:29:17	METER 1 - M: 15810 METER 2 - H: 3664
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/13/2020 08:11:53	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.93	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.93** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/11/2020 07:11:15	05/11/2020 07:39:10	0.47	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/11/2020 07:06:07	05/11/2020 07:33:56	0.46	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242801 2018 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 36363

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH/JW performed pm

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36687

USING DEPT NO: 507121	OPENED DATE: 06/03/2020 13:40:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/03/2020 15:16:23	METER 1 - M: 16386 METER 2 - H: 2754
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/04/2020 13:16:53	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PR-01-002	PROGRAM HEATING & VENTILATING	DON	O	N	GARAGE	0.29	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.29** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PR-01-002	PROGRAM HEATING & VENTILATING	11170580	06/03/2020 14:43:25	06/03/2020 14:56:49	0.22	\$0.00
PR-01-002	PROGRAM HEATING & VENTILATING	11170580	06/03/2020 14:30:00	06/03/2020 14:33:52	0.06	\$0.00
PR-01-002	PROGRAM HEATING & VENTILATING	11170580	06/03/2020 14:21:36	06/03/2020 14:21:36	0.00	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36687

Work Order Notes

(LISAPATE) Reprogram A/C for Corona virus

Job Notes

PR-01-002 - PROGRAM HEATING & VENTILATING

(ABLACK) AB reprogrammed PCM, BCM, and HVAC modules in order to active the coronavirus disinfectant mode. Activate by pressing set + set x 2 and ON/OFF x 2 on the cruise control.

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36835

USING DEPT NO: 507121	OPENED DATE: 06/17/2020 08:06:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/19/2020 13:44:32	METER 1 - M: 16844 METER 2 - H: 2867
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/22/2020 07:45:52	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.21	\$0.00	\$18.01	\$0.00	\$18.01
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.03	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.20	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.31	\$0.00	\$520.86	\$0.00	\$520.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 5	WORK ORDER TOTAL:	2.37	0.00	561.60	0.00	561.60
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	06/17/2020 10:59:50	06/17/2020 11:50:35	0.85	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	06/17/2020 13:05:03	06/17/2020 13:33:00	0.47	\$0.00
09-15	ALIGN STEERING	11310047	06/18/2020 10:01:00	06/18/2020 10:10:53	0.16	\$0.00
09-15	ALIGN STEERING	11310047	06/18/2020 11:06:15	06/18/2020 11:06:53	0.01	\$0.00
09-15	ALIGN STEERING	11310047	06/18/2020 11:07:33	06/18/2020 11:09:13	0.03	\$0.00
06-15	INSPECT STEERING	12052187	06/17/2020 10:57:58	06/17/2020 10:59:35	0.03	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/17/2020 08:22:37	06/17/2020 09:00:09	0.63	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	10208562	06/17/2020 08:22:01	06/17/2020 08:34:23	0.21	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
03-51-038	REPLACE NEW WIPER BLADES	NPB26	WIPER 26" SECURITY INTERCEPTOR	9.35	1	\$9.35
03-51-038	REPLACE NEW WIPER BLADES	NPB22	WIPER 22" MALIBU	8.66	1	\$8.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000177	TIRE P245/55R18 FIREHAWK PURSU	126.98	4	\$507.92
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	10	\$2.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.56	4	\$10.24

Work Order Charge Detail

PARTS	561.60
--------------	---------------

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36835

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

06-15 - INSPECT STEERING

(LISAPATE) JW inspected front end with AMG. Found no issues

09-15 - ALIGN STEERING

(EHOWELL) performed alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced and balanced all 4 tires. Aired and torqued to spec. Relearned tpms

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Performed pm service. Found no issues at this time SH,EK/JE
Coolant -35'

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37132

USING DEPT NO: 507121	OPENED DATE: 07/17/2020 08:02:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/17/2020 10:01:14	METER 1 - M: 18067 METER 2 - H: 3076
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/17/2020 14:52:12	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.29** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/17/2020 09:15:00	07/17/2020 09:16:44	0.03	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/17/2020 08:44:12	07/17/2020 09:00:00	0.26	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37132

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Tires did not need to be rotated at this time

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37301

USING DEPT NO: 507121	OPENED DATE: 08/11/2020 07:06:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/12/2020 12:34:25	METER 1 - M: 18726 METER 2 - H: 3237
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 08/12/2020 12:34:29	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.11	\$0.00	\$98.63	\$0.00	\$98.63
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.22	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 4 **WORK ORDER TOTAL:** **2.18** **0.00** **121.36** **0.00** **121.36**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11915538	08/11/2020 08:13:59	08/11/2020 08:20:49	0.11	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/11/2020 08:13:43	08/11/2020 09:04:27	0.85	\$0.00
66-79-002	PERFORM SERVICE CALL	11901357	08/11/2020 07:13:06	08/11/2020 07:49:57	0.61	\$0.00
66-79-002	PERFORM SERVICE CALL	11074414	08/11/2020 07:12:27	08/11/2020 07:49:03	0.61	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.41	2	\$0.82
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	97.81	1	\$97.81
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	121.36

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37301

Work Order Notes

(LISAPATE) UAPD requested a service call to their lot for a dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) RC removed and installed a new battery. Rechecked ok

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Tire rotation not needed at this time. AMG

66-79-002 - PERFORM SERVICE CALL

(AGUERRA) jumped vehicle off and returned to shop for repairs.

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Rotation not needed. AMG

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38226

USING DEPT NO: 507121	OPENED DATE: 11/02/2020 07:49:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/03/2020 07:53:42	METER 1 - M: 20927 METER 2 - H: 4646
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/03/2020 10:07:23	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.83	\$97.58	\$0.00	\$0.00	\$97.58
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.97	\$113.87	\$60.20	\$0.00	\$174.07
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.01	\$0.85	\$5.33	\$0.00	\$6.18

JOB COUNT: 3 **WORK ORDER TOTAL:** **1.80** **212.30** **65.53** **0.00** **277.83**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2020 09:30:05	11/02/2020 10:10:15	0.67	\$78.99
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	11/02/2020 10:13:07	11/02/2020 10:36:16	0.39	\$45.53
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	11/02/2020 10:36:30	11/02/2020 10:36:56	0.01	\$0.85
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	11/02/2020 10:10:37	11/02/2020 10:37:05	0.44	\$52.05
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/02/2020 10:08:11	11/02/2020 10:08:20	0.00	\$0.30
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/02/2020 09:50:00	11/02/2020 10:07:35	0.29	\$34.58
					LABOR	212.30

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.86	1	\$6.86
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4068	FILTER- CABIN AIR	5.33	1	\$5.33
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	18.42	1	\$18.42
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	65.53

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38226

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) SH AMG Rotated tires and inspected brakes.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM. SH Vacuumed vehicle did not wash this time.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin filter. SH

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38677

USING DEPT NO: 507121	OPENED DATE: 12/16/2020 09:46:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/16/2020 13:27:54	METER 1 - M: 22110 METER 2 - H: 4646
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/17/2020 08:35:26	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$34.92	\$0.00	\$73.86

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.33** **38.94** **34.92** **0.00** **73.86**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/16/2020 12:27:40	12/16/2020 12:27:40	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/16/2020 12:27:40	12/16/2020 12:27:40	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/16/2020 12:27:40	12/16/2020 12:47:28	0.33	\$38.94
					LABOR	38.94

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	34.92

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38677

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Miles: 22110 Idle Hrs: 3792 Josh completed PM Bottom side, Ronny was topside. JW RC Completed checklist. AMG

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39246

USING DEPT NO:	507121	OPENED DATE:	03/01/2021 12:39:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/02/2021 14:19:57	METER 1 - M:	23468	METER 2 - H: 5320
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	03/04/2021 09:01:53	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLAC	DON	O	N	GARAGE	0.07	\$8.82	\$39.20	\$0.00	\$48.02
06-03	INSPECT INSTRUMENTS, GAUGES, ME	DON	O	N	GARAGE	0.02	\$2.33	\$0.00	\$0.00	\$2.33
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.89	\$104.63	\$36.42	\$0.00	\$141.05

JOB COUNT: 3	WORK ORDER TOTAL:	0.98	115.78	75.62	0.00	191.40
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	12052187	03/01/2021 14:57:28	03/01/2021 15:00:07	0.04	\$5.21
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	12052187	03/01/2021 15:01:10	03/01/2021 15:03:00	0.03	\$3.61
06-03	INSPECT INSTRUMENTS, GAUGES, METERS	12052187	03/01/2021 15:03:09	03/01/2021 15:04:20	0.02	\$2.33
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/01/2021 14:04:00	03/01/2021 14:57:12	0.89	\$104.63
					LABOR	115.78

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.78	1	\$9.78
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	MOTFP68	CABIN FILTER	39.20	1	\$39.20
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
					PARTS	75.62

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39246

Work Order Notes

(LISAPATE) PM-Per driver unit has an issue where the low fuel light stays on even after vehicle has been refueled.

Job Notes

03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT

(JWRIGHT) Replaced cabin filter. JAW

06-03 - INSPECT INSTRUMENTS, GAUGES, METERS

(JWRIGHT) Inspected with MS and this is normal operation due to unit idling for long periods of time. No issues JAW

(IFALLS) Fuel Gauge / miles per gal

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/JAW

MILEAGE-23468

IDLE HRS-4098

ENG HRS-5320

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39803

USING DEPT NO: 507121	OPENED DATE: 04/26/2021 09:15:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/27/2021 11:50:07	METER 1 - M: 24517 METER 2 - H: 4410
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/27/2021 14:53:48	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.55	\$64.31	\$9.29	\$0.00	\$73.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$100.63	\$31.13	\$0.00	\$131.76

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.40** **164.94** **40.42** **0.00** **205.36**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	04/26/2021 12:44:29	04/26/2021 12:47:20	0.05	\$5.61
66-17-030	PERFORM TIRE PATCH	11901357	04/26/2021 10:27:12	04/26/2021 10:57:03	0.50	\$58.71
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/26/2021 10:08:44	04/26/2021 10:34:11	0.42	\$50.05
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/26/2021 10:00:42	04/26/2021 10:26:25	0.43	\$50.58
					LABOR	164.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.84	1	\$3.84
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	4.01	1	\$4.01
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	1	\$0.48
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	(1)	(\$0.48)
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	3	\$1.44
					PARTS	40.42

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39803

Work Order Notes

(LISAPATE) PM-slow leak in LR tire air has been added several times

Job Notes

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) Repaired R/R tire, rechecked for leak and balanced, all good. SH AMG

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 24517 Engine hours 5691 Idle hours 4410. SH/AMG Performed PM.

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39861

USING DEPT NO: 507121	OPENED DATE: 05/04/2021 07:36:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/06/2021 15:18:51	METER 1 - M: 24576 METER 2 - H: 4410
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/10/2021 08:13:30	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.66	\$195.91	\$0.00	\$0.00	\$195.91

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.66** **195.91** **0.00** **0.00** **195.91**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	05/04/2021 13:00:00	05/04/2021 13:02:55	0.05	\$5.74
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	05/04/2021 10:23:18	05/04/2021 12:00:00	1.61	\$190.18
					LABOR	195.92

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39861

Work Order Notes

(LISAPATE) Per driver unit was fueled last night to full. tank is still about 3/4 full but gauge is showing 37 miles to empty. and low fuel light is on.

Job Notes

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(ABLACK) No codes present

(ABLACK) Reset the destination to empty calculation. Vehicle was averaging 5.8 miles per gallon. When the vehicle idles for so long over the years and the DTE never gets reset it will throw the miles to empty off. Reset DTE and the mileage went up some and got the low fuel light off. Since the vehicle only idles most of the time and drives a short distance this is a normal characteristic. No repairs are needed.

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40208

USING DEPT NO: 507121	OPENED DATE: 06/21/2021 07:06:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/23/2021 13:55:56	METER 1 - M: 26307 METER 2 - H: 4410
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 06/23/2021 13:55:59	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.26	\$30.39	\$0.00	\$0.00	\$30.39
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.98	\$115.84	\$782.31	\$0.00	\$898.15
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$58.71	\$46.94	\$0.00	\$105.65

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.94** **228.54** **829.25** **0.00** **1,057.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11310047	06/21/2021 12:54:13	06/21/2021 13:09:40	0.26	\$30.39
06-15	INSPECT STEERING	12052187	06/21/2021 10:52:39	06/21/2021 10:52:55	0.00	(\$0.52)
06-15	INSPECT STEERING	12052187	06/21/2021 10:52:39	06/21/2021 10:52:55	0.00	\$0.52
06-15	INSPECT STEERING	12052187	06/21/2021 10:52:39	06/21/2021 11:04:39	0.20	\$23.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	06/21/2021 09:53:37	06/21/2021 10:52:31	0.98	\$115.84
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/21/2021 08:18:34	06/21/2021 08:36:15	0.29	\$34.78
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/21/2021 08:20:12	06/21/2021 08:32:22	0.20	\$23.93
					LABOR	228.54

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PF63	FILTER-OIL	9.68	1	\$9.68
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000177	TIRE P245/55R18 FIREHAWK PURSU	190.43	4	\$761.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	10	\$4.95
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.92	4	\$15.66
					PARTS	829.25

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40208

Work Order Notes

(IFALLS) PM

Job Notes

06-15 - INSPECT STEERING

(JWRIGHT) Front end checked good. JAW,SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. Did not make any adjustments. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced all 4 tires. Aired and balanced to spec. Torqued all lugs to spec. Relearned tpms. Need to recheck brakes at next pm service per EH. brakes are good at this time.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG

MILEAGE-26313

HRS-6085

IDLE HRS-4711

All 4 tires need replaced. Below dot spec and RR tire sidewall is split open. JAW

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40788

USING DEPT NO: 507121	OPENED DATE: 08/20/2021 07:19:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/20/2021 15:16:15	METER 1 - M: 27822 METER 2 - H: 5013
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/23/2021 07:22:53	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.57	\$31.82	\$0.00	\$37.39
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$56.80	\$43.19	\$0.00	\$99.99
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.53	62.37	75.01	2.00	139.38
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/20/2021 08:39:29	08/20/2021 09:04:54	0.42	\$49.99
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/20/2021 08:16:16	08/20/2021 08:19:44	0.06	\$6.82
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/20/2021 09:05:07	08/20/2021 09:07:57	0.05	\$5.57
LABOR					62.38	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.84	1	\$5.84
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
PARTS					75.01	

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40788

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers.SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 27822 Engine hours 6472 Idle hours 5013. SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41253

USING DEPT NO: 507121	OPENED DATE: 10/07/2021 15:31:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/12/2021 10:24:52	METER 1 - M: 28230 METER 2 - H: 5090
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/13/2021 11:09:28	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.21	\$31.82	\$0.00	\$35.03
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.09	\$10.65	\$8.85	\$0.00	\$19.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.24	\$10.71	\$0.00	\$37.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.35** **41.10** **51.38** **2.00** **94.48**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/08/2021 07:53:02	10/08/2021 07:54:40	0.03	\$3.21
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/08/2021 07:39:04	10/08/2021 07:52:55	0.23	\$27.24
66-17-030	PERFORM TIRE PATCH	12052187	10/08/2021 07:33:30	10/08/2021 07:38:55	0.09	\$10.65
					LABOR 41.10	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.92	1	\$3.92
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
66-17-030	PERFORM TIRE PATCH	58101	.50 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.41	2	\$0.81
					PARTS 51.38	

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41253

Work Order Notes

(LISAPATE) nail in LR tire-PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades. JAW

66-17-030 - PERFORM TIRE PATCH

(JWRIGHT) Repaired LR tire. Aired to spec and balanced. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been driven 408 miles and idled 77hrs. Checked all fluids and tires. Updated sticker. Coolant -34°. JAW

MILEAGE-28230

IDLE HRS-5090

ENG HRS-6574

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41723

USING DEPT NO: 507121	OPENED DATE: 11/29/2021 10:01:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/01/2021 10:51:43	METER 1 - M: 29182 METER 2 - H: 5327
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 12/02/2021 12:28:55	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.07	\$8.16	\$46.74	\$0.00	\$54.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.07** **8.16** **46.74** **2.00** **56.90**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/30/2021 07:17:43	11/30/2021 07:21:52	0.07	\$8.16
LABOR					8.16	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.48	1	\$9.48
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS					46.74	

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41723

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG
MILEAGE-29182

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42549

USING DEPT NO: 507121	OPENED DATE: 03/03/2022 09:14:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/08/2022 11:14:24	METER 1 - M: 30770 METER 2 - H: 5675
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/08/2022 14:08:26	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$45.36	\$0.00	\$0.00	\$45.36
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.38** **45.36** **0.00** **2.00** **47.36**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/03/2022 13:08:56	03/03/2022 13:32:00	0.38	\$45.36
LABOR						45.36

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42549

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Cancelled from Work Order# 42214. By User ID LISAPATE on 1/31/2022 8:26 AM.

(AGUERRA) miles: 30770 hours: 7296 idle hours: 5675 Vehicle has been 436 miles and 105 idle hours. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43549

USING DEPT NO: 507121	OPENED DATE: 06/07/2022 10:26:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/13/2022 14:45:09	METER 1 - M: 31065 METER 2 - H: 5738
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/14/2022 08:05:06	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	1.53	\$181.00	\$424.69	\$0.00	\$605.69
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.09	\$10.16	\$113.55	\$0.00	\$123.71
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.61	\$31.82	\$0.00	\$37.43
66-13-130	PERFORM Burnish Brakes	DON	O	N	GARAGE	0.27	\$32.16	\$0.00	\$0.00	\$32.16
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.15	\$17.86	\$0.00	\$0.00	\$17.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$66.54	\$55.61	\$0.00	\$122.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 7 **WORK ORDER TOTAL:** **2.66** **313.33** **625.67** **2.00** **941.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-13-130	PERFORM Burnish Brakes	11310047	06/09/2022 10:47:05	06/09/2022 11:03:26	0.27	\$32.16
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	06/09/2022 09:15:03	06/09/2022 10:47:05	1.53	\$181.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	06/07/2022 15:15:35	06/07/2022 15:24:40	0.15	\$17.86
03-32-002	REPLACE NEW BATTERY	11074414	06/07/2022 15:10:07	06/07/2022 15:15:17	0.09	\$10.16
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/07/2022 14:41:12	06/07/2022 15:06:51	0.43	\$50.45
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/07/2022 14:58:42	06/07/2022 15:06:53	0.14	\$16.09
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/07/2022 15:07:05	06/07/2022 15:09:56	0.05	\$5.61
					LABOR	313.33

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.63	6	\$33.75
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.15	1	\$11.15
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	1	\$5.93
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABSP1611APPH	BRAKE PAD SET	100.97	1	\$100.97
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	GG1Z1125A	FRONT ROTORS	158.90	2	\$317.79
					PARTS	625.67

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43549

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(EHOWELL) Replaced front brake pads and rotors. Greased slide pins. EH

03-32-002 - REPLACE NEW BATTERY

(HHARBIN) Battery tested bad cell. Replaced the battery. SH EH Reset the charging system.

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made multiple hard stops after brake job was performed. EH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(HHARBIN) Rotated tires and inspected brakes. Found the left front inner pad at 3MM and the right front pad at 4MM. SH JW

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43790

USING DEPT NO: 507121	OPENED DATE: 06/29/2022 13:11:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/08/2022 15:28:43	METER 1 - M: 31081 METER 2 - H: 5738
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/09/2022 08:03:12	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.67	\$23.12	\$0.00	\$28.79
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.43	\$50.74	\$0.00	\$0.00	\$50.74
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.49	\$61.31	\$0.00	\$83.80
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.11	\$18.81	\$0.00	\$19.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.68	80.01	103.24	5.00	188.25
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/07/2022 14:41:40	09/07/2022 14:44:33	0.05	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/07/2022 14:30:00	09/07/2022 14:41:26	0.19	\$22.49
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/07/2022 14:14:50	09/07/2022 14:14:50	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	09/07/2022 14:44:45	09/07/2022 14:45:19	0.01	\$1.11
66-79-003	PERFORM SAFETY INSPECTION	12296277	09/08/2022 07:04:49	09/08/2022 07:30:37	0.43	\$50.74
					LABOR	80.01

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.40	1	\$10.40
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	6	\$36.54
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.66	1	\$11.66
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	18.83	1	\$18.83
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	18.83	(1)	(\$18.83)

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	18.81	1	\$18.81
					PARTS	103.24

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43790

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI
(LISAPATE) Has old Wordmarks

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers.SH

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed si all good JM

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH/JM

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 45233

USING DEPT NO: 507121	OPENED DATE: 11/11/2022 07:36:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/11/2022 13:27:14	METER 1 - M: 32143 METER 2 - H: 6124
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/14/2022 07:42:12	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.58	\$45.29	\$0.00	\$79.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.29** **34.58** **45.29** **5.00** **84.87**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/11/2022 10:31:28	11/11/2022 10:49:03	0.29	\$34.58
LABOR						34.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.76	1	\$7.76
PARTS						45.29

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 45233

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW

MILEAGE-32143

HRS-7821

IDLE-6124

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46239

USING DEPT NO: 507121	OPENED DATE: 02/22/2023 07:54:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/28/2023 09:07:23	METER 1 - M: 34309 METER 2 - H: 8359
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/28/2023 14:44:37	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-42-004	TRANSPORT WATER PUMP	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$9.96	\$43.20	\$0.00	\$53.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.83** **98.46** **43.20** **5.00** **146.66**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-42-004	TRANSPORT WATER PUMP	11399745	02/28/2023 07:00:00	02/28/2023 07:30:00	0.50	\$59.00
35-42	DIAGNOSE COOLING SYSTEM	11310047	02/23/2023 12:12:45	02/23/2023 12:27:45	0.25	\$29.50
35-42	DIAGNOSE COOLING SYSTEM	11310047	02/23/2023 12:12:45	02/23/2023 12:12:45	0.00	\$0.00
35-42	DIAGNOSE COOLING SYSTEM	11310047	02/23/2023 12:12:45	02/23/2023 12:12:45	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/22/2023 10:18:47	02/22/2023 10:23:51	0.08	\$9.96
					LABOR 98.46	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
					PARTS 43.20	

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46239

Work Order Notes

(CWIGLEY) PM

Job Notes

16-42-004 - TRANSPORT WATER PUMP

(IFALLS) chad drove unit to for leaking water pump covered under warranty

35-42 - DIAGNOSE COOLING SYSTEM

(LISAPATE) EH checked and found water pump leaking. Unit was sent to Ford for repairs.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-34309

ENG-8359

IDLE-6540

Unit is low on coolant and the radiator hose is collapsed. Sending to tech 2 for further diagnosis

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46299

USING DEPT NO: 507121	OPENED DATE: 02/28/2023 09:07:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/03/2023 11:38:27	METER 1 - M: 34283 METER 2 - H: 6124
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/03/2023 13:52:27	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-006	REPLACE NEW NEW TERMINAL(S)	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
15-42-004	WARRANTY WATER PUMP	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
17-05-020	RECALL PCM/PROCESSOR ASSEMBLY	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-42-004	WARRANTY WATER PUMP	11078175	109779		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-42	TRANSPORT COOLING SYSTEM	11915538	04/03/2023 07:00:00	04/03/2023 07:30:00	0.50	\$59.00
LABOR					59.00	

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46299

Work Order Notes

(EKIMBREL) WARRANTY WATER PUMP

Job Notes

03-32-006 - REPLACE NEW NEW TERMINAL(S)

(LISAPATE) Found battery was not staying charged Spliced 4 new terminals to battery junction box and rerouted new terminals to a larger relay as per Ford customer satisfaction program

15-42-004 - WARRANTY WATER PUMP

(LISAPATE) Tuscaloosa Ford found water leaking from weep hole behind the ac compressor. Removed and replaced all parts as needed. See attached

16-42 - TRANSPORT COOLING SYSTEM

(LISAPATE) Taken to Ford by RC/CW

17-05-020 - RECALL PCM/PROCESSOR ASSEMBLY

(LISAPATE) Reprogrammed PCM to latest IDS release as per Ford emission recall 19e02

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47080

USING DEPT NO: 507121	OPENED DATE: 05/16/2023 13:39:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/17/2023 15:17:50	METER 1 - M: 35012 METER 2 - H: 8359
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/18/2023 07:26:44	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.11	\$56.31	\$0.00	\$91.42
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.04	\$4.69	\$30.32	\$0.00	\$35.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.34	39.80	86.63	5.00	131.43
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/17/2023 09:03:26	05/17/2023 09:05:49	0.04	\$4.69
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/17/2023 08:45:23	05/17/2023 09:03:14	0.30	\$35.11
LABOR					39.80	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP68	CABIN FILTER	30.32	1	\$30.32
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
PARTS					86.63	

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47080

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH CW/SH Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47893

USING DEPT NO: 507121	OPENED DATE: 08/14/2023 08:41:34	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/18/2023 12:58:28	METER 1 - M: 36516 METER 2 - H: 8359
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/22/2023 13:18:56	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$34.15	\$0.00	\$51.85
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.17	\$19.80	\$0.00	\$0.00	\$19.80
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.20	\$23.14	\$0.00	\$0.00	\$23.14
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.06	\$7.64	\$822.39	\$0.00	\$830.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$27.93	\$64.32	\$0.00	\$92.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.82	96.21	920.86	5.00	1,022.07
---------------------	--------------------------	-------------	--------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/14/2023 09:19:03	08/14/2023 09:28:03	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/14/2023 09:00:48	08/14/2023 09:15:00	0.24	\$27.93
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/14/2023 09:19:03	08/14/2023 09:19:03	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/14/2023 09:19:03	08/14/2023 09:19:03	0.00	\$0.00
06-15	INSPECT STEERING	11074414	08/14/2023 09:26:32	08/14/2023 09:26:32	0.00	\$0.00
06-15	INSPECT STEERING	11074414	08/14/2023 09:30:00	08/14/2023 09:40:04	0.17	\$19.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/15/2023 12:03:28	08/15/2023 12:03:28	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/15/2023 13:00:00	08/15/2023 13:03:53	0.06	\$7.64
66-17-013	PERFORM ALIGNMENT	12052187	08/15/2023 15:20:47	08/15/2023 15:32:33	0.20	\$23.14
					LABOR	96.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.50	1	\$13.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.87	4	\$15.48
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.63	2	\$1.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.66	1	\$0.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.90	1	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	2	\$2.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	1.31	1	\$1.31
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000702	TIRE 245/55R18 FSTONE PURSUIT	200.09	4	\$800.34
					PARTS	920.86

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47893

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

06-15 - INSPECT STEERING

(GARAGE) Inspected the steering. Found no issues at this time. SH

66-17-013 - PERFORM ALIGNMENT

(GARAGE) Performed alignment. No adjustments needed. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and balanced 4 tires and relearned the tire positions. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. Needs 4 tires due to excessive shoulder wear. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49019

USING DEPT NO: 507121	OPENED DATE: 11/20/2023 11:56:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/21/2023 10:55:41	METER 1 - M: 39147 METER 2 - H: 9726
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/21/2023 13:16:04	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$13.64	\$64.16	\$0.00	\$77.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.12** **13.64** **64.16** **5.00** **82.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/21/2023 08:44:09	11/21/2023 08:51:05	0.12	\$13.64
LABOR					0.12	13.64

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
PARTS					6	64.16

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49019

Work Order Notes

(LRUSHING) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed and fluid check cw rc fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49712

USING DEPT NO: 507121	OPENED DATE: 02/06/2024 10:20:34	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/06/2024 15:52:29	METER 1 - M: 40349 METER 2 - H: 9726
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/07/2024 15:31:42	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.66	\$80.15	\$0.00	\$131.81
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.44** **51.66** **80.15** **5.00** **136.81**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/06/2024 11:03:57	02/06/2024 11:30:13	0.44	\$51.66
LABOR						51.66

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	19.59	1	\$19.59
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
PARTS						80.15

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49712

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49982

USING DEPT NO: 507121	OPENED DATE: 02/28/2024 09:28:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/29/2024 10:36:06	METER 1 - M: 40687 METER 2 - H: 9726
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/29/2024 15:31:35	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.37	\$43.63	\$0.00	\$0.00	\$43.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.37** **43.63** **0.00** **5.00** **48.63**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11074414	02/28/2024 14:57:28	02/28/2024 15:19:39	0.37	\$43.63
LABOR						43.63

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49982

Work Order Notes

(LISAPATE) Install LB GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240145. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50578

USING DEPT NO: 507121	OPENED DATE: 04/15/2024 13:22:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/18/2024 13:44:51	METER 1 - M: 41404 METER 2 - H: 10310
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/18/2024 15:02:58	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-44-075	REPLACE NEW PURGE SOLENOID VAL	DON	N	N	GARAGE	0.00	\$0.00	\$47.30	\$0.00	\$47.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	47.30	5.00	52.30
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-44-075	REPLACE NEW PURGE SOLENOID VALVE	STICP758	CANISTER PURGE VALVE	47.30	1	\$47.30
PARTS						47.30

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50578

Work Order Notes

(EHANNAH) driver reports GPS giving error messages please see other sheet.

Job Notes

03-44-075 - REPLACE NEW PURGE SOLENOID VALVE

(EHOWELL) Replaced the EVAP purge solenoid valve. Cleared the DTCs. The check engine light is no longer illuminated. EH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found the following DTCs: P2198 O2 Sensor Signal Stuck Rich Bank 2 Sensor 1, P1450 Unable to Bleed Up Fuel Tank Vacuum, and P0456 EVAP Emission Control System Leak Very Small. Consulted Ford service information for DTCs P1450 and P2198. Found a possible cause of the EVAP purge solenoid being stuck open. Unplugged the EVAP purge solenoid and started the vehicle. The valve was pulling a vacuum all of the time (stuck open.) EH

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50788

USING DEPT NO: 507121	OPENED DATE: 05/08/2024 15:48:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/09/2024 10:01:44	METER 1 - M: 41599 METER 2 - H: 10310
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/09/2024 13:16:01	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.64	\$52.89	\$0.00	\$54.53
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.11	\$32.21	\$0.00	\$33.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.02** **2.75** **85.10** **5.00** **92.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	05/09/2024 07:48:23	05/09/2024 07:48:57	0.01	\$1.11
66-PM-PMA	PERFORM OIL CHANGE	12395904	05/09/2024 07:47:09	05/09/2024 07:47:59	0.01	\$1.64
LABOR					2.75	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.67	6	\$34.02
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP68	CABIN FILTER	32.21	1	\$32.21
PARTS					85.10	

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50788

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc - ah

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replaced new cabin filter fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51700

USING DEPT NO:	507121	OPENED DATE:	08/05/2024 14:05:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/09/2024 13:26:55	METER 1 - M:	43152	METER 2 - H: 10310
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/12/2024 07:43:00	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51700

Work Order Notes

(EHANNAH) remove GPS- 87U030240145

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(EHOWELL) Visit Reason Changed On 8/9/2024 1:20 PM By EHOWELL

(EHOWELL) Removed GPS# 87U030240145.

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 52100

USING DEPT NO:	507121	OPENED DATE:	09/11/2024 14:19:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2024 08:24:35	METER 1 - M:	43152	METER 2 - H: 10310
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2024 08:24:55	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 242801 2018 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 52100

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) closed due to year end, will reopen

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 52403

USING DEPT NO: 507121	OPENED DATE: 10/07/2024 11:33:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/08/2024 07:24:13	METER 1 - M: 43152 METER 2 - H: 10310
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/08/2024 10:32:51	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8AR2JGC29280	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-33-006	REMOVE IGNITION LOCK CYLINDER	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-00-999	PERFORM PREPARE UNIT FOR DISPOS	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
RY-33-006	REKEY IGNITION LOCK CYLINDER	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$95.22	\$95.22

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **100.22** **100.22**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>				
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2315035		(\$92.00)				
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2315035		\$92.00				
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2315035		\$95.22				
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00				
COMML									100.22

Work Order Charge Detail

UNIT NO: 242801 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 52403

Work Order Notes

(EKIMBREL) PREP FOR SALE

Job Notes

25-33-006 - REMOVE IGNITION LOCK CYLINDER

66-00-999 - PERFORM PREPARE UNIT FOR DISPOSAL

(EKIMBREL) REMOVED WORDMARKS AND TAG \CW\RC

CH-SP - CHARGE Shop Supplies

RY-33-006 - REKEY IGNITION LOCK CYLINDER

(EKIMBREL) A1 rekeyed 4 locks

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Feb 06 2025 12:39:38 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242801') //Q=