

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37423

USING DEPT NO: 507121	OPENED DATE: 08/25/2020 07:15:28	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/25/2020 07:33:15	METER 1 - M: 103 METER 2 - H: 1
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/25/2020 09:11:47	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	08/25/2020 07:17:59	08/25/2020 07:47:59	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 243749 2020 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 37423

Work Order Notes

(LISAPATE) new unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38824

USING DEPT NO:	507121	OPENED DATE:	01/19/2021 10:01:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2021 10:29:27	METER 1 - M:	792	METER 2 - H: 1
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2021 10:29:27	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38824

Work Order Notes

(LISAPATE) Opened WO for documentation per Tony J. Unit has not been put in service yet. Being held up due to a strobe light issue

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38885

USING DEPT NO: 507121	OPENED DATE: 01/25/2021 07:17:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/26/2021 07:52:15	METER 1 - M: 981 METER 2 - H: 153
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/27/2021 14:36:02	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.15	\$135.21	\$48.37	\$0.00	\$183.58

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.15** **135.21** **48.37** **0.00** **183.58**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/25/2021 14:31:21	01/25/2021 15:40:06	1.15	\$135.21

LABOR **135.21**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	5066517	WSWF RAIN-X -20DEG DEICER GAL	6.89	1	\$6.89

PARTS **48.37**

Work Order Charge Detail

UNIT NO: 243749 2020 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 38885

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 981 Idle hours 153. SH PERFORMED PM.

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39343

USING DEPT NO: 507121	OPENED DATE: 03/09/2021 07:15:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/10/2021 10:07:01	METER 1 - M: 2401 METER 2 - H: 456
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/12/2021 14:08:54	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.22	\$26.45	\$0.00	\$0.00	\$26.45
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$73.32	\$42.80	\$0.00	\$116.12

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.85** **99.77** **42.80** **0.00** **142.57**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	03/09/2021 14:01:33	03/09/2021 14:15:00	0.22	\$26.45
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/09/2021 10:17:55	03/09/2021 10:55:12	0.62	\$73.32
					LABOR	99.77

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.45	1	\$5.45
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
					PARTS	42.80

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39343

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires and inspected brakes. All pads are 13mm. Torqued all lugs to 110ft lbs. JAW

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 2401 Engine hours 584 Idle hours 456. SH Performed PM.

(SHARBIN) Added 1 can of Sea Foam to gas tank. SH

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39634

USING DEPT NO: 507121	OPENED DATE: 04/12/2021 08:32:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/14/2021 10:24:01	METER 1 - M: 3618 METER 2 - H: 719
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/19/2021 09:32:43	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	DON	O	N	GARAGE	0.13	\$14.82	\$0.00	\$0.00	\$14.82
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.10	\$11.47	\$27.68	\$0.00	\$39.15

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.22** **26.29** **27.68** **0.00** **53.97**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11213180	04/13/2021 10:40:51	04/13/2021 10:46:41	0.10	\$11.47
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11213180	04/13/2021 10:33:11	04/13/2021 10:40:43	0.13	\$14.82
					LABOR	26.29

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	JX6Z19N619BA	CABIN FILTER EXPLORER	27.68	1	\$27.68
					PARTS	27.68

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39634

Work Order Notes

(LISAPATE) Per driver bad mildew smell coming thru vents when a/c and heat are on

Job Notes

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(MSIDES) Removed cabin filter and found evidence of a rodent chewing and urinating on the filter. MS

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) Replaced cabin filter and deodorized vent system with non-inventory deodorizer. . MS

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39816

USING DEPT NO: 507121	OPENED DATE: 04/28/2021 07:34:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/29/2021 10:15:25	METER 1 - M: 3839 METER 2 - H: 777
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/29/2021 10:44:47	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT	2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.40	\$165.63	\$41.84	\$0.00	\$207.47

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.40** **165.63** **41.84** **0.00** **207.47**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/28/2021 08:28:17	04/28/2021 09:42:59	1.25	\$146.91
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/28/2021 09:03:00	04/28/2021 09:12:31	0.16	\$18.72
					LABOR	165.63

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	41.84

Work Order Charge Detail

UNIT NO: 243749 2020 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 39816

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 3839 Engine hours 991 Idle hours 777. SH/AMG Performed PM.

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40160

USING DEPT NO: 507121	OPENED DATE: 06/14/2021 07:47:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/28/2021 08:42:34	METER 1 - M: 5062 METER 2 - H: 1074
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/28/2021 12:16:59	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-02-018	INSPECT DOOR MECHANISM	DON	O	N	GARAGE	1.35	\$159.79	\$0.00	\$0.00	\$159.79
15-02-058	WARRANTY DOOR LOCK	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.11	\$12.98	\$0.00	\$0.00	\$12.98

JOB COUNT: 3 **WORK ORDER TOTAL:** **1.46** **172.77** **0.00** **0.00** **172.77**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-02-058	WARRANTY DOOR LOCK	4910000	620395		\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	11915538	06/23/2021 07:30:07	06/23/2021 07:36:43	0.11	\$12.98
06-02-018	INSPECT DOOR MECHANISM	11170580	06/15/2021 07:04:21	06/15/2021 08:25:36	1.35	\$159.79
LABOR					172.77	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40160

Work Order Notes

(IFALLS) Inspect drivers door locking mechanism.

Job Notes

06-02-018 - INSPECT DOOR MECHANISM

(ABLACK) AB took door panel off and found exterior door handle reinforcement was cracked where the door lock cylinder turns. Needs to go to the dealer and be repaired under the SSM 49189 bulletin. Needs revised door handle reinforcements on both front doors. Right and Left doors are messed up.

15-02-058 - WARRANTY DOOR LOCK

(LISAPATE) Town and Country replaced both front door latches and supplied customer with a new key.

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to T&C by RC

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40297

USING DEPT NO: 507121	OPENED DATE: 06/30/2021 07:48:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/30/2021 13:35:37	METER 1 - M: 5141 METER 2 - H: 1074
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/06/2021 09:25:33	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$32.09	\$47.13	\$0.00	\$79.22

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.27** **32.09** **47.13** **0.00** **79.22**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/30/2021 10:00:45	06/30/2021 10:17:04	0.27	\$32.09
					LABOR	32.09

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.78	1	\$9.78
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
					PARTS	47.13

Work Order Charge Detail

UNIT NO: 243749 2020 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 40297

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 5141 hours: 1360 idle hours: 1074 Completed PM topside, Josh was bottomsides. Completed checklist. AMG/JW

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40568

USING DEPT NO: 507121	OPENED DATE: 07/29/2021 07:33:28	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/05/2021 11:47:37	METER 1 - M: 5141 METER 2 - H: 1074
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/09/2021 09:05:27	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT	2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	DON	O	N	GARAGE	1.28	\$150.91	\$0.00	\$0.00	\$150.91
66-01-058	PERFORM EVAC AND RECHARGE FREON	DON	O	N	GARAGE	1.05	\$123.87	\$8.10	\$0.00	\$131.97
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **2.33** **274.78** **8.10** **2.00** **284.88**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	08/04/2021 10:53:42	08/04/2021 11:56:41	1.05	\$123.87
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	08/04/2021 09:36:24	08/04/2021 10:53:08	1.28	\$150.91
LABOR					274.78	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.13	5	\$0.67
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.01	2	\$2.01
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.29	19	\$5.42
PARTS					8.10	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40568

Work Order Notes

(LISAPATE) Per driver A/C is not cooling at all. Was cooling a little at first but after 15 min would go hot. Now just hot

Job Notes

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(ABLACK) AB found ac blowing hot. Found freon was low
(IFALLS) Checked for Freon leak, no leak found at this time.

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(ABLACK) AB performed evac and recharge

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41008

USING DEPT NO: 507121	OPENED DATE: 09/13/2021 15:25:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/15/2021 10:36:59	METER 1 - M: 6660 METER 2 - H: 1428
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/15/2021 13:46:33	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.21	\$31.80	\$0.00	\$37.01
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.64	\$75.49	\$11.00	\$0.00	\$86.49
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.31	\$36.81	\$0.00	\$0.00	\$36.81
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.83	\$98.10	\$48.73	\$0.00	\$146.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5 **WORK ORDER TOTAL:** **1.83** **215.61** **91.53** **2.00** **309.14**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	09/14/2021 13:00:00	09/14/2021 13:38:19	0.64	\$75.36
66-17-030	PERFORM TIRE PATCH	11074414	09/14/2021 12:59:33	09/14/2021 12:59:33	0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	11074414	09/14/2021 11:50:55	09/14/2021 11:50:59	0.00	\$0.13
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/14/2021 11:28:10	09/14/2021 11:46:53	0.31	\$36.81
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/14/2021 11:00:57	09/14/2021 11:03:36	0.04	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/14/2021 10:10:49	09/14/2021 11:00:42	0.83	\$98.10
LABOR					215.61	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.91	1	\$4.91
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.17	1	\$10.17

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.18	1	\$6.18
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	1	\$0.48
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	(1)	(\$0.48)
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	2	\$0.96
PARTS						91.53

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41008

Work Order Notes

(LISAPATE) PM-Nail in RR tire

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-030 - PERFORM TIRE PATCH

(SHARBIN) Found a screw in the left rear tire. Patched tire rechecks good. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Cross rotated tires relearned tire positions and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 6660 Engine hours 1805 Idle hours 1428. SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41552

USING DEPT NO: 507121	OPENED DATE: 11/09/2021 07:19:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/09/2021 15:30:10	METER 1 - M: 7890 METER 2 - H: 1784
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/10/2021 07:55:57	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT	2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.78	\$209.68	\$46.22	\$0.00	\$255.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.78** **209.68** **46.22** **2.00** **257.90**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/09/2021 08:34:12	11/09/2021 09:27:52	0.89	\$105.54
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/09/2021 08:59:18	11/09/2021 09:52:15	0.88	\$104.14
LABOR					209.68	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.96	1	\$8.96
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
PARTS					46.22	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41552

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Completed bottom side. JAW

(AGUERRA) miles: 7890 hours: 2235 idle hours: 1784 Completed PM topside, Josh was bottomside, vehicle has underbody cover. Completed checklist. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42201

USING DEPT NO: 507121	OPENED DATE: 01/27/2022 12:38:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/28/2022 08:11:42	METER 1 - M: 9275 METER 2 - H: 2129
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/28/2022 09:40:25	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$30.06	\$47.84	\$0.00	\$77.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.25** **30.06** **47.84** **2.00** **79.90**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/27/2022 13:59:43	01/27/2022 14:15:00	0.25	\$30.06
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/27/2022 14:16:05	01/27/2022 14:16:05	0.00	\$0.00
LABOR					30.06	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	10.58	1	\$10.58
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS					47.84	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42201

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,RC/SH

MILEAGE-9275

IDLE HRS-2129

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42800

USING DEPT NO: 507121	OPENED DATE: 04/01/2022 13:35:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/13/2022 10:37:36	METER 1 - M: 9275 METER 2 - H: 2129
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 04/14/2022 07:46:29	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT	2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$753.25	\$753.25
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.15	\$17.47	\$146.72	\$0.00	\$164.19
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.17	\$19.54	\$22.62	\$0.00	\$42.16
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.16	\$19.40	\$0.00	\$0.00	\$19.40
16-02-061	TRANSPORT WINDSHIELD	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6 **WORK ORDER TOTAL:** **0.98** **115.41** **169.34** **755.25** **1,040.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	298067		\$753.25
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					755.25

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02-061	TRANSPORT WINDSHIELD	11074414	04/13/2022 07:00:00	04/13/2022 07:30:00	0.50	\$59.00
03-32-002	REPLACE NEW BATTERY	11074414	04/04/2022 07:12:21	04/04/2022 07:21:14	0.15	\$17.47
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/01/2022 15:12:25	04/01/2022 15:22:21	0.17	\$19.54
06-32-002	INSPECT BATTERY	11074414	04/01/2022 14:30:00	04/01/2022 14:39:52	0.16	\$19.40
06-32-002	INSPECT BATTERY	11074414	04/01/2022 14:28:13	04/01/2022 14:28:13	0.00	\$0.00
LABOR						115.41

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	146.72	1	\$146.72
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.19	1	\$10.19
PARTS						169.34

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42800

Work Order Notes

(CHANNELL) replace wipers\ charge and check battery

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield. Pd by CC

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Removed battery and tested. Battery tested bad replaced battery. MS Reset charging system with the scan tool. SH

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers per customer request. Driver side wiper was missing found where the wiper blade arm had been dropped on the windshield and cracked it all the way to the top. Windshield will need to be replaced. SH

06-32-002 - INSPECT BATTERY

(SHARBIN) Battery tested bad will need to be replaced. SH

16-02-061 - TRANSPORT WINDSHIELD

(CHANNELL) transport to glass doctor

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43016

USING DEPT NO: 507121	OPENED DATE: 04/22/2022 13:15:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/05/2022 15:06:20	METER 1 - M: 10310 METER 2 - H: 2342
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/10/2022 13:52:11	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-01-058	WARRANTY EVAC AND RECHARGE FRI	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	1.28	\$151.04	\$0.00	\$0.00	\$151.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.65	\$76.18	\$54.03	\$0.00	\$130.21
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.12	\$13.70	\$42.42	\$0.00	\$56.12
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.54	299.92	96.45	2.00	398.37
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-01-058	WARRANTY EVAC AND RECHARGE FREON	11078175	99424		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11074414	05/05/2022 07:00:00	05/05/2022 07:30:00	0.50	\$59.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11213180	04/25/2022 08:25:33	04/25/2022 09:42:21	1.28	\$151.04
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	04/25/2022 07:22:26	04/25/2022 07:29:24	0.12	\$13.70
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/25/2022 07:05:11	04/25/2022 07:22:14	0.28	\$33.53
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/22/2022 15:06:20	04/22/2022 15:28:01	0.36	\$42.64
LABOR						299.91

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	CAF15046P	CABIN FILTER 2020 INTERCEPTOR	42.42	1	\$42.42
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.63	6	\$33.75
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.57	1	\$9.57
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						96.45

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43016

Work Order Notes

(LISAPATE) PM-A/C is blowing hot air

Job Notes

15-01-058 - WARRANTY EVAC AND RECHARGE FREON

(LISAPATE) Ford evac and recharged a/c system. system held vacuum and did not show any present leaks. Also removed blower motor and looked for dye around evaporator. no leaks present at this time.

16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Taken to Ford by CW-RC

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(MSIDES) Found unit to be leaking freon, will need to go to dealer. MS

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43714

USING DEPT NO: 507121	OPENED DATE: 06/23/2022 07:19:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/27/2022 10:34:46	METER 1 - M: 12063 METER 2 - H: 2723
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/27/2022 15:48:43	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$79.98	\$56.87	\$0.00	\$136.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.68** **79.98** **56.87** **2.00** **138.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/23/2022 09:37:09	06/23/2022 09:46:33	0.16	\$18.49
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/23/2022 09:04:24	06/23/2022 09:35:40	0.52	\$61.49
LABOR					79.98	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.24	1	\$11.24
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.82	6	\$34.92
PARTS					56.87	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43714

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 12063 hours: 3422 idle hours: 2723 Completed PM topside, Josh was bottomsides. Completed checklist. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44107

USING DEPT NO: 507121	OPENED DATE: 07/28/2022 14:47:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/29/2022 15:21:43	METER 1 - M: 13087 METER 2 - H: 3029
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/02/2022 13:56:39	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$17.47	\$46.58	\$0.00	\$64.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.15** **17.47** **46.58** **2.00** **66.05**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/29/2022 10:21:41	07/29/2022 10:30:34	0.15	\$17.47
LABOR					17.47	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.66	1	\$11.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.82	6	\$34.92
PARTS					46.58	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44107

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-13087

ENG HRS-3785

IDLE HRS-3029

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44267

USING DEPT NO: 507121	OPENED DATE: 08/12/2022 08:25:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/16/2022 08:13:25	METER 1 - M: 13739 METER 2 - H: 3152
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/16/2022 09:50:40	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.40	\$47.20	\$11.55	\$0.00	\$58.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.40** **47.20** **11.55** **2.00** **60.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	08/16/2022 07:00:00	08/16/2022 07:24:00	0.40	\$47.20
LABOR					47.20	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-030	PERFORM TIRE PATCH	58102	.75 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.18	1	\$6.18
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	4.31	1	\$4.31
PARTS					11.55	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44267

Work Order Notes

(EKIMBREL) RF TIRE LOW

Job Notes

66-17-030 - PERFORM TIRE PATCH

(EKIMBREL) SH PATCHED RF TIRE. METAL WAS IN TIRE

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44466

USING DEPT NO: 507121	OPENED DATE: 08/25/2022 11:21:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/26/2022 09:51:40	METER 1 - M: 13739 METER 2 - H: 3152
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/26/2022 13:50:02	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT	2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.40	\$47.20	\$5.30	\$0.00	\$52.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.40** **47.20** **5.30** **5.00** **57.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	12052187	08/25/2022 12:04:02	08/25/2022 12:28:02	0.40	\$47.20
24-17-011	REPAIR TIRE PLUG	12052187	08/25/2022 12:04:02	08/25/2022 12:04:02	0.00	\$0.00
24-17-011	REPAIR TIRE PLUG	12052187	08/25/2022 12:04:02	08/25/2022 12:04:02	0.00	\$0.00
LABOR					47.20	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.31	1	\$2.31
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.73	1	\$2.73
66-17-030	PERFORM TIRE PATCH	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
PARTS					5.30	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44466

Work Order Notes

(IFALLS) Nail in rear tire.
uapd

Job Notes

24-17-011 - REPAIR TIRE PLUG

(JWRIGHT) Repaired RR tire. Aired to spec and balanced. Torqued lug nuts to spec. JAW

66-17-030 - PERFORM TIRE PATCH

(EKIMBREL) Repaired RR tire. Aired to spec and balanced. Torqued lug nuts to spec. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44489

USING DEPT NO:	507121	OPENED DATE:	08/29/2022 08:51:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/29/2022 13:21:46	METER 1 - M:	13739	METER 2 - H: 3152
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/29/2022 14:58:01	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-01	INSPECT AIR CONDITIONING, HEAT, VE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44489

Work Order Notes

(CWIGLEY) Driver side blowing hot.
(LISAPATE) Unit went to Ford for a warranty repair. This wo closed due to fiscal year end

Job Notes

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Needs to go to dealer

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44831

USING DEPT NO: 507121	OPENED DATE: 10/03/2022 11:06:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/18/2022 13:32:24	METER 1 - M: 14285 METER 2 - H: 3272
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/19/2022 08:56:19	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-01	WARRANTY AIR CONDITIONING, HEAT,	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	1.44	\$169.69	\$0.00	\$0.00	\$169.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$37.69	\$45.39	\$0.00	\$83.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.76** **207.38** **45.39** **5.00** **257.77**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-01	WARRANTY AIR CONDITIONING, HEAT, VENT	11078175	103753		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/11/2022 15:21:16	10/11/2022 15:40:26	0.32	\$37.69
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11915538	10/10/2022 14:29:57	10/10/2022 15:56:14	1.44	\$169.69
LABOR					207.38	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.56
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.86	1	\$7.86
PARTS					45.39	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44831

Work Order Notes

(LISAPATE) Unit is a Tuscaloosa Ford for a/c not cooling. Previous wo was closed due to fiscal year end.

Job Notes

15-01 - WARRANTY AIR CONDITIONING, HEAT, VENT

(LISAPATE) Tuscaloosa Ford Found evaporator was leaking. Replaced Evap then evac and recharged rechecked ok

16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Taken to Ford by RC

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 45187

USING DEPT NO: 507121	OPENED DATE: 11/07/2022 09:18:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/08/2022 07:48:37	METER 1 - M: 14289 METER 2 - H: 3272
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/09/2022 09:13:43	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT	2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.32	\$37.76	\$0.00	\$0.00	\$37.76
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.32** **37.76** **0.00** **5.00** **42.76**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11074414	11/07/2022 11:39:53	11/07/2022 11:40:34	0.01	\$1.34
CH-32-002	CHARGE BATTERY	11074414	11/07/2022 10:33:32	11/07/2022 10:52:03	0.31	\$36.42
LABOR					37.76	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 45187

Work Order Notes

(LISAPATE) Check battery had to jump off

Job Notes

CH-32-002 - CHARGE BATTERY

(SHARBIN) Charged battery rechecks good ALT charging at 14 volts. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 45715

USING DEPT NO: 507121	OPENED DATE: 01/09/2023 09:06:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/23/2023 07:49:08	METER 1 - M: 14304 METER 2 - H: 3283
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/24/2023 07:14:23	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15-005	INSPECT POWER STEERING PUMP	DON	O	N	GARAGE	0.42	\$49.79	\$0.00	\$0.00	\$49.79
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.80	\$0.00	\$0.00	\$21.80
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.76	207.29	0.00	5.00	212.29
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	01/24/2023 07:00:00	01/24/2023 08:00:00	1.00	\$118.00
CH-32-002	CHARGE BATTERY	11310047	01/23/2023 07:00:00	01/23/2023 07:09:00	0.15	\$17.70
06-15-005	INSPECT POWER STEERING PUMP	11310047	01/09/2023 14:30:00	01/09/2023 14:55:19	0.42	\$49.79
06-15-005	INSPECT POWER STEERING PUMP	11310047	01/09/2023 14:28:32	01/09/2023 14:28:32	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/09/2023 14:30:00	01/09/2023 14:41:05	0.18	\$21.80
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/09/2023 14:24:47	01/09/2023 14:24:47	0.00	\$0.00
LABOR					207.29	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 45715

Work Order Notes

(EHANNAH) pm- replace wipers

INSPECT ALL WHEEL DRIVE- driver reports the All wheel drive light came on, on the way over here, and the car became hard to steer.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-15-005 - INSPECT POWER STEERING PUMP

(IFALLS) The vehicles electric steering was acting abnormal due to a discharged battery. The battery was removed and charged. It tested good afterwards. Reset battery monitoring sensor using learned values using the Ford scan tool. The alternator is charging. No warning lights are illuminated and the vehicle is no longer hard to steer. EH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 19 miles and has 11 idle hours on it. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-32-002 - CHARGE BATTERY

(LISAPATE) The vehicle was acting abnormal due to a discharged battery. The battery was removed and charged. It tested good afterwards. Reset battery monitoring sensor using learned values using the Ford scan tool. The alternator is charging. No warning lights are illuminated and the vehicle is no longer hard to steer. EH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Reset battery monitoring sensor using learned values using the Ford scan tool.

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46748

USING DEPT NO: 507121	OPENED DATE: 04/18/2023 09:47:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/19/2023 10:48:46	METER 1 - M: 15818 METER 2 - H: 3283
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/19/2023 13:22:30	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.23	\$27.37	\$33.72	\$0.00	\$61.09
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.08	\$8.95	\$0.00	\$0.00	\$8.95
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.66	\$77.78	\$0.00	\$0.00	\$77.78
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$43.86	\$46.97	\$0.00	\$90.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.34	157.96	80.69	5.00	243.65
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	04/18/2023 11:11:30	04/18/2023 11:16:03	0.08	\$8.95
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/18/2023 10:30:22	04/18/2023 11:09:55	0.66	\$77.78
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/18/2023 10:16:12	04/18/2023 10:30:07	0.23	\$27.37
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/18/2023 09:53:42	04/18/2023 10:16:00	0.37	\$43.86
LABOR					157.96	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	9.53	1	\$9.53
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.18	1	\$13.18
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.47	1	\$10.47
PARTS					80.69	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46748

Work Order Notes

(EHANNAH) pm- replace wipers- do SI- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires relearned the tire positions and inspected the brakes. Found no issues at this time. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front pads measure 7MM rear pads measure 5MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47405

USING DEPT NO: 507121	OPENED DATE: 06/22/2023 07:43:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/28/2023 14:41:36	METER 1 - M: 17060 METER 2 - H: 3888
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/05/2023 07:49:33	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.16	\$18.32	\$24.06	\$0.00	\$42.38
03-51-041	REPLACE NEW WIPER TRANSMISSION	DON	O	N	GARAGE	0.68	\$80.01	\$136.32	\$0.00	\$216.33
03-51-043	REPLACE NEW WIPER ARM	DON	O	N	GARAGE	0.22	\$26.29	\$59.96	\$0.00	\$86.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$79.42	\$61.91	\$0.00	\$141.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.73	204.04	282.25	5.00	491.29
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML
					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-041	REPLACE NEW WIPER TRANSMISSION LINKAGE	12052187	06/27/2023 14:55:54	06/27/2023 15:36:35	0.68	\$80.01
03-51-043	REPLACE NEW WIPER ARM	11074414	06/27/2023 15:33:45	06/27/2023 15:34:16	0.01	\$1.02
03-51-043	REPLACE NEW WIPER ARM	11074414	06/23/2023 13:40:37	06/23/2023 13:53:28	0.21	\$25.27
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/22/2023 08:30:39	06/22/2023 09:11:02	0.67	\$79.42
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/22/2023 08:11:23	06/22/2023 08:20:42	0.16	\$18.32
					LABOR	204.04

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.83	1	\$10.83
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
03-51-043	REPLACE NEW WIPER ARM	LB5Z17526A	WIPER ARM	59.96	1	\$59.96
03-51-041	REPLACE NEW WIPER TRANSMISSION LINKAGE	LB5Z17566A	WIPER ARM TRANSMISSION/LINKAGE	136.32	1	\$136.32

Work Order Charge Detail

PARTS	282.25
--------------	---------------

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47405

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wiper blades per customer request. Discovered right side wiper blade was not contacting the windshield properly. Adjusted the wiper arm and rechecked for proper operation all good. SH

03-51-041 - REPLACE NEW WIPER TRANSMISSION LINKAGE

(LISAPATE) Finished removing the wiper linkages and installed new. Found no other issues. JAW

03-51-043 - REPLACE NEW WIPER ARM

(SHARBIN) Replaced the passenger side wiper arm. SH

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) Cancelled from Work Order# 47405. By User ID EHANNAH on 6/22/2023 7:48 AM.

The job was restored for Work Order# 47405. By User ID EKIMBREL on 6/22/2023 8:29 AM.

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47470

USING DEPT NO: 507121	OPENED DATE: 06/29/2023 09:08:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/30/2023 10:36:57	METER 1 - M: 17060 METER 2 - H: 3888
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/28/2023 21:01:06	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.50** **59.00** **0.00** **5.00** **64.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	2109986		(\$776.25)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2109986		\$776.25
03-02-061	REPLACE NEW WINDSHIELD	11078716	2109986		(\$419.75)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2109986		\$419.75
03-02-061	REPLACE NEW WINDSHIELD	11078716	2109986		\$0.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	11399745	06/30/2023 07:00:00	06/30/2023 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47470

Work Order Notes

(EHANNAH) replace new windshield- Glass Dr.

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed and recal new windshield. Pd by CC

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47574

USING DEPT NO: 507121	OPENED DATE: 07/12/2023 07:01:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/06/2023 08:36:23	METER 1 - M: 18055 METER 2 - H: 4212
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/11/2023 11:18:48	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-01	INSPECT AIR CONDITIONING, HEAT, VE	DON	O	N	GARAGE	1.05	\$123.41	\$0.81	\$0.00	\$124.22
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.32	\$37.73	\$0.00	\$0.00	\$37.73
15-01	WARRANTY AIR CONDITIONING, HEAT,	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
15-21-002	WARRANTY CV AXLES/SEALS	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
15-21-005	WARRANTY CV AXLE BOOT	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
16-21	TRANSPORT AXLES - DRIVEN, FRONT :	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	1.40	\$164.64	\$0.00	\$0.00	\$164.64
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.19	\$140.32	\$836.54	\$0.00	\$976.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.59	\$69.75	\$56.58	\$0.00	\$126.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 11 **WORK ORDER TOTAL:** **6.04** **712.85** **893.93** **5.00** **1,611.78**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11078175	114736		\$0.00
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11078175	114736		\$0.00
15-21-005	WARRANTY CV AXLE BOOT	11099772	100610831		\$0.00
15-01	WARRANTY AIR CONDITIONING, HEAT, VENT	11078175	114736		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
15-21-002	WARRANTY CV AXLES/SEALS	11078175	116252		\$0.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-21-002	TRANSPORT CV AXLES/SEALS	11399745	09/06/2023 07:00:00	09/06/2023 12:00:00	(5.00)	(\$590.00)
16-21-002	TRANSPORT CV AXLES/SEALS	11399745	09/06/2023 07:00:00	09/06/2023 12:00:00	5.00	\$590.00
16-21	TRANSPORT AXLES - DRIVEN, FRONT STEERING	11399745	09/06/2023 07:00:00	09/06/2023 07:30:00	0.50	\$59.00

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11915538	09/06/2023 07:00:00	09/06/2023 07:30:00	0.50	\$59.00
16-21	TRANSPORT AXLES - DRIVEN, FRONT STEERING	11399745	09/06/2023 07:00:00	09/06/2023 07:30:00	0.50	\$59.00
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11310047	07/13/2023 10:57:15	07/13/2023 12:00:00	1.05	\$123.41
66-17-013	PERFORM ALIGNMENT	11310047	08/23/2023 14:30:00	08/23/2023 15:34:46	1.08	\$127.37
66-17-013	PERFORM ALIGNMENT	11310047	08/23/2023 13:56:03	08/23/2023 14:15:00	0.32	\$37.27
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/23/2023 07:08:39	08/23/2023 08:06:24	0.96	\$113.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/22/2023 15:13:41	08/22/2023 15:27:17	0.23	\$26.75
06-15	INSPECT STEERING	11074414	08/21/2023 08:18:47	08/21/2023 08:37:58	0.32	\$37.73
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/21/2023 07:43:19	08/21/2023 08:18:47	0.59	\$69.75

LABOR 712.86

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11894	TIRE 255/60R18 FTONE FHAWK PST	200.42	4	\$801.66
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	6	\$0.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	1.31	1	\$1.31
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	1.22	2	\$2.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.90	2	\$1.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.66	3	\$1.98
66-17-028	PERFORM MOUNT AND BALANCE TIRES	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.84	4	\$27.36
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71

PARTS 893.93

Work Order Charge Detail

UNIT NO: 243749 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 47574

Work Order Notes

(EHANNAH) A/C not working- driver reports not blowing at all.
(GARAGE) Also, found LF cv axle slinging grease. EH
(EHANNAH) pm-wipers

Job Notes

Work Order Charge Detail

03-51-038 - REPLACE NEW WIPER BLADES

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(GARAGE) Found vehicle low on 1234YF refrigerant. Recovered .35 lb. of refrigerant. Did not recharge AC system. Found history of vehicle being low on refrigerant in 2021 and 2022. Tuscaloosa Ford replaced the evaporator in October.

Inspected the system for leaks using a black light, but did not find any. The vehicle is still under 3 years and 36,000 miles. Vehicle is going back to Tuscaloosa Ford. EH

06-15 - INSPECT STEERING

(GARAGE) Inspected the steering. Found the left front outer CV boot leaking grease. Found no other issues at this time. SH

15-01 - WARRANTY AIR CONDITIONING, HEAT, VENT

(LISAPATE) Tuscaloosa Ford found low and high side Shrader valves were leaking. Installed new valves. Verified repair.

15-21 - WARRANTY AXLES - DRIVEN, FRONT STEERING

15-21-002 - WARRANTY CV AXLES/SEALS

(LISAPATE) Long Lewis Ford Removed and replaced RF axle shaft was leaking

15-21-005 - WARRANTY CV AXLE BOOT

(LISAPATE) Tuscaloosa Ford replaced LF axle shaft was leaking

16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Taken to Ford by RC/CW

16-21 - TRANSPORT AXLES - DRIVEN, FRONT STEERING

(LISAPATE) Taken to Ford by RC/CW

16-21-002 - TRANSPORT CV AXLES/SEALS

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed 4 wheel alignment. Calibrated lane keep assist during road test. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires and relearned the tire positions. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. Vehicle needs 4 tires due to tread depth and shoulder wear. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

WA-01 - WASH AIR CONDITIONING, HEAT, VENT

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48848

USING DEPT NO: 507121	OPENED DATE: 11/06/2023 11:13:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/10/2023 13:46:57	METER 1 - M: 18442 METER 2 - H: 4340
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/10/2023 14:30:36	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT	2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$67.88	\$64.16	\$0.00	\$132.04
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.58** **67.88** **64.16** **5.00** **137.04**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/06/2023 13:16:41	11/06/2023 13:51:12	0.58	\$67.88
LABOR						67.88

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
PARTS						64.16

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48848

Work Order Notes

(LRUSHING) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed and fluid check fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49343

USING DEPT NO: 507121	OPENED DATE: 01/05/2024 07:07:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/08/2024 15:50:56	METER 1 - M: 19094 METER 2 - H: 4611
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/09/2024 07:31:30	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-33-004	INSPECT SPARK PLUGS	DON	N	N	GARAGE	0.41	\$48.81	\$0.00	\$0.00	\$48.81
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	4.01	\$472.79	\$0.00	\$0.00	\$472.79

JOB COUNT: 3	WORK ORDER TOTAL:	4.42	521.60	0.00	5.00	526.60
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-33-004	INSPECT SPARK PLUGS	11310047	01/05/2024 13:30:02	01/05/2024 13:54:51	0.41	\$48.81
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	01/05/2024 13:03:13	01/05/2024 13:20:09	0.28	\$33.30
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	01/05/2024 07:43:49	01/05/2024 11:27:17	3.72	\$439.48
LABOR					521.59	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49343

Work Order Notes

(EHANNAH) check engine light is on

Job Notes

06-33-004 - INSPECT SPARK PLUGS

(EHOWELL) Removed the #6 spark plug. Inspected the plug and the ignition coil for arcing and carbon tracking. No concerns were found. Performed a road test and examined the misfire graphic. Also, examined graphic while placing the vehicle under a load. The vehicle is not misfiring at this time. EH .25 HR

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC: P0306 Cylinder 6 Misfire Detected. The check engine light was not on. Checked TSBs. EH

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49609

USING DEPT NO: 507121	OPENED DATE: 01/29/2024 08:08:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/13/2024 08:38:17	METER 1 - M: 19474 METER 2 - H: 5837
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/13/2024 09:29:34	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$70.24	\$60.56	\$0.00	\$130.80
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.10	\$11.80	\$33.45	\$0.00	\$45.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.70** **82.04** **94.01** **5.00** **181.05**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	02/13/2024 07:00:00	02/13/2024 07:06:00	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/29/2024 13:01:11	01/29/2024 13:36:54	0.60	\$70.24
LABOR					82.04	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	33.45	1	\$33.45
PARTS					94.01	

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49609

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter. FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50031

USING DEPT NO: 507121	OPENED DATE: 03/01/2024 14:20:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/04/2024 08:54:32	METER 1 - M: 19667 METER 2 - H: 5837
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/04/2024 14:11:10	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.07	\$7.93	\$0.00	\$0.00	\$7.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.07** **7.93** **0.00** **5.00** **12.93**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	12201267	03/01/2024 15:33:47	03/01/2024 15:37:49	0.07	\$7.93
LABOR						7.93

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50031

Work Order Notes

(EHANNAH) install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GRCOOK) Installed GPS SN:87U030240192 in unit 9335B-GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50561

USING DEPT NO: 507121	OPENED DATE: 04/12/2024 13:50:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/15/2024 09:53:55	METER 1 - M: 20289 METER 2 - H: 5837
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/15/2024 12:23:19	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT	2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.79	\$68.30	\$0.00	\$118.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.42** **49.79** **68.30** **5.00** **123.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/12/2024 14:32:38	04/12/2024 14:57:57	0.42	\$49.79
LABOR					49.79	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.67	6	\$34.02
PARTS					68.30	

Work Order Charge Detail

UNIT NO: 243749 2020 FORD INTERCEPTOR EXPLORER **WORK ORDER NO:** 50561

Work Order Notes

(LRUSHING) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51054

USING DEPT NO:	507121	OPENED DATE:	06/05/2024 16:21:30	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2024 08:24:50	METER 1 - M:	21143	METER 2 - H:	5837		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2024 08:57:35	IN-SERVICE DATE:	08/20/2020				
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB2LGC15613				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-02-074	RECALL WINDOW SWITCH	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51054

Work Order Notes

(EHANNAH) prep and schedule- RECALL for power window switch

Job Notes

17-02-074 - RECALL WINDOW SWITCH

(EHANNAH) LL Ford came to our shop for Recall for power window switch

17-GA-005 - RECALL Scheduling and Preparation

(EHANNAH) prep and scheduling by Denise

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51267

USING DEPT NO: 507121	OPENED DATE: 06/24/2024 08:00:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/25/2024 08:42:47	METER 1 - M: 21855 METER 2 - H: 5837
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/25/2024 10:24:47	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$76.31	\$0.00	\$76.31
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.00** **76.31** **5.00** **81.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.88	(6)	(\$47.25)
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.88	6	\$47.25
PARTS						76.31

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51267

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-FC,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 21,855

Idle Hours, 5,216

Total Hours, 6,455

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51677

USING DEPT NO: 507121	OPENED DATE: 08/02/2024 08:05:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/13/2024 07:35:12	METER 1 - M: 22291 METER 2 - H: 5837
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/13/2024 11:22:33	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$223.29	\$0.00	\$223.29
06-32-002	INSPECT BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-32-002	SCAN OUT BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.00** **0.00** **223.29** **5.00** **228.29**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	223.29	1	\$223.29
PARTS						223.29

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51677

Work Order Notes

(EHANNAH) inspect battery- and possibly what is cause the battery to drain- SI

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) Replaced battery. Reset the Battery sensor. alternator charging at 13.9 volts. Let unit sit overnight and battery stayed charged overnight. Found no other issues. JAW

06-32-002 - INSPECT BATTERY

(GARAGE) Inspected battery at fully charged and found after 3 hrs it started draining itself while not connected to unit. needs new battery.
JAW

66-79-003 - PERFORM SAFETY INSPECTION

CH-SP - CHARGE Shop Supplies

SO-32-002 - SCAN OUT BATTERY

(EHOWELL) The scan tool was used to reset the battery monitoring system.

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 52007

USING DEPT NO: 507121	OPENED DATE: 09/04/2024 07:17:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/09/2024 15:23:17	METER 1 - M: 23504 METER 2 - H: 5837
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/09/2024 15:23:17	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>		
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	N	N	GARAGE	0.00	\$0.00	\$259.35	\$0.00	\$259.35		
24-78-038	REPAIR UNDER CARRIAGE SKID PLATE	DON	N	N	GARAGE	0.00	\$0.00	\$17.82	\$0.00	\$17.82		
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00		
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00		
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$69.30	\$0.00	\$69.30		
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00		
JOB COUNT: 6						WORK ORDER TOTAL:		0.00	0.00	346.47	5.00	351.47

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWRZ362231	REAR BRAKE PADS	71.85	1	\$71.85
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBRSB682614	REAR ROTORS	93.75	2	\$187.50
24-78-038	REPAIR UNDER CARRIAGE SKID PLATES	W715060S450B	CLIPS FOR SKID PLATES EXPL INT	4.46	4	\$17.82
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	14.07	1	\$14.07
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.02	6	\$42.12
					PARTS	346.47

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 52007

Work Order Notes

(EHANNAH) pm- SI

Job Notes

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(GARAGE) Replaced rear pads and rotors. JAW

24-78-038 - REPAIR UNDER CARRIAGE SKID PLATES

(GARAGE) While changing oil and removing the skid pan, skid pan was installed wrong on last PM. Installed skid pan after PM and put it back the correct way and had to add some new screws that were also missing-GC

66-13-130 - PERFORM Burnish Brakes

(GARAGE) Burnished brakes. JAW

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed safety inspection, found no issues at this time-GC
Rear brakes need new rotors and pads. Front brake pads are 6mm-GC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 23,504

Idle Hours, 5,500

Total Hours, 6,839

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 53133

USING DEPT NO: 507121	OPENED DATE: 12/13/2024 07:51:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/16/2024 11:50:11	METER 1 - M: 27523 METER 2 - H: 5909
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/16/2024 12:40:04	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT	2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$62.57	\$0.00	\$62.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.00** **62.57** **5.00** **67.57**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.03	1	\$11.03
PARTS						62.57

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 53133

Work Order Notes

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- topside,

JR- pit

perform PM, changed oil and filter, checked air filters, checked fluids, checked tires and tire pressures

25190 miles, 5905 idle hours, 7346 total hours

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 54111

USING DEPT NO: 507121	OPENED DATE: 03/24/2025 07:44:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/01/2025 13:47:41	METER 1 - M: 27672 METER 2 - H: 6346
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/02/2025 12:46:19	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer	UNIT SERIAL NO: 1FM5K8AB2LGC15613	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$67.48	\$0.00	\$67.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	67.48	5.00	72.48
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	DG7408	GASKET	1.62	1	\$1.62
66-PM-PMA	PERFORM OIL CHANGE	DP7825	OIL DRAIN PLUG	2.49	1	\$2.49
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	12.98	1	\$12.98
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.96	1	\$11.96
PARTS						67.48

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 54111

Work Order Notes

(EHANNAH) pm- inspect tires for ware
(GARAGE) Pending approval for 4 tires & alignment.
(EKIMBREL) VEHICLE IS BEING SOLD, DENIED REPAIRS.

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) FJ- Inspected tires. Severe wear on all 4 tires. 4 tires & alignment quoted.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- PM. Mileage is 27,672. Idle hours: 6396. Engine hours: 7977. Oil change, topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths.
(EKIMBREL) FJ REPLACED OIL DRAIN PLUG AND PLUG GASKET.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243749 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 54423

USING DEPT NO: 507121	OPENED DATE: 04/08/2025 13:27:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: OPEN	COMPLETED DATE:	METER 1 - M: 27672 METER 2 - H: 6346
WO VISIT REASON: UNSCHEDULED	CLOSED DATE:	IN-SERVICE DATE: 08/20/2020
TECH SPEC NO: 20FORDEXPLINT 2020 Ford Interceptor Explorer		UNIT SERIAL NO: 1FM5K8AB2LGC15613

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	WFA	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 243749 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 54423

Work Order Notes

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Apr 08 2025 13:35:07 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243749') //Q=