

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 37574

USING DEPT NO:	507121	OPENED DATE:	09/11/2020 09:02:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/11/2020 09:03:30	METER 1 - M:	132	METER 2 - H: 5
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2020 14:11:08	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	09/11/2020 09:02:55	09/11/2020 09:32:55	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 37574

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 38831

USING DEPT NO:	507121	OPENED DATE:	01/19/2021 11:15:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2021 11:15:36	METER 1 - M:	357	METER 2 - H: 5
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2021 11:15:36	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: **243754** **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** **38831**

Work Order Notes

(LISAPATE) Opened WO for documentation per Tony J. Unit has not been put in service yet. Being held up due to a strobe light issue

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 38886

USING DEPT NO:	507121	OPENED DATE:	01/25/2021 07:19:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/26/2021 09:31:57	METER 1 - M:	474	METER 2 - H: 15
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/27/2021 14:33:37	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$37.24	\$0.00	\$0.00	\$37.24

JOB COUNT: 1	WORK ORDER TOTAL:	0.32	37.24	0.00	0.00	37.24
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/26/2021 07:05:22	01/26/2021 07:24:18	0.32	\$37.24
					LABOR	37.24

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 38886

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 474 Engine hours 27 Idle hours 15. Did not drop oil due to low mileage and hours. Checked fluids battery tire pressure and updated oil change sticker. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39792

USING DEPT NO:	507121	OPENED DATE:	04/23/2021 12:30:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/26/2021 14:40:38	METER 1 - M:	1868	METER 2 - H: 281
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2021 08:39:16	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$37.69	\$0.00	\$76.63

JOB COUNT: 1	WORK ORDER TOTAL:	0.33	38.94	37.69	0.00	76.63
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/23/2021 13:47:28	04/23/2021 14:07:16	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/23/2021 13:47:28	04/23/2021 13:52:33	(0.08)	(\$10.00)
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/23/2021 13:47:28	04/23/2021 13:52:33	0.08	\$10.00
					LABOR	38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	37.69

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39792

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. SH/JAW

MILEAGE-1868

ENG HRS-364

IDLE HRS-281

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40199

USING DEPT NO:	507121	OPENED DATE:	06/17/2021 15:01:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/27/2021 10:34:35	METER 1 - M:	3732	METER 2 - H: 582
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	07/27/2021 15:32:40	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.33	\$30.54	\$0.00	\$32.87
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.64	\$75.32	\$6.53	\$0.00	\$81.85
66-79-002	PERFORM SERVICE CALL	DON	O	N	GARAGE	0.27	\$31.47	\$0.00	\$0.00	\$31.47
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$33.83	\$47.04	\$0.00	\$80.87

JOB COUNT: 4	WORK ORDER TOTAL:	1.21	142.95	84.11	0.00	227.06
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11901357	07/23/2021 15:26:14	07/23/2021 15:29:07	0.05	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/23/2021 15:12:36	07/23/2021 15:15:19	0.05	\$5.34
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/23/2021 15:13:19	07/23/2021 15:14:30	0.02	\$2.33
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/23/2021 14:58:25	07/23/2021 15:12:54	0.24	\$28.48
66-17-030	PERFORM TIRE PATCH	11901357	06/18/2021 07:02:35	06/18/2021 07:38:00	0.59	\$69.65
66-79-002	PERFORM SERVICE CALL	11901357	06/17/2021 15:38:19	06/17/2021 15:54:19	0.27	\$31.47
					LABOR	142.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	11.97	1	\$11.97
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	8.85	1	\$8.85
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	9.72	1	\$9.72
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-17-030	PERFORM TIRE PATCH	21097	TPMS NICKEL VALVE CORE	0.29	1	\$0.29
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.78	1	\$9.78
66-17-030	PERFORM TIRE PATCH	14042	PATCH 3/8 PILOT WIRE	5.73	1	\$5.73
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.51	1	\$0.51
					PARTS	84.11

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40199

Work Order Notes

(LISAPATE) service call tire-PM due

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wipers

24-17-011 - REPAIR TIRE PLUG

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) Repaired and balanced L/R tire, rechecked for leak, all good. AMG

66-79-002 - PERFORM SERVICE CALL

(AGUERRA) Put spare on and brought damaged tire to shop for repair. AMG AB

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/AMG
MILEAGE-3732

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41105

USING DEPT NO:	507121	OPENED DATE:	09/22/2021 15:00:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/23/2021 10:06:07	METER 1 - M:	5610	METER 2 - H: 882
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2021 07:43:00	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.38	\$31.80	\$0.00	\$39.18
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$50.97	\$42.21	\$0.00	\$93.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.49	58.35	74.01	2.00	134.36
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/22/2021 15:35:17	09/22/2021 15:39:02	0.06	\$7.38
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/22/2021 15:09:09	09/22/2021 15:35:04	0.43	\$50.97
LABOR						58.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.86	1	\$4.86
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.17	1	\$10.17
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
PARTS						74.01

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41105

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 5610 Engine hours 1107 Idle hours 882. SH/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41730

USING DEPT NO:	507121	OPENED DATE:	11/30/2021 07:53:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2021 10:32:52	METER 1 - M:	6992	METER 2 - H: 1197
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	12/02/2021 12:31:00	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$70.44	\$46.74	\$0.00	\$117.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.60 70.44 46.74 2.00 119.18

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/30/2021 10:05:00	11/30/2021 10:27:51	0.38	\$44.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/30/2021 10:04:47	11/30/2021 10:17:45	0.22	\$25.50
LABOR						70.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.48	1	\$9.48
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
PARTS						46.74

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41730

Work Order Notes

(IFALLS) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG

MILEAGE-6992

IDLE HRS-1197

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42293

USING DEPT NO:	507121	OPENED DATE:	02/08/2022 08:16:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/16/2022 08:39:42	METER 1 - M:	7667	METER 2 - H: 1197
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2022 08:20:35	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-35-016	WARRANTY POWER MIRROR SWITCH	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-35	TRANSPORT MULTI-FUNC ELECTRON/I	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	2.00	61.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
15-35-016	WARRANTY POWER MIRROR SWITCH	11078175	96816		\$0.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-35	TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS	11915538	02/16/2022 07:00:00	02/16/2022 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: **243754** **2020 FORD INTERCEPTOR EXPLORER**

WORK ORDER NO: **42293**

Work Order Notes

(LISAPATE) Driver mirror switch is inop take to Ford to repair under warranty

Job Notes

15-35-016 - WARRANTY POWER MIRROR SWITCH

(LISAPATE) Ford installed a new mirror switch under warranty

16-35 - TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS

(LISAPATE) Taken to Ford by RC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42551

USING DEPT NO:	507121	OPENED DATE:	03/03/2022 09:46:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/07/2022 14:38:05	METER 1 - M:	7853	METER 2 - H: 1778
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2022 07:20:53	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.52	\$31.82	\$0.00	\$36.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.55	\$43.49	\$0.00	\$72.04
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.28	33.07	75.31	2.00	110.38
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	03/03/2022 15:15:14	03/03/2022 15:17:32	0.04	\$4.52
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/03/2022 15:09:17	03/03/2022 15:15:05	0.10	\$11.41
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/03/2022 14:56:49	03/03/2022 15:05:32	0.15	\$17.14
LABOR						33.07

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.23	1	\$6.23
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						75.31

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42551

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW

MILEAGE-7853

HRS-1778

IDLE-1451

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43461

USING DEPT NO:	507121	OPENED DATE:	06/01/2022 10:43:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2022 15:14:01	METER 1 - M:	9636	METER 2 - H: 1823
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/03/2022 12:39:48	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$32.22	\$61.91	\$0.00	\$94.13
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.08	\$9.60	\$20.91	\$0.00	\$30.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.35	41.82	82.82	2.00	126.64
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	11901357	06/02/2022 14:10:07	06/02/2022 14:15:00	0.08	\$9.60
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/01/2022 11:43:37	06/01/2022 12:00:00	0.27	\$32.22
					LABOR	41.82

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	16.92	1	\$16.92
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	KSLST5501	K-SEAL COOLANT LEAK STOP	20.91	1	\$20.91
66-PM-PMA	PERFORM OIL CHANGE	KSLST5501	K-SEAL COOLANT LEAK STOP	20.91	(1)	(\$20.91)
66-PM-PMA	PERFORM OIL CHANGE	KSLST5501	K-SEAL COOLANT LEAK STOP	20.91	1	\$20.91
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.15	1	\$11.15
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.64	6	\$33.84
					PARTS	82.82

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43461

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 9636 hours: 2230 idle hours: 1823 Completed PM top and bottom side. Completed checklist. AMG/AMG

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

(AGUERRA) Added stop leak to coolant system then topped off system. Recheck system in a few days for level drop. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44875

USING DEPT NO:	507121	OPENED DATE:	10/05/2022 11:07:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/06/2022 11:18:57	METER 1 - M:	10876	METER 2 - H: 1985
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/06/2022 12:07:06	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.55	\$65.36	\$54.26	\$0.00	\$119.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.55	65.36	54.26	5.00	124.62
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/05/2022 14:57:06	10/05/2022 15:28:18	0.52	\$61.36
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/05/2022 14:54:23	10/05/2022 14:56:25	0.03	\$4.00
LABOR						65.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	7.10	6	\$42.57
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.69	1	\$11.69
PARTS						54.26

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44875

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45185

USING DEPT NO:	507121	OPENED DATE:	11/07/2022 08:34:41	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	12/16/2022 08:09:36	METER 1 - M:	11922	METER 2 - H:	1985				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/16/2022 15:25:49	IN-SERVICE DATE:	09/10/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer			UNIT SERIAL NO:	1FM5K8AB0LGC15612					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.72	\$84.63	\$0.00	\$0.00	\$84.63
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$61.52	\$43.10	\$0.00	\$104.62
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.10	\$11.80	\$30.95	\$0.00	\$42.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:					1.34	157.95	74.05	5.00	237.00
--------------	-------------------	--	--	--	--	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	12/16/2022 07:00:00	12/16/2022 07:06:00	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	12201267	12/08/2022 08:38:08	12/08/2022 09:09:25	0.52	\$61.52
66-79-002	PERFORM SERVICE CALL	11901357	11/07/2022 09:20:13	11/07/2022 10:03:15	0.72	\$84.63
LABOR						157.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.66	1	\$5.66
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	30.95	1	\$30.95
PARTS						74.05

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45185

Work Order Notes

(LISAPATE) Per driver unit was leaking fluid bad Saturday night, unit was parked in Publix parking lot and left there.

Job Notes

66-79-002 - PERFORM SERVICE CALL

(AGUERRA) Verified transmission leak, requested tow truck to take to dealership for warranty repairs. AMG
(IFALLS) Tuscaloosa ford did not have the invoice ready
will add later

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM changed oil and oil filter-AG/GC checked fluids and tires and tire pressure, battery good
Miles-11,984
(GARAGE) Add 1/2 hr for dropping skid pan

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) changed cabin air filter-GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46525

USING DEPT NO:	507121	OPENED DATE:	03/24/2023 09:46:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/03/2023 10:32:27	METER 1 - M:	12917	METER 2 - H: 2436
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2023 14:04:23	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	0.20	\$24.03	\$0.00	\$0.00	\$24.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$31.34	\$76.17	\$0.00	\$107.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:		0.47	55.37	76.17	5.00	136.54
--------------	-------------------	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-42	DIAGNOSE COOLING SYSTEM	12052187	03/27/2023 13:16:24	03/27/2023 13:23:59	0.13	\$14.91
35-42	DIAGNOSE COOLING SYSTEM	11310047	03/27/2023 07:59:44	03/27/2023 08:04:22	0.08	\$9.11
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2023 13:32:34	03/24/2023 13:48:30	0.27	\$31.34
LABOR						55.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	19.77	1	\$19.77
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
PARTS						76.17

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46525

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

35-42 - DIAGNOSE COOLING SYSTEM

(JWRIGHT) Added coolant. Pressurized to 20psi for 1 hour and found no leak. Per EH let unit go for now. JAW

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM. NO Coolant in the reservoir. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47199

USING DEPT NO:	507121	OPENED DATE:	05/30/2023 14:18:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/07/2023 14:01:20	METER 1 - M:	15175	METER 2 - H: 2679
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/12/2023 15:31:05	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$6.62	\$34.03	\$0.00	\$40.65
15-42-006	WARRANTY THERMOSTATS	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.39	\$46.58	\$0.00	\$0.00	\$46.58
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$26.09	\$61.82	\$0.00	\$87.91
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
JOB COUNT: 6		WORK ORDER TOTAL:				1.17	138.29	95.85	5.00	239.14

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
15-42-006	WARRANTY THERMOSTATS	11078175	113207		\$0.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-42	TRANSPORT COOLING SYSTEM	11399745	06/12/2023 07:00:00	06/12/2023 07:30:00	0.50	\$59.00
66-79-003	PERFORM SAFETY INSPECTION	11074414	05/31/2023 07:48:15	05/31/2023 07:50:05	0.03	\$3.61
66-79-003	PERFORM SAFETY INSPECTION	11074414	05/30/2023 15:21:57	05/30/2023 15:43:48	0.36	\$42.97
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/30/2023 14:57:58	05/30/2023 15:01:20	0.06	\$6.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/30/2023 14:44:28	05/30/2023 14:57:44	0.22	\$26.09
					LABOR	138.29

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.73	1	\$10.73
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
PARTS						95.85

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47199

Work Order Notes

(EHANNAH) pm- replace wiper- do SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

15-42-006 - WARRANTY THERMOSTATS

(EKIMBREL) tusc ford warrantied thermostat

16-42 - TRANSPORT COOLING SYSTEM

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Vehicle has a coolant leak possible upper radiator hose. Found no other issues at this time. Front brake pads measure 10MM. Read brake pads measure 6MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM. No coolant in the resivor and the left front CV boot ID leaking grease.

(SHARBIN) CV Axle has been replaced area was not cleaned up. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47655

USING DEPT NO:	507121	OPENED DATE:	07/19/2023 14:48:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/19/2023 14:55:52	METER 1 - M:	15894	METER 2 - H: 2679
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/20/2023 08:51:39	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-21-005	WARRANTY CV AXLE BOOT	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-21-005	WARRANTY CV AXLE BOOT	11099772	100610834		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47655

Work Order Notes

(LISAPATE) Left front axle boot is torn

Job Notes

15-21-005 - WARRANTY CV AXLE BOOT

(LISAPATE) Long Lewis tech removed and replaced LF axle boot.

17-21-005 - RECALL CV AXLE BOOT

(LISAPATE) Long Lewis tech came to the shop and replaced the LF axle shaft half shaft. Rechecked ok

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47805

USING DEPT NO:	507121	OPENED DATE:	08/02/2023 09:26:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/09/2023 14:41:08	METER 1 - M:	16209	METER 2 - H: 2679
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/10/2023 07:43:49	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-02-053	INSPECT WINDOW REGULATOR	DON	N	N	GARAGE	0.08	\$9.34	\$0.00	\$0.00	\$9.34
15-02-074	WARRANTY WINDOW SWITCH	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
15-34-011	WARRANTY TAILLIGHT ASSEMBLY	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.58	68.34	0.00	5.00	73.34
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-02-074	WARRANTY WINDOW SWITCH	11078175	115413		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11399745	08/09/2023 07:00:00	08/09/2023 07:30:00	0.50	\$59.00
06-02-053	INSPECT WINDOW REGULATOR	12052187	08/02/2023 10:48:21	08/02/2023 10:53:06	0.08	\$9.34
LABOR						68.34

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47805

Work Order Notes

(LISAPATE) RR window is down will not go up

Job Notes

06-02-053 - INSPECT WINDOW REGULATOR

(GARAGE) Inspected and found the window regulator is bad and window motor is extremely hot for the RR. Lisa called and it will be covered under warranty. JAW

15-02-074 - WARRANTY WINDOW SWITCH

(LISAPATE) Tuscaloosa Ford installed new RR window switch

15-34-011 - WARRANTY TAILLIGHT ASSEMBLY

(LISAPATE) Tuscaloosa Ford installed new LR taillight assy stated had water in it and was flickering.

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Ford by RC/CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48549

USING DEPT NO:	507121	OPENED DATE:	10/16/2023 09:42:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/17/2023 09:08:40	METER 1 - M:	16913	METER 2 - H: 3161
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2023 08:10:31	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$72.41	\$64.16	\$0.00	\$136.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.61	72.41	64.16	5.00	141.57
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/16/2023 11:00:18	10/16/2023 11:37:07	0.61	\$72.41
					LABOR	72.41

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
					PARTS	64.16

Work Order Charge Detail

UNIT NO:2437542020 FORD INTERCEPTOR EXPLORERWORK ORDER NO:48549

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49252

USING DEPT NO:	507121	OPENED DATE:	12/14/2023 07:03:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/20/2023 15:10:50	METER 1 - M:	17283	METER 2 - H: 3349
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/21/2023 07:34:59	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-44-029	REPLACE NEW FUEL TANK PRESSURE	DON	N	N	GARAGE	2.40	\$283.27	\$368.46	\$0.00	\$651.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	N	N	GARAGE	13.61	\$1,605.65	\$0.00	\$0.00	\$1,605.65

JOB COUNT: 3	WORK ORDER TOTAL:	16.01	1,888.92	368.46	5.00	2,262.38
--------------	-------------------	-------	----------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-44-029	REPLACE NEW FUEL TANK PRESSURE SENSOR	11310047	12/19/2023 13:13:06	12/19/2023 15:37:08	2.40	\$283.27
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	12/19/2023 08:02:42	12/19/2023 11:53:16	3.84	\$453.45
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	12/18/2023 07:23:07	12/18/2023 11:57:39	4.58	\$539.92
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	12/14/2023 14:30:00	12/14/2023 14:42:53	0.21	\$25.34
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	12/14/2023 13:00:00	12/14/2023 14:15:00	1.25	\$147.50
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	12/14/2023 09:30:00	12/14/2023 12:00:00	2.50	\$295.00
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	12/14/2023 08:01:33	12/14/2023 09:15:00	1.22	\$144.45
				LABOR		1888.93

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-44-029	REPLACE NEW FUEL TANK PRESSURE SENSOR	L1MZ9D683D	FUEL HOSE W/ SENSOR	368.46	1	\$368.46
03-44-029	REPLACE NEW FUEL TANK PRESSURE SENSOR	L1MZ9D683D	FUEL HOSE W/ SENSOR	368.46	(1)	(\$368.46)
03-44-029	REPLACE NEW FUEL TANK PRESSURE SENSOR	L1MZ9D683D	FUEL HOSE W/ SENSOR	368.46	1	\$368.46
					PARTS	368.46

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49252

Work Order Notes

(EHANNAH) scan out

Job Notes

03-44-029 - REPLACE NEW FUEL TANK PRESSURE SENSOR

(EHOWELL) Dropped the fuel tank and replaced the EVAP line. The fuel tank pressure sensor was made into the line. Cleaned multiple line connections, reinstalled fuel tank, and connected lines. The fuel tank pressure sensor is now reading 0" of water with the fuel system vented. Also, commanded vent valve closed and pulled a vacuum on the EVAP system. The FTP sensor changed accordingly. EH

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(EHOWELL) Found DTC: P0451:00:68 EVAP System Pressure Sensor/Switch 'A' Circuit Range/Performance. The fuel tank pressure sensor should be reading 0" of H2O with the fuel system vented. The sensor was reading 2.75" of H2O with the funnel installed in the fuel filler neck. EH

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49708

USING DEPT NO:	507121	OPENED DATE:	02/06/2024 09:05:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/06/2024 15:46:24	METER 1 - M:	17773	METER 2 - H: 3535
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/07/2024 15:32:12	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$46.35	\$60.56	\$0.00	\$106.91
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.05	\$6.00	\$33.45	\$0.00	\$39.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.44	52.35	94.01	5.00	151.36
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	02/06/2024 09:53:34	02/06/2024 09:56:37	0.05	\$6.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/06/2024 09:30:00	02/06/2024 09:53:34	0.39	\$46.35
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/06/2024 09:23:02	02/06/2024 09:23:02	0.00	\$0.00
LABOR						52.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	33.45	1	\$33.45
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
PARTS						94.01

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49708

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49767

USING DEPT NO:	507121	OPENED DATE:	02/12/2024 07:03:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2024 13:52:58	METER 1 - M:	17929	METER 2 - H: 3594
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/26/2024 07:34:18	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.49	\$58.21	\$0.00	\$0.00	\$58.21
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.49	58.21	0.00	5.00	63.21
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	12052187	03/05/2024 07:00:00	03/05/2024 07:15:00	(0.25)	(\$29.50)
06-15	INSPECT STEERING	12052187	03/05/2024 07:00:00	03/05/2024 07:15:00	0.25	\$29.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/05/2024 07:00:00	03/05/2024 07:48:00	0.80	\$94.40
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/05/2024 07:00:00	03/05/2024 07:48:00	(0.80)	(\$94.40)
14-52-021	INSTALL GPS SYSTEM	12052187	03/05/2024 07:00:00	03/05/2024 07:15:00	0.25	\$29.50
66-17-013	PERFORM ALIGNMENT	12052187	03/05/2024 07:00:00	03/05/2024 08:00:00	1.00	\$118.00
66-17-013	PERFORM ALIGNMENT	12052187	03/05/2024 07:00:00	03/05/2024 08:00:00	(1.00)	(\$118.00)
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/05/2024 07:00:00	03/05/2024 07:49:48	(0.83)	(\$97.94)
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/05/2024 07:00:00	03/05/2024 07:49:48	0.83	\$97.94
14-52-021	INSTALL GPS SYSTEM	11074414	02/27/2024 15:22:29	02/27/2024 15:37:05	0.24	\$28.71
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	02/13/2024 07:00:37	02/13/2024 07:30:02	(0.49)	(\$57.85)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	02/13/2024 07:00:37	02/13/2024 07:30:02	0.49	\$57.85
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	02/12/2024 14:56:00	02/12/2024 15:41:37	(0.76)	(\$89.71)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	02/12/2024 14:56:00	02/12/2024 15:41:37	0.76	\$89.71
06-15	INSPECT STEERING	11074414	02/12/2024 10:59:14	02/12/2024 11:06:54	0.13	\$15.08
06-15	INSPECT STEERING	11074414	02/12/2024 10:59:14	02/12/2024 11:06:54	(0.13)	(\$15.08)
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/12/2024 10:13:11	02/12/2024 10:59:14	0.77	\$90.57

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/12/2024 10:13:11	02/12/2024 10:59:14	(0.77)	(\$90.57)
					LABOR	58.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	012114	TIRE 255/60R18 FTONE FHAWK PST	0.00	(4)	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	012114	TIRE 255/60R18 FTONE FHAWK PST	0.00	4	\$0.00
					PARTS	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49767

Work Order Notes

(EHANNAH) pm- tire rotation- alignment
(EKIMBREL) CANCELLED WRONG UNIT
(LRUSHING) install gps

Job Notes

06-15 - INSPECT STEERING

(EKIMBREL)

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240140. SH

66-17-013 - PERFORM ALIGNMENT

66-17-015 - PERFORM TIRE ROTATION

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL)

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL)

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50785

USING DEPT NO:	507121	OPENED DATE:	05/08/2024 12:20:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/09/2024 08:45:07	METER 1 - M:	19461	METER 2 - H: 3945
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/09/2024 13:20:02	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.08	\$34.15	\$0.00	\$35.23
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.21	\$60.65	\$0.00	\$61.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.02	2.29	94.80	5.00	102.09
--------------	-------------------	------	------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/08/2024 14:02:01	05/08/2024 14:02:34	0.01	\$1.08
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/08/2024 14:01:24	05/08/2024 14:02:01	0.01	\$1.21
LABOR					2.29	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.67	6	\$34.02
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
PARTS					94.80	

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50785

Work Order Notes

(EHANNAH) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH CW

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51394

USING DEPT NO:	507121	OPENED DATE:	07/08/2024 08:17:13	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	07/11/2024 15:40:11	METER 1 - M:	21920	METER 2 - H:	4294		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/17/2024 12:14:32	IN-SERVICE DATE:	09/10/2020				
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-40-451	INSPECT NOISE	DON	N	N	GARAGE	0.02	\$2.62	\$0.00	\$0.00	\$2.62
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.05	\$5.54	\$0.00	\$0.00	\$5.54
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.05	\$68.66	\$0.00	\$69.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:					0.08	9.21	68.66	5.00	82.87
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	07/08/2024 13:07:51	07/08/2024 13:10:40	0.05	\$5.54
06-40-451	INSPECT NOISE	12395904	07/08/2024 13:06:04	07/08/2024 13:07:24	0.02	\$2.62
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/08/2024 10:11:31	07/08/2024 10:12:03	0.01	\$1.05
LABOR					9.21	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
PARTS					68.66	

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51394

Work Order Notes

(EHANNAH) pm- rattling noise like the muffler or something.

Job Notes

06-40-451 - INSPECT NOISE

(EKIMBREL) replaced 2 bolts fc

(EHOWELL) Per FC: A metal shield/plate was loose beneath the vehicle. He installed two bolts.

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) perform rotate 2 tires and check brakes F 6- m -R - 5 -m fc

(EKIMBREL) Will possibly have to have new tires next pm.

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51494

USING DEPT NO:	507121	OPENED DATE:	07/16/2024 08:27:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/24/2024 08:46:31	METER 1 - M:	21922	METER 2 - H: 4295
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2024 08:46:35	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$225.51	\$0.00	\$225.51
03-43-009	REPLACE NEW CATALYTIC CONVERTE	DON	N	N	GARAGE	0.00	\$0.00	\$967.73	\$0.00	\$967.73
06-15	INSPECT STEERING	DON	N	N	GARAGE	22.60	\$2,666.90	\$0.00	\$0.00	\$2,666.90
06-40-451	INSPECT NOISE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$766.77	\$0.00	\$766.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7	WORK ORDER TOTAL:	22.60	2,666.90	1,960.01	5.00	4,631.91
--------------	-------------------	-------	----------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	11310047	09/17/2024 14:30:00	09/17/2024 15:10:17	0.67	\$79.22
06-15	INSPECT STEERING	11310047	09/17/2024 13:00:00	09/17/2024 14:15:00	1.25	\$147.50
06-15	INSPECT STEERING	11310047	09/17/2024 09:30:00	09/17/2024 12:00:00	2.50	\$295.00
06-15	INSPECT STEERING	11310047	09/16/2024 15:04:14	09/17/2024 09:15:00	18.18	\$2,145.17
				LABOR		2666.89

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	225.51	1	\$225.51
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.50	2	\$0.99
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	1.65	1	\$1.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.99	3	\$2.97
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.81	2	\$1.62
03-43-009	REPLACE NEW CATALYTIC CONVERTER	L1MZ5E212AC	CATALYTIC CONVERTER	967.73	1	\$967.73

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.33	4	\$13.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	F012114	TIRE 255/60R18 FSTONE PURSUIT	186.56	4	\$746.22
					PARTS	1960.01

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51494

Work Order Notes

(EHANNAH) inspect Rattling noise

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) installed new battery cm
(IFALLS) used scan tool to relearn charge pids

03-43-009 - REPLACE NEW CATALYTIC CONVERTER

(EKIMBREL) CM REPLACED CATALYTIC CONVERTER

06-15 - INSPECT STEERING

(EHOWELL) Checked front end.

06-40-451 - INSPECT NOISE

(EKIMBREL) inspected vehicle found hole in exhaust system

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment.

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) mounted and balance tires cm

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52804

USING DEPT NO:	507121	OPENED DATE:	11/14/2024 07:39:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/14/2024 15:27:44	METER 1 - M:	22744	METER 2 - H: 4295
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/15/2024 09:44:42	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$63.86	\$0.00	\$63.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:		0.00	0.00	63.86	5.00	68.86
--------------	-------------------	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
PARTS						63.86

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52804

Work Order Notes

(EHANNAH) pm- SI

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) FJ- Performed SI & rotated tires.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- Performed PM service.

(GARAGE) GC- Top

FJ- Bottom

GC- Topped off all fluids and set tire pressure.

FJ- Drained oil, swapped filter.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53550

USING DEPT NO:	507121	OPENED DATE:	01/30/2025 11:04:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/31/2025 09:30:18	METER 1 - M:	24434	METER 2 - H: 4866
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/31/2025 12:36:06	IN-SERVICE DATE:	09/10/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$62.94	\$0.00	\$62.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.00 0.00 62.94 5.00 67.94

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.40	1	\$11.40
PARTS						62.94

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53550

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- topside

FJ- pit

perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid

24434 miles, 4866 idle hours, 5963 total hours

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54237

USING DEPT NO:	507121	OPENED DATE:	03/31/2025 09:36:54	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	03/31/2025 09:39:58	METER 1 - M:	24660	METER 2 - H:	4866				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/31/2025 14:40:04	IN-SERVICE DATE:	09/10/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer			UNIT SERIAL NO:	1FM5K8AB0LGC15612					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-074	REPLACE NEW WINDOW SWITCH	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.00	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-074	REPLACE NEW WINDOW SWITCH	2714700	176652		\$0.00
66-PM-PMA	PERFORM OIL CHANGE	2714700	176651		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: **243754** **2020 FORD INTERCEPTOR EXPLORER**

WORK ORDER NO: **54237**

Work Order Notes

Job Notes

03-02-074 - REPLACE NEW WINDOW SWITCH

(EKIMBREL) stivers performed recall on power window switch

17-GA-005 - RECALL Scheduling and Preparation

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) stivers performed recall pm

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 54715

USING DEPT NO:	507121	OPENED DATE:	05/08/2025 11:41:20	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	OPEN	COMPLETED DATE:		METER 1 - M:	24660	METER 2 - H:	4866		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	09/10/2020				
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB0LGC15612				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-33-006	TRANSPORT IGNITION LOCK CYLINDEI	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
RY-33-006	REKEY IGNITION LOCK CYLINDER	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 3						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/15/2025 08:34:49 By User: GLOBETTI

UNIT NO: 243754 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54715

Work Order Notes

(CHANNELL) prep 4 sale
(CHANNELL) prep 4 sale
(EHANNAH) Transport and rekey

Job Notes

16-33-006 - TRANSPORT IGNITION LOCK CYLINDER

(GARAGE) CW- Transported locks to locksmith to be re-keyed.

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) FJ- Prep for sale. Mileage is 24,756. Removed all UA logos, wordmarks, and numbers. No GPS in the vehicle at this time. Removed all UA paperwork from the vehicle.

RY-33-006 - REKEY IGNITION LOCK CYLINDER

(GARAGE) FJ- Removed & installed locks

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu May 15 2025 08:34:49 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '1FM5K8AB0LGC15612') //Q=