

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 37429

USING DEPT NO:	507121	OPENED DATE:	08/25/2020 07:43:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2020 09:14:53	METER 1 - M:	103	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2020 09:14:57	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 WORK ORDER TOTAL: 0.50 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11074414	08/25/2020 09:14:26	08/25/2020 09:44:26	0.50	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 37429

---

## Work Order Notes

(LISAPATE) New unit do PDI

---

## Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 38829

USING DEPT NO:	507121	OPENED DATE:	01/19/2021 10:36:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2021 10:37:33	METER 1 - M:	104	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2021 10:37:34	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 38829

## Work Order Notes

(LISAPATE) Opened WO for documentation per Tony J. Unit has not been put in service yet. Being held up due to a strobe light issue

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39573

USING DEPT NO:	507121	OPENED DATE:	04/06/2021 14:27:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/07/2021 11:07:06	METER 1 - M:	1746	METER 2 - H: 300
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/08/2021 07:34:15	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$118.26	\$42.79	\$0.00	\$161.05

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	118.26	42.79	0.00	161.05
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/07/2021 07:28:10	04/07/2021 08:28:18	1.00	\$118.26
					LABOR	118.26

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PF63	FILTER-OIL	9.68	1	\$9.68
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
					PARTS	42.79

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI*

**UNIT NO:**                    **243752**                    **2020 FORD INTERCEPTOR EXPLORER**

**WORK ORDER NO:**                    **39573**

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 1746 idle hours: 300 Completed PM bottom side, Scott was top side. SH/AMG Completed checklist. AMG

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40001

USING DEPT NO:	507121	OPENED DATE:	05/21/2021 08:34:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/24/2021 13:14:13	METER 1 - M:	2490	METER 2 - H: 300
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2021 15:13:06	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-13-002	INSPECT REAR BRAKES & DRUMS/ROTOR	DON	O	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60
66-79-002	PERFORM SERVICE CALL	DON	O	N	GARAGE	0.71	\$83.78	\$0.00	\$0.00	\$83.78

JOB COUNT: 2 WORK ORDER TOTAL: 0.91 107.38 0.00 0.00 107.38

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11213180	05/21/2021 09:01:03	05/21/2021 09:15:00	0.23	\$27.44
66-79-002	PERFORM SERVICE CALL	11213180	05/21/2021 09:30:00	05/21/2021 09:47:07	0.29	\$33.66
06-13-002	INSPECT REAR BRAKES & DRUMS/ROTORS	11213180	05/24/2021 07:00:00	05/24/2021 07:12:00	0.20	\$23.60
66-79-002	PERFORM SERVICE CALL	11901357	05/21/2021 09:03:28	05/21/2021 09:15:00	0.19	\$22.68
					LABOR	107.38

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40001

## Work Order Notes

(LISAPATE) Per John Turner when wheels turn making a loud squealing noise in the rear feels like a caliper is locked up and brakes are grinding unit is at Campus Dr and Bryce Lawn Dr

## Job Notes

### **06-13-002 - INSPECT REAR BRAKES & DRUMS/ROTORS**

(LISAPATE) Drove back to shop and removed driver rear tire and caliper found a piece of gravel stuck between rotor and backing plate, removed rock and rechecked ok. MS

### **66-79-002 - PERFORM SERVICE CALL**

(AGUERRA) Grinding noise in left rear wheel, Matt determined vehicle was drivable and brought back to shop for repairs. AMG MS  
(LISAPATE)



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40214

USING DEPT NO:	507121	OPENED DATE:	06/21/2021 14:05:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/23/2021 14:56:32	METER 1 - M:	2999	METER 2 - H: 300
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/23/2021 14:56:35	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$100.23	\$53.45	\$0.00	\$153.68

JOB COUNT: 1	WORK ORDER TOTAL:					0.85	100.23	53.45	0.00	153.68
--------------	-------------------	--	--	--	--	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/21/2021 15:05:35	06/21/2021 15:48:47	0.72	\$84.96
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/21/2021 15:35:48	06/21/2021 15:43:34	0.13	\$15.27
					<b>LABOR</b>	<b>100.23</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	PF63	FILTER-OIL	9.68	1	\$9.68
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.51	1	\$6.51
					<b>PARTS</b>	<b>53.45</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40214

## Work Order Notes

(CHANNELL) pm

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40449

USING DEPT NO:	507121	OPENED DATE:	07/15/2021 13:43:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/04/2021 14:38:18	METER 1 - M:	3960	METER 2 - H: 300
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/05/2021 07:46:50	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-02-010	INSPECT MIRRORS	DON	O	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
15-35-016	WARRANTY POWER MIRROR SWITCH	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-35	TRANSPORT MULTI-FUNC ELECTRON/I	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.15	135.70	0.00	2.00	137.70
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-35-016	WARRANTY POWER MIRROR SWITCH	4910000	622394		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-02-010	INSPECT MIRRORS	11213180	08/05/2021 07:00:00	08/05/2021 07:09:00	0.15	\$17.70
16-35	TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS	11901357	07/23/2021 07:00:00	07/23/2021 08:00:00	1.00	\$118.00
16-35	TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS	11901357	07/23/2021 07:00:00	07/23/2021 07:06:00	(0.10)	(\$11.80)
16-35	TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS	11901357	07/23/2021 07:00:00	07/23/2021 07:06:00	0.10	\$11.80
LABOR						135.70

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40449

## Work Order Notes

(LISAPATE) Per Dept the side mirror adjustment mechanism is malfunctioning and does not consistently allow for adjusting of the side mirrors, particularly the passenger side mirror.

## Job Notes

### 06-02-010 - INSPECT MIRRORS

(LISAPATE) Inspected unit sent to T&C to repair under warranty  
(IFALLS) MS found power mirror switch to be bad.

### 15-35-016 - WARRANTY POWER MIRROR SWITCH

(LISAPATE) Town & Country replaced power window switch under warranty

### 16-35 - TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS

(IFALLS) Taken to Town and Country by AG

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40717

USING DEPT NO:	507121	OPENED DATE:	08/11/2021 14:35:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/13/2021 13:43:40	METER 1 - M:	4434	METER 2 - H: 300
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	08/16/2021 08:08:30	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.37	\$43.99	\$215.70	\$0.00	\$259.69
66-79-002	PERFORM SERVICE CALL	DON	O	N	GARAGE	0.84	\$99.48	\$0.00	\$0.00	\$99.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.22	143.47	215.70	2.00	361.17
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	08/13/2021 07:09:03	08/13/2021 07:31:25	0.37	\$43.99
66-79-002	PERFORM SERVICE CALL	11901357	08/11/2021 14:41:24	08/11/2021 15:31:59	0.84	\$99.48
					LABOR	143.47

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.51	1	\$0.51
66-17-028	PERFORM MOUNT AND BALANCE TIRES	732005563	TIRE 255/60R18 GY ENFORCE 108V	215.19	1	\$215.19
					PARTS	215.70

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40717

## Work Order Notes

(LISAPATE) Flat tire mars spring and campus drive

## Job Notes

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(JWRIGHT) Mounted new tire on RF and put spare back in the rear. Aired and balanced new tire to spec and torqued lug nuts to spec

### **66-79-002 - PERFORM SERVICE CALL**

(AGUERRA) miles: 40717 Removed R/F tire and installed spare. Brought damaged tire back to shop for repair. AMG RC

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40754

USING DEPT NO:	507121	OPENED DATE:	08/16/2021 07:05:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/18/2021 09:18:47	METER 1 - M:	4540	METER 2 - H: 300
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	08/18/2021 09:18:55	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.57	\$31.70	\$0.00	\$35.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.73	\$85.94	\$38.95	\$0.00	\$124.89
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.76	89.51	70.65	2.00	162.16
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/16/2021 08:38:37	08/16/2021 08:40:26	0.03	\$3.57
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/16/2021 08:03:37	08/16/2021 08:47:19	0.73	\$85.94
LABOR						89.51

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.84	1	\$5.84
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.07	1	\$10.07
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
PARTS						70.65

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40754

## Work Order Notes

(IFALLS) PM

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 4564 Engine hours 1152 Idle hours 931. SH Performed PM.

### CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41025

USING DEPT NO:	507121	OPENED DATE:	09/15/2021 07:12:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/15/2021 10:22:48	METER 1 - M:	5835	METER 2 - H: 1236
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/15/2021 13:51:07	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.02	\$31.80	\$0.00	\$36.82
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.23	\$27.34	\$0.00	\$0.00	\$27.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.91	\$48.82	\$0.00	\$79.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.54	63.27	80.62	2.00	145.89
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/15/2021 09:01:06	09/15/2021 09:15:00	0.23	\$27.34
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/15/2021 08:53:02	09/15/2021 08:55:35	0.04	\$5.02
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/15/2021 08:37:09	09/15/2021 08:52:52	0.26	\$30.91
				LABOR	63.27	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.17	1	\$10.17
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	1	\$4.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.91	1	\$4.91
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	(1)	(\$4.43)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
					PARTS	80.62

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41025

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

### 66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) SH AMG Rotated tires and inspected brakes.

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 5835 Engine hours 1530 Idle hours 1236. SH/AMG Performed PM.

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41430

USING DEPT NO:	507121	OPENED DATE:	10/27/2021 07:13:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/28/2021 07:38:02	METER 1 - M:	6992	METER 2 - H: 1535
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2021 07:56:52	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.28	\$32.55	\$0.00	\$0.00	\$32.55
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.27	\$149.50	\$45.59	\$0.00	\$195.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.54	182.05	45.59	2.00	229.64
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	10/27/2021 09:30:00	10/27/2021 09:46:33	0.28	\$32.55
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	10/27/2021 09:22:54	10/27/2021 09:22:54	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/27/2021 09:00:46	10/27/2021 09:45:06	0.74	\$87.19
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/27/2021 08:43:19	10/27/2021 09:15:00	0.53	\$62.31
LABOR						182.05

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						45.59

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41430

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires relearned tire positions and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) SH/JW Performed PM. had to remove skid plate to service

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41808

USING DEPT NO:	507121	OPENED DATE:	12/07/2021 08:55:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/21/2021 10:00:02	METER 1 - M:	8073	METER 2 - H: 1858
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/04/2022 08:01:53	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.01	\$22.62	\$0.00	\$31.63
15-42-004	WARRANTY WATER PUMP	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$75.19	\$59.51	\$0.00	\$134.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.21	143.20	82.13	2.00	227.33
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-42-004	WARRANTY WATER PUMP	11078175	94887		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-42	TRANSPORT COOLING SYSTEM	11915538	12/20/2021 07:00:00	12/20/2021 07:30:00	0.50	\$59.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/08/2021 08:59:32	12/08/2021 09:04:07	0.08	\$9.01
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/08/2021 08:21:07	12/08/2021 08:59:21	0.64	\$75.19
LABOR						143.20

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	16.92	1	\$16.92
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.57	1	\$9.57
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.57	(1)	(\$9.57)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	(6)	(\$26.64)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.24	1	\$5.24
					<b>PARTS</b>	<b>82.13</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41808

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

### **15-42-004 - WARRANTY WATER PUMP**

(LISAPATE) Ford Pressure tested cooling system, put vehicle on a rack and took the skid plate off and inspected for a coolant leak. Found the water pump was leaking, between the gasket and the block. Removed the thermostat housing to get to the water pump. Installed a new water pump and gasket. Filled the cooling system up with coolant. Test drove and inspected for leaks. Verified repair

### **16-42 - TRANSPORT COOLING SYSTEM**

(LISAPATE) Taken to Ford by RC

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) PM Was completed except for dropping the oil and filter. Vehicle has a coolant leak and needs to go to the dealer. SH

(SHARBIN) Oil and filter were changed when vehicle returned from the dealer. SH

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42361

USING DEPT NO:	507121	OPENED DATE:	02/14/2022 10:44:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/18/2022 07:30:40	METER 1 - M:	9274	METER 2 - H: 2169
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2022 07:30:42	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.29	\$152.68	\$47.24	\$0.00	\$199.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 1.29 152.68 47.24 2.00 201.92

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/14/2022 14:16:06	02/14/2022 15:33:44	1.29	\$152.68
LABOR						152.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.98	1	\$9.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
PARTS						47.24



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42361

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-9274

ENG HRS-2653

IDLE HRS-2169

(LISAPATE) required skid plate removal

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42641

USING DEPT NO:	507121	OPENED DATE:	03/10/2022 13:26:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2022 13:43:23	METER 1 - M:	9350	METER 2 - H: 2169
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/25/2022 14:23:12	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.50	59.00	0.00	2.00	61.00
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	169068066		\$0.00
24-71	REPAIR BODY	11150605	169068066		\$3,406.22
24-71	REPAIR BODY	11150605	169068066		(\$3,406.22)
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11399745	03/25/2022 07:00:00	03/25/2022 07:30:00	0.50	\$59.00
LABOR						59.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42641

## Work Order Notes

(LISAPATE) Take to Andrews Body Shop to repair rear body damage per the estimate

## Job Notes

### **16-71 - TRANSPORT BODY**

(LISAPATE) Taken to Andrews by CW

### **24-71 - REPAIR BODY**

(IFALLS) Andrews repaired body damage per estimate from State farm paid in full, they were paid by ck# 109527555 3/22/22 \$2961.93

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43301

USING DEPT NO:	507121	OPENED DATE:	05/18/2022 14:44:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/20/2022 14:58:47	METER 1 - M:	7684	METER 2 - H: 2199
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/23/2022 08:07:50	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	P	N	GARAGE	0.45	\$53.33	\$11.24	\$0.00	\$64.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.45 53.33 11.24 2.00 66.57

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11074414	05/19/2022 07:09:12	05/19/2022 07:36:19	0.45	\$53.33
LABOR						53.33

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	4.31	1	\$4.31
66-17-030	PERFORM TIRE PATCH	58100	.25 OZ WHEEL WEIGHT	0.18	1	\$0.18
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.18	(1)	(\$6.18)
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.18	1	\$6.18
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.18	1	\$6.18
PARTS						11.24

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43301

## Work Order Notes

(CWIGLEY) LR Tire

## Job Notes

66-17-030 - PERFORM TIRE PATCH

(HHARBIN) Patched left rear tire.SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43522

USING DEPT NO:	507121	OPENED DATE:	06/06/2022 07:33:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/07/2022 13:28:43	METER 1 - M:	10040	METER 2 - H: 2347
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/08/2022 09:04:40	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.30	\$35.60	\$146.72	\$0.00	\$182.32
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.24	\$22.62	\$0.00	\$27.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$78.80	\$55.61	\$0.00	\$134.41
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.01	119.64	224.95	2.00	346.59
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11074414	06/06/2022 13:29:33	06/06/2022 13:47:39	0.30	\$35.60
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/06/2022 11:45:45	06/06/2022 11:48:25	0.04	\$5.24
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/06/2022 11:05:26	06/06/2022 11:45:30	0.67	\$78.80
				LABOR		119.64

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.63	6	\$33.75
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.15	1	\$11.15
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	146.72	1	\$146.72
				PARTS		224.95

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43522

## Work Order Notes

(LISAPATE) PM-replace wipers-battery keeps going dead jumped off numerous times over the weekend.

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(HHARBIN) Battery tested bad. Replaced battery ALT charging 14.25 volts. SH

### **03-51-038 - REPLACE NEW WIPER BLADES**

(HHARBIN) Replaced wipers. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(HHARBIN) SH Performed PM. Battery tested bad.

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43843

USING DEPT NO:	507121	OPENED DATE:	07/05/2022 13:40:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/07/2022 13:53:56	METER 1 - M:	11343	METER 2 - H: 2711
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2022 10:04:16	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$32.91	\$46.35	\$0.00	\$79.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.28 32.91 46.35 2.00 81.26

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/06/2022 07:49:21	07/06/2022 08:06:05	0.28	\$32.91
LABOR						32.91

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.81	6	\$34.83
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.52	1	\$11.52
PARTS						46.35



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43843

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm. Coolant -34°. JAW,AMG,SH/JAW

MILEAGE-11343

ENG HRS-3302

IDLE HRS-2711

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43951

USING DEPT NO:	507121	OPENED DATE:	07/13/2022 07:12:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/28/2022 11:01:57	METER 1 - M:	11664	METER 2 - H: 2711
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/28/2022 13:13:37	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-42-004	WARRANTY WATER PUMP	DON	W	J	GARAGE	0.00	\$0.00	\$27.60	\$0.00	\$27.60
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	0.30	\$35.11	\$0.00	\$0.00	\$35.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:					0.80	94.11	27.60	2.00	123.71
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-42-004	WARRANTY WATER PUMP	11078175	102224		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-42	TRANSPORT COOLING SYSTEM	11915538	07/28/2022 07:00:00	07/28/2022 07:30:00	0.50	\$59.00
35-42	DIAGNOSE COOLING SYSTEM	11310047	07/13/2022 08:02:19	07/13/2022 08:20:10	0.30	\$35.11
LABOR						94.11

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
15-42-004	WARRANTY WATER PUMP	VC13G	FORD YELLOW AF CONC 2019-UP	27.60	1	\$27.60
PARTS						27.60

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43951

## Work Order Notes

(LISAPATE) Driver said display says overheating and can smell coolant

## Job Notes

### **15-42-004 - WARRANTY WATER PUMP**

(LISAPATE) Tuscaloosa Ford installed a new waterpump under warranty

### **16-42 - TRANSPORT COOLING SYSTEM**

(LISAPATE) Taken to Tuscaloosa Ford by RC

### **35-42 - DIAGNOSE COOLING SYSTEM**

(EHOWELL) Topped off coolant. It appears that the water pump is leaking at the gasket mating surface. The vehicle needs to go to the dealership. EH .5 HR

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44384

USING DEPT NO:	507121	OPENED DATE:	08/19/2022 07:09:31	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2022 09:56:52	METER 1 - M:	12913	METER 2 - H:	3057		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/23/2022 08:51:46	IN-SERVICE DATE:	08/21/2020				
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$18.16	\$32.30	\$0.00	\$50.46
15-02-074	WARRANTY WINDOW SWITCH	DON	W	J	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
15-21-001	WARRANTY AXLE ASSY-FRONT STEER	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-21	TRANSPORT AXLES - DRIVEN, FRONT :	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	0.66	\$77.72	\$35.70	\$0.00	\$113.42
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.48	\$57.16	\$0.00	\$0.00	\$57.16
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.95	\$59.82	\$0.00	\$115.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 8	WORK ORDER TOTAL:	2.77	326.99	127.82	5.00	459.81
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-02-074	WARRANTY WINDOW SWITCH	4910000	2321263		\$0.00
15-02-074	WARRANTY WINDOW SWITCH	4910000	2321263		\$0.00
15-02-074	WARRANTY WINDOW SWITCH	4910000	2321263		\$0.00
15-02-074	WARRANTY WINDOW SWITCH	4910000	2321263		\$0.00
15-21-001	WARRANTY AXLE ASSY-FRONT STEERING,DRIVN	11078175	103685		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
15-02-074	WARRANTY WINDOW SWITCH	11901357	09/23/2022 07:00:00	09/23/2022 07:30:00	0.50	\$59.00
16-21	TRANSPORT AXLES - DRIVEN, FRONT STEERING	11901357	09/22/2022 07:00:00	09/22/2022 07:30:00	0.50	\$59.00
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11915538	08/26/2022 12:00:00	08/26/2022 12:01:35	0.03	\$3.11
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11915538	08/26/2022 10:22:04	08/26/2022 11:00:00	0.63	\$74.60
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11310047	08/19/2022 14:21:11	08/19/2022 14:50:15	0.48	\$57.16
03-51-038	REPLACE NEW WIPER BLADES	11901357	08/19/2022 09:51:14	08/19/2022 09:57:02	0.10	\$11.41

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	08/19/2022 09:33:41	08/19/2022 09:37:07	0.06	\$6.75
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/19/2022 09:57:25	08/19/2022 10:00:23	0.05	\$5.83
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/19/2022 12:07:37	08/19/2022 12:33:06	0.42	\$50.12
					<b>LABOR</b>	<b>326.98</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.38	1	\$10.38
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	6	\$36.54
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.43	1	\$11.43
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	08984	ADHESIVE REMOVER	35.70	1	\$35.70
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	5.93	2	\$11.85
					<b>PARTS</b>	<b>127.82</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44384

## Work Order Notes

(CWIGLEY) PM/ Driver says that they are having problems with the side mirror adjuster pad, and having difficulty unlocking the passenger side door from the outside. There's a copy of the email in the sleeve.

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

### 15-02-074 - WARRANTY WINDOW SWITCH

(IFALLS) TOWN & COUNTRY WARRANTED WINDOW/MIRROR SWITCH

(LISAPATE) Visit Reason Changed On 9/22/2022 9:43 AM By LISAPATE

(IFALLS) Mirror switch was installed at the shop part was provided by Town and Country under warranty. Invoice 2321263 \$0.00

### 15-21-001 - WARRANTY AXLE ASSY-FRONT STEERING,DRIVN

(LISAPATE) Tuscaloosa Ford Found both front axle boots were cut along the bands and were leaking grease. Installed new front axle's. Verified repair

### 16-21 - TRANSPORT AXLES - DRIVEN, FRONT STEERING

(LISAPATE) Taken to Ford by RC

### 25-53-006 - REMOVE WORDMARKS/IDENTIFIERS

(GARAGE) removed rear quarter panel decal from both sides\RC

### 66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(EHOWELL) Rotated tires. Front brake pad is near 7mm. Rear brake pad is near 6mm. Tire positions were relearned. EH

### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 12913 hours: 3725 idle hours: 3051 Completed PM bottom side, Ethan was top side. EH/AMG

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45159

USING DEPT NO:	507121	OPENED DATE:	11/03/2022 07:51:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2022 09:43:19	METER 1 - M:	14007	METER 2 - H: 3318
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/07/2022 07:20:00	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.99	\$43.20	\$0.00	\$73.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.25	29.99	43.20	5.00	78.19
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/03/2022 08:50:55	11/03/2022 09:06:10	0.25	\$29.99
LABOR						29.99

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.67	1	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
PARTS						43.20

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45159

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH

MILEAGE-14007

IDLE HRS-3318

ENG HRS-4049

### CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45738

USING DEPT NO:	507121	OPENED DATE:	01/10/2023 08:42:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/11/2023 10:48:10	METER 1 - M:	15191	METER 2 - H: 3634
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/17/2023 11:13:06	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$43.73	\$56.72	\$0.00	\$100.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.37 43.73 56.72 5.00 105.45

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/10/2023 10:09:19	01/10/2023 10:31:33	0.37	\$43.73
LABOR						43.73

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.08	(1)	(\$6.08)
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.08	1	\$6.08
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.08	1	\$6.08
PARTS						56.72

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI*

**UNIT NO:** 243752      2020 FORD INTERCEPTOR EXPLORER      **WORK ORDER NO:** 45738

---

## Work Order Notes

(EHANNAH) pm- replace wipers

---

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 15191 hours: 1184 idle hours: 3634 Completed PM topside, Gregg was bottomside. AMG/GC

CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46653

USING DEPT NO:	507121	OPENED DATE:	04/10/2023 08:36:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/11/2023 08:03:20	METER 1 - M:	16295	METER 2 - H: 3943
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/11/2023 15:45:02	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.28	\$33.72	\$0.00	\$39.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$12.82	\$60.08	\$0.00	\$72.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80

JOB COUNT: 4	WORK ORDER TOTAL:	0.25	29.90	93.80	5.00	128.70
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	04/11/2023 07:00:00	04/11/2023 07:06:00	0.10	\$11.80
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/10/2023 09:06:53	04/10/2023 09:09:34	0.04	\$5.28
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/10/2023 09:00:08	04/10/2023 09:06:39	0.11	\$12.82
				LABOR		29.90

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.18	1	\$13.18
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	9.53	1	\$9.53
				PARTS		93.80

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46653

## Work Order Notes

(EHANNAH) pm- replace wipers- wash

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/GC Performed PM.

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47149

USING DEPT NO:	507121	OPENED DATE:	05/23/2023 08:22:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/24/2023 10:56:38	METER 1 - M:	16645	METER 2 - H: 4071
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2023 14:06:49	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	O	N	GARAGE	0.08	\$9.60	\$0.00	\$0.00	\$9.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.08	9.60	0.00	5.00	14.60
--------------	-------------------	--	--	--	--	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	05/23/2023 08:42:48	05/23/2023 08:47:41	0.08	\$9.60
LABOR						9.60

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47149

## Work Order Notes

(EHANNAH) FP tire has nail in it

## Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(SHARBIN) Screw did not puncture the tire. SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47506

USING DEPT NO:	507121	OPENED DATE:	07/03/2023 08:21:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/05/2023 09:45:14	METER 1 - M:	17074	METER 2 - H: 4245
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/05/2023 10:20:52	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$88.55	\$0.00	\$127.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.33 38.94 88.55 5.00 132.49

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/03/2023 12:33:21	07/03/2023 12:33:21	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/03/2023 12:33:21	07/03/2023 12:33:21	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/03/2023 12:33:21	07/03/2023 12:53:09	0.33	\$38.94
LABOR						38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	(6)	(\$37.44)
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	10.70	6	\$64.17
PARTS						88.55

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47506

## Work Order Notes

(EHANNAH) pm- replace wipers

(EKIMBREL) cancelled wipers, got them 2 months ago

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

## 66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

Note, All 4 tires are at 4mm and will need to be changed at next PM-GC

Miles, 17,074

Engine Hours, 5,154

Idle Hours, 4,245

CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47654

USING DEPT NO:	507121	OPENED DATE:	07/19/2023 14:43:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/19/2023 14:46:49	METER 1 - M:	17250	METER 2 - H: 4245
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/20/2023 08:52:32	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
17-05-020	RECALL PCM/PROCESSOR ASSEMBLY	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-22	RECALL AXLES - DRIVEN, REAR	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
17-05-020	RECALL PCM/PROCESSOR ASSEMBLY	11099772	100610661		\$0.00
				COMML	0.00

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI*

**UNIT NO:**                    **243752**                    **2020 FORD INTERCEPTOR EXPLORER**

**WORK ORDER NO:**                    **47654**

---

## Work Order Notes

(LISAPATE) Long Lewis came to the shop to completed recalls. MV99pm and 22S27.

---

## Job Notes

### **17-05-020 - RECALL PCM/PROCESSOR ASSEMBLY**

(LISAPATE) Tech replaced subframe bushing

### **17-22 - RECALL AXLES - DRIVEN, REAR**

(LISAPATE) Reprogrammed PCM per 22S27

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48019

USING DEPT NO:	507121	OPENED DATE:	08/29/2023 08:08:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/05/2023 11:34:53	METER 1 - M:	18303	METER 2 - H: 4560
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2023 14:26:55	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.44	\$34.15	\$0.00	\$37.59
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	1.04	\$122.20	\$0.00	\$0.00	\$122.20
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.25	\$147.50	\$999.42	\$0.00	\$1,146.92
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$6.82	\$64.34	\$0.00	\$71.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
JOB COUNT: 6		WORK ORDER TOTAL:		2.62		309.46		1,097.91		5.00
										1,412.37

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	09/01/2023 13:46:39	09/01/2023 13:48:24	0.03	\$3.44
66-PM-PMA	PERFORM OIL CHANGE	12201267	09/01/2023 13:43:11	09/01/2023 13:46:39	0.06	\$6.82
66-17-013	PERFORM ALIGNMENT	11310047	09/01/2023 13:22:15	09/01/2023 13:38:42	0.27	\$32.35
66-17-013	PERFORM ALIGNMENT	11310047	09/01/2023 11:08:11	09/01/2023 11:53:52	0.76	\$89.84
06-15	INSPECT STEERING	12201267	08/31/2023 14:18:10	08/31/2023 14:33:10	0.25	\$29.50
06-15	INSPECT STEERING	12201267	08/31/2023 14:18:10	08/31/2023 14:18:10	0.00	\$0.00
06-15	INSPECT STEERING	12201267	08/31/2023 14:18:10	08/31/2023 14:18:10	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	08/31/2023 13:00:00	08/31/2023 14:15:00	1.25	\$147.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	08/31/2023 12:44:52	08/31/2023 12:44:52	0.00	\$0.00
					LABOR	309.45

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.63	3	\$1.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.66	1	\$0.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.90	1	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	1.22	1	\$1.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.87	4	\$15.48
66-17-028	PERFORM MOUNT AND BALANCE TIRES	91852	TIRE 255/60R18 BFG ELITE FORCE	244.50	4	\$978.00
					<b>PARTS</b>	<b>1097.91</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48019

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-FC

### 06-15 - INSPECT STEERING

(GRCOOK) Inspected steering, found no issues at this time-GC

Miles, 18,303

Idle Hrs, 4,560

Total Hrs, 5,538

### 66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment and calibrated lane departure system during road test. EH

### 66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GRCOOK) Mounted and Balanced 4 new tires-GC,

Inspected brakes, front left brake pad 6mm, front right brake pad 8mm, both rear brake pads are 4mm, got EH to inspect and he said it will need rear brake pads at next PM Service-GC

Miles, 18,303

Idle Hrs, 4,560

Total Hrs, 5,538

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

The tread on the tires are low and vehicle needs new tires-FC

Miles, 18,303

Idle Hrs, 4,560

Total Hrs, 5,538

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48310

USING DEPT NO:	507121	OPENED DATE:	09/25/2023 07:13:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2023 11:20:25	METER 1 - M:	18849	METER 2 - H: 4560
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2023 13:30:02	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11915538	09/26/2023 07:00:00	09/26/2023 07:30:00	0.50	\$59.00
					LABOR	59.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48310

## Work Order Notes

(EHANNAH) Service call for dead battery

## Job Notes

### **06-32-002 - INSPECT BATTERY**

(LISAPATE) FC checked battery, checked good.  
LP rechecked with Officer Turned unit is cranking ok

### **66-79-002 - PERFORM SERVICE CALL**

(LISAPATE) Jumper off and brought to the shop. RC/CW

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48805

USING DEPT NO:	507121	OPENED DATE:	11/02/2023 07:36:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/29/2023 08:05:50	METER 1 - M:	20068	METER 2 - H: 4866
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/29/2023 09:55:59	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	N	N	GARAGE	2.24	\$264.12	\$410.33	\$0.00	\$674.45
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.43	\$50.45	\$0.00	\$0.00	\$50.45
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.85	\$100.56	\$0.00	\$0.00	\$100.56
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.77	\$90.30	\$64.16	\$0.00	\$154.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	4.28	505.43	474.49	5.00	984.92
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-13-130	PERFORM Burnish Brakes	11310047	11/09/2023 14:39:48	11/09/2023 15:05:27	0.43	\$50.45
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	11/08/2023 15:40:31	11/09/2023 07:43:38	(16.05)	(\$1,894.13)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	11/08/2023 15:40:31	11/09/2023 07:43:38	16.05	\$1,894.13
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	11/08/2023 15:40:31	11/08/2023 16:10:31	0.50	\$59.00
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	11/07/2023 14:09:28	11/07/2023 15:53:46	1.74	\$205.12
66-79-003	PERFORM SAFETY INSPECTION	12395904	11/03/2023 09:33:16	11/03/2023 10:24:24	0.85	\$100.56
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/02/2023 13:04:36	11/02/2023 13:50:31	0.77	\$90.30
				LABOR		505.43

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	C111	RED BRAKE CLEANER	6.40	1	\$6.40
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	40012	DOT 4 BRAKE FLUID 12OZ	3.82	1	\$3.82



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	AR85205	REAR ROTORS	131.37	2	\$262.74
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	L1MZ2200F	REAR BRAKE PADS	137.37	1	\$137.37
					<b>PARTS</b>	<b>474.49</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48805

## Work Order Notes

(EHANNAH) pm- do SI

## Job Notes

### 03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(EHOWELL) Replaced rear brake pads, rotors, and hardware. Bled brakes at all four corners of the vehicle. Performed a road test after repairs.

### 66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made multiple hard stops after brake job was performed. EH

### 66-79-003 - PERFORM SAFETY INSPECTION

(FCONTRER) Perform safety inspection back brakes no good 2 m frunt 8 m 6 m FC

### 66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed and fluid check fc

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49581

USING DEPT NO:	507121	OPENED DATE:	01/25/2024 13:50:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/31/2024 12:43:18	METER 1 - M:	22063	METER 2 - H: 5165
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/05/2024 13:24:43	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-44-061	PERFORM SMOKE TEST	DON	N	N	GARAGE	1.00	\$117.90	\$0.00	\$0.00	\$117.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.49	\$175.85	\$0.00	\$0.00	\$175.85

JOB COUNT: 3	WORK ORDER TOTAL:		2.49	293.75	0.00	5.00	298.75
--------------	-------------------	--	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-44-061	PERFORM SMOKE TEST	11310047	01/26/2024 09:30:00	01/26/2024 09:46:26	0.27	\$32.32
66-44-061	PERFORM SMOKE TEST	11310047	01/26/2024 08:31:29	01/26/2024 09:15:00	0.73	\$85.58
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	01/26/2024 07:02:04	01/26/2024 08:31:29	1.49	\$175.85
LABOR						293.75

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49581

## Work Order Notes

(EHANNAH) scan out- check engine light came on

## Job Notes

### **66-44-061 - PERFORM SMOKE TEST**

(EHOWELL) Injected smoke into the EVAP system at the line after the purge valve. The float dropped to the bottom after a while. The system is sealed when the float drops to the bottom.

Also, injected smoke back towards the purge valve and the system was sealed. EH

### **CH-SP - CHARGE Shop Supplies**

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(EHOWELL) Found DTC: P0456:00:EC EVAP System Leak Detected (Very Small Leak).

The vapor blocking valve test graphed consistently.

The canister purge valve test passe.

The EVAP system test-vacuum bleed up phase-test passed.

Cleared DTC and released vehicle to the customer. EH

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49749

USING DEPT NO:	507121	OPENED DATE:	02/09/2024 07:23:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/09/2024 13:43:57	METER 1 - M:	22394	METER 2 - H: 5203
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/12/2024 07:54:37	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$25.70	\$60.56	\$0.00	\$86.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.22	25.70	60.56	5.00	91.26
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/09/2024 07:42:42	02/09/2024 07:55:46	0.22	\$25.70
LABOR						25.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
PARTS						60.56

# Work Order Charge Detail

UNIT NO:	243752	2020 FORD INTERCEPTOR EXPLORER	WORK ORDER NO:	49749
----------	--------	--------------------------------	----------------	-------

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50151

USING DEPT NO:	507121	OPENED DATE:	03/19/2024 08:15:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/20/2024 14:44:40	METER 1 - M:	23412	METER 2 - H: 5315
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/20/2024 15:21:59	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.08	\$9.08	\$0.00	\$0.00	\$9.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.08	9.08	0.00	5.00	14.08
--------------	-------------------	--	--	--	--	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-021	INSTALL GPS SYSTEM	11074414	03/19/2024 08:36:12	03/19/2024 08:40:49	0.08	\$9.08
LABOR						9.08

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50151

## Work Order Notes

(EHANNAH) install GPS

## Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240193. SH

CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50745

USING DEPT NO:	507121	OPENED DATE:	05/06/2024 08:35:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/24/2024 09:29:51	METER 1 - M:	25040	METER 2 - H: 5465
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2024 11:55:46	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-070	REPLACE NEW DOOR LATCH SWITCH	DON	N	N	GARAGE	0.00	\$0.00	\$479.75	\$0.00	\$479.75
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	N	N	GARAGE	0.00	\$0.00	\$375.65	\$0.00	\$375.65
03-51-044	REPLACE NEW KEY FOB/REMOTE	DON	N	N	GARAGE	0.00	\$0.00	\$63.45	\$0.00	\$63.45
06-02-018	INSPECT DOOR MECHANISM	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
06-13	INSPECT BRAKES	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$60.65	\$0.00	\$60.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 8	WORK ORDER TOTAL:	0.00	0.00	979.50	5.00	984.50
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
03-51-044	REPLACE NEW KEY FOB/REMOTE	GB5Z15K601C	KEY FOB	56.70	1	\$56.70
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWRZ362229	FRONT BRAKES	131.93	1	\$131.93
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAB682616R	FRONT ROTORS	118.04	2	\$236.07
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
03-51-044	REPLACE NEW KEY FOB/REMOTE	CR2032	BUTTON CELL BATTERY 3V	6.75	1	\$6.75
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.67	6	\$34.02
03-02-070	REPLACE NEW DOOR LATCH SWITCH	MB5Z78219A64C	DOOR LATCH	479.75	1	\$479.75
PARTS						979.50

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50745

## Work Order Notes

(EHANNAH) pm- batteries for key clicker- inspect brakes making squeaking noises- pass. door lock not locking with clicker or key

## Job Notes

**03-02-069 - REPLACE NEW DOOR LOCK ACTUATOR**

**03-02-070 - REPLACE NEW DOOR LATCH SWITCH**

(GARAGE) Replaced rf door lock motor. JAW

**03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(GARAGE) Replaced front pads and rotors. JAW

**03-51-044 - REPLACE NEW KEY FOB/REMOTE**

(EHOWELL) Programmed a new transmitter to the vehicle. EH .5 HR

**06-02-018 - INSPECT DOOR MECHANISM**

(IFALLS) Inspected and found passenger door lock motor bad. JAW

**06-13 - INSPECT BRAKES**

(GARAGE) Inspected brakes. Found front pads down to 3mm and rotors are 31.6mm. Need new rotors and pads on front.JAW

**66-13-130 - PERFORM Burnish Brakes**

(GARAGE) Burnished brakes. JAW

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM-GC,FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 25,040

Idle Hours, 5,465

Total Hours, 6,785

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51055

USING DEPT NO:	507121	OPENED DATE:	06/05/2024 16:27:55	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2024 08:14:57	METER 1 - M:	25040	METER 2 - H:	5465				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2024 08:58:09	IN-SERVICE DATE:	08/21/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-02-074	RECALL WINDOW SWITCH	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51055

## Work Order Notes

(EHANNAH) prep and schedule- RECALL power window switch

## Job Notes

### **17-02-074 - RECALL WINDOW SWITCH**

(EHANNAH) LL Ford came to our shop for Recall for power window switch

### **17-GA-005 - RECALL Scheduling and Preparation**

(EHANNAH) prep and scheduling by Denise

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51610

USING DEPT NO:	507121	OPENED DATE:	07/26/2024 07:09:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/30/2024 16:18:34	METER 1 - M:	27991	METER 2 - H: 5465
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/31/2024 15:58:32	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-33-001	INSPECT IGNITION SWITCH	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:		0.00		0.00	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51610

## Work Order Notes

(EHANNAH) transport to FORD for ignition switch

## Job Notes

### 06-33-001 - INSPECT IGNITION SWITCH

(GARAGE) Inspected ignition and found battery was dead. Charged battery and tested good. Started and shutoff unit multiple times for 2 days and had no issues. Scanned unit and found no history codes. Driver will have to bring it back to us if issues arises again. JAW

1hr labor

(GARAGE) BMS did not need resetting. JAW

### 16-71 - TRANSPORT BODY

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51719

USING DEPT NO:	507121	OPENED DATE:	08/06/2024 10:27:05	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	08/15/2024 17:00:11	METER 1 - M:	27991	METER 2 - H:	5465				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/16/2024 07:47:17	IN-SERVICE DATE:	08/21/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-32-002	INSPECT BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 3						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51719

## Work Order Notes

(EHANNAH) Service Call for vehicle not cranking and all dash lights on.

## Job Notes

### **06-32-002 - INSPECT BATTERY**

(GARAGE) Charged battery overnight and let sit in unit for 2 days and did not loose any voltage. Battery tested good. Performed battery draw test and has no draw to it. Released unit. JAW

### **66-79-002 - PERFORM SERVICE CALL**

(EHOWELL) EH/RC went to apartments off campus and jumped the vehicle off. The battery was completely dead. The vehicle was driven back to our shop. No warning lights were illuminated while driving back, however we still need to perform a scan out.

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(GARAGE) Scanned unit out and found no engine codes. JAW



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51874

USING DEPT NO:	507121	OPENED DATE:	08/20/2024 07:17:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/27/2024 09:54:46	METER 1 - M:	28793	METER 2 - H: 5709
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/27/2024 11:38:07	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-065	REPAIR WINDOW SEAL STRIP	DON	N	N	GARAGE	0.00	\$0.00	\$10.50	\$0.00	\$10.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	10.50	5.00	15.50
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-02-065	REPAIR WINDOW SEAL STRIP	GGL78050	SUPER GLUE	10.50	1	\$10.50
PARTS						10.50

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51874

## Work Order Notes

(EHANNAH) repair or remove strip on rear pass. window.

## Job Notes

24-02-065 - REPAIR WINDOW SEAL STRIP

(EHOWELL) TRIED TO GLUE STRIP DOWN, BUT IT WOULD NOT STAY. REMOVED WINDOW STRIP.

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52034

USING DEPT NO:	507121	OPENED DATE:	09/05/2024 09:15:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/05/2024 14:42:40	METER 1 - M:	29125	METER 2 - H: 5786
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2024 07:25:09	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-78-038	REPAIR UNDER CARRIAGE SKID PLATE	DON	N	N	GARAGE	0.00	\$0.00	\$17.82	\$0.00	\$17.82
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$76.40	\$0.00	\$76.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:		0.00	0.00	94.22	5.00	99.22
--------------	-------------------	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-78-038	REPAIR UNDER CARRIAGE SKID PLATES	W715060S450B	CLIPS FOR SKID PLATES EXPL INT	4.46	4	\$17.82
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	14.42	1	\$14.42
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	8.15	6	\$48.87
PARTS						94.22

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52034

## Work Order Notes

(EHANNAH) pm

## Job Notes

### **24-78-038 - REPAIR UNDER CARRIAGE SKID PLATES**

(GARAGE) Removed skid pan for PM, skid pan was missing several bolts and like other UAPD units skid pan was installed incorrectly. Skid pan is installed back in the correct place and missing bolts are added.-GC

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 29,125

Idle Hours, 5,786

Total Hours, 7,297

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52866

USING DEPT NO:	507121	OPENED DATE:	11/21/2024 07:46:02	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	11/27/2024 07:19:02	METER 1 - M:	31551	METER 2 - H:	5786				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/27/2024 07:39:24	IN-SERVICE DATE:	08/21/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer			UNIT SERIAL NO:	1FM5K8AB6LGC15615					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$931.38	\$0.00	\$931.38
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$96.77	\$0.00	\$96.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:					0.00	0.00	1,028.15	5.00	1,033.15
--------------	-------------------	--	--	--	--	------	------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	91852	TIRE 255/60R18 BFG ELITE FORCE	229.50	4	\$918.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.35	4	\$13.38
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	25.26	1	\$25.26
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
PARTS						1028.15

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 52866

## Work Order Notes

(EHANNAH) pm- SI- inspect tires- alignment - inspect front end

## Job Notes

**06-17 - INSPECT TIRES, TUBES, LINERS & VALVES**

**66-17-013 - PERFORM ALIGNMENT**

(GARAGE) performed alignment cm test drove checked ok,

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) FJ-mount and balanced tires

**66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) JR-perform SI per SI sheet

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) FJ/CW- Top

JR- Bottom

FJ/CW topped off fluids, set tire pressure to spec, recorded date codes & tread depths.

JR- Drained oil and swapped oil filter.

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53706

USING DEPT NO:	507121	OPENED DATE:	02/11/2025 07:45:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/13/2025 08:07:08	METER 1 - M:	32040	METER 2 - H: 6440
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/13/2025 13:32:05	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$225.51	\$0.00	\$225.51
06-32-002	INSPECT BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$63.86	\$0.00	\$63.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	289.37	5.00	294.37
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	225.51	1	\$225.51
					PARTS	289.37

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53706

## Work Order Notes

(EHANNAH) pm- inspect battery - driver reports having to jump off to get vehicle here.

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(EHOWELL) EH replaced battery and performed a battery monitoring system reset procedure. The alternator is charging at 14.7 volts.

### **06-32-002 - INSPECT BATTERY**

(EHOWELL) Arrived at UAPD and found the battery dead. The battery was older.

### **66-79-002 - PERFORM SERVICE CALL**

(EHOWELL) UAPD could not jump this vehicle off. EH went to UAPD headquarters and installed a new battery. The customer has been contacted and they're supposed to be bringing this vehicle to our shop for the PM service.

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) JR- topside

FJ- pit

perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid

32040 miles, 6440 idle hours, 8123 total hours

### **CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 53992

USING DEPT NO:	507121	OPENED DATE:	03/06/2025 07:39:49	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	03/17/2025 09:14:59	METER 1 - M:	32147	METER 2 - H:	6440				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/17/2025 09:15:04	IN-SERVICE DATE:	08/21/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53992

## Work Order Notes

(EHANNAH) pm  
(IFALLS) service was performed by dealer

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54240

USING DEPT NO:	507121	OPENED DATE:	03/31/2025 09:46:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/31/2025 09:47:43	METER 1 - M:	32322	METER 2 - H: 6440
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/31/2025 14:38:50	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB6LGC15615	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	2714700	176647		\$0.00
				COMML	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 54240

---

## Work Order Notes

### Job Notes

17-GA-005 - RECALL Scheduling and Preparation

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) stivers performed recall pm

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 54713

USING DEPT NO:	507121	OPENED DATE:	05/08/2025 11:34:52	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	OPEN	COMPLETED DATE:		METER 1 - M:	32551	METER 2 - H:	6440		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	08/21/2020				
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer							
			UNIT SERIAL NO:	1FM5K8AB6LGC15615					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-33-006	TRANSPORT IGNITION LOCK CYLINDEI	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
RY-33-006	REKEY IGNITION LOCK CYLINDER	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 3						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:34:53 By User: GLOBETTI

UNIT NO: 243752 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54713

## Work Order Notes

(CHANNELL) prep-4 sale  
(EHANNAH) tranport and rekey

## Job Notes

16-33-006 - TRANSPORT IGNITION LOCK CYLINDER

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) performed prep disposal cm 32605 miles, cm removed ua decal there was not a gps in vehicle,

RY-33-006 - REKEY IGNITION LOCK CYLINDER

(GARAGE) removed all lock cylinders, from vehicle sent to be re keyed, after being rekeyed installed all lock cylinders tested units checked 3 hours, labor cm

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Wed May 14 2025 08:34:53 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '243752') //Q=