

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 33919

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 08/30/2019 07:39:47 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 09/03/2019 11:28:24 | METER 1 - M: | 1814 | METER 2 - H: 277 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 09/03/2019 11:28:25 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.47 | \$0.00 | \$27.01 | \$0.00 | \$27.01 |

| | | | | | | | | | | |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|
| JOB COUNT: 1 | WORK ORDER TOTAL: | | | | | 0.47 | 0.00 | 27.01 | 0.00 | 27.01 |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|--------------|-------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 08/30/2019 07:46:30 | 08/30/2019 08:03:28 | 0.28 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 08/30/2019 07:50:22 | 08/30/2019 08:01:46 | 0.19 | \$0.00 |
| | | | | | LABOR | 0.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|--------------|--------------|
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.95 | 6 | \$17.70 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 14OZ | 4.28 | 1 | \$4.28 |
| | | | | | PARTS | 27.01 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 33919

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK,JW/AG

Coolant -34'

(AJONES) Engine Idle=200

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 34407

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 10/10/2019 11:38:32 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 10/23/2019 07:29:55 | METER 1 - M: | 3477 | METER 2 - H: 396 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 10/23/2019 07:29:58 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 09-15 | ALIGN STEERING | DON | P | N | GARAGE | 0.52 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRE | DON | O | N | GARAGE | 0.44 | \$0.00 | \$130.25 | \$0.00 | \$130.25 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 1.00 | \$0.00 | \$22.73 | \$0.00 | \$22.73 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEME | DON | O | N | GARAGE | 0.30 | \$0.00 | \$3.55 | \$0.00 | \$3.55 |

| | | | | | | |
|--------------|-------------------|------|------|--------|------|--------|
| JOB COUNT: 4 | WORK ORDER TOTAL: | 2.26 | 0.00 | 156.53 | 0.00 | 156.53 |
|--------------|-------------------|------|------|--------|------|--------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|----------------------------------|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 11901357 | 10/18/2019 07:00:00 | 10/18/2019 07:18:00 | 0.30 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 10/11/2019 08:23:59 | 10/11/2019 08:56:09 | 0.54 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 10/11/2019 08:22:44 | 10/11/2019 08:50:42 | 0.47 | \$0.00 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11074414 | 10/10/2019 13:11:09 | 10/10/2019 13:37:19 | 0.44 | \$0.00 |
| 09-15 | ALIGN STEERING | 11310047 | 10/17/2019 10:19:58 | 10/17/2019 10:51:06 | 0.52 | \$0.00 |

| | | | | | | |
|--|--|--|--|--|-------|------|
| | | | | | LABOR | 0.00 |
|--|--|--|--|--|-------|------|

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|----------------------------------|--------------|--------------------------------|------------|----------|------------|
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 000177 | TIRE P245/55R18 FIREHAWK PURSU | 127.14 | 1 | \$127.14 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 4068 | FILTER- CABIN AIR | 3.55 | 1 | \$3.55 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE 21060 | 2.53 | 1 | \$2.53 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | WHEEL WEIGHT | WHEEL WEIGHT KNOCK ON | 0.29 | 2 | \$0.58 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.95 | 6 | \$17.70 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| | | | | | PARTS | 156.53 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 34407

Work Order Notes

(LISAPATE) PM-RR tire has a hole in the sidewall driver hit a curb

Job Notes

09-15 - ALIGN STEERING

(EKIMBREL) EH checked front end and performed alignment.

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) SH mounted and balanced 2 tires.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) EK/AG. Coolant -20

Syn read 1.54, Reel dispensed 6 qts of 5w20bt

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) AG replaced cabin filter.

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 35071

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 12/06/2019 07:31:17 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 12/09/2019 07:33:28 | METER 1 - M: | 5346 | METER 2 - H: 747 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 12/09/2019 07:33:30 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|------------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALV | DON | P | N | GARAGE | 0.42 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.95 | \$0.00 | \$22.31 | \$0.00 | \$22.31 |

| | | | | | | | | | | |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | | | | | 1.37 | 0.00 | 22.31 | 0.00 | 22.31 |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------------------------|--------------|---------------------|---------------------|----------|------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 12052187 | 12/06/2019 08:08:32 | 12/06/2019 08:20:50 | 0.21 | \$0.00 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 11901357 | 12/06/2019 08:07:30 | 12/06/2019 08:20:11 | 0.21 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 12/06/2019 07:37:33 | 12/06/2019 08:08:32 | 0.52 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 12/06/2019 07:41:21 | 12/06/2019 08:07:30 | 0.44 | \$0.00 |
| | | | | | LABOR | 0.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.88 | 6 | \$17.28 |
| | | | | | PARTS | 22.31 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 35071

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/JW

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 35601

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 02/07/2020 09:34:45 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 02/18/2020 07:51:04 | METER 1 - M: | 5346 | METER 2 - H: 747 |
| WO VISIT REASON: | UNSCHEDULED | CLOSED DATE: | 02/18/2020 07:51:06 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|------------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 15-13-028 | WARRANTY ABS ECU/ECM | DON | W | J | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALV | DON | P | N | GARAGE | 0.33 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.42 | \$0.00 | \$22.73 | \$0.00 | \$22.73 |
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC | DON | O | N | GARAGE | 2.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | |
|--------------|-------------------|------|------|-------|------|-------|
| JOB COUNT: 4 | WORK ORDER TOTAL: | 2.75 | 0.00 | 22.73 | 0.00 | 22.73 |
|--------------|-------------------|------|------|-------|------|-------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|-----------|----------------------|------------|-------------|--------------------|------------|
| 15-13-028 | WARRANTY ABS ECU/ECM | 4910000 | 594064 | | \$0.00 |
| | | | | COMML | 0.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|---------------------------------------|--------------|---------------------|---------------------|----------|------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 11074414 | 02/12/2020 15:37:45 | 02/12/2020 15:57:40 | 0.33 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 02/12/2020 15:12:36 | 02/12/2020 15:37:45 | 0.42 | \$0.00 |
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC SYSTEM | 11170580 | 02/13/2020 07:00:00 | 02/13/2020 09:00:00 | 2.00 | \$0.00 |
| | | | | LABOR | 0.00 | |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.95 | 6 | \$17.70 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| | | | | | PARTS | 22.73 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 35601

Work Order Notes

(EKIMBREL) pm

Job Notes

15-13-028 - WARRANTY ABS ECU/ECM

(EKIMBREL) Town & Country tech performed recall 19B12, ABS module software update.

15-13-103 - WARRANTY ABS SENSOR

(EKIMBREL) Town & Country tech performed recall 19B12, ABS module so

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(EKIMBREL) SH/JW/EH/RC rotated tires.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) SH/SH. Coolant -50

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EKIMBREL) AB scanned out with IDS. Codes: C0061:64 AB Lateral Acceleration Sensor, V0415:00-OA Invalid data received from ABS

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 36015

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 03/13/2020 07:39:40 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 03/13/2020 09:34:54 | METER 1 - M: | 8498 | METER 2 - H: 1166 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 03/24/2020 08:43:53 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|------------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALV | DON | P | N | GARAGE | 0.34 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.45 | \$0.00 | \$28.37 | \$0.00 | \$28.37 |

| | | | | | | |
|--------------|-------------------|------|------|-------|------|-------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | 0.79 | 0.00 | 28.37 | 0.00 | 28.37 |
|--------------|-------------------|------|------|-------|------|-------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------------------------|--------------|---------------------|---------------------|----------|------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 11074414 | 03/13/2020 08:10:41 | 03/13/2020 08:31:08 | 0.34 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 03/13/2020 07:48:04 | 03/13/2020 08:10:41 | 0.38 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 03/13/2020 07:54:59 | 03/13/2020 07:59:21 | 0.07 | \$0.00 |
| | | | | | LABOR | 0.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------------------------|----------|-------------------|------------|----------|------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 5W20TQT | 5W20 FULL SYN QTS | 3.89 | 6 | \$23.34 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 5W20TQT | 5W20 FULL SYN QTS | 3.89 | (6) | (\$23.34) |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20TQT | 5W20 FULL SYN QTS | 3.89 | 6 | \$23.34 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | FL500S | FILTER-OIL FORD | 5.03 | (1) | (\$5.03) |
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| | | | | | PARTS | 28.37 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 36015

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires and relearned tire positions

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 36617

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 05/29/2020 07:37:30 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 05/29/2020 14:36:28 | METER 1 - M: | 9885 | METER 2 - H: 1357 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 05/29/2020 14:40:47 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.74 | \$0.00 | \$27.02 | \$0.00 | \$27.02 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | DON | O | N | GARAGE | 0.05 | \$0.00 | \$3.55 | \$0.00 | \$3.55 |

| | | | | | | | | | | |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | | | | | 0.79 | 0.00 | 30.57 | 0.00 | 30.57 |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|----------------------------------|--------------|---------------------|---------------------|--------------|-------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 05/29/2020 07:43:21 | 05/29/2020 08:20:12 | 0.61 | \$0.00 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 11901357 | 05/29/2020 08:11:29 | 05/29/2020 08:14:20 | 0.05 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 05/29/2020 08:03:54 | 05/29/2020 08:11:29 | 0.13 | \$0.00 |
| | | | | | LABOR | 0.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|----------------------------------|----------|--------------------------------|------------|--------------|--------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.95 | 6 | \$17.70 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 4068 | FILTER- CABIN AIR | 3.55 | 1 | \$3.55 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 14OZ | 4.29 | 1 | \$4.29 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| | | | | | PARTS | 30.57 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 36617

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG,JW/JW performed pm. Coolant -34

(IFALLS) Will install survey tire on next pm

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) AG replaced cabin filter.

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 36672

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 06/03/2020 08:56:33 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 06/04/2020 10:58:39 | METER 1 - M: | 10106 | METER 2 - H: 1368 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 06/05/2020 11:01:06 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|----------|---|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 09-15 | ALIGN STEERING | DON | O | N | GARAGE | 0.44 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| SU-17 | SURVEY TEST TIRES, TUBES, LINERS & VALVES | DON | O | N | GARAGE | 0.50 | \$0.00 | \$11.86 | \$0.00 | \$11.86 |

| | | | | | | | | | | |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | | | | | 0.94 | 0.00 | 11.86 | 0.00 | 11.86 |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|----------|---|--------------|---------------------|---------------------|----------|------------|
| SU-17 | SURVEY TEST TIRES, TUBES, LINERS & VALVES | 11213180 | 06/04/2020 07:00:00 | 06/04/2020 07:30:00 | 0.50 | \$0.00 |
| 09-15 | ALIGN STEERING | 11170580 | 06/04/2020 08:27:50 | 06/04/2020 08:54:06 | 0.44 | \$0.00 |
| | | | | | LABOR | 0.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|----------|---|--------------|--------------------------|------------|----------|------------|
| SU-17 | SURVEY TEST TIRES, TUBES, LINERS & VALVES | 23131 | TPMS SNAP IN VALVE 21060 | 2.56 | 4 | \$10.24 |
| SU-17 | SURVEY TEST TIRES, TUBES, LINERS & VALVES | WHEEL WEIGHT | WHEEL WEIGHT KNOCK ON | 0.27 | 6 | \$1.62 |
| | | | | | PARTS | 11.86 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 36672

Work Order Notes

(LISAPATE) Install 4 survey tires and align

(LISAPATE) Per Patrick Hinkle do no do Covid software program on this unit.

Job Notes

09-15 - ALIGN STEERING

(ABBLACK) AB performed alignment

SU-17 - SURVEY TEST TIRES, TUBES, LINERS & VALVES

(LISAPATE) MS Mounted and balanced 4 General GMax Pursuit survey tires

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 36972

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 06/29/2020 15:00:07 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 07/28/2020 11:57:21 | METER 1 - M: | 10169 | METER 2 - H: 1767 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 07/29/2020 12:21:39 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 16-71 | TRANSPORT BODY | DON | O | N | GARAGE | 0.31 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 24-71 | REPAIR BODY | DON | A | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2,000.00 | \$2,000.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.26 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | |
|--------------|-------------------|------|------|------|----------|----------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.57 | 0.00 | 0.00 | 2,000.00 | 2,000.00 |
|--------------|-------------------|------|------|------|----------|----------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|-----------------|------------|-------------|--------------------|------------|
| 24-71 | REPAIR BODY | 11150605 | 1690133 | | \$2,000.00 |
| COMML | | | | | 2000.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|----------|------------|
| 16-71 | TRANSPORT BODY | 10208562 | 06/30/2020 10:01:07 | 06/30/2020 10:19:25 | 0.31 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 07/24/2020 13:23:56 | 07/24/2020 13:39:41 | 0.26 | \$0.00 |
| LABOR | | | | | | 0.00 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 36972

Work Order Notes

(LISAPATE) Unit was side swiped at Hinkle's house. Take to Andrews to repair body damage to both passenger doors and RF wheel area to be paid by State Auto

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by EK

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired Body damage on the right side both doors. PD by State Auto per estimate. UA pd \$2000.00 Ded See attached

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Did not drop oil at this time. Unit has only been 209 miles since last service. Checked fluids, battery and tire pressures. Updated sticker

Coolant -34'

JW

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 37408

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 08/21/2020 14:28:50 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 08/31/2020 11:09:19 | METER 1 - M: | 10169 | METER 2 - H: 1767 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 08/31/2020 13:10:49 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|------------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 03-01-004 | REPLACE NEW BLOWER MOTOR | DON | O | N | GARAGE | 0.43 | \$0.00 | \$116.65 | \$0.00 | \$116.65 |
| 03-01-014 | REPLACE NEW RESISTOR | DON | O | N | GARAGE | 0.25 | \$0.00 | \$44.60 | \$0.00 | \$44.60 |
| 35-01 | DIAGNOSE AIR CONDITIONING, HEAT, ' | DON | O | N | GARAGE | 0.35 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | |
|--------------|-------------------|------|------|--------|------|--------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 1.03 | 0.00 | 161.25 | 0.00 | 161.25 |
|--------------|-------------------|------|------|--------|------|--------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|---------------------------------------|--------------|---------------------|---------------------|----------|------------|
| 03-01-014 | REPLACE NEW RESISTOR | 11213180 | 08/27/2020 14:11:34 | 08/27/2020 14:11:54 | (0.01) | \$0.00 |
| 03-01-014 | REPLACE NEW RESISTOR | 11213180 | 08/27/2020 14:11:34 | 08/27/2020 14:11:54 | 0.01 | \$0.00 |
| 03-01-014 | REPLACE NEW RESISTOR | 11213180 | 08/27/2020 14:11:34 | 08/27/2020 14:26:34 | 0.25 | \$0.00 |
| 03-01-004 | REPLACE NEW BLOWER MOTOR | 11213180 | 08/27/2020 13:56:38 | 08/27/2020 14:11:27 | 0.25 | \$0.00 |
| 35-01 | DIAGNOSE AIR CONDITIONING, HEAT, VENT | 11213180 | 08/24/2020 09:30:00 | 08/24/2020 09:46:13 | 0.27 | \$0.00 |
| 35-01 | DIAGNOSE AIR CONDITIONING, HEAT, VENT | 11213180 | 08/24/2020 09:09:57 | 08/24/2020 09:15:00 | 0.08 | \$0.00 |
| 03-01-004 | REPLACE NEW BLOWER MOTOR | 11213180 | 08/24/2020 08:58:45 | 08/24/2020 09:09:42 | 0.18 | \$0.00 |
| | | | | | LABOR | 0.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------------|-------------|----------------------------|------------|----------|------------|
| 03-01-014 | REPLACE NEW RESISTOR | AE9Z19E624C | BLOWER CONTROL RESISTOR | 44.60 | 1 | \$44.60 |
| 03-01-004 | REPLACE NEW BLOWER MOTOR | AE9Z19805D | HVAC AUX BLOWER MOTOR ASSY | 116.65 | 1 | \$116.65 |
| 03-01-014 | REPLACE NEW RESISTOR | RU573 | BLOWER MOTOR RESISTOR | 64.74 | (1) | (\$64.74) |
| 03-01-004 | REPLACE NEW BLOWER MOTOR | 700274 | BLOWER MOTOR ASSEMBLY | 63.46 | (1) | (\$63.46) |
| 03-01-014 | REPLACE NEW RESISTOR | RU573 | BLOWER MOTOR RESISTOR | 64.74 | 1 | \$64.74 |
| 03-01-004 | REPLACE NEW BLOWER MOTOR | 700274 | BLOWER MOTOR ASSEMBLY | 63.46 | 1 | \$63.46 |
| | | | | | PARTS | 161.25 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 37408

Work Order Notes

(LISAPATE) Rear A/C will not blow

Job Notes

03-01-004 - REPLACE NEW BLOWER MOTOR

(MSIDES) Replaced new rear blower motor. MS

03-01-014 - REPLACE NEW RESISTOR

(MSIDES) Replaced rear blower motor resistor. Ms

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(MSIDES) Found blower motor to work intermittently due to excessive debris on motor. Ordered new motor and resistor. MS

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 37497

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 09/03/2020 07:53:47 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 09/03/2020 09:51:34 | METER 1 - M: | 11314 | METER 2 - H: 1550 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 09/04/2020 13:19:21 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|------------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALV | DON | P | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.91 | \$0.00 | \$22.79 | \$0.00 | \$22.79 |

| | | | | | | | | | | |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | | | | | 0.91 | 0.00 | 22.79 | 0.00 | 22.79 |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------------------------|--------------|---------------------|---------------------|----------|------------|
| 31-17 | ROTATE TIRES, TUBES, LINERS & VALVES | 12052187 | 09/03/2020 08:39:57 | 09/03/2020 08:40:13 | 0.00 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 09/03/2020 08:04:25 | 09/03/2020 08:39:34 | 0.59 | \$0.00 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 09/03/2020 08:04:41 | 09/03/2020 08:24:04 | 0.32 | \$0.00 |
| | | | | | LABOR | 0.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 5.03 | 1 | \$5.03 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 2.96 | 6 | \$17.76 |
| | | | | | PARTS | 22.79 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 37497

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(JWRIGHT) Did not rotate tires at this time

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34° JAW/SH
(IFALLS) also checked tire pressure

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 37537

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 09/09/2020 07:46:49 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 09/09/2020 09:58:20 | METER 1 - M: | 11461 | METER 2 - H: 1571 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 09/09/2020 15:37:31 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRE | DON | O | N | GARAGE | 0.20 | \$0.00 | \$129.26 | \$0.00 | \$129.26 |
| 66-17-030 | PERFORM TIRE PATCH | DON | O | N | GARAGE | 0.36 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | | | | | |
|--------------|-------------------|--|--|--|--|------|------|--------|------|--------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | | | | | 0.56 | 0.00 | 129.26 | 0.00 | 129.26 |
|--------------|-------------------|--|--|--|--|------|------|--------|------|--------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|---------------------------------|--------------|---------------------|---------------------|----------|------------|
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11901357 | 09/09/2020 08:17:27 | 09/09/2020 08:29:27 | 0.20 | \$0.00 |
| 66-17-030 | PERFORM TIRE PATCH | 11901357 | 09/09/2020 07:55:37 | 09/09/2020 08:17:27 | 0.36 | \$0.00 |
| | | | | | LABOR | 0.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|---------------------------------|--------------|--------------------------------|------------|----------|------------|
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 1555395 | TIRE 245/55R18 GEN GMAXPURSUIT | 126.42 | 1 | \$126.42 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | WHEEL WEIGHT | WHEEL WEIGHT KNOCK ON | 0.28 | 1 | \$0.28 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE 21060 | 2.56 | 1 | \$2.56 |
| | | | | | PARTS | 129.26 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 37537

Work Order Notes

(LISAPATE) Nail in LF tire

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Replaced and balanced L/F tire. Retained old survey tire. AMG AB

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) Could not patch tire had to install new tire

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 38311

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 11/09/2020 07:49:30 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 11/09/2020 10:37:07 | METER 1 - M: | 13077 | METER 2 - H: 1842 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 11/10/2020 07:10:02 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------|------|-----|------|---------|-----------|----------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 2.62 | \$308.64 | \$41.78 | \$0.00 | \$350.42 |

| | | | | | | |
|--------------|-------------------|------|--------|-------|------|--------|
| JOB COUNT: 1 | WORK ORDER TOTAL: | 2.62 | 308.64 | 41.78 | 0.00 | 350.42 |
|--------------|-------------------|------|--------|-------|------|--------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|--------------|---------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 11/09/2020 07:56:22 | 11/09/2020 10:07:16 | 2.18 | \$257.44 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 11/09/2020 07:56:22 | 11/09/2020 08:22:24 | 0.43 | \$51.20 |
| | | | | | LABOR | 308.64 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|--------------|--------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.43 | 6 | \$26.55 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 8.37 | 1 | \$8.37 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 14OZ | 6.86 | 1 | \$6.86 |
| | | | | | PARTS | 41.78 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 38311

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Completed PM topside, Scott was bottomside. Completed checklist. Washed, vacuumed and fueled up vehicle. AMG SH

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 38726

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 01/08/2021 09:57:41 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 01/13/2021 07:43:27 | METER 1 - M: | 14727 | METER 2 - H: 2097 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 01/13/2021 12:51:29 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 03-02-010 | REPLACE NEW MIRRORS | DON | O | N | GARAGE | 0.77 | \$90.96 | \$307.20 | \$0.00 | \$398.16 |

| | | | | | | | | | | |
|---------------------|--------------------------|--|--|--|--|-------------|--------------|---------------|-------------|---------------|
| JOB COUNT: 1 | WORK ORDER TOTAL: | | | | | 0.77 | 90.96 | 307.20 | 0.00 | 398.16 |
|---------------------|--------------------------|--|--|--|--|-------------|--------------|---------------|-------------|---------------|

| <u>Job Code</u> | <u>Job Description</u> | <u>Employee No.</u> | <u>Start</u> | <u>Finish</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|---------------------|---------------------|---------------------|-----------------|-------------------|
| 03-02-010 | REPLACE NEW MIRRORS | 11213180 | 01/11/2021 11:13:45 | 01/11/2021 12:00:00 | 0.77 | \$90.96 |
| | | | | | LABOR | 90.96 |

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------|-----------------|---------------------|-------------------|-----------------|-------------------|
| 03-02-010 | REPLACE NEW MIRRORS | DB5Z17682UK | RH DOOR MIRROR ASSY | 307.20 | 1 | \$307.20 |
| | | | | | PARTS | 307.20 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: **243200** **2019 FORD INTERCEPTOR**

WORK ORDER NO: **38726**

Work Order Notes

(RTUNAITI) RH door mirror assembly is broken.

Job Notes

03-02-010 - REPLACE NEW MIRRORS

(MSIDES) Replaced passenger side mirror had to transfer corner strobe to new mirror requiring disassembly of new mirror. Add 1.0 hrs for mirror disassembly. MS

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 38888

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 01/25/2021 08:08:16 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 01/25/2021 12:25:14 | METER 1 - M: | 14981 | METER 2 - H: 2134 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 01/26/2021 07:23:38 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.64 | \$75.09 | \$48.37 | \$0.00 | \$123.46 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | DON | O | N | GARAGE | 0.10 | \$11.80 | \$12.14 | \$0.00 | \$23.94 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | 0.74 | 86.89 | 60.51 | 0.00 | 147.40 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|----------------------------------|--------------|---------------------|---------------------|--------------|--------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 11074414 | 01/25/2021 09:01:48 | 01/25/2021 09:07:48 | 0.10 | \$11.80 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 01/25/2021 08:23:37 | 01/25/2021 09:01:48 | 0.64 | \$75.09 |
| | | | | | LABOR | 86.89 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|----------------------------------|----------|--------------------------------|------------|--------------|--------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 800151C | CABIN AIR FILTER REPL 4068 | 12.14 | 1 | \$12.14 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 8.37 | 1 | \$8.37 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 800151C | CABIN AIR FILTER REPL 4068 | 12.14 | (1) | (\$12.14) |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 800151C | CABIN AIR FILTER REPL 4068 | 12.14 | 1 | \$12.14 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5066517 | WSWF RAIN-X -20DEG DEICER GAL | 6.89 | 1 | \$6.89 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 14OZ | 6.56 | 1 | \$6.56 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.43 | 6 | \$26.55 |
| | | | | | PARTS | 60.51 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 38888

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 14981 Engine hours 2706 Idle hours 2134. SH JW / AMG Performed PM. JW Vacuumed SH washed and filled with gas.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) SH replaced cabin filter.

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 39640

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 04/13/2021 07:58:03 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 04/14/2021 10:37:44 | METER 1 - M: | 17698 | METER 2 - H: 2481 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 04/14/2021 14:01:14 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.23 | \$27.11 | \$31.13 | \$0.00 | \$58.24 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|-------|
| JOB COUNT: 1 | WORK ORDER TOTAL: | 0.23 | 27.11 | 31.13 | 0.00 | 58.24 |
|--------------|-------------------|------|-------|-------|------|-------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 04/13/2021 09:52:54 | 04/13/2021 10:06:41 | 0.23 | \$27.11 |
| | | | | | LABOR | 27.11 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.43 | 6 | \$26.55 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 4.58 | 1 | \$4.58 |
| | | | | | PARTS | 31.13 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 39640

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°JAW/SH

MILEAGE-17698

IDLE HRS-2481

ENG HRS-3164

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 40237

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 06/23/2021 12:22:37 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 06/30/2021 11:57:53 | METER 1 - M: | 20023 | METER 2 - H: 2782 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 07/06/2021 10:41:33 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|------------------------------------|------|-----|------|---------|-----------|----------|----------|------------|------------|
| 03-01-004 | REPLACE NEW BLOWER MOTOR | DON | O | N | GARAGE | 0.41 | \$48.77 | \$181.19 | \$0.00 | \$229.96 |
| 03-32-002 | REPLACE NEW BATTERY | DON | O | N | GARAGE | 0.32 | \$38.02 | \$115.49 | \$0.00 | \$153.51 |
| 06-15 | INSPECT STEERING | DON | O | N | GARAGE | 0.27 | \$31.40 | \$0.00 | \$0.00 | \$31.40 |
| 35-01 | DIAGNOSE AIR CONDITIONING, HEAT, ' | DON | O | N | GARAGE | 0.54 | \$63.20 | \$0.00 | \$0.00 | \$63.20 |
| 66-17-013 | PERFORM ALIGNMENT | DON | O | N | GARAGE | 0.64 | \$75.72 | \$0.00 | \$0.00 | \$75.72 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRE | DON | O | N | GARAGE | 1.82 | \$215.09 | \$786.42 | \$0.00 | \$1,001.51 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.98 | \$115.74 | \$47.04 | \$0.00 | \$162.78 |

| | | | | | | |
|--------------|-------------------|------|--------|----------|------|----------|
| JOB COUNT: 7 | WORK ORDER TOTAL: | 4.98 | 587.94 | 1,130.14 | 0.00 | 1,718.08 |
|--------------|-------------------|------|--------|----------|------|----------|

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|---------------------------------------|--------------|---------------------|---------------------|----------|------------|
| 35-01 | DIAGNOSE AIR CONDITIONING, HEAT, VENT | 11213180 | 06/24/2021 12:56:01 | 06/24/2021 13:28:09 | 0.54 | \$63.20 |
| 03-01-004 | REPLACE NEW BLOWER MOTOR | 11213180 | 06/24/2021 12:30:54 | 06/24/2021 12:55:42 | 0.41 | \$48.77 |
| 66-17-013 | PERFORM ALIGNMENT | 11310047 | 06/24/2021 08:16:59 | 06/24/2021 08:55:29 | 0.64 | \$75.72 |
| 06-15 | INSPECT STEERING | 11901357 | 06/24/2021 08:17:49 | 06/24/2021 08:33:47 | 0.27 | \$31.40 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11901357 | 06/24/2021 07:21:22 | 06/24/2021 08:16:26 | 0.92 | \$108.30 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 11074414 | 06/24/2021 07:21:54 | 06/24/2021 08:16:12 | 0.91 | \$106.79 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 06/23/2021 14:01:52 | 06/23/2021 14:35:08 | 0.55 | \$65.42 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 06/23/2021 14:02:30 | 06/23/2021 14:28:05 | 0.43 | \$50.31 |
| 03-32-002 | REPLACE NEW BATTERY | 11901357 | 06/23/2021 13:42:07 | 06/23/2021 14:01:27 | 0.32 | \$38.02 |

LABOR 587.93

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------------|----------|------------------------------|------------|----------|------------|
| 03-01-004 | REPLACE NEW BLOWER MOTOR | SHIPPING | SHIPPING AND HANDLING | 39.00 | 1 | \$39.00 |
| 03-01-004 | REPLACE NEW BLOWER MOTOR | FOR75869 | BLOWER MOTOR | 142.19 | 1 | \$142.19 |
| 03-32-002 | REPLACE NEW BATTERY | 650 | BATTERY BCI 65 650 CCA | 113.55 | 1 | \$113.55 |
| 03-32-002 | REPLACE NEW BATTERY | 01253 | BATT TERM PROTECTOR, PAIR PK | 1.94 | 1 | \$1.94 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|---------------------------------|-----------------|--------------------------------|-------------------|-----------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.43 | 6 | \$26.55 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 9.78 | 1 | \$9.78 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 78864 | TIRE 245/55R18 BFG ADV T/A SPT | 191.70 | 4 | \$766.80 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | WHEEL WEIGHT | WHEEL WEIGHT KNOCK ON | 0.50 | 8 | \$3.96 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE 21060 | 3.92 | 4 | \$15.66 |
| | | | | | PARTS | 1130.14 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 40237

Work Order Notes

(CHANNELL) pm\ rear a/c not working\ check tires

Job Notes

03-01-004 - REPLACE NEW BLOWER MOTOR

(EKIMBREL) Replaced blower motor and cleaned off resistor. MS. There is a \$26 shipping fee because we had to get blower motor shipped across country. Without that it would have taken a week or more. No warehouses in surrounding state had one available.

03-32-002 - REPLACE NEW BATTERY

(EHOWELL) Replaced battery and checked charging system, good at 14.7. AMG. Reset battery monitoring system. EH

06-15 - INSPECT STEERING

(AGUERRA) Checked front end, no issues found. AMG JW

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(MSIDES) Found rear blower motor to be randomly shorting out due to dog hair and dirt. MS

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) Replaced and balanced all 4 tires, reset TPMS. AMG SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 20023 hours: 3551 idle hours: 2782 Completed PM topside, Josh was bottomside. Completed checklist. Vehicle needs new set of tires. AMG/JW

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 41082

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 09/21/2021 07:43:50 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 09/22/2021 11:53:54 | METER 1 - M: | 22429 | METER 2 - H: 3113 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 09/23/2021 08:46:53 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.02 | \$2.16 | \$31.82 | \$0.00 | \$33.98 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.48 | \$56.31 | \$63.02 | \$0.00 | \$119.33 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.50 | 58.47 | 94.84 | 2.00 | 155.31 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| | | | | COMML | 2.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------------|--------------|---------------------|---------------------|----------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 11074414 | 09/21/2021 09:13:54 | 09/21/2021 09:15:00 | 0.02 | \$2.16 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 09/21/2021 08:45:05 | 09/21/2021 09:13:43 | 0.48 | \$56.31 |
| | | | | LABOR | | 58.47 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 4.86 | 1 | \$4.86 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.44 | 6 | \$26.64 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 60-011-G | WIPER-REAR FORD EXPLORER | 9.20 | 1 | \$9.20 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 10.19 | 1 | \$10.19 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19260 | WIPER BLADE 26 IN OE BEAM | 12.43 | 1 | \$12.43 |
| 66-PM-PMA | PERFORM OIL CHANGE | 46935 | AIR FILTER-SECURITY INTERCEP. | 20.81 | 1 | \$20.81 |
| | | | | PARTS | | 94.84 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 41082

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 22429 Engine hours 3968 Idle hours 3113. SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 41641

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 11/16/2021 08:11:24 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 11/19/2021 14:18:46 | METER 1 - M: | 24425 | METER 2 - H: 3448 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 11/22/2021 08:00:44 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.05 | \$5.64 | \$31.82 | \$0.00 | \$37.46 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.51 | \$60.64 | \$46.41 | \$0.00 | \$107.05 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | DON | O | N | GARAGE | 0.01 | \$0.75 | \$14.37 | \$0.00 | \$15.12 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 4 | WORK ORDER TOTAL: | 0.57 | 67.03 | 92.60 | 2.00 | 161.63 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| | | | | COMML | 2.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|----------------------------------|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 11074414 | 11/16/2021 11:46:55 | 11/16/2021 11:47:18 | 0.01 | \$0.75 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 11074414 | 11/16/2021 11:43:53 | 11/16/2021 11:46:45 | 0.05 | \$5.64 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 11/16/2021 11:33:11 | 11/16/2021 11:43:38 | 0.17 | \$20.55 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 11/16/2021 10:29:07 | 11/16/2021 10:49:30 | 0.34 | \$40.09 |
| | | | | LABOR | | 67.03 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|----------------------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 4068 | FILTER- CABIN AIR | 14.37 | 1 | \$14.37 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 800151C | CABIN AIR FILTER REPL 4068 | 11.67 | (1) | (\$11.67) |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 800151C | CABIN AIR FILTER REPL 4068 | 11.67 | 1 | \$11.67 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 9.15 | 1 | \$9.15 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.43 | 6 | \$26.55 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 60-011-G | WIPER-REAR FORD EXPLORER | 9.20 | 1 | \$9.20 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 10.19 | 1 | \$10.19 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19260 | WIPER BLADE 26 IN OE BEAM | 12.43 | 1 | \$12.43 |

Work Order Charge Detail

| | |
|-------|-------|
| PARTS | 92.60 |
|-------|-------|

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 41641

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 42164

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 01/25/2022 07:52:22 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 01/25/2022 11:16:13 | METER 1 - M: | 26537 | METER 2 - H: 3747 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 01/25/2022 14:08:20 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.08 | \$8.85 | \$46.80 | \$0.00 | \$55.65 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | | | | | |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | | | | | 0.08 | 8.85 | 46.80 | 2.00 | 57.65 |
|--------------|-------------------|--|--|--|--|------|------|-------|------|-------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| COMML | | | | | 2.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 01/25/2022 08:24:43 | 01/25/2022 08:29:13 | 0.08 | \$8.85 |
| LABOR | | | | | | 8.85 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 9.54 | 1 | \$9.54 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.43 | 6 | \$26.55 |
| PARTS | | | | | | 46.80 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 42164

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH

MILEAGE-26537

ENG HRS-4748

IDLE HRS-3747

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 42807

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 04/04/2022 08:18:32 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 04/04/2022 14:49:19 | METER 1 - M: | 28645 | METER 2 - H: 4051 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 04/15/2022 09:23:03 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.15 | \$17.70 | \$31.82 | \$0.00 | \$49.52 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.37 | \$43.92 | \$42.74 | \$0.00 | \$86.66 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.52 | 61.62 | 74.56 | 2.00 | 138.18 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| COMML | | | | | 2.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------------|--------------|---------------------|---------------------|----------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 11901357 | 04/06/2022 07:00:00 | 04/06/2022 07:09:00 | 0.15 | \$17.70 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 04/04/2022 09:44:22 | 04/04/2022 10:06:42 | 0.37 | \$43.92 |
| LABOR | | | | | | 61.62 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------------|----------|--------------------------------|------------|----------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 60-011-G | WIPER-REAR FORD EXPLORER | 9.20 | 1 | \$9.20 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 10.19 | 1 | \$10.19 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19260 | WIPER BLADE 26 IN OE BEAM | 12.43 | 1 | \$12.43 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 5.39 | 1 | \$5.39 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 4.44 | 6 | \$26.64 |
| PARTS | | | | | | 74.56 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 42807

Work Order Notes

(CHANNELL) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 28645 hours: 5136 idle hours: 4051 Completed PM topside, Josh assisted, Scott was bottomsides. Completed checklist. AMG JW/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 43006

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 04/21/2022 13:51:42 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 04/22/2022 11:24:50 | METER 1 - M: | 28645 | METER 2 - H: 4051 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 04/25/2022 08:12:43 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------------|------|-----|------|---------|-----------|----------|----------|------------|------------|
| 03-01-004 | REPLACE NEW BLOWER MOTOR | DON | O | N | GARAGE | 1.60 | \$188.80 | \$176.97 | \$0.00 | \$365.77 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | |
|--------------|-------------------|------|--------|--------|------|--------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | 1.60 | 188.80 | 176.97 | 2.00 | 367.77 |
|--------------|-------------------|------|--------|--------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| | | | | COMML | 2.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------------|--------------|---------------------|---------------------|----------|------------|
| 03-01-004 | REPLACE NEW BLOWER MOTOR | 11310047 | 04/21/2022 14:04:05 | 04/21/2022 15:40:05 | 1.60 | \$188.80 |
| | | | | | LABOR | 188.80 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------------|------------|----------------------------|------------|----------|------------|
| 03-01-004 | REPLACE NEW BLOWER MOTOR | AE9Z19805D | HVAC AUX BLOWER MOTOR ASSY | 176.97 | 1 | \$176.97 |
| 03-01-004 | REPLACE NEW BLOWER MOTOR | AE9Z19805D | HVAC AUX BLOWER MOTOR ASSY | 176.97 | (1) | (\$176.97) |
| 03-01-004 | REPLACE NEW BLOWER MOTOR | AE9Z19805D | HVAC AUX BLOWER MOTOR ASSY | 176.97 | 1 | \$176.97 |
| | | | | | PARTS | 176.97 |

Work Order Charge Detail

| | | | | |
|----------|--------|-----------------------|----------------|-------|
| UNIT NO: | 243200 | 2019 FORD INTERCEPTOR | WORK ORDER NO: | 43006 |
|----------|--------|-----------------------|----------------|-------|

Work Order Notes

(EKIMBREL) REPLACE REAR BLOWER MOTOR

Job Notes

03-01-004 - REPLACE NEW BLOWER MOTOR

(EKIMBREL) EH REPLACED REAR BLOWER MOTOR

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 43694

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 06/21/2022 07:22:32 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 06/22/2022 10:44:59 | METER 1 - M: | 30908 | METER 2 - H: 4373 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 06/27/2022 13:43:25 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.44 | \$51.53 | \$63.77 | \$0.00 | \$115.30 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | 0.44 | 51.53 | 63.77 | 2.00 | 117.30 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| COMML | | | | | 2.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 06/21/2022 07:37:23 | 06/21/2022 07:44:06 | 0.11 | \$13.21 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12052187 | 06/21/2022 07:28:05 | 06/21/2022 07:38:21 | 0.17 | \$20.19 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 06/21/2022 07:28:18 | 06/21/2022 07:37:31 | 0.15 | \$18.13 |
| LABOR | | | | | | 51.53 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 10.71 | 1 | \$10.71 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 11.24 | 1 | \$11.24 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 14OZ | 6.90 | 1 | \$6.90 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 5.82 | 6 | \$34.92 |
| PARTS | | | | | | 63.77 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 43694

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 30908 hours: 5551 idle hours: 4373 Completed PM topside, Josh assisted, Scott was bottomsides. Completed checklist. AMG JW/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 44369

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 08/18/2022 07:56:15 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 08/19/2022 14:15:19 | METER 1 - M: | 33522 | METER 2 - H: 4626 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 08/22/2022 09:09:32 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------------------|------|-----|------|---------|-----------|----------|----------|------------|------------|
| 06-15 | INSPECT STEERING | DON | O | N | GARAGE | 0.61 | \$71.49 | \$0.00 | \$0.00 | \$71.49 |
| 09-15 | ALIGN STEERING | DON | O | N | GARAGE | 0.27 | \$31.37 | \$0.00 | \$0.00 | \$31.37 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRE | DON | O | N | GARAGE | 1.10 | \$129.96 | \$849.87 | \$0.00 | \$979.83 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.15 | \$17.57 | \$47.97 | \$0.00 | \$65.54 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2.00 | \$2.00 |

| | | | | | | |
|--------------|-------------------|------|--------|--------|------|----------|
| JOB COUNT: 5 | WORK ORDER TOTAL: | 2.12 | 250.39 | 897.84 | 2.00 | 1,150.23 |
|--------------|-------------------|------|--------|--------|------|----------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$2.00 |
| | | | | COMML | 2.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|---------------------------------|--------------|---------------------|---------------------|----------|------------|
| 06-15 | INSPECT STEERING | 11310047 | 08/18/2022 13:14:12 | 08/18/2022 13:50:33 | 0.61 | \$71.49 |
| 09-15 | ALIGN STEERING | 11310047 | 08/18/2022 11:39:06 | 08/18/2022 11:55:03 | 0.27 | \$31.37 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 12052187 | 08/18/2022 10:19:36 | 08/18/2022 11:25:41 | 1.10 | \$129.96 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 08/18/2022 09:46:10 | 08/18/2022 09:55:06 | 0.15 | \$17.57 |
| | | | | | LABOR | 250.39 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|---------------------------------|-----------|--------------------------------|------------|----------|------------|
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58102 | .75 OZ WHEEL WEIGHT | 0.45 | 1 | \$0.45 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58103 | 1.00 OZ WHEEL WEIGHT | 0.57 | 5 | \$2.85 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 58106 | 1.75 OZ WHEEL WEIGHT | 0.81 | 1 | \$0.81 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 732026500 | GDY EAGLE RS-A POLIC 245/55R18 | 209.13 | 4 | \$836.52 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 11.43 | 1 | \$11.43 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.09 | 6 | \$36.54 |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES | 23131 | TPMS SNAP IN VALVE 21060 | 2.31 | 4 | \$9.24 |
| | | | | | PARTS | 897.84 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 44369

Work Order Notes

(CWIGLEY) PM/ Mount and Balance Tires

Job Notes

06-15 - INSPECT STEERING

(EHOWELL) Front end good.

09-15 - ALIGN STEERING

(EHOWELL) Checked alignment. Did not make any adjustments. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced all 4 tires. Aired to spec and balanced. Torqued all lug nuts to spec. JAW

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 33522 hours: 5875 idle hours: 4626 Completed PM top side, Scott was bottom side. AMG/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 44531

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 08/31/2022 10:10:56 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 09/01/2022 15:04:00 | METER 1 - M: | 33522 | METER 2 - H: 4626 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 09/09/2022 11:48:50 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|------------------------------|------|-----|------|---------|-----------|----------|----------|------------|------------|
| 03-32-002 | REPLACE NEW BATTERY | DON | O | N | GARAGE | 2.48 | \$293.07 | \$113.55 | \$0.00 | \$406.62 |
| 06-32-002 | INSPECT BATTERY | DON | O | N | GARAGE | 0.83 | \$97.58 | \$0.00 | \$0.00 | \$97.58 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| PR-05-020 | PROGRAM PCM/PROCESSOR ASSEMB | DON | O | N | GARAGE | 0.50 | \$59.00 | \$0.00 | \$0.00 | \$59.00 |

| | | | | | | |
|--------------|-------------------|------|--------|--------|------|--------|
| JOB COUNT: 4 | WORK ORDER TOTAL: | 3.81 | 449.65 | 113.55 | 5.00 | 568.20 |
|--------------|-------------------|------|--------|--------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | COMML | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------------------|--------------|---------------------|---------------------|----------|------------|
| PR-05-020 | PROGRAM PCM/PROCESSOR ASSEMBLY | 11213180 | 09/09/2022 07:00:00 | 09/09/2022 07:30:00 | 0.50 | \$59.00 |
| 06-32-002 | INSPECT BATTERY | 11213180 | 08/31/2022 14:58:27 | 08/31/2022 15:48:04 | 0.83 | \$97.58 |
| 03-32-002 | REPLACE NEW BATTERY | 11213180 | 08/31/2022 12:29:15 | 08/31/2022 14:58:16 | 2.48 | \$293.07 |
| | | | | LABOR | | 449.65 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|---------------------|----------|------------------------|------------|----------|------------|
| 03-32-002 | REPLACE NEW BATTERY | 650 | BATTERY BCI 65 650 CCA | 113.55 | 1 | \$113.55 |
| | | | | | PARTS | 113.55 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 44531

Work Order Notes

(CWIGLEY) Its slow to crank, per driver.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(MSIDES) Replaced battery and reset battery monitoring system.MS
(LISAPATE)

06-32-002 - INSPECT BATTERY

(MSIDES) Found battery to test bad will need replacement. MS

CH-SP - CHARGE Shop Supplies

PR-05-020 - PROGRAM PCM/PROCESSOR ASSEMBLY

(LISAPATE) Reset battery monitoring system with ford IDS scan tool. MS

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 44685

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 09/14/2022 08:27:01 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 09/27/2022 15:26:31 | METER 1 - M: | 33522 | METER 2 - H: 4626 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 09/28/2022 10:38:12 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|---------------------------|------|-----|------|---------|-----------|----------|----------|------------|------------|
| 03-51-055 | REPLACE NEW WIPER NOZZLES | DON | O | N | GARAGE | 1.00 | \$118.00 | \$46.77 | \$0.00 | \$164.77 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | | | | | |
|--------------|-------------------|--|--|--|--|------|--------|-------|------|--------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | | | | | 1.00 | 118.00 | 46.77 | 5.00 | 169.77 |
|--------------|-------------------|--|--|--|--|------|--------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|---------------------------|--------------|---------------------|---------------------|----------|------------|
| 03-51-055 | REPLACE NEW WIPER NOZZLES | 11310047 | 09/27/2022 07:00:00 | 09/27/2022 08:00:00 | 1.00 | \$118.00 |
| LABOR | | | | | | 118.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|---------------------------|-------------|----------------|------------|----------|------------|
| 03-51-055 | REPLACE NEW WIPER NOZZLES | FB5Z17603A | WIPER LINE KIT | 11.45 | 2 | \$22.89 |
| 03-51-055 | REPLACE NEW WIPER NOZZLES | FB5Z17A605B | WIPER HOSE | 23.88 | 1 | \$23.88 |
| PARTS | | | | | | 46.77 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 44685

Work Order Notes

(EKIMBREL) replace rear washer nozzles/lines

Job Notes

03-51-055 - REPLACE NEW WIPER NOZZLES

(MSIDES) Replaced broken washer fluid lines attached to bottom of hood. MS 0.3HRS

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 45332

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 11/21/2022 07:39:16 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 11/22/2022 14:16:04 | METER 1 - M: | 36425 | METER 2 - H: 5061 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 11/30/2022 07:44:26 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.36 | \$42.09 | \$64.31 | \$0.00 | \$106.40 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | | | | | |
|--------------|-------------------|--|--|--|--|------|-------|-------|------|--------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | | | | | 0.36 | 42.09 | 64.31 | 5.00 | 111.40 |
|--------------|-------------------|--|--|--|--|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 11901357 | 11/21/2022 08:03:07 | 11/21/2022 08:24:31 | 0.36 | \$42.09 |
| LABOR | | | | | | 42.09 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.24 | 6 | \$37.44 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 8.36 | 1 | \$8.36 |
| 66-PM-PMA | PERFORM OIL CHANGE | 46935 | AIR FILTER-SECURITY INTERCEP. | 18.51 | 1 | \$18.51 |
| PARTS | | | | | | 64.31 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 45332

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 36425 hours: 6414 idle hours: 5061 Completed PM topside, Josh assisted, Scott was bottomsides. AMG JW/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 46366

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 03/06/2023 08:36:16 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 03/06/2023 11:36:12 | METER 1 - M: | 39573 | METER 2 - H: 5508 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 03/06/2023 13:12:35 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.07 | \$7.93 | \$56.40 | \$0.00 | \$64.33 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEME | DON | P | N | GARAGE | 0.02 | \$2.13 | \$30.32 | \$0.00 | \$32.45 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.09 | 10.06 | 86.72 | 5.00 | 101.78 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | COMML | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|----------------------------------|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | 12201267 | 03/06/2023 09:02:38 | 03/06/2023 09:03:43 | 0.02 | \$2.13 |
| 66-PM-PMA | PERFORM OIL CHANGE | 12201267 | 03/06/2023 08:58:07 | 03/06/2023 09:02:09 | 0.07 | \$7.93 |
| | | | | LABOR | | 10.06 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|----------------------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | BALB7449 | OIL FILTER | 5.76 | 1 | \$5.76 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.26 | 6 | \$37.53 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | FP68 | CABIN FILTER | 30.32 | 1 | \$30.32 |
| | | | | | PARTS | 86.72 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 46366

Work Order Notes

(LISAPATE) PM

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- GC,SH- Changed oil and oil filter, checked fluids, tires and tire pressure,
Miles, 39,573- Idle Hrs, 5,508

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GRCOOK) Replaced cabin filter- GC 3-6-23

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 46993

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 05/09/2023 14:26:08 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 05/15/2023 15:34:21 | METER 1 - M: | 41485 | METER 2 - H: 5789 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 05/16/2023 07:48:43 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|---------------------------------------|------|-----|------|---------|-----------|----------|----------|------------|------------|
| 03-01-005 | REPLACE NEW COMPRESSOR | DON | O | N | GARAGE | 7.75 | \$914.07 | \$507.15 | \$0.00 | \$1,421.22 |
| 03-01-006 | REPLACE NEW CONDENSER | DON | O | N | GARAGE | 0.87 | \$103.02 | \$421.91 | \$0.00 | \$524.93 |
| 03-01-077 | REPLACE NEW EXPANSION VALVE | DON | O | N | GARAGE | 1.05 | \$123.67 | \$34.95 | \$0.00 | \$158.62 |
| 03-01-100 | REPLACE NEW BELT, AIR CONDITIONING | DON | O | N | GARAGE | 0.10 | \$11.80 | \$34.83 | \$0.00 | \$46.63 |
| 35-01 | DIAGNOSE AIR CONDITIONING, HEAT, VENT | DON | O | N | GARAGE | 1.50 | \$176.48 | \$0.00 | \$0.00 | \$176.48 |
| 36-01-055 | FLUSH A/C LINE(S) | DON | O | N | GARAGE | 0.39 | \$46.09 | \$41.43 | \$0.00 | \$87.52 |
| 66-01-058 | PERFORM EVAC AND RECHARGE FREON | DON | O | N | GARAGE | 0.11 | \$13.28 | \$10.55 | \$0.00 | \$23.83 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|--------------|-------------------|-------|----------|----------|------|----------|
| JOB COUNT: 8 | WORK ORDER TOTAL: | 11.77 | 1,388.41 | 1,050.82 | 5.00 | 2,444.23 |
|--------------|-------------------|-------|----------|----------|------|----------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|---------------------------------------|--------------|---------------------|---------------------|----------|------------|
| 03-01-100 | REPLACE NEW BELT, AIR CONDITIONING | 11310047 | 05/15/2023 07:00:00 | 05/15/2023 07:06:00 | 0.10 | \$11.80 |
| 66-01-058 | PERFORM EVAC AND RECHARGE FREON | 11310047 | 05/12/2023 13:00:10 | 05/12/2023 13:06:55 | 0.11 | \$13.28 |
| 35-01 | DIAGNOSE AIR CONDITIONING, HEAT, VENT | 11310047 | 05/12/2023 11:30:26 | 05/12/2023 13:00:10 | 1.50 | \$176.48 |
| 03-01-077 | REPLACE NEW EXPANSION VALVE | 11310047 | 05/12/2023 07:01:00 | 05/12/2023 08:03:53 | 1.05 | \$123.67 |
| 36-01-055 | FLUSH A/C LINE(S) | 11310047 | 05/11/2023 15:29:41 | 05/11/2023 15:53:07 | 0.39 | \$46.09 |
| 03-01-006 | REPLACE NEW CONDENSER | 11310047 | 05/11/2023 14:00:26 | 05/11/2023 14:52:49 | 0.87 | \$103.02 |
| 03-01-005 | REPLACE NEW COMPRESSOR | 11310047 | 05/10/2023 13:00:10 | 05/10/2023 15:55:07 | 2.92 | \$344.07 |
| 03-01-005 | REPLACE NEW COMPRESSOR | 11310047 | 05/10/2023 07:03:59 | 05/10/2023 11:53:49 | 4.83 | \$570.01 |
| LABOR | | | | | | 1388.42 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|----------|-----------------|----------|-------------|------------|----------|------------|
|----------|-----------------|----------|-------------|------------|----------|------------|

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

| <u>Job Code</u> | <u>Job Description</u> | <u>Part No.</u> | <u>Description</u> | <u>Unit Price</u> | <u>Quantity</u> | <u>Total Cost</u> |
|-----------------|------------------------------------|--------------------|-----------------------------|-------------------|-----------------|-------------------|
| 03-01-005 | REPLACE NEW COMPRESSOR | FJC2468 | A/C PAG OIL | 9.09 | 1 | \$9.09 |
| 03-01-100 | REPLACE NEW BELT, AIR CONDITIONING | CTL4060450 | BELT | 34.83 | 1 | \$34.83 |
| 03-01-005 | REPLACE NEW COMPRESSOR | FOR198358 | A/C COMPRESSOR | 449.45 | 1 | \$449.45 |
| 03-01-077 | REPLACE NEW EXPANSION VALVE | FOR39481 | EXPANSION VALVE | 19.02 | 1 | \$19.02 |
| 03-01-006 | REPLACE NEW CONDENSER | EB5Z19712F | CONDENSER / A/T COOLER ASSY | 421.91 | 1 | \$421.91 |
| 66-01-058 | PERFORM EVAC AND RECHARGE FREON | RECYCLED FREON OZ | RECLAIMED FREON OZ | 0.14 | 37 | \$5.00 |
| 66-01-058 | PERFORM EVAC AND RECHARGE FREON | ESTER OIL | A/C ESTER OIL OUNCE | 1.11 | 5 | \$5.55 |
| 03-01-077 | REPLACE NEW EXPANSION VALVE | MAHMS19928 | PLENUM GASKET | 15.93 | 1 | \$15.93 |
| 36-01-055 | FLUSH A/C LINE(S) | ANTIFREEZE DEXCOOL | ANTIFREEZE-GM | 20.72 | 2 | \$41.43 |
| 03-01-005 | REPLACE NEW COMPRESSOR | A/C FLUSH | A/C FLUSH DURA II 32OZ | 48.61 | 1 | \$48.61 |
| | | | | | PARTS | 1050.82 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 46993

Work Order Notes

(EHOWELL) - AC is not working

Job Notes

03-01-005 - REPLACE NEW COMPRESSOR

(EHOWELL) Replaced the AC compressor and the serpentine belt. EH No extra time for belt.

03-01-006 - REPLACE NEW CONDENSER

(EHOWELL) Removed cooling fans and radiator hose. Replaced the condenser. A new receiver drier came inside of the condenser. Filled cooling system with coolant after repairs. EH

03-01-077 - REPLACE NEW EXPANSION VALVE

(EHOWELL) Replaced the front expansion valve. It was necessary to removed the upper intake manifold to gain access to the expansion valve. Replaced upper intake gasket. EH

03-01-100 - REPLACE NEW BELT, AIR CONDITIONING

(LISAPATE) Replaced the AC compressor and the serpentine belt. EH No extra time for belt.

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(EHOWELL) The AC was not blowing cool air. The high side pressure was 200 psi and the low side pressure was 70 psi. EH

36-01-055 - FLUSH A/C LINE(S)

(EHOWELL) Flushed AC lines with compressed air and cleaner. EH

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(EHOWELL) Recovered 2.29 lb. of refrigerant and drained 0.4 oz. of oil. Pulled a vacuum on the AC system. Leak test passed. Charged the vehicle with 2.38 lb. of refrigerant. Injected 5.0 oz of ester oil with dye. EH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 47524

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 07/05/2023 07:43:59 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 07/06/2023 09:51:58 | METER 1 - M: | 42977 | METER 2 - H: 5938 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 07/06/2023 10:33:24 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.05 | \$6.13 | \$34.15 | \$0.00 | \$40.28 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.40 | \$46.68 | \$61.91 | \$0.00 | \$108.59 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.45 | 52.81 | 96.06 | 5.00 | 153.87 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | COMML | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------------|--------------|---------------------|---------------------|----------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 11074414 | 07/05/2023 08:19:40 | 07/05/2023 08:22:47 | 0.05 | \$6.13 |
| 66-PM-PMA | PERFORM OIL CHANGE | 11074414 | 07/05/2023 07:55:56 | 07/05/2023 08:19:40 | 0.40 | \$46.68 |
| | | | | LABOR | | 52.81 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------------|----------|--------------------------------|------------|----------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 19260 | WIPER BLADE 26 IN OE BEAM | 13.23 | 1 | \$13.23 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19220 | WIPER 22 IN OE BEAM | 10.85 | 1 | \$10.85 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 60-011-G | WIPER-REAR FORD EXPLORER | 10.07 | 1 | \$10.07 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.26 | 6 | \$37.53 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 11.27 | 1 | \$11.27 |
| | | | | PARTS | | 96.06 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 47524

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced the wipers. sh gc

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) sh gc/sh performed pm.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 47777

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 07/31/2023 08:15:02 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 08/01/2023 08:02:22 | METER 1 - M: | 43311 | METER 2 - H: 5973 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 08/01/2023 11:31:44 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 03-32-002 | REPLACE NEW BATTERY | DON | N | N | GARAGE | 0.08 | \$9.08 | \$170.21 | \$0.00 | \$179.29 |
| 06-32-002 | INSPECT BATTERY | DON | O | N | GARAGE | 0.35 | \$40.78 | \$0.00 | \$0.00 | \$40.78 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|--------------|-------------------|------|-------|--------|------|--------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | 0.42 | 49.86 | 170.21 | 5.00 | 225.07 |
|--------------|-------------------|------|-------|--------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|---------------------|--------------|---------------------|---------------------|----------|------------|
| 03-32-002 | REPLACE NEW BATTERY | 11074414 | 07/31/2023 08:40:33 | 07/31/2023 08:45:10 | 0.08 | \$9.08 |
| 06-32-002 | INSPECT BATTERY | 11074414 | 07/31/2023 08:19:49 | 07/31/2023 08:40:33 | 0.35 | \$40.78 |
| LABOR | | | | | | 49.86 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|---------------------|----------|------------------------|------------|----------|------------|
| 03-32-002 | REPLACE NEW BATTERY | 650 | BATTERY BCI 65 650 CCA | 170.21 | 1 | \$170.21 |
| PARTS | | | | | | 170.21 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 47777

Work Order Notes

(EHANNAH) inspect battery- driver reports battery is going bad.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) Installed a new battery. JW Reset the charging system. ALT Charging at 14.5 volts. SH

06-32-002 - INSPECT BATTERY

(GARAGE) Battery tested bad. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 48747

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 10/30/2023 07:04:15 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 10/31/2023 08:47:29 | METER 1 - M: | 4362 | METER 2 - H: 6029 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 10/31/2023 11:23:24 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.34 | \$40.22 | \$64.16 | \$0.00 | \$104.38 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | 0.34 | 40.22 | 64.16 | 5.00 | 109.38 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | COMML | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 12395904 | 10/30/2023 09:39:11 | 10/30/2023 09:59:38 | 0.34 | \$40.22 |
| | | | | | LABOR | 40.22 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 13.52 | 1 | \$13.52 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 6.26 | 6 | \$37.53 |
| | | | | | PARTS | 64.16 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 48747

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed and fluid check FC -gc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 49608

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 01/29/2024 08:06:27 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 01/29/2024 13:10:58 | METER 1 - M: | 6057 | METER 2 - H: 6057 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 01/29/2024 15:30:07 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.32 | \$37.17 | \$60.56 | \$0.00 | \$97.73 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|--------------|-------------------|------|-------|-------|------|--------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | 0.32 | 37.17 | 60.56 | 5.00 | 102.73 |
|--------------|-------------------|------|-------|-------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| | | | | COMML | 5.00 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | 12395904 | 01/29/2024 11:33:08 | 01/29/2024 11:52:02 | 0.32 | \$37.17 |
| | | | | | LABOR | 37.17 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 13.52 | 1 | \$13.52 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 5.66 | 6 | \$33.93 |
| | | | | | PARTS | 60.56 |

Work Order Charge Detail

UNIT NO: 243200 2019 FORD INTERCEPTOR WORK ORDER NO: 49608

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 50605

| | | | | | | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|------|--|--|--|--|
| USING DEPT NO: | 507121 | OPENED DATE: | 04/17/2024 15:30:10 | LOCATION: | GARAGE - University Automotive Services | | | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 04/23/2024 14:08:37 | METER 1 - M: | 47668 | METER 2 - H: | 6057 | | | | |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 04/29/2024 10:24:11 | IN-SERVICE DATE: | 03/01/2019 | | | | | | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | | | | | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 03-34-010 | REPLACE NEW TAG LIGHT | DON | P | N | GARAGE | 0.00 | \$0.00 | \$0.39 | \$0.00 | \$0.39 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.00 | \$0.00 | \$80.24 | \$0.00 | \$80.24 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | DON | P | N | GARAGE | 0.00 | \$0.00 | \$32.21 | \$0.00 | \$32.21 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| SO-05 | SCAN OUT ELECTRONIC ENGINE EEC | DON | O | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |

| | | | | | | |
|--------------|-------------------|------|------|--------|------|--------|
| JOB COUNT: 5 | WORK ORDER TOTAL: | 0.00 | 0.00 | 112.84 | 5.00 | 117.84 |
|--------------|-------------------|------|------|--------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|----------------------------------|----------|--------------------------------|------------|----------|------------|
| 03-34-010 | REPLACE NEW TAG LIGHT | 194 | BULB-TAG/MARKER | 0.39 | 1 | \$0.39 |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT | FP68 | CABIN FILTER | 32.21 | 1 | \$32.21 |
| 66-PM-PMA | PERFORM OIL CHANGE | 46935 | AIR FILTER-SECURITY INTERCEP. | 19.59 | 1 | \$19.59 |
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 13.52 | 1 | \$13.52 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W20BT | BULK OIL 5W20 SYNTHETIC THOMAS | 5.67 | 6 | \$34.02 |
| PARTS | | | | | | 112.84 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 50605

Work Order Notes

(EHANNAH) pm- Scan out - driver repost check engine light on

Job Notes

03-34-010 - REPLACE NEW TAG LIGHT

(LISAPATE) replaced tag light

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC replaced air filter

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) replaced cabin filter FC

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC: P0456 EVAP Leak Detected (Very Small Leak). Performed an EVAP System test for an 18.6-gallon fuel tank using the Ford IDS application. The test passed. Cleared the code and released the vehicle to the waiting customer. EH

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 50813

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 05/10/2024 13:41:44 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 05/13/2024 08:43:01 | METER 1 - M: | 47668 | METER 2 - H: 6057 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 05/13/2024 14:36:05 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 14-52-021 | INSTALL GPS SYSTEM | DON | 5 | N | GARAGE | 0.03 | \$3.90 | \$0.00 | \$0.00 | \$3.90 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$3.90 | \$3.90 |

| | | | | | | | | | | |
|--------------|-------------------|--|--|--|--|------|------|------|------|------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | | | | | 0.03 | 3.90 | 0.00 | 3.90 | 7.80 |
|--------------|-------------------|--|--|--|--|------|------|------|------|------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$3.90 |
| COMML | | | | | 3.90 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--------------------|--------------|---------------------|---------------------|----------|------------|
| 14-52-021 | INSTALL GPS SYSTEM | 12201267 | 05/10/2024 14:06:29 | 05/10/2024 14:08:28 | 0.03 | \$3.90 |
| LABOR | | | | | | 3.90 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 50813

Work Order Notes

(EHANNAH) install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GRCOOK) Installed GPS # SN: 87U030240058 in unit 2476C -GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 51077

| | | | | | | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|------|--|--|--|--|
| USING DEPT NO: | 507121 | OPENED DATE: | 06/06/2024 13:44:29 | LOCATION: | GARAGE - University Automotive Services | | | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 06/06/2024 13:51:28 | METER 1 - M: | 47668 | METER 2 - H: | 6057 | | | | |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 06/06/2024 15:32:04 | IN-SERVICE DATE: | 03/01/2019 | | | | | | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | | | | | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|-----------------------------------|-------------------|------------|-------------|----------------|------------------|--------------|-----------------|-------------------|-------------------|
| 17-GA-005 | RECALL Scheduling and Preparation | DON | R | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 17-PU-SVC | RECALL Service Manual | DON | R | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| JOB COUNT: 2 | | WORK ORDER TOTAL: | | | | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: **243200** **2019 FORD INTERCEPTOR**

WORK ORDER NO: **51077**

Work Order Notes

(EHANNAH) prep and scheduling- Recall for owner's manual

Job Notes

17-GA-005 - RECALL Scheduling and Preparation

(EHANNAH) prep and scheduling by Denise

17-PU-SVC - RECALL Service Manual

(EHANNAH) LL Ford came to our shop for Recall on owner's manual.

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 51888

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 08/20/2024 14:04:19 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 08/22/2024 09:59:11 | METER 1 - M: | 50120 | METER 2 - H: 6892 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 08/23/2024 11:15:28 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.00 | \$0.00 | \$68.66 | \$0.00 | \$68.66 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | |
|--------------|-------------------|------|------|-------|------|-------|
| JOB COUNT: 2 | WORK ORDER TOTAL: | 0.00 | 0.00 | 68.66 | 5.00 | 73.66 |
|--------------|-------------------|------|------|-------|------|-------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------|----------|--------------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 13.52 | 1 | \$13.52 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 14OZ | 7.65 | (1) | (\$7.65) |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 13.11 | 1 | \$13.11 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 14OZ | 7.65 | 1 | \$7.65 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30BT | 5W30 BULK | 7.01 | 6 | \$42.03 |
| PARTS | | | | | | 68.66 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 51888

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-JW,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 50,120

Idle Hours, 6,892

Total Hours, 8,731

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 53181

| | | | | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|--------------|------|--|--|
| USING DEPT NO: | 507121 | OPENED DATE: | 12/17/2024 13:59:38 | LOCATION: | GARAGE - University Automotive Services | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 12/17/2024 14:37:36 | METER 1 - M: | 50120 | METER 2 - H: | 6892 | | |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 12/17/2024 14:37:46 | IN-SERVICE DATE: | 03/01/2019 | | | | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | | | | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|------------------------|-------------|------------|-------------|----------------|-------------------|--------------|-----------------|-------------------|-------------------|
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| JOB COUNT: 1 | | | | | | WORK ORDER TOTAL: | 0.00 | 0.00 | 0.00 | 0.00 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: **243200** **2019 FORD INTERCEPTOR**

WORK ORDER NO: **53181**

Work Order Notes

(EHANNAH) no labor- waiting to be sold- remove equipment

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 53823

| | | | | | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|------|--|--|--|
| USING DEPT NO: | 507121 | OPENED DATE: | 02/20/2025 07:19:49 | LOCATION: | GARAGE - University Automotive Services | | | | | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 02/27/2025 07:56:30 | METER 1 - M: | 50294 | METER 2 - H: | 6925 | | | |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 02/27/2025 13:11:43 | IN-SERVICE DATE: | 03/01/2019 | | | | | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | | | | |

| <u>JOB CODE</u> | <u>JOB DESCRIPTION</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | <u>JOB LOC</u> | <u>LABOR HRS</u> | <u>LABOR</u> | <u>MATERIAL</u> | <u>COMMERCIAL</u> | <u>TOTAL COST</u> |
|-----------------|---------------------------|-------------|------------|-------------|----------------|-------------------|--------------|-----------------|-------------------|-------------------|
| 66-79-003 | PERFORM SAFETY INSPECTION | DON | Y | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| JOB COUNT: 1 | | | | | | WORK ORDER TOTAL: | 0.00 | 0.00 | 0.00 | 0.00 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 53823

Work Order Notes

(EKIMBREL) SI
(EKIMBREL) vehicle will go to surplus

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) GC- performed safety inspection, found no issues at this time, other than all 4 of the tires tread depths are down to 2 and 3 and need to be replaced, the front and rear brakes are 5-4 mm and the rotors have light grooving around them. Had CM also check the brakes.

Miles, 50,294

Idle Hours, 6,925

Total Hours, 8,772

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 54803

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 05/16/2025 07:21:30 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 05/16/2025 13:40:12 | METER 1 - M: | 51168 | METER 2 - H: 7034 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 05/19/2025 08:22:23 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|--------------------------|------|-----|------|---------|-----------|--------|----------|------------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | DON | P | N | GARAGE | 0.00 | \$0.00 | \$38.64 | \$0.00 | \$38.64 |
| 66-PM-PMA | PERFORM OIL CHANGE | DON | P | N | GARAGE | 0.00 | \$0.00 | \$63.20 | \$0.00 | \$63.20 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |

| | | | | | | | |
|--------------|-------------------|--|------|------|--------|------|--------|
| JOB COUNT: 3 | WORK ORDER TOTAL: | | 0.00 | 0.00 | 101.84 | 5.00 | 106.84 |
|--------------|-------------------|--|------|------|--------|------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|----------|----------------------|------------|-------------|--------------------|------------|
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 5.00 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--------------------------|----------|-----------------------------|------------|----------|------------|
| 66-PM-PMA | PERFORM OIL CHANGE | FL500S | FILTER-OIL FORD | 11.96 | 1 | \$11.96 |
| 66-PM-PMA | PERFORM OIL CHANGE | SF16 | SEA FOAM 16OZ | 12.81 | 1 | \$12.81 |
| 66-PM-PMA | PERFORM OIL CHANGE | 5W30BT | 5W30 BULK | 6.41 | 6 | \$38.43 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 60-011-G | WIPER-REAR FORD EXPLORER | 10.07 | 1 | \$10.07 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 25-260 | BEAM WIPER BLADE | 17.72 | 1 | \$17.72 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19210 | WIPER BLADE 21IN BEAM STYLE | 10.85 | 1 | \$10.85 |
| PARTS | | | | | | 101.84 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 54803

Work Order Notes

(EHANNAH) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Replaced front & rear blades.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- PM. Mileage: 51,168, Idle hours: 7,034, Total hours: 8,914. Oil change, checked filters, topped off fluids, set tire pressure, recorded date codes & tread depths.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 56144

| | | | | | | |
|------------------|---------------|---------------------------------------|---------------------|------------------|---|-------------------|
| USING DEPT NO: | 507121 | OPENED DATE: | 08/28/2025 14:22:26 | LOCATION: | GARAGE - University Automotive Services | |
| WO STATUS: | CLOSED | COMPLETED DATE: | 09/04/2025 15:54:32 | METER 1 - M: | 51169 | METER 2 - H: 7034 |
| WO VISIT REASON: | SCHEDULED | CLOSED DATE: | 09/05/2025 08:26:01 | IN-SERVICE DATE: | 03/01/2019 | |
| TECH SPEC NO: | 19FORDEXPINTR | 2019 Ford Explorer Police Interceptor | | UNIT SERIAL NO: | 1FM5K8AR9KGB28058 | |

| JOB CODE | JOB DESCRIPTION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
|-----------|----------------------------------|------|-----|------|---------|-----------|---------|----------|------------|------------|
| 16-33-006 | TRANSPORT IGNITION LOCK CYLINDEI | DON | 5 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| 25-33-006 | REMOVE IGNITION LOCK CYLINDER | DON | 5 | N | GARAGE | 0.48 | \$60.31 | \$0.00 | \$0.00 | \$60.31 |
| 66-79-002 | PERFORM SERVICE CALL | DON | B | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| CH-SP | CHARGE Shop Supplies | DON | 2 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| PD-00-999 | PREP DISPOSE PREPARE UNIT FOR DI | DON | D | N | GARAGE | 0.58 | \$73.09 | \$40.40 | \$0.00 | \$113.49 |
| RY-33-006 | REKEY IGNITION LOCK CYLINDER | DON | 5 | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$122.60 | \$122.60 |

| | | | | | | |
|--------------|-------------------|------|--------|-------|--------|--------|
| JOB COUNT: 6 | WORK ORDER TOTAL: | 1.07 | 133.40 | 40.40 | 127.60 | 301.40 |
|--------------|-------------------|------|--------|-------|--------|--------|

| Job Code | Job Description | Vendor No. | Invoice No. | Purchase Order No. | Total Cost |
|-----------|------------------------------|------------|-------------|--------------------|------------|
| RY-33-006 | REKEY IGNITION LOCK CYLINDER | 11111231 | 2321097 | | \$122.60 |
| RY-33-006 | REKEY IGNITION LOCK CYLINDER | 11111231 | 2321097 | | (\$122.60) |
| RY-33-006 | REKEY IGNITION LOCK CYLINDER | 11111231 | 2321097 | | \$122.60 |
| CH-SP | CHARGE Shop Supplies | 503163 | 1 | | \$5.00 |
| COMML | | | | | 127.60 |

| Job Code | Job Description | Employee No. | Start | Finish | Quantity | Total Cost |
|-----------|--|--------------|---------------------|---------------------|----------|------------|
| 25-33-006 | REMOVE IGNITION LOCK CYLINDER | 12480657 | 08/29/2025 10:10:37 | 08/29/2025 10:39:34 | (0.48) | (\$60.31) |
| 25-33-006 | REMOVE IGNITION LOCK CYLINDER | 12480657 | 08/29/2025 10:10:37 | 08/29/2025 10:39:34 | 0.48 | \$60.31 |
| 25-33-006 | REMOVE IGNITION LOCK CYLINDER | 12480657 | 08/29/2025 10:10:37 | 08/29/2025 10:39:34 | 0.48 | \$60.31 |
| PD-00-999 | PREP DISPOSE PREPARE UNIT FOR DISPOSAL | 12480657 | 08/29/2025 13:01:13 | 08/29/2025 13:36:18 | 0.58 | \$73.09 |
| LABOR | | | | | | 133.40 |

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--|----------|------------------|------------|----------|------------|
| PD-00-999 | PREP DISPOSE PREPARE UNIT FOR DISPOSAL | 08984 | ADHESIVE REMOVER | 40.40 | 1 | \$40.40 |
| PARTS | | | | | | 40.40 |

Work Order Charge Detail

The University of Alabama

Report Printed: 09/16/2025 09:17:49 By User: GLOBETTI

UNIT NO: 243200 2019 FORD INTERCEPTOR

WORK ORDER NO: 56144

Work Order Notes

(EHANNAH) service call for dead battery

Job Notes

06-32-002 - INSPECT BATTERY

16-33-006 - TRANSPORT IGNITION LOCK CYLINDER

(EHOWELL) RC/CW TRANSPORTED LOCKS TO AND FROM a-1 LOCKSMITH.
We're charging .25 HR since we took the lock cylinders for another UAPD unit. (Work order #56133)

25-33-006 - REMOVE IGNITION LOCK CYLINDER

(GARAGE) cm removed lock cylinders, sent to be rekeyed, installed new lock cylinders, unit checked ok, 1.5 labor,
(EHOWELL) cm removed and rekeyed ignition key cylinder installed new unit checked ok, .5 labor

25-52-021 - REMOVE GPS SYSTEM

66-79-002 - PERFORM SERVICE CALL

(GARAGE) JR- & RC- went to UAPD, jumped vehicle back to the shot to be prepped for sale

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) cm 51169 performed prep for sale, unit checked ok,

RY-33-006 - REKEY IGNITION LOCK CYLINDER

(EHOWELL) A1 rekeyed all four lock cylinders.

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Sep 16 2025 09:17:49 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243200') //Q=