

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 35010

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 11/27/2019 10:44:48	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/02/2019 14:42:47	<b>METER 1 - M:</b> 55 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/02/2019 14:42:48	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.50**      **0.00**      **0.00**      **0.00**      **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	11/27/2019 10:45:30	11/27/2019 11:15:30	0.50	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 35010

---

**Work Order Notes**

(LISAPATE) New unit do PDI

---

**Job Notes**

**PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION**

(LISAPATE) PDI completed

---

# Work Order Charge Detail

**UNIT NO:** 243579      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 35784

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 02/26/2020 08:28:34	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/28/2020 08:04:03	<b>METER 1 - M:</b> 2741 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/28/2020 08:04:05	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$210.00	\$210.00
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	0.33	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.33**      **0.00**      **0.00**      **210.00**      **210.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
14-78-028	INSTALL WINDOW TINT	5564144	32154		\$210.00
<b>COMML</b>					<b>210.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	10208562	02/26/2020 10:47:23	02/26/2020 11:07:25	0.33	\$0.00
<b>LABOR</b>						<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 35784

---

**Work Order Notes**

(LISAPATE) Take to Bama Trim to install window tint per Rusty

---

**Job Notes**

**14-78-028 - INSTALL WINDOW TINT**

(LISAPATE) Bama Trim tinted all windows and windshield strip. Pd by CC

**16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE**

(LISAPATE) Taken to Bama Trim by EK

---

# Work Order Charge Detail

**UNIT NO:** 243579      **2020 TOYOTA CAMRY**

**WORK ORDER NO:** 36120

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 04/09/2020 09:42:15	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/09/2020 14:13:15	<b>METER 1 - M:</b> 4199 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/10/2020 07:16:02	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.67	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$0.00	\$24.03	\$0.00	\$24.03

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **1.34**      **0.00**      **24.03**      **0.00**      **24.03**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11901357	04/09/2020 10:17:13	04/09/2020 10:37:17	0.33	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	04/09/2020 10:16:53	04/09/2020 10:36:59	0.34	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/09/2020 09:57:21	04/09/2020 10:17:13	0.33	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/09/2020 09:56:35	04/09/2020 10:16:53	0.34	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.94	5	\$19.70
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
					<b>PARTS</b>	<b>24.03</b>

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 36120

---

**Work Order Notes**

(IFALLS) PM

---

**Job Notes**

**31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(IFALLS) SH/AG ROTATED TIRES

**66-PM-PMA - PERFORM OIL CHANGE**

(IFALLS) SH/AG PERFORMED PM

---

# Work Order Charge Detail

**UNIT NO:** 243579      **2020 TOYOTA CAMRY**

**WORK ORDER NO:** 37864

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 10/05/2020 09:55:20	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/05/2020 12:19:56	<b>METER 1 - M:</b> 7612 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/06/2020 08:03:44	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-71	INSPECT BODY	DON	O	N	GARAGE	0.09	\$10.42	\$0.00	\$0.00	\$10.42
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.69	\$81.39	\$35.75	\$0.00	\$117.14

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.78**      **91.81**      **35.75**      **0.00**      **127.56**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-71	INSPECT BODY	11074414	10/05/2020 10:26:49	10/05/2020 10:32:07	0.09	\$10.42
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/05/2020 10:08:03	10/05/2020 10:30:50	0.38	\$44.81
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/05/2020 10:08:02	10/05/2020 10:26:38	0.31	\$36.58
					<b>LABOR</b>	<b>91.81</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.85	5	\$29.25
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					<b>PARTS</b>	<b>35.75</b>

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 37864

---

**Work Order Notes**

(LISAPATE) PM while here and check undercarriage ran over debris in the road

---

**Job Notes**

**06-71 - INSPECT BODY**

(SHARBIN) Inspected underside of vehicle did not find any damage. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°JAW/SH

---



# Work Order Charge Detail

**UNIT NO:** 243579      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 38960

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 01/29/2021 11:34:10	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/01/2021 10:52:22	<b>METER 1 - M:</b> 10650 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/02/2021 08:55:11	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$28.94	\$35.75	\$0.00	\$64.69

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.25**      **28.94**      **35.75**      **0.00**      **64.69**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/29/2021 14:30:00	01/29/2021 14:44:43	0.25	\$28.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/29/2021 14:27:23	01/29/2021 14:27:23	0.00	\$0.00
					<b>LABOR</b>	<b>28.94</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.85	5	\$29.25
					<b>PARTS</b>	<b>35.75</b>

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 38960

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Found no issues. Coolant -34°. JAW/SH  
MILEAGE-34

---

# Work Order Charge Detail

**UNIT NO:** 243579      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 39653

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 04/13/2021 11:50:22	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/14/2021 10:49:59	<b>METER 1 - M:</b> 12377 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/14/2021 13:54:36	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.03	\$121.84	\$35.68	\$0.00	\$157.52

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **1.03**      **121.84**      **35.68**      **0.00**      **157.52**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/13/2021 14:00:21	04/13/2021 14:28:17	0.47	\$54.94
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/13/2021 13:40:59	04/13/2021 14:15:00	0.57	\$66.90
					<b>LABOR</b>	<b>121.84</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					<b>PARTS</b>	<b>35.68</b>

# Work Order Charge Detail

UNIT NO: 243579 2020 TOYOTA CAMRY

WORK ORDER NO: 39653

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 12377 Completed PM top side, Scott was bottom side. AMG/SH Completed checklist and vacuumed out vehicle. AMG

---

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 40377

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 07/07/2021 09:04:25	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/08/2021 13:41:28	<b>METER 1 - M:</b> 15426 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/09/2021 08:15:02	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$20.60	\$0.00	\$32.40
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.59	\$69.55	\$43.59	\$0.00	\$113.14

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.69** **81.35** **64.19** **0.00** **145.54**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/08/2021 07:00:00	07/08/2021 07:06:00	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/07/2021 12:11:07	07/07/2021 12:35:39	0.41	\$48.25
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/07/2021 12:13:13	07/07/2021 12:24:03	0.18	\$21.31
					<b>LABOR</b>	<b>81.36</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	10.94	1	\$10.94
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	9.66	1	\$9.66
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.87	1	\$6.87
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.23	5	\$46.13
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.87	(1)	(\$6.87)
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.87	5	\$34.35
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.23	(5)	(\$46.13)
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.24	1	\$9.24
					<b>PARTS</b>	<b>64.19</b>

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 40377

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE) Replaced wipers

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG  
MILEAGE-15426

---

# Work Order Charge Detail

UNIT NO: 243579 2020 TOYOTA CAMRY

WORK ORDER NO: 40775

USING DEPT NO:	507121	OPENED DATE:	08/18/2021 13:36:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/20/2021 10:28:00	METER 1 - M:	16732	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	08/23/2021 10:54:20	IN-SERVICE DATE:	11/27/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2LU893166	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.71	\$83.55	\$8.28	\$0.00	\$91.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.71 83.55 8.28 2.00 93.83

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML 2.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11901357	08/18/2021 13:44:57	08/18/2021 14:27:26	0.71	\$83.55
					<b>LABOR</b>	<b>83.55</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.92	1	\$3.92
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	1	\$0.50
					<b>PARTS</b>	<b>8.28</b>

# Work Order Charge Detail

UNIT NO: 243579 2020 TOYOTA CAMRY

WORK ORDER NO: 40775

---

**Work Order Notes**

(CHANNELL) hole in tire \patch

---

**Job Notes**

**66-17-030 - PERFORM TIRE PATCH**

(AGUERRA) Repaired and balanced L/R tire, rechecked for leak, all good. AMG

**CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

UNIT NO: 243579 2020 TOYOTA CAMRY

WORK ORDER NO: 41357

USING DEPT NO:	507121	OPENED DATE:	10/18/2021 13:43:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/20/2021 11:40:30	METER 1 - M:	19507	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/20/2021 12:52:09	IN-SERVICE DATE:	11/27/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2LU893166	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.44	\$22.62	\$0.00	\$28.06
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.29	\$33.93	\$0.00	\$0.00	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.51	\$177.72	\$71.04	\$0.00	\$248.76
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>1.84</b>	<b>217.09</b>	<b>93.66</b>	<b>2.00</b>	<b>312.75</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML 2.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/19/2021 07:08:44	10/19/2021 07:13:51	0.09	\$10.06
03-51-038	REPLACE NEW WIPER BLADES	11901357	10/18/2021 15:46:15	10/18/2021 15:49:01	0.05	\$5.44
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	10/18/2021 15:27:36	10/18/2021 15:44:51	0.29	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/18/2021 14:35:18	10/18/2021 15:26:23	0.85	\$100.46
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/18/2021 14:51:59	10/18/2021 15:26:09	0.57	\$67.19
					<b>LABOR</b>	<b>217.08</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	26.15	1	\$26.15
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.26	1	\$9.26
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.13	5	\$35.63
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
					<b>PARTS</b>	<b>93.66</b>

# Work Order Charge Detail

UNIT NO: 243579 2020 TOYOTA CAMRY

WORK ORDER NO: 41357

---

## Work Order Notes

(LISAPATE) PM-replace wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 19507 Completed PM topside, Josh was bottomsides. Completed checklist. AMG

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243579      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 41759

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 12/01/2021 14:45:59	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/03/2021 07:02:47	<b>METER 1 - M:</b> 20779 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/03/2021 07:45:25	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.00**      **0.00**      **0.00**      **59.50**      **59.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>				
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00				
24-02-061	REPAIR WINDSHIELD	11078716	294848		\$57.50				
<b>COMML</b>									<b>59.50</b>

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 41759

---

**Work Order Notes**

(LISAPATE) Driver has a ding on passenger side just above the wipers.

---

**Job Notes**

**24-02-061 - REPAIR WINDSHIELD**

(LISAPATE) Glass Dr came to the shop and repaired the windshield. PD by CC

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243579      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 42530

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 03/02/2022 11:32:53	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/03/2022 15:25:15	<b>METER 1 - M:</b> 22725 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/07/2022 07:44:52	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.88	\$22.62	\$0.00	\$25.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.45	\$39.78	\$0.00	\$84.23
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.40</b>	<b>47.33</b>	<b>62.40</b>	<b>2.00</b>	<b>111.73</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	03/02/2022 13:50:44	03/02/2022 13:52:12	0.02	\$2.88
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/02/2022 13:27:59	03/02/2022 13:50:35	0.38	\$44.45
<b>LABOR</b>					<b>47.33</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.18	1	\$6.18
<b>PARTS</b>					<b>62.40</b>	

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 42530

---

## Work Order Notes

(LISAPATE) PM-replace wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Replaced wiper blades

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) Cancelled from Work Order# 42343. By User ID LISAPATE on 2/14/2022 1:48 PM.

(JWRIGHT) Performed pm service. Coolant -34°. JAW,RC/JAW

MILEAGE-22725

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 44424

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 08/23/2022 09:32:20	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/23/2022 15:12:00	<b>METER 1 - M:</b> 23355 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/24/2022 07:24:36	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$32.75	\$0.00	\$0.00	\$32.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.28** **32.75** **0.00** **5.00** **37.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/23/2022 10:11:40	08/23/2022 10:28:19	0.28	\$32.75
					<b>LABOR</b>	<b>32.75</b>

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 44424

---

**Work Order Notes**

(CWIGLEY) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Vehicle has been driven 630 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

**CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

**UNIT NO:** 243579      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 45687

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 01/05/2023 10:55:32	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/06/2023 12:54:03	<b>METER 1 - M:</b> 24748 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/06/2023 12:54:06	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.03	\$23.26	\$0.00	\$31.29
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$37.43	\$47.55	\$0.00	\$84.98
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.07	\$7.90	\$20.52	\$0.00	\$28.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 4**      **WORK ORDER TOTAL:**      **0.45**      **53.36**      **91.33**      **5.00**      **149.69**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/05/2023 14:33:57	01/05/2023 14:52:59	0.32	\$37.43
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/05/2023 14:29:39	01/05/2023 14:33:44	0.07	\$8.03
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	01/05/2023 14:25:14	01/05/2023 14:29:15	0.07	\$7.90
					<b>LABOR</b> <b>53.36</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	20.52	1	\$20.52
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	12.45	1	\$12.45
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
					<b>PARTS</b> <b>91.33</b>	

# Work Order Charge Detail

UNIT NO: 243579 2020 TOYOTA CAMRY

WORK ORDER NO: 45687

---

## Work Order Notes

(EHANNAH) pm- replace wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 24748 Completed PM topside, Gregg was bottomside. AMG/GC

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(AGUERRA) Replaced cabin filter. AMG

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243579      **2020 TOYOTA CAMRY**      **WORK ORDER NO:** 47030

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 05/12/2023 10:46:24	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/15/2023 11:05:59	<b>METER 1 - M:</b> 25196 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/16/2023 08:01:26	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY      2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$74.08	\$0.00	\$0.00	\$74.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.63**      **74.08**      **0.00**      **5.00**      **79.08**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/12/2023 14:55:35	05/12/2023 15:33:15	0.63	\$74.08
<b>LABOR</b>						<b>74.08</b>

# Work Order Charge Detail

UNIT NO: 243579 2020 TOYOTA CAMRY

WORK ORDER NO: 47030

---

## Work Order Notes

(EHANNAH) pm-replace wipers- wash

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Unit has been 448 miles. Checked fluids and tires. Coolant -34°. JAW  
MILEAGE-25196

Unit will need new tires at next pm service

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

---

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 48705

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 10/25/2023 09:22:19	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/26/2023 11:15:15	<b>METER 1 - M:</b> 26178 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/26/2023 13:12:34	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.24	\$65.01	\$0.00	\$80.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** 0.13 15.24 65.01 5.00 85.25

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML 5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/25/2023 14:07:15	10/25/2023 14:15:00	0.13	\$15.24
					<b>LABOR</b>	<b>15.24</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.55	1	\$11.55
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.07	5	\$40.35
					<b>PARTS</b>	<b>65.01</b>

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 48705

---

**Work Order Notes**

(EHANNAH) pm- wash

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/FC Performed PM. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

---

# Work Order Charge Detail

UNIT NO: 243579 2020 TOYOTA CAMRY

WORK ORDER NO: 50105

USING DEPT NO:	507121	OPENED DATE:	03/07/2024 12:46:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2024 08:17:10	METER 1 - M:	27485	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2024 10:27:35	IN-SERVICE DATE:	11/27/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.02	\$1.90	\$0.00	\$0.00	\$1.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.90	\$1.90

**JOB COUNT: 2** **WORK ORDER TOTAL: 0.02 1.90 0.00 1.90 3.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$1.90
					<b>COMML 1.90</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	12395904	03/07/2024 13:25:56	03/07/2024 13:26:54	0.02	\$1.90
					<b>LABOR</b>	<b>1.90</b>

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 50105

---

**Work Order Notes**

(EHANNAH) install GPS

---

**Job Notes**

**14-52-021 - INSTALL GPS SYSTEM**

(FCONTRER) install GPS system fc  
(LISAPATE) GPS 87U030240068

**66-PM-PMA - PERFORM OIL CHANGE**

**CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 50514

<b>USING DEPT NO:</b> 507121	<b>OPENED DATE:</b> 04/10/2024 09:56:50	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/11/2024 14:54:36	<b>METER 1 - M:</b> 28125 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/12/2024 13:53:55	<b>IN-SERVICE DATE:</b> 11/27/2019
<b>TECH SPEC NO:</b> 20TOYOTACAMRY 2020 Toyota Camry	<b>UNIT SERIAL NO:</b> 4T1C11AK2LU893166	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.28	\$24.08	\$0.00	\$29.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$37.01	\$79.06	\$0.00	\$116.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>0.36</b>	<b>42.29</b>	<b>103.14</b>	<b>5.00</b>	<b>150.43</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/10/2024 14:00:51	04/10/2024 14:03:32	0.04	\$5.28
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/10/2024 13:42:02	04/10/2024 14:00:51	0.31	\$37.01
					<b>LABOR</b>	<b>42.29</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	14.33	5	\$71.63
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
					<b>PARTS</b>	<b>103.14</b>

# Work Order Charge Detail

UNIT NO: 243579 2020 TOYOTA CAMRY

WORK ORDER NO: 50514

---

**Work Order Notes**

(EHANNAH) PM- WASH

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced the wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

---

# Work Order Charge Detail

UNIT NO: 243579 2020 TOYOTA CAMRY WORK ORDER NO: 51682

USING DEPT NO:	507121	OPENED DATE:	08/02/2024 09:42:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/13/2024 08:07:32	METER 1 - M:	29420	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/13/2024 11:21:12	IN-SERVICE DATE:	11/27/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK2LU893166	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.26	\$2.26
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.26	\$0.00	\$0.00	\$2.26

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.02</b>	<b>2.26</b>	<b>0.00</b>	<b>2.26</b>	<b>4.52</b>
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.26
<b>COMML</b>					<b>2.26</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	08/12/2024 14:15:21	08/12/2024 14:16:30	0.02	\$2.26
<b>LABOR</b>					<b>2.26</b>	

# Work Order Charge Detail

**UNIT NO:** 243579 2020 TOYOTA CAMRY

**WORK ORDER NO:** 51682

---

**Work Order Notes**

(EHANNAH) prep for sale - remove GPS and intall in 7367B

---

**Job Notes**

**25-52-021 - REMOVE GPS SYSTEM**

(EHOWELL) Removed GPS# 87U030240068 out of unit S2856C. Reinstalled GPS into unit S7367B.

(EHOWELL) Visit Reason Changed On 8/13/2024 8:05 AM By EHOWELL

**CH-SP - CHARGE Shop Supplies**

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) No wordmarks. Removed tag 2856C. Checked inside of vehicle. CW

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Wed Aug 21 2024 12:35:23 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '243579') //Q=