

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32483

USING DEPT NO: 507121	OPENED DATE: 03/29/2019 14:50:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/11/2019 07:49:06	METER 1 - M: 5389 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/11/2019 07:49:07	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-27	WARRANTY TRANSMISSION - MAIN, AL	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-27	TRANSPORT TRANSMISSION - MAIN, A	DON	O	N	GARAGE	0.45	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$0.00	\$22.85	\$0.00	\$22.85

JOB COUNT: 3	WORK ORDER TOTAL:	1.12	0.00	22.85	0.00	22.85
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-27	WARRANTY TRANSMISSION - MAIN, AUTOMATIC	11078175	W41709	0047534	\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-27	TRANSPORT TRANSMISSION - MAIN, AUTOMATIC	11915538	04/02/2019 15:26:56	04/02/2019 15:54:12	0.45	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/29/2019 14:56:35	03/29/2019 15:36:39	0.67	\$0.00
LABOR					0.00	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.97	6	\$17.82
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
PARTS					22.85	

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32483

Work Order Notes

(EKIMBREL) pm

Job Notes

15-27 - WARRANTY TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) Tuscaloosa Ford found missing vent from PTU,
Installed new vent, cleaned and rechecked ok

16-27 - TRANSPORT TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) Taken to Ford by EK

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by RC,SH/SH
Coolant -37'

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32975

USING DEPT NO: 507121	OPENED DATE: 05/22/2019 07:45:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/23/2019 14:23:52	METER 1 - M: 7607 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/23/2019 14:23:54	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.36** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/22/2019 10:45:53	05/22/2019 11:07:33	0.36	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 32975

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 5/22/2019 7:46 AM By LISAPATE

(LISAPATE) PM by SH

Coolant -10'

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33376

USING DEPT NO: 507121	OPENED DATE: 07/10/2019 09:06:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/12/2019 13:32:23	METER 1 - M: 10064 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/12/2019 13:32:25	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/11/2019 06:00:00	07/11/2019 06:18:36	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33376

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33949

USING DEPT NO: 507121	OPENED DATE: 09/04/2019 08:15:56	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/05/2019 07:35:46	METER 1 - M: 12447 METER 2 - H: 386
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/05/2019 07:35:47	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.39** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/04/2019 08:29:15	09/04/2019 08:40:55	0.19	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/04/2019 08:28:55	09/04/2019 08:40:50	0.20	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 33949

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/JW

Coolant -35'

(AJONES) Engine Idle =96

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34563

USING DEPT NO: 507121	OPENED DATE: 10/23/2019 07:58:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/25/2019 06:41:46	METER 1 - M: 14872 METER 2 - H: 126
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/25/2019 06:41:48	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$0.00	\$32.66	\$0.00	\$32.66

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.14** **0.00** **32.66** **0.00** **32.66**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/23/2019 08:21:30	10/23/2019 08:29:53	0.14	\$0.00
LABOR						0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	3.89	6	\$23.34
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
PARTS						32.66

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 34563

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,RC/JW
Coolant -35'

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35819

USING DEPT NO: 507121	OPENED DATE: 02/28/2020 08:04:12	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/06/2020 11:34:52	METER 1 - M: 18719 METER 2 - H: 160
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/09/2020 07:27:37	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.36	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.76	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.12** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	02/28/2020 08:32:26	02/28/2020 08:43:10	0.18	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	02/28/2020 08:31:59	02/28/2020 08:42:59	0.18	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/28/2020 08:09:21	02/28/2020 08:32:26	0.38	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/28/2020 08:09:40	02/28/2020 08:31:59	0.37	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 35819

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires SH/JW

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW/SH
Coolant -34'

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36594

USING DEPT NO: 507121	OPENED DATE: 05/27/2020 07:38:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/27/2020 10:32:30	METER 1 - M: 21386 METER 2 - H: 179
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/27/2020 13:43:48	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.42** **0.00** **22.73** **0.00** **22.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/27/2020 08:21:49	05/27/2020 08:46:58	0.42	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 36594

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW performed pm. Coolant -34. Tires were rotate dat last pm, will let it go another service before rotating to let tire wear even out more.

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37224

USING DEPT NO: 507121	OPENED DATE: 07/31/2020 07:39:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/03/2020 07:45:15	METER 1 - M: 23530 METER 2 - H: 193
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/03/2020 07:45:19	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$98.65	\$0.00	\$98.65
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$0.00	\$22.73	\$0.00	\$22.73

JOB COUNT: 3	WORK ORDER TOTAL:	1.10	0.00	121.38	0.00	121.38
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12052187	07/31/2020 08:27:44	07/31/2020 08:57:44	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/31/2020 07:42:10	07/31/2020 08:18:21	0.60	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.42	2	\$0.84
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	97.81	1	\$97.81
					PARTS	121.38

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 37224

Work Order Notes

(LISAPATE) Driver had to jump off numerous times. PM and rotate tires

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Removed and installed a new battery rechecked charging at 13.9 volts

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Did not rotate tires at this time

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/JW

Coolant -35'

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38478

USING DEPT NO:	507121	OPENED DATE:	11/25/2020 07:43:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2020 14:44:38	METER 1 - M:	26909	METER 2 - H: 218
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2020 08:10:10	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8ARXJGC18480	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.42	\$34.92	\$0.00	\$63.34

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.24** **28.42** **34.92** **0.00** **63.34**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/25/2020 13:00:00	11/25/2020 13:14:27	0.24	\$28.42
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/25/2020 12:26:21	11/25/2020 12:26:21	0.00	\$0.00
					LABOR	28.42

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
					PARTS	34.92

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38478

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 26909 Engine hours 853 Idle hours 218. SH Performed PM and vacuumed. Customer was waiting did not wash or fill with gas.

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39278

USING DEPT NO: 507121	OPENED DATE: 03/03/2021 07:57:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/17/2021 08:36:54	METER 1 - M: 29656 METER 2 - H: 237
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/18/2021 12:51:32	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$891.25	\$891.25
03-PM-PMC	REPLACE NEW CABIN FILTER REPLAC	DON	O	N	GARAGE	0.10	\$11.80	\$7.20	\$0.00	\$19.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$37.47	\$54.83	\$0.00	\$92.30

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.42** **49.27** **62.03** **891.25** **1,002.55**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	2-85152		\$891.25
COMML					891.25

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	12052187	03/17/2021 07:00:00	03/17/2021 07:06:00	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/04/2021 13:00:42	03/04/2021 13:03:54	0.05	\$6.29
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/04/2021 11:36:50	03/04/2021 11:52:41	0.26	\$31.17
LABOR					49.26	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	18.41	1	\$18.41
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.78	1	\$9.78
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	800151C	CABIN AIR FILTER REPL 4068	7.20	1	\$7.20
PARTS					62.03	

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 39278

Work Order Notes

(LISAPATE) PM-Replace windshield has a large crack running across

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr removed and installed new windshield and moldings. Pd by CC

03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT

(EHOWELL) Cabin filter was replaced. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Windshield needs replaced. Coolant -34°. JAW/AMG

MILEAGE-29656

IDLE HRS-237

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40075

USING DEPT NO: 507121	OPENED DATE: 06/02/2021 08:02:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/02/2021 10:29:07	METER 1 - M: 32827 METER 2 - H: 258
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/03/2021 08:41:22	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$63.65	\$31.13	\$0.00	\$94.78

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.54** **63.65** **31.13** **0.00** **94.78**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/02/2021 08:08:56	06/02/2021 08:27:59	0.32	\$37.47
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/02/2021 08:12:31	06/02/2021 08:25:50	0.22	\$26.19
					LABOR	63.66

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	31.13

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 40075

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH

MILEAGE-32827

HRS-1028

IDLE HRS-258

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41201

USING DEPT NO: 507121	OPENED DATE: 10/05/2021 07:44:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/05/2021 10:36:32	METER 1 - M: 37045 METER 2 - H: 290
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/05/2021 14:06:08	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.54	\$31.82	\$0.00	\$33.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$36.45	\$31.50	\$0.00	\$67.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.32** **37.99** **63.32** **2.00** **103.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/05/2021 08:30:14	10/05/2021 08:31:01	0.01	\$1.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/05/2021 08:11:31	10/05/2021 08:30:03	0.31	\$36.45
LABOR					37.99	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.86	1	\$4.86
PARTS					63.32	

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41201

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 37045 Engine hours 1159 Idle hours 290. SH JW/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41895

USING DEPT NO: 507121	OPENED DATE: 12/15/2021 07:42:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/15/2021 15:14:45	METER 1 - M: 39838 METER 2 - H: 312
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/16/2021 07:38:36	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$44.55	\$0.00	\$83.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.48** **56.64** **44.55** **2.00** **103.19**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	12/15/2021 12:16:34	12/15/2021 12:25:34	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/15/2021 12:16:34	12/15/2021 12:16:34	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/15/2021 12:16:34	12/15/2021 12:16:34	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/15/2021 12:16:34	12/15/2021 12:36:22	0.33	\$38.94
LABOR					56.64	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.20	1	\$7.20
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
PARTS					44.55	

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 41895

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW
MILEAGE-39838
ENG HRS-1248
IDLE HRS-312

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42832

USING DEPT NO: 507121	OPENED DATE: 04/05/2022 13:31:12	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/05/2022 15:41:33	METER 1 - M: 43927 METER 2 - H: 312
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/15/2022 09:28:12	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.79	\$22.62	\$0.00	\$25.41
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$65.59	\$42.74	\$0.00	\$108.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.58** **68.38** **65.36** **2.00** **135.74**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/05/2022 13:56:32	04/05/2022 13:57:57	0.02	\$2.79
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/05/2022 13:44:31	04/05/2022 13:56:22	0.20	\$23.31
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/05/2022 13:44:07	04/05/2022 13:55:25	0.19	\$22.22
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/05/2022 13:44:21	04/05/2022 13:54:33	0.17	\$20.06
LABOR						68.38

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.39	1	\$5.39
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						65.36

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42832

Work Order Notes

(CHANNELL) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH JW/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42903

USING DEPT NO:	507121	OPENED DATE:	04/13/2022 07:21:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/18/2022 11:38:47	METER 1 - M:	44064	METER 2 - H: 312
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/20/2022 08:38:41	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8ARXJGC18480	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **59.50** **59.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
24-02-061	REPAIR WINDSHIELD	11078716	298150		\$57.50
				COMML	59.50

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 42903

Work Order Notes

(CHANNELL) glass doctor \ rock ding repair

Job Notes

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) Glass Dr came to the shop and repaired the ding in the windshield. PD by CC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43840

USING DEPT NO: 507121	OPENED DATE: 07/05/2022 13:24:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/08/2022 13:15:13	METER 1 - M: 46483 METER 2 - H: 364
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/11/2022 07:58:34	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.26	\$30.48	\$0.00	\$0.00	\$30.48
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.70	\$83.09	\$0.00	\$0.00	\$83.09
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.26	\$149.11	\$850.03	\$0.00	\$999.14
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.91	\$59.46	\$0.00	\$102.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.59	305.59	909.49	2.00	1,217.08
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00	
					COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	07/06/2022 09:38:28	07/06/2022 10:54:17	1.26	\$149.11
06-15	INSPECT STEERING	11901357	07/06/2022 09:22:41	07/06/2022 09:38:11	0.26	\$30.48
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/06/2022 08:31:01	07/06/2022 08:52:50	0.36	\$42.91
66-17-013	PERFORM ALIGNMENT	11213180	07/06/2022 15:07:50	07/06/2022 15:50:05	0.70	\$83.09
					LABOR	305.59

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.61	4	\$10.44
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.26	2	\$0.51
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.44	2	\$0.87
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	1	\$0.80
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.81	6	\$34.83
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.52	1	\$11.52

Work Order Charge Detail

The University of Alabama

Report Printed: 02/06/2025 12:33:05 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-17-028	PERFORM MOUNT AND BALANCE TIRES	732026500	GDY EAGLE RS-A POLIC 245/55R18	209.13	4	\$836.52
					PARTS	909.49

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 43840

Work Order Notes

(LISAPATE) PM-check tires are worn-seatbelt chime was going off for no reason has stopped now.

Job Notes

06-15 - INSPECT STEERING

(AGUERRA) Checked steering, no issues found. AMG

66-17-013 - PERFORM ALIGNMENT

(MSIDES) Performed alignment. MS

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) Mounted and balanced 4 tires. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 46483 hours: 1453 idle hours: 364 Completed PM topside, Scott was bottomside. Completed checklist. AMG/SH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44853

USING DEPT NO: 507121	OPENED DATE: 10/04/2022 07:47:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/06/2022 08:53:54	METER 1 - M: 49711 METER 2 - H: 389
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/06/2022 09:28:10	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.79	\$23.16	\$0.00	\$23.95
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.32	\$75.22	\$0.00	\$109.54
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$0.89	\$30.32	\$0.00	\$31.21
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.31** **36.00** **128.70** **5.00** **169.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	10/04/2022 08:37:29	10/04/2022 08:37:56	0.01	\$0.89
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/04/2022 08:36:46	10/04/2022 08:37:10	0.01	\$0.79
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/04/2022 08:19:08	10/04/2022 08:36:35	0.29	\$34.32
					LABOR 36.00	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP68	CABIN FILTER	30.32	1	\$30.32
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.85	1	\$7.85
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.44	1	\$10.44
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.38	(1)	(\$10.38)
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.69	1	\$11.69
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	7.10	6	\$42.57
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.38	1	\$10.38
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
					PARTS 128.70	

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 44853

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46294

USING DEPT NO: 507121	OPENED DATE: 02/28/2023 07:23:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/28/2023 08:38:16	METER 1 - M: 54197 METER 2 - H: 425
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/28/2023 09:07:41	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.40	\$75.45	\$0.00	\$96.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.18** **21.40** **75.45** **5.00** **101.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/28/2023 07:36:47	02/28/2023 07:47:40	0.18	\$21.40
LABOR					21.40	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	19.05	1	\$19.05
PARTS					75.45	

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 46294

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47399

USING DEPT NO: 507121	OPENED DATE: 06/21/2023 12:44:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/30/2023 09:36:12	METER 1 - M: 57546 METER 2 - H: 425
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/05/2023 09:26:18	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$442.75	\$442.75
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.50** **59.00** **0.00** **447.75** **506.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	2109792		\$442.75
COMML					447.75

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-71	TRANSPORT BODY	11915538	06/30/2023 07:00:00	06/30/2023 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 47399

Work Order Notes

(EHANNAH) transport for windshield- vendor

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

16-71 - TRANSPORT BODY

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48030

USING DEPT NO: 507121	OPENED DATE: 08/29/2023 09:57:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/31/2023 08:24:22	METER 1 - M: 59360 METER 2 - H: 463
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/31/2023 09:43:28	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.24	\$64.34	\$0.00	\$85.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.18** **21.24** **64.34** **5.00** **90.58**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	08/29/2023 10:14:37	08/29/2023 10:25:25	0.18	\$21.24
LABOR					21.24	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
PARTS					64.34	

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48030

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC,FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

Miles, 59,360

Idle Hrs, 463

Total Hrs, 1,838

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48268

USING DEPT NO:	507121	OPENED DATE:	09/20/2023 09:41:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2023 09:46:15	METER 1 - M:	59448	METER 2 - H: 463
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2023 09:46:19	IN-SERVICE DATE:	08/06/2018	
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8ARXJGC18480	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$224.25	\$224.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **229.25** **229.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>				
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00				
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	11078716	2-110895		\$224.25				
COMML									229.25

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48268

Work Order Notes

(IFALLS) replace driver pillar trim

Job Notes

03-02-031 - REPLACE NEW EXTERIOR BODY MOLDINGS

(IFALLS) replaced by glass dr

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48811

USING DEPT NO: 507121	OPENED DATE: 11/02/2023 11:40:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/06/2023 08:42:10	METER 1 - M: 59668 METER 2 - H: 463
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/06/2023 13:24:46	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.26	\$30.94	\$199.64	\$0.00	\$230.58
AD-42-011	ADDED COOLANT	DON	N	N	GARAGE	0.92	\$108.63	\$20.72	\$0.00	\$129.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	5	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **2.18** **257.57** **220.36** **5.00** **482.93**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	11/06/2023 07:00:00	11/06/2023 08:00:00	1.00	\$118.00
03-32-002	REPLACE NEW BATTERY	11310047	11/03/2023 07:55:56	11/03/2023 08:09:30	0.23	\$26.68
AD-42-011	ADDED COOLANT	11310047	11/02/2023 14:57:54	11/02/2023 15:53:08	0.92	\$108.63
03-32-002	REPLACE NEW BATTERY	11310047	11/02/2023 14:30:00	11/02/2023 14:32:10	0.04	\$4.26
03-32-002	REPLACE NEW BATTERY	11310047	11/02/2023 14:28:48	11/02/2023 14:28:48	0.00	\$0.00
					LABOR 257.57	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	199.64	1	\$199.64
AD-42-011	ADDED COOLANT	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	20.72	1	\$20.72
					PARTS 220.36	

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 48811

Work Order Notes

(LRUSHING) replace battery and add fluids

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) The battery had corrosion and was failing to start. Replaced battery, cleaned cables and reset the battery monitoring system. EH

AD-42-011 - ADDED COOLANT

(GARAGE) Topped off coolant. EH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) reset the battery monitoring system. EH

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49705

USING DEPT NO: 507121	OPENED DATE: 02/06/2024 07:59:13	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/07/2024 15:33:00	METER 1 - M: 63030 METER 2 - H: 463
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/07/2024 15:33:03	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$48.97	\$60.56	\$0.00	\$109.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.42** **48.97** **60.56** **5.00** **114.53**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/06/2024 08:06:54	02/06/2024 08:31:48	0.42	\$48.97
LABOR					48.97	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
PARTS					60.56	

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49705

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc -sh

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49805

USING DEPT NO: 507121	OPENED DATE: 02/14/2024 15:15:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/15/2024 08:33:19	METER 1 - M: 63426 METER 2 - H: 463
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/16/2024 11:47:35	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR 2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-061	REPAIR WINDSHIELD	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.00** **0.00** **62.50** **62.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>				
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00				
24-02-061	REPAIR WINDSHIELD	11078716	2115730		\$57.50				
COMML									62.50

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 49805

Work Order Notes

(EKIMBREL) repair windshield

Job Notes

24-02-061 - REPAIR WINDSHIELD

(EKIMBREL) glass dr repaired windshield

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50083

USING DEPT NO: 507121	OPENED DATE: 03/06/2024 08:08:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/07/2024 07:27:06	METER 1 - M: 63982 METER 2 - H: 463
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/07/2024 12:56:25	IN-SERVICE DATE: 08/06/2018
TECH SPEC NO: 18FORDEXPINTR	2018 Ford Explorer Interceptor	UNIT SERIAL NO: 1FM5K8ARXJGC18480

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.03	\$3.64	\$0.00	\$0.00	\$3.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$3.64	\$3.64

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.03** **3.64** **0.00** **3.64** **7.28**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$3.64
COMML					3.64

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	12395904	03/06/2024 08:47:38	03/06/2024 08:49:29	0.03	\$3.64
LABOR						3.64

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 50083

Work Order Notes

(EHANNAH) install GPS- inside light bar strobe has a bulb out.

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(FCONTRER) install GPS system fc
(LISAPATE) Serial# 87U030240164

24-34-022 - REPAIR STROBE LIGHT/BULB/MOTOR/ASSY

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51964

USING DEPT NO:	507121	OPENED DATE:	08/29/2024 07:10:54	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	08/30/2024 11:57:12	METER 1 - M:	65642	METER 2 - H:	463		
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	08/30/2024 12:35:24	IN-SERVICE DATE:	08/06/2018				
TECH SPEC NO:	18FORDEXPINTR	2018 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8ARXJGC18480				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 242799 **2018 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 51964

Work Order Notes

(EHANNAH) prep for sale

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(EHOWELL) GPS# 87U030240164 was removed.

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EHOWELL) Vehicle was prepped for sale.

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Feb 06 2025 12:33:05 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242799') //Q=