

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 37426

USING DEPT NO:	507121	OPENED DATE:	08/25/2020 07:36:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2020 07:38:06	METER 1 - M:	103	METER 2 - H: 3
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2020 09:13:25	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	08/25/2020 07:37:35	08/25/2020 08:07:35	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 37426

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 38826

USING DEPT NO:	507121	OPENED DATE:	01/19/2021 10:30:38	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2021 10:31:21	METER 1 - M:	104	METER 2 - H:	3				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2021 10:31:24	IN-SERVICE DATE:	08/20/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 38826

Work Order Notes

(LISAPATE) Opened WO for documentation per Tony J. Unit has not been put in service yet. Being held up due to a strobe light issue

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39650

USING DEPT NO:	507121	OPENED DATE:	04/13/2021 10:48:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/14/2021 10:46:58	METER 1 - M:	856	METER 2 - H: 70
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/14/2021 13:57:29	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.88	\$0.00	\$0.00	\$28.88

JOB COUNT: 1	WORK ORDER TOTAL:	0.24	28.88	0.00	0.00	28.88
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/13/2021 15:29:10	04/13/2021 15:43:51	0.24	\$28.88
					LABOR	28.88

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39650

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 856 idle hours: 70 New unit vehicle does not have enough miles or hours. Checked all fluids, battery and tires. Completed checklist. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40219

USING DEPT NO:	507121	OPENED DATE:	06/22/2021 07:13:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/23/2021 14:39:03	METER 1 - M:	2266	METER 2 - H: 70
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/23/2021 14:39:07	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.29	\$152.06	\$53.45	\$0.00	\$205.51
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.01	\$1.38	\$14.72	\$0.00	\$16.10

JOB COUNT: 2	WORK ORDER TOTAL:	1.30	153.44	68.17	0.00	221.61
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/22/2021 07:25:59	06/22/2021 07:43:38	0.29	\$34.71
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/22/2021 08:00:30	06/22/2021 08:06:42	0.10	\$12.19
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/22/2021 08:33:17	06/22/2021 09:13:09	0.66	\$78.40
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/22/2021 09:15:34	06/22/2021 09:29:10	0.23	\$26.75
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	06/22/2021 09:29:30	06/22/2021 09:30:12	0.01	\$1.38
					LABOR	153.43

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	PF63	FILTER-OIL	9.68	1	\$9.68
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.51	1	\$6.51
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800180C	CABIN FILTER	14.72	1	\$14.72
					PARTS	68.17

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 40219

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/JAW

MILEAGE-2270

IDLE HRS-301

ENG HRS-420

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(JWRIGHT) Installed new filter. Had to cut a different style to make it fit. New style is on back order.

Work Order Charge Detail

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40654

USING DEPT NO:	507121	OPENED DATE:	08/06/2021 07:57:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/09/2021 11:37:44	METER 1 - M:	3835	METER 2 - H: 604
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/09/2021 15:17:46	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$29.50	\$31.35	\$0.00	\$60.85
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.79	\$46.94	\$0.00	\$96.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.67	79.29	78.29	2.00	159.58
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/06/2021 08:43:46	08/06/2021 09:03:34	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/06/2021 08:34:47	08/06/2021 08:40:18	0.09	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/06/2021 08:43:46	08/06/2021 08:45:17	0.03	\$2.98
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/06/2021 08:43:46	08/06/2021 08:45:17	(0.03)	(\$2.98)
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/06/2021 08:47:47	08/06/2021 09:02:47	0.25	\$29.50
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/06/2021 08:47:47	08/06/2021 08:48:06	0.01	\$0.62
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/06/2021 08:47:47	08/06/2021 08:48:06	(0.01)	(\$0.62)
					LABOR	79.29

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	9.72	1	\$9.72
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	PF63	FILTER-OIL	9.68	1	\$9.68
					PARTS	78.29

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40654

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 3835 Engine hours 812 Idle hours 604. AMG SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41003

USING DEPT NO:	507121	OPENED DATE:	09/13/2021 09:19:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/16/2021 11:23:27	METER 1 - M:	5076	METER 2 - H: 1125
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/16/2021 12:32:40	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-35-016	REPLACE NEW POWER MIRROR SWITCH	DON	W	J	GARAGE	0.27	\$31.70	\$0.00	\$0.00	\$31.70
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.05	\$31.80	\$0.00	\$36.85
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.36	\$42.12	\$0.00	\$0.00	\$42.12
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$72.08	\$42.17	\$0.00	\$114.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.28	150.95	73.97	2.00	226.92
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/14/2021 11:05:26	09/14/2021 11:26:51	0.36	\$42.12
03-35-016	REPLACE NEW POWER MIRROR SWITCH	11170580	09/14/2021 15:02:51	09/14/2021 15:18:58	0.27	\$31.70
03-35-016	REPLACE NEW POWER MIRROR SWITCH	11170580	09/14/2021 15:02:51	09/14/2021 15:18:58	(0.27)	(\$31.70)
03-35-016	REPLACE NEW POWER MIRROR SWITCH	11170580	09/14/2021 15:02:51	09/14/2021 15:18:58	0.27	\$31.70
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/14/2021 09:44:11	09/14/2021 09:46:45	0.04	\$5.05
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/14/2021 09:30:00	09/14/2021 09:43:57	0.23	\$27.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/14/2021 08:52:18	09/14/2021 09:15:00	0.38	\$44.64
				LABOR		150.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.17	1	\$10.17
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.91	1	\$4.91

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						73.97

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41003

Work Order Notes

(LISAPATE) PM-replace wipers-power window switch is broken

Job Notes

03-35-016 - REPLACE NEW POWER MIRROR SWITCH

(ABBLACK) AB found drivers mirror switch was not working right. Warrantied part from town and country. Rechecked ok

(LISAPATE) Town and Country invoice 2194063 9-14-21 \$0.00

(LISAPATE) Visit Reason Changed On 9/16/2021 11:23 AM By LISAPATE

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

15-35-016 - WARRANTY POWER MIRROR SWITCH

16-35 - TRANSPORT MULTI-FUNC ELECTRON/ELEC DEVCS

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires relearned tire positions and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 5076 Engine hours 1125 Idle hours 832. SH Performed PM add 1/2 hour labor for skid plate removal.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41731

USING DEPT NO:	507121	OPENED DATE:	11/30/2021 07:56:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2021 10:32:06	METER 1 - M:	6472	METER 2 - H: 1132
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	12/02/2021 12:31:35	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$39.37	\$53.30	\$0.00	\$92.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.33	39.37	53.30	2.00	94.67
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/30/2021 09:41:20	11/30/2021 10:01:21	0.33	\$39.37
					LABOR	39.37

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.48	1	\$9.48
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
					PARTS	53.30

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41731

Work Order Notes

(IFALLS) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG

MILEAGE-6472

IDLE HRS-1132

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42552

USING DEPT NO:	507121	OPENED DATE:	03/03/2022 09:48:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2022 11:19:27	METER 1 - M:	7909	METER 2 - H: 1401
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2022 14:08:00	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.80	\$31.82	\$0.00	\$35.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.29	\$151.73	\$43.49	\$0.00	\$195.22
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.32	155.53	75.31	2.00	232.84
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/03/2022 14:28:30	03/03/2022 14:55:37	0.45	\$53.33
03-51-038	REPLACE NEW WIPER BLADES	11901357	03/03/2022 15:06:20	03/03/2022 15:08:16	0.03	\$3.80
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/03/2022 14:18:21	03/03/2022 15:08:23	0.83	\$98.40
LABOR						155.53

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.23	1	\$6.23
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						75.31

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42552

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Josh replaced front and rear wipers. JW

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 7909 hours: 1878 idle hours: 1401 Completed PM topside, Josh was bottomsides. Completed checklist. AMG/JW Add .5 for underbody cover. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43635

USING DEPT NO:	507121	OPENED DATE:	06/13/2022 10:24:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/14/2022 09:47:44	METER 1 - M:	9305	METER 2 - H: 1668
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/16/2022 09:56:19	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.26	\$81.29	\$0.00	\$136.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.47	55.26	81.29	2.00	138.55
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/13/2022 14:39:27	06/13/2022 15:07:33	0.47	\$55.26
LABOR						55.26

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.82	1	\$5.82
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.21	1	\$11.21
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	6	\$64.26
PARTS						81.29

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43635

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44606

USING DEPT NO:	507121	OPENED DATE:	09/08/2022 08:25:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/09/2022 13:32:38	METER 1 - M:	9807	METER 2 - H: 1715
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/12/2022 07:58:15	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	0.72	\$84.99	\$35.48	\$0.00	\$120.47
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.48	\$0.00	\$0.00	\$34.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:		1.01	119.47	35.48	5.00	159.95
--------------	-------------------	--	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11074414	09/08/2022 14:44:52	09/08/2022 15:17:36	0.55	\$64.38
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11074414	09/08/2022 13:54:53	09/08/2022 14:05:22	0.17	\$20.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/08/2022 13:37:06	09/08/2022 13:54:38	0.29	\$34.48
LABOR						119.48

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	08984	ADHESIVE REMOVER	35.48	1	\$35.48
PARTS						35.48

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44606

Work Order Notes

(CWIGLEY) PM. Remove wordmarks off both sides of rear bumper.

Job Notes

25-53-006 - REMOVE WORDMARKS/IDENTIFIERS

(SHARBIN) Removed word marks from bottom right and left rear of the vehicle. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 502 miles and idled 47 hours since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45032

USING DEPT NO:	507121	OPENED DATE:	10/19/2022 15:19:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2022 11:00:34	METER 1 - M:	11095	METER 2 - H: 2043
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/24/2022 13:59:03	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.75	\$23.24	\$0.00	\$31.99
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.66	\$78.40	\$56.28	\$0.00	\$134.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.74	87.15	79.52	5.00	171.67
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/20/2022 07:55:18	10/20/2022 07:59:45	0.07	\$8.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/20/2022 07:15:15	10/20/2022 07:55:07	0.66	\$78.40
LABOR						87.15

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.77	1	\$12.77
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.73	1	\$5.73
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
PARTS						79.52

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45032

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45404

USING DEPT NO:	507121	OPENED DATE:	12/01/2022 09:52:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/02/2022 07:49:33	METER 1 - M:	11888	METER 2 - H: 3021
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2022 09:50:02	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.91	\$51.47	\$0.00	\$96.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.38 44.91 51.47 5.00 101.38

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/01/2022 13:02:25	12/01/2022 13:25:15	0.38	\$44.91
LABOR						44.91

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.17	1	\$6.17
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
PARTS						51.47

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45404

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46172

USING DEPT NO:	507121	OPENED DATE:	02/16/2023 07:42:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/17/2023 08:08:01	METER 1 - M:	12722	METER 2 - H: 3021
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/17/2023 14:37:03	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.24	\$146.25	\$56.31	\$0.00	\$202.56
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 1.24 146.25 56.31 5.00 207.56

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/16/2023 08:16:10	02/16/2023 09:30:32	1.24	\$146.25
LABOR						146.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	8.25	6	\$49.50
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	8.25	(6)	(\$49.50)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
PARTS						56.31

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46172

Work Order Notes

(EHANNAH) pm-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) cancel

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-12722

HRS-3362

IDLE-2601

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46865

USING DEPT NO:	507121	OPENED DATE:	04/27/2023 07:53:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/28/2023 08:22:47	METER 1 - M:	13775	METER 2 - H: 3021
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/28/2023 13:32:46	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.11	\$13.44	\$0.00	\$0.00	\$13.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.96	\$70.62	\$0.00	\$90.58
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.05	\$5.64	\$33.45	\$0.00	\$39.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.33	39.04	104.07	5.00	148.11
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/27/2023 09:04:51	04/27/2023 09:15:00	0.17	\$19.96
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	04/27/2023 09:15:38	04/27/2023 09:15:38	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	04/27/2023 09:30:00	04/27/2023 09:36:50	0.11	\$13.44
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	04/27/2023 13:19:23	04/27/2023 13:22:15	0.05	\$5.64
				LABOR		39.04

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	AF99517	AIR FILTER FORD EXPLORER	14.31	1	\$14.31
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	33.45	1	\$33.45
				PARTS		104.07

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46865

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires relearned the tire positions and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47228

USING DEPT NO:	507121	OPENED DATE:	06/01/2023 07:11:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2023 10:03:29	METER 1 - M:	14458	METER 2 - H: 3055
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/05/2023 09:06:07	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.51	\$34.03	\$0.00	\$41.54
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.45	\$52.58	\$61.82	\$0.00	\$114.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.51	60.09	95.85	5.00	160.94
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/01/2023 10:56:59	06/01/2023 11:23:43	0.45	\$52.58
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/01/2023 11:24:30	06/01/2023 11:28:19	0.06	\$7.51
LABOR						60.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.73	1	\$10.73
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
PARTS						95.85

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47228

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47291

USING DEPT NO:	507121	OPENED DATE:	06/08/2023 07:13:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/08/2023 08:51:38	METER 1 - M:	14550	METER 2 - H: 3089
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/12/2023 12:56:39	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	P	N	GARAGE	0.44	\$51.95	\$10.07	\$0.00	\$62.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.44	51.95	10.07	5.00	67.02
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11074414	06/08/2023 07:21:55	06/08/2023 07:48:20	0.44	\$51.95
LABOR						51.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.50	1	\$3.50
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.25	1	\$5.25
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.66	2	\$1.32
PARTS						10.07

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47291

Work Order Notes

(EHANNAH) LF tire has a leak in it.

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

66-17-030 - PERFORM TIRE PATCH

(SHARBIN) Found a screw in the left front tire. Patched the tire rechecks good. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47531

USING DEPT NO:	507121	OPENED DATE:	07/06/2023 07:07:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/06/2023 13:16:16	METER 1 - M:	15208	METER 2 - H: 3362
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/06/2023 14:35:13	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.71	\$72.58	\$0.00	\$101.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.24 28.71 72.58 5.00 106.29

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/06/2023 07:40:42	07/06/2023 07:55:18	0.24	\$28.71
					LABOR	28.71

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
					PARTS	72.58

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47531

Work Order Notes

(EHANNAH) pm- replace wipers
(EKIMBREL) got wipers last month

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47657

USING DEPT NO:	507121	OPENED DATE:	07/19/2023 15:01:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/19/2023 15:04:19	METER 1 - M:	15496	METER 2 - H: 3362
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/20/2023 08:50:07	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-21-005	WARRANTY CV AXLE BOOT	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-21-005	WARRANTY CV AXLE BOOT	11099772	100610830		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: **243747** **2020 FORD INTERCEPTOR EXPLORER**

WORK ORDER NO: **47657**

Work Order Notes

(LISAPATE) RF axle boot is leaking

Job Notes

15-21-005 - WARRANTY CV AXLE BOOT

(LISAPATE) Long Lewis tech removed and replaced the RF axle shaft

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47775

USING DEPT NO:	507121	OPENED DATE:	07/31/2023 07:55:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/01/2023 08:01:23	METER 1 - M:	15496	METER 2 - H: 3362
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/01/2023 11:32:17	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-78-038	INSPECT UNDER CARRIAGE SKID PLAT	DON	O	N	GARAGE	0.39	\$46.38	\$0.00	\$0.00	\$46.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.39 46.38 0.00 5.00 51.38

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-78-038	INSPECT UNDER CARRIAGE SKID PLATES	12201267	07/31/2023 08:13:18	07/31/2023 08:36:53	0.39	\$46.38
					LABOR	46.38

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47775

Work Order Notes

(EHANNAH) skid plate came off please replace it

Job Notes

06-78-038 - INSPECT UNDER CARRIAGE SKID PLATES

(GARAGE) Fixed and Reinstalled skid pan underneath the unit, skid pan look to have been ripped off some how, most bolts that hold skid pan on were still screwed into their holes, fixed tabs and screwed everything back in.-GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48042

USING DEPT NO:	507121	OPENED DATE:	08/30/2023 08:56:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/31/2023 10:23:29	METER 1 - M:	16904	METER 2 - H: 3797
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2023 15:13:33	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.23	\$64.34	\$0.00	\$119.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.47 55.23 64.34 5.00 124.57

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/30/2023 14:31:43	08/30/2023 14:59:48	0.47	\$55.23
LABOR						55.23

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
PARTS						64.34

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48042

Work Order Notes

(EHANNAH) pm- wipers
(EKIMBREL) just got wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) FC GC/SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48219

USING DEPT NO:	507121	OPENED DATE:	09/15/2023 07:40:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2023 15:03:02	METER 1 - M:	17268	METER 2 - H: 3797
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2023 09:37:20	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	O	N	GARAGE	0.26	\$30.42	\$0.00	\$0.00	\$30.42
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.07	\$8.49	\$0.00	\$0.00	\$8.49
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.58	\$186.15	\$1,014.71	\$0.00	\$1,200.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.91	225.06	1,014.71	5.00	1,244.77
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/18/2023 14:30:00	09/18/2023 15:55:30	1.43	\$168.15
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/18/2023 14:06:28	09/18/2023 14:15:00	0.14	\$16.78
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	09/15/2023 08:24:59	09/15/2023 08:40:27	0.26	\$30.42
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/19/2023 14:35:45	09/19/2023 14:36:22	0.01	\$1.21
66-17-013	PERFORM ALIGNMENT	12052187	09/19/2023 14:34:57	09/19/2023 14:39:16	0.07	\$8.49
				LABOR		225.05

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.84	4	\$27.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.43	3	\$1.30
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.90	1	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	2	\$2.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	1.22	1	\$1.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	1.31	3	\$3.92
66-17-028	PERFORM MOUNT AND BALANCE TIRES	91852	TIRE 255/60R18 BFG ELITE FORCE	244.50	4	\$978.00
					PARTS	1014.71

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48219

Work Order Notes

(IFALLS) Front Driver tire is going low

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(SHARBIN) Inspected the left front tire. Did not find anything in the tire. Inspected the other 3 tires and found both rear tires at 2/32 tread depth and both have screws in them that are leaking. The right front tire is also at 2/32 tread depth. Suggest 4 new tires. SH

(LISAPATE) Checked front end SH

66-17-013 - PERFORM ALIGNMENT

(GARAGE) Performed alignment. Adjusted the RR camber and the rear toe on both tires. Adjusted front toe both sides. Relearned the LDW system. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires and relearned tire positions. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48947

USING DEPT NO:	507121	OPENED DATE:	11/13/2023 14:41:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/15/2023 10:47:18	METER 1 - M:	17658	METER 2 - H: 3980
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/15/2023 13:28:13	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.31	\$36.94	\$0.00	\$0.00	\$36.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.31	36.94	0.00	5.00	41.94
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-021	INSTALL GPS SYSTEM	11074414	11/13/2023 14:56:59	11/13/2023 15:15:46	0.31	\$36.94
LABOR						36.94

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 48947

Work Order Notes

(EHANNAH) install GPS- 87X032360265

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(SHARBIN) Installed GPS# 87X032360265.SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49310

USING DEPT NO:	507121	OPENED DATE:	12/20/2023 09:17:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/20/2023 14:37:40	METER 1 - M:	23411	METER 2 - H: 3980
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/21/2023 07:26:50	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$39.37	\$64.16	\$0.00	\$103.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.33	39.37	64.16	5.00	108.53
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/20/2023 11:15:46	12/20/2023 11:35:47	0.33	\$39.37
LABOR						39.37

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
PARTS						64.16

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49310

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EHANNAH) pm fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 49963

USING DEPT NO:	507121	OPENED DATE:	02/27/2024 09:50:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/29/2024 13:58:14	METER 1 - M:	20280	METER 2 - H: 4742
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/29/2024 14:45:36	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$46.97	\$60.56	\$0.00	\$107.53
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.01	\$1.21	\$33.45	\$0.00	\$34.66
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.41	48.18	94.01	5.00	147.19
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-021	INSTALL GPS SYSTEM	11074414	02/27/2024 13:48:39	02/27/2024 13:49:48	0.02	\$2.26
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	02/27/2024 13:48:02	02/27/2024 13:48:39	0.01	\$1.21
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/27/2024 13:24:09	02/27/2024 13:48:02	0.40	\$46.97
14-52-021	INSTALL GPS SYSTEM	11074414	02/27/2024 13:48:39	02/27/2024 13:49:48	(0.02)	(\$2.26)
LABOR						48.18

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	33.45	1	\$33.45
PARTS						94.01

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49963

Work Order Notes

(EHANNAH) pm- install GPS
(LISAPATE) already had a GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Already has a GPS. SH
(LISAPATE) Did not replace

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) FC Replaced the cabin filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50500

USING DEPT NO:	507121	OPENED DATE:	04/10/2024 07:17:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2024 10:44:27	METER 1 - M:	21510	METER 2 - H: 4742
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/09/2024 08:12:53	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-21-002	WARRANTY CV AXLES/SEALS	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-21	TRANSPORT AXLES - DRIVEN, FRONT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.19	\$22.13	\$0.00	\$0.00	\$22.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$39.89	\$68.21	\$0.00	\$108.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.53	62.02	68.21	5.00	135.23
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
15-21-002	WARRANTY CV AXLES/SEALS	11078175	124567		\$0.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	04/10/2024 07:45:12	04/10/2024 07:56:27	0.19	\$22.13
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/10/2024 07:24:55	04/10/2024 07:45:12	0.34	\$39.89
				LABOR		62.02

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
				PARTS		68.21

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50500

Work Order Notes

(EHANNAH) pm

Job Notes

15-21-002 - WARRANTY CV AXLES/SEALS

(LISAPATE) Ford installed a new LF axle assy test drover verified repair

16-21 - TRANSPORT AXLES - DRIVEN, FRONT STEERING

(LISAPATE) Taken to Ford by RC/CW

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) SH Rotated the left side. FC Rotated the right side and inspected the brakes. Found the left front CV axel leaking. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50932

USING DEPT NO:	507121	OPENED DATE:	05/23/2024 14:43:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2024 15:13:35	METER 1 - M:	22542	METER 2 - H: 5251
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2024 08:07:44	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.03	\$3.02	\$221.08	\$0.00	\$224.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.03	3.02	221.08	5.00	229.10
--------------	-------------------	--	--	--	--	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11074414	05/23/2024 15:08:03	05/23/2024 15:09:35	0.03	\$3.02
LABOR						3.02

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	221.08	1	\$221.08
PARTS						221.08

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50932

Work Order Notes

(EHANNAH) dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) Officer came to pick vehicle and the battery was dead. Battery was 4 years old. Installed a new battery ALT charging at 14.4 volts. SH

06-32-002 - INSPECT BATTERY

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51071

USING DEPT NO:	507121	OPENED DATE:	06/06/2024 09:12:09	LOCATION:	GARAGE - University Automotive Services					
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2024 09:18:45	METER 1 - M:	23089	METER 2 - H:	5251			
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2024 10:15:02	IN-SERVICE DATE:	08/20/2020					
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-02-074	RECALL WINDOW SWITCH	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51071

Work Order Notes

(EHANNAH) prep and schedule- Recall for power window switch

Job Notes

17-02-074 - RECALL WINDOW SWITCH

(EHANNAH) LL Ford came to our shop for Recall for power window switch.

17-GA-005 - RECALL Scheduling and Preparation

(EHANNAH) prep and scheduling by Denise

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51172

USING DEPT NO:	507121	OPENED DATE:	06/13/2024 07:12:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/13/2024 09:02:23	METER 1 - M:	23412	METER 2 - H: 5251
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/13/2024 10:12:19	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$68.66	\$0.00	\$68.66
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$37.50	\$0.00	\$37.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	106.16	5.00	111.16
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP100	CABIN FILTER	37.50	1	\$37.50
PARTS						106.16

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51172

Work Order Notes

(LRUSHING) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC,FC, Changed oil and oil filter, checked fluids, air filter good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 23,412

Idle Hours, 5,429

Total Hours, 6,768

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced cabin filter-FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51605

USING DEPT NO:	507121	OPENED DATE:	07/25/2024 07:58:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/31/2024 14:29:18	METER 1 - M:	24679	METER 2 - H: 5830
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/31/2024 15:59:36	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	N	N	GARAGE	0.00	\$0.00	\$259.35	\$0.00	\$259.35
06-34-011	INSPECT TAILLIGHT ASSEMBLY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$0.95	\$68.66	\$0.00	\$69.61
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.01	0.95	328.01	5.00	333.96
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/25/2024 14:07:14	07/25/2024 14:07:43	0.01	\$0.95
					LABOR	0.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWRZ362231	REAR BRAKE PADS	71.85	1	\$71.85
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBRSB682614	REAR ROTORS	93.75	2	\$187.50
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
					PARTS	328.01

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51605

Work Order Notes

(EHANNAH) pm- SI- tail light

Job Notes

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(GARAGE) Replaced rear pads and rotors. JAW

06-34-011 - INSPECT TAILLIGHT ASSEMBLY

(GARAGE) No issues with taillight assemblies. JAW/FC

66-13-130 - PERFORM Burnish Brakes

(GARAGE) Burnished brakes. JAW

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed safety inspection, rear brake pads and rotors need to be replaced, got with JW and let him know, No other issues found.-GC

Brake pads Front 6mm Rear 2mm

Miles, 24,679

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51763

USING DEPT NO:	507121	OPENED DATE:	08/12/2024 07:13:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/17/2024 08:59:16	METER 1 - M:	25267	METER 2 - H: 5830
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/17/2024 09:06:11	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-010	REPLACE NEW TAG LIGHT	DON	N	N	GARAGE	0.00	\$0.00	\$0.78	\$0.00	\$0.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.78	\$0.78

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	0.78	0.78	1.56
--------------	-------------------	--	--	--	--	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$0.78
COMML					0.78

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-010	REPLACE NEW TAG LIGHT	194	BULB-TAG/MARKER	0.39	2	\$0.78
PARTS						0.78

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51763

Work Order Notes

(EHANNAH) replace new taillight

Job Notes

03-34-010 - REPLACE NEW TAG LIGHT

(EHOWELL) GC replaced both tag light bulbs.

03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52006

USING DEPT NO:	507121	OPENED DATE:	09/04/2024 07:14:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/04/2024 15:23:26	METER 1 - M:	26003	METER 2 - H: 6195
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/05/2024 07:16:26	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$69.30	\$0.00	\$69.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	69.30	5.00	74.30
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	14.07	1	\$14.07
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.02	6	\$42.12
PARTS						69.30

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52006

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 26,003

Idle Hours, 6,195

Total Hours, 7,680

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52539

USING DEPT NO:	507121	OPENED DATE:	10/21/2024 07:41:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/22/2024 08:21:14	METER 1 - M:	27301	METER 2 - H: 6555
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/22/2024 08:33:35	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$108.20	\$0.00	\$108.20
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.00 0.00 108.20 5.00 113.20

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	25.26	1	\$25.26
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	9.59	6	\$57.51
PARTS						108.20

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52539

Work Order Notes

(EHANNAH) pm-

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm-JR,FJ, changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 27,301

Idle Hours, 6,555

Total Hours, 8,117

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52930

USING DEPT NO:	507121	OPENED DATE:	12/02/2024 07:22:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/11/2024 11:46:30	METER 1 - M:	28034	METER 2 - H: 6555
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/11/2024 14:05:40	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-01	INSPECT AIR CONDITIONING, HEAT, VE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
15-42-004	WARRANTY WATER PUMP	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42-004	TRANSPORT WATER PUMP	DON	W	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-42-004	WARRANTY WATER PUMP	11078175	FOCP10005		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52930

Work Order Notes

(EHANNAH) heater not working properly

Job Notes

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(EHOWELL) We pressure tested the cooling system. We found the vehicle low on coolant due to a leaking water pump. CM/EH

15-42-004 - WARRANTY WATER PUMP

(EHOWELL) Tuscaloosa Ford warrantied the water pump.

16-42-004 - TRANSPORT WATER PUMP

(EHOWELL) The vehicle was taken to Tuscaloosa Ford for the water pump to be replaced under warranty.

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53558

USING DEPT NO:	507121	OPENED DATE:	01/31/2025 07:15:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/05/2025 07:19:31	METER 1 - M:	28942	METER 2 - H: 6555
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/05/2025 13:35:10	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$770.46	\$0.00	\$770.46
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$63.86	\$0.00	\$63.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	858.40	5.00	863.40
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	F012114	TIRE 255/60R18 FSTONE PURSUIT	186.56	4	\$746.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.06	4	\$24.24
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	858.40

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53558

Work Order Notes

(EHANNAH) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) FJ replaced wipers

06-15 - INSPECT STEERING

(GARAGE) inspected steering checked ok cm 28942 miles,

66-17-013 - PERFORM ALIGNMENT

(GARAGE) performed alignment cm test drove checked ok,

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) FJ- Mounted/balanced 4 new tires. Set tire pressure to 36 PSI.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- PM. Oil change, topped off fluids, checked filters, set tire pressure, recorded date codes & tread depths (all 4 tires replaced)

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54236

USING DEPT NO:	507121	OPENED DATE:	03/31/2025 09:34:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/31/2025 09:36:06	METER 1 - M:	29025	METER 2 - H: 6555
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/31/2025 14:41:35	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	2714700	176745		\$0.00
				COMML	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 54236

Work Order Notes

Job Notes

17-GA-005 - RECALL Scheduling and Preparation

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) stivers performed recall pm

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 54714

USING DEPT NO:	507121	OPENED DATE:	05/08/2025 11:39:50	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	OPEN	COMPLETED DATE:		METER 1 - M:	29025	METER 2 - H:	6555				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	08/20/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB7LGC15610						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-33-006	TRANSPORT IGNITION LOCK CYLINDEI	WFA	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
RY-33-006	REKEY IGNITION LOCK CYLINDER	WFA	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 3						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:48:46 By User: GLOBETTI

UNIT NO: 243747 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54714

Work Order Notes

(CHANNELL) prep 4 sale
(EHANNAH) transport and rekey

Job Notes

16-33-006 - TRANSPORT IGNITION LOCK CYLINDER

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Performed prep for sale per decommission sheet. no gps and put tag in work folder. removed all locks and ignition switch, that involved removing the police scanner center console and the center display to access the ignition switch. installed all locks and ignition switch and all that was removed after locks got re-keyed. cq

RY-33-006 - REKEY IGNITION LOCK CYLINDER

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed May 14 2025 08:48:46 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243747') //Q=