

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 37427

USING DEPT NO:	507121	OPENED DATE:	08/25/2020 07:38:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2020 07:39:38	METER 1 - M:	105	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2020 09:13:54	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11901357	08/25/2020 07:39:07	08/25/2020 08:09:07	0.50	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 37427

## Work Order Notes

(LISAPATE) New unit do PDI

## Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39396

USING DEPT NO:	507121	OPENED DATE:	03/12/2021 11:58:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/16/2021 15:27:33	METER 1 - M:	1897	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/16/2021 15:27:45	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.19	\$22.13	\$0.00	\$0.00	\$22.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.88	\$103.55	\$38.45	\$0.00	\$142.00

JOB COUNT: 2 WORK ORDER TOTAL: 1.07 125.68 38.45 0.00 164.13

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	03/12/2021 14:30:00	03/12/2021 14:31:05	0.02	\$2.13
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	03/12/2021 14:04:50	03/12/2021 14:15:00	0.17	\$19.99
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/12/2021 13:05:21	03/12/2021 13:58:00	0.88	\$103.55
					<b>LABOR</b>	<b>125.67</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	5066517	WSWF RAIN-X -20DEG DEICER GAL	6.89	1	\$6.89
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.92	1	\$4.92
					<b>PARTS</b>	<b>38.45</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39396

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(SHARBIN) SH Rotated tires and inspected brakes and relearned tire positions.

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Mileage 1897 Engine hours 398 Idle hours 306. SH Performed PM.

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40148

USING DEPT NO:	507121	OPENED DATE:	06/11/2021 08:04:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/15/2021 14:04:03	METER 1 - M:	3044	METER 2 - H: 618
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/17/2021 11:29:02	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$25.30	\$31.13	\$0.00	\$56.43

JOB COUNT: 1	WORK ORDER TOTAL:	0.21	25.30	31.13	0.00	56.43
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/11/2021 12:27:39	06/11/2021 12:40:31	0.21	\$25.30
					LABOR	25.30

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	31.13

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40148

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/AMG

MILEAGE-3044

IDLE HRS-618

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40221

USING DEPT NO:	507121	OPENED DATE:	06/22/2021 07:32:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/23/2021 14:37:16	METER 1 - M:	3196	METER 2 - H: 618
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	06/23/2021 14:37:19	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.45	\$53.10	\$216.18	\$0.00	\$269.28

JOB COUNT: 1	WORK ORDER TOTAL:	0.45	53.10	216.18	0.00	269.28
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	06/22/2021 13:46:54	06/22/2021 14:13:54	0.45	\$53.10
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	12052187	06/22/2021 08:06:51	06/22/2021 08:25:00	(0.30)	(\$35.70)
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	12052187	06/22/2021 08:06:51	06/22/2021 08:25:00	0.30	\$35.70
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	12052187	06/22/2021 07:43:50	06/22/2021 08:00:19	(0.27)	(\$32.42)
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	12052187	06/22/2021 07:43:50	06/22/2021 08:00:19	0.27	\$32.42
					<b>LABOR</b>	<b>53.10</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	2	\$0.99
66-17-028	PERFORM MOUNT AND BALANCE TIRES	732005563	TIRE 255/60R18 GY ENFORCE 108V	215.19	1	\$215.19
					<b>PARTS</b>	<b>216.18</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 40221

## Work Order Notes

(IFALLS) Replace tire

## Job Notes

**03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(JWRIGHT) Replaced RR tire due to screw in sidewall. JAW

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(IFALLS) Josh mounted and balanced right rear tire



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40279

USING DEPT NO:	507121	OPENED DATE:	06/28/2021 15:25:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/12/2021 11:44:33	METER 1 - M:	3697	METER 2 - H: 618
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/12/2021 13:43:13	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-02-058	WARRANTY DOOR LOCK	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:					1.00	118.00	0.00	0.00	118.00
--------------	-------------------	--	--	--	--	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-02-058	WARRANTY DOOR LOCK	4910000	621181		\$0.00
COMML					0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11915538	06/29/2021 13:10:57	06/29/2021 13:19:06	(0.14)	(\$16.03)
16-02	TRANSPORT CAB & SHEET METAL	11915538	06/29/2021 13:10:57	06/29/2021 13:19:06	0.14	\$16.03
16-02	TRANSPORT CAB & SHEET METAL	11915538	06/29/2021 13:10:57	06/29/2021 14:10:57	1.00	\$118.00
LABOR						118.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40279

## Work Order Notes

(LISAPATE) Per driver both front door locks will not work at times. Take to the dealer

## Job Notes

### **15-02-058 - WARRANTY DOOR LOCK**

(LISAPATE) Town and Country replaced both front door latch assy and cut new key blank

### **16-02 - TRANSPORT CAB & SHEET METAL**

(LISAPATE) Transported by drivers to Town and Country

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40609

USING DEPT NO:	507121	OPENED DATE:	08/02/2021 14:17:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/03/2021 14:01:04	METER 1 - M:	4244	METER 2 - H: 939
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/05/2021 08:18:35	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$21.69	\$0.00	\$33.49
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.47	\$38.95	\$0.00	\$60.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.28	33.27	60.64	2.00	95.91
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/03/2021 08:35:18	08/03/2021 08:41:18	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/03/2021 08:24:23	08/03/2021 08:35:18	0.18	\$21.47
LABOR						33.27

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.84	1	\$5.84
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	9.72	1	\$9.72
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	11.97	1	\$11.97
PARTS						60.64

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40609

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 4244 Idle hours 939. SH/AMG Performed PM.

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40804

USING DEPT NO:	507121	OPENED DATE:	08/23/2021 07:55:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/27/2021 15:36:28	METER 1 - M:	4728	METER 2 - H: 939
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/30/2021 12:17:10	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-42-023	WARRANTY COOLANT TEMP SENSOR	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	0.46	\$54.51	\$0.00	\$0.00	\$54.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.56	66.31	0.00	2.00	68.31
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-42-023	WARRANTY COOLANT TEMP SENSOR	11078175	90928		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-42	TRANSPORT COOLING SYSTEM	11915538	08/27/2021 07:00:00	08/27/2021 07:06:00	0.10	\$11.80
35-42	DIAGNOSE COOLING SYSTEM	11213180	08/23/2021 09:35:13	08/23/2021 10:02:56	0.46	\$54.51
LABOR						66.31

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40804

## Work Order Notes

(LISAPATE) Per Rachel Grooms at 702am: unit overheated began to show dash lights for coolant hot. Unit displayed these problems while at the west commuter lot and was shut down to cool for a while before attempting to make it to the shop. Unit stalled out, was driving in a staggering momentum, and would not accelerate over 20mph. unit was left at that location.

Per John Brown at 107pm Unit was parked here at the shop. rifle has been pulled.

## Job Notes

### **15-42-023 - WARRANTY COOLANT TEMP SENSOR**

(IFALLS) Tuscaloosa Ford warrantied engine temp sensor.

### **16-42 - TRANSPORT COOLING SYSTEM**

(IFALLS) MS performed transport

### **35-42 - DIAGNOSE COOLING SYSTEM**

(MSIDES) Found code, P1299 - Cylinder head overtemperature protection active, stored in PCM. Also noticed that the cooling fans appear to not be working. MS

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40946

USING DEPT NO:	507121	OPENED DATE:	09/07/2021 08:11:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/24/2021 08:12:00	METER 1 - M:	4901	METER 2 - H: 1099
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2021 10:13:39	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.02	\$31.77	\$0.00	\$36.79
15-42-038	WARRANTY COOLANT TEMPERATURE	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
31-17-033	ROTATE TIRE ROTATION AND BRAKE IN	DON	O	N	GARAGE	0.24	\$28.81	\$0.00	\$0.00	\$28.81
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.31	\$36.19	\$0.00	\$0.00	\$36.19
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.71	\$83.78	\$42.48	\$0.00	\$126.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.96	\$113.31	\$0.00	\$0.00	\$113.31

JOB COUNT: 8	WORK ORDER TOTAL:	2.76	326.11	74.25	2.00	402.36
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-42-038	WARRANTY COOLANT TEMPERATURE SWITCH	11078175	91571		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-42	TRANSPORT COOLING SYSTEM	11915538	09/24/2021 07:00:00	09/24/2021 07:30:00	0.50	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/07/2021 14:46:43	09/07/2021 15:24:30	0.63	\$74.31
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/07/2021 15:19:23	09/07/2021 15:24:12	0.08	\$9.47
03-51-038	REPLACE NEW WIPER BLADES	12052187	09/07/2021 15:16:22	09/07/2021 15:18:55	0.04	\$5.02
31-17-033	ROTATE TIRE ROTATION AND BRAKE INSPECTION	11310047	09/07/2021 13:19:32	09/07/2021 13:34:11	0.24	\$28.81
66-79-003	PERFORM SAFETY INSPECTION	11310047	09/07/2021 13:01:08	09/07/2021 13:19:32	0.31	\$36.19
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	09/07/2021 09:30:00	09/07/2021 10:03:40	0.56	\$66.21
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	09/07/2021 08:51:03	09/07/2021 09:15:00	0.40	\$47.10
LABOR						326.11

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.14	1	\$10.14
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.13	1	\$5.13
					<b>PARTS</b>	<b>74.25</b>



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40946

## Work Order Notes

(LISAPATE) PM-replace wipers-do annual SI

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Installed new wiper blades

### **15-42-038 - WARRANTY COOLANT TEMPERATURE SWITCH**

(LISAPATE) Tuscaloosa Ford repaired CHT circuit VE712 BU-GY wire. Retaped harness with harness tape. cleared codes test drove ok verified repair

### **16-42 - TRANSPORT COOLING SYSTEM**

(LISAPATE) Taken to Tuscaloosa Ford by RC

### **31-17-033 - ROTATE TIRE ROTATION AND BRAKE INSPECTION**

(EHOWELL) Rotated tires and inspected brakes. EH

### **66-79-003 - PERFORM SAFETY INSPECTION**

(EHOWELL) EH Performed Safety Inspection. Needs front wipers.

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Mileage 4901 Engine hours 1347 Idle hours 1099

### **CH-SP - CHARGE Shop Supplies**

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(EHOWELL) This vehicle came in with the Check Engine Light On. The following DTCs were stored:

P0217:00-6C Engine Coolant Overtemperature Condition

P1285:00-6C Cylinder Head Overtemperature Condition

P1299:00EC Cylinder Head Overtemperature Protection Active

Performed a road test, but could not get the vehicle to overheat. The Cylinder head temperature sensor and the engine coolant temperature sensor are both reading properly.

The vehicle is going to the dealership.

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41623

USING DEPT NO:	507121	OPENED DATE:	11/15/2021 08:20:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/17/2021 08:28:41	METER 1 - M:	5809	METER 2 - H: 1412
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/17/2021 15:03:40	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$31.82	\$0.00	\$49.52
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$37.76	\$46.34	\$0.00	\$84.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.47	55.46	78.16	2.00	135.62
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/17/2021 07:00:00	11/17/2021 07:09:00	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/15/2021 15:10:05	11/15/2021 15:29:17	0.32	\$37.76
LABOR						55.46

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.08	1	\$9.08
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
PARTS						78.16

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41623

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipers

### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 5809 hours: 1716 idle hours: 1412 Completed PM topside Isaac assisted, Josh was bottomside. AMG IF/JW

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42082

USING DEPT NO:	507121	OPENED DATE:	01/14/2022 10:54:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/18/2022 10:14:44	METER 1 - M:	6557	METER 2 - H: 1715
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2022 10:01:45	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.79	\$93.09	\$42.48	\$0.00	\$135.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.79	93.09	42.48	2.00	137.57
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/18/2022 07:37:47	01/18/2022 07:40:38	0.05	\$5.61
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/14/2022 14:39:48	01/14/2022 15:24:17	0.74	\$87.48
LABOR						93.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.22	1	\$5.22
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
PARTS						42.48

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42082

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,EH/JAW  
MILEAGE-6557

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42792

USING DEPT NO:	507121	OPENED DATE:	04/01/2022 10:50:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/04/2022 08:00:56	METER 1 - M:	8957	METER 2 - H: 2361
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/15/2022 09:45:59	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.08	\$127.41	\$42.74	\$0.00	\$170.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 1.08 127.41 42.74 2.00 172.15

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/04/2022 07:02:05	04/04/2022 07:12:07	0.17	\$19.73
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/01/2022 15:27:52	04/01/2022 15:41:39	0.23	\$27.11
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/01/2022 14:19:44	04/01/2022 15:00:42	0.68	\$80.57
LABOR						127.41

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.39	1	\$5.39
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
PARTS						42.74

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42792

## Work Order Notes

(CHANNELL) pm

## Job Notes

06-15 - INSPECT STEERING

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43814

USING DEPT NO:	507121	OPENED DATE:	07/01/2022 14:05:58	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	07/01/2022 15:41:13	METER 1 - M:	9749	METER 2 - H:	2574				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2022 07:42:26	IN-SERVICE DATE:	08/21/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer			UNIT SERIAL NO:	1FM5K8AB4LGC15614					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,369.00	\$2,369.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.99	\$46.07	\$0.00	\$92.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:					0.89	104.99	46.07	2,371.00	2,522.06
--------------	-------------------	--	--	--	--	------	--------	-------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	1696902		\$2,369.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2371.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11915538	07/07/2022 07:00:00	07/07/2022 07:30:00	0.50	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/01/2022 14:30:00	07/01/2022 14:53:23	0.39	\$45.99
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/01/2022 14:26:27	07/01/2022 14:26:27	0.00	\$0.00
LABOR						104.99

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.24	1	\$11.24
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.81	6	\$34.83
PARTS						46.07



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43814

## Work Order Notes

(LISAPATE) PM-take to Body Shop to repair RR fender area. Pmnt was issued to Andrews

## Job Notes

### **16-71 - TRANSPORT BODY**

(EKIMBREL) RC TRANSPORTED TRUCK TO AND FROM ANDREW'S BODY SHOP

### **24-71 - REPAIR BODY**

(LISAPATE) State Auto pd \$278.28 on ck# 1001077209 UA paid \$2000.00 ded and 3\$ cc fee \$60.00.

### **66-PM-PMA - PERFORM OIL CHANGE**

(HHARBIN) Performed PM.SH

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45023

USING DEPT NO:	507121	OPENED DATE:	10/18/2022 09:04:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/19/2022 08:38:46	METER 1 - M:	9800	METER 2 - H: 2576
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/19/2022 09:56:45	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.35	\$40.87	\$146.72	\$0.00	\$187.59
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.57	\$0.00	\$0.00	\$27.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:		0.58	68.44	146.72	5.00	220.16
--------------	-------------------	--	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11901357	10/18/2022 15:12:17	10/18/2022 15:33:04	0.35	\$40.87
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/18/2022 14:30:00	10/18/2022 14:44:01	0.23	\$27.57
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/18/2022 14:18:41	10/18/2022 14:18:41	0.00	\$0.00
LABOR						68.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	146.72	1	\$146.72
PARTS						146.72

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45023

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 03-32-002 - REPLACE NEW BATTERY

(AGUERRA) Replaced battery and checked charging system, good at 14.4 volts. AMG

### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 9800 hours: 3097 idle hours: 2576 Vehicle has been 51 miles and 2 idle hours, oil was changed at last PM. Updated oil change stickers. AMG

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45531

USING DEPT NO:	507121	OPENED DATE:	12/12/2022 10:28:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/12/2022 15:15:55	METER 1 - M:	11363	METER 2 - H: 2576
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2022 08:35:14	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$71.52	\$58.80	\$0.00	\$130.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.61 71.52 58.80 5.00 135.32

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/12/2022 13:00:00	12/12/2022 13:23:42	0.40	\$46.61
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/12/2022 12:40:49	12/12/2022 12:40:49	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/12/2022 11:40:18	12/12/2022 11:52:58	0.21	\$24.91
LABOR						71.52

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.25	1	\$8.25
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
PARTS						58.80

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45531

## Work Order Notes

(EHANNAH) pm replace wipers

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 11363 hours: 3581 idle hours: 2976 Completed PM bottomside, Scott was topside. SH/AMG

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46526

USING DEPT NO:	507121	OPENED DATE:	03/24/2023 09:51:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/24/2023 14:43:03	METER 1 - M:	12605	METER 2 - H: 3286
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2023 10:38:02	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.56	\$32.73	\$0.00	\$35.29
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$70.73	\$56.40	\$0.00	\$127.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.62	73.29	89.13	5.00	167.42
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	03/24/2023 13:50:05	03/24/2023 13:51:23	0.02	\$2.56
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/24/2023 13:13:49	03/24/2023 13:49:47	0.60	\$70.73
				LABOR		73.29

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.47	1	\$10.47
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.47	1	\$9.47
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
				PARTS		89.13

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46526

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

### 66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC. Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

Miles, 12,605 Idle Hrs, 3,286

Add 1/2 he for dropping skid pan

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46582

USING DEPT NO:	507121	OPENED DATE:	04/03/2023 07:57:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/04/2023 07:16:49	METER 1 - M:	12612	METER 2 - H: 3286
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/04/2023 15:24:56	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.06	\$6.75	\$5.55	\$0.00	\$12.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.06	6.75	5.55	5.00	17.30
--------------	-------------------	--	--	--	--	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	12201267	04/03/2023 08:32:38	04/03/2023 08:36:04	0.06	\$6.75
LABOR						6.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.16	1	\$2.16
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.73	1	\$2.73
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.66	1	\$0.66
PARTS						5.55



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46582

## Work Order Notes

(LISAPATE) Nail in RF tire

## Job Notes

66-17-030 - PERFORM TIRE PATCH

(GRCOOK) Performed tire patch-GC

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47459

USING DEPT NO:	507121	OPENED DATE:	06/28/2023 13:02:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2023 15:47:06	METER 1 - M:	13702	METER 2 - H: 3487
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/05/2023 07:43:21	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.16	\$61.82	\$0.00	\$83.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.19	22.16	61.82	5.00	88.98
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/28/2023 13:53:20	06/28/2023 14:04:36	0.19	\$22.16
LABOR						22.16

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
PARTS						61.82

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47459

## Work Order Notes

(EHANNAH) pm- replace wipers  
(EKIMBREL) just got wipers 2 months ago

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48454

USING DEPT NO:	507121	OPENED DATE:	10/09/2023 11:23:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/26/2023 10:37:30	METER 1 - M:	15630	METER 2 - H: 3487
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/26/2023 13:20:43	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-13	INSPECT BRAKES	DON	N	N	GARAGE	0.46	\$54.28	\$8.28	\$0.00	\$62.56
15-21-002	WARRANTY CV AXLES/SEALS	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-21	TRANSPORT AXLES - DRIVEN, FRONT :	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.72	\$84.73	\$0.00	\$0.00	\$84.73
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.18	\$139.34	\$64.34	\$0.00	\$203.68
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	N	N	GARAGE	2.00	\$235.77	\$0.00	\$0.00	\$235.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7	WORK ORDER TOTAL:	4.86	573.12	72.62	5.00	650.74
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
15-21-002	WARRANTY CV AXLES/SEALS	11078175	118203		\$0.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	11310047	10/11/2023 09:07:19	10/11/2023 11:07:12	2.00	\$235.77
16-21	TRANSPORT AXLES - DRIVEN, FRONT STEERING	11399745	10/26/2023 07:00:00	10/26/2023 07:30:00	0.50	\$59.00
06-13	INSPECT BRAKES	11310047	10/24/2023 13:20:50	10/24/2023 13:41:34	0.35	\$40.78
06-13	INSPECT BRAKES	11310047	10/11/2023 08:51:15	10/11/2023 08:58:07	0.11	\$13.50
66-79-003	PERFORM SAFETY INSPECTION	12395904	10/10/2023 07:45:10	10/10/2023 08:28:15	0.72	\$84.73
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/10/2023 06:58:22	10/10/2023 07:44:37	0.77	\$90.96
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/09/2023 15:17:26	10/09/2023 15:42:02	0.41	\$48.38
					LABOR	573.12

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
06-13	INSPECT BRAKES	C111	RED BRAKE CLEANER	6.40	1	\$6.40
06-13	INSPECT BRAKES	07480	ROLOC DISC 2 IN COARSE	1.88	1	\$1.88
					<b>PARTS</b>	<b>72.62</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48454

## Work Order Notes

(LISAPATE) PM-Do SI brakes are noisy when stopping

## Job Notes

### **06-13 - INSPECT BRAKES**

(IFALLS) A noise could be heard coming from the left rear brake area. Removed LR brake caliper and cleaned pads and rotor using a Roloc disc. Performed a road test after repair. Brakes sound good. Also, found right front backing plate rubbing the rotor. Bent backing plate away from the rotor. Examined left front rotor to make sure it was not rubbing the backing plate. EH

### **15-21-002 - WARRANTY CV AXLES/SEALS**

(LISAPATE) Tuscaloosa Ford Replaced both CV axles and vehicles is operating as normal at this time.

### **16-21 - TRANSPORT AXLES - DRIVEN, FRONT STEERING**

(LISAPATE) Transported by CW

### **66-79-003 - PERFORM SAFETY INSPECTION**

(FCONTRER) Performed safety inspection. Found both front cv axles leaking grease.

(GARAGE) The vehicle will need to go to Tuscaloosa Ford to have the front CV axles replaced under warranty. EH

### **66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Perform oil changed fluid check tires pressure and tread fc

### **AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&**

(IFALLS) The rear differential fluid was just a little low. Topped off fluid with non inventory fluid. EH

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49546

USING DEPT NO:	507121	OPENED DATE:	01/24/2024 07:15:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2024 14:59:36	METER 1 - M:	17624	METER 2 - H: 4244
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/25/2024 07:37:05	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.50	\$58.93	\$0.00	\$0.00	\$58.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.28	\$60.56	\$0.00	\$61.84
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.03	\$3.93	\$33.45	\$0.00	\$37.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.54	64.14	94.01	5.00	163.15
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	01/24/2024 08:45:02	01/24/2024 09:15:00	0.50	\$58.93
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	01/24/2024 08:42:37	01/24/2024 08:44:37	0.03	\$3.93
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/24/2024 08:41:29	01/24/2024 08:42:08	0.01	\$1.28
				LABOR		64.14

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	33.45	1	\$33.45
				PARTS		94.01

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49546

## Work Order Notes

(EHANNAH) pm

## Job Notes

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(FCONTRER) Rotate tires and check Brakes F 8 m R 6 m fc

### **66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) perform oil changes fc

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(FCONTRER) perform cabin filter replaced FC

### **CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50132

USING DEPT NO:	507121	OPENED DATE:	03/18/2024 08:10:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/20/2024 10:56:22	METER 1 - M:	19083	METER 2 - H: 4489
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/20/2024 11:55:01	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-78-038	INSPECT UNDER CARRIAGE SKID PLAT	DON	N	N	GARAGE	0.28	\$33.34	\$0.00	\$0.00	\$33.34
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.28	33.34	0.00	5.00	38.34
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-78-038	INSPECT UNDER CARRIAGE SKID PLATES	11074414	03/18/2024 09:30:00	03/18/2024 09:46:57	0.28	\$33.34
06-78-038	INSPECT UNDER CARRIAGE SKID PLATES	11074414	03/18/2024 09:23:15	03/18/2024 09:23:15	0.00	\$0.00
LABOR						33.34

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 50132

## Work Order Notes

(EHANNAH) request skid plate be reattached.

## Job Notes

06-78-038 - INSPECT UNDER CARRIAGE SKID PLATES

(SHARBIN) Screws that hold skid plate on were missing. Installed screws and washers rechecks good. SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50358

USING DEPT NO:	507121	OPENED DATE:	04/01/2024 07:17:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/02/2024 07:54:05	METER 1 - M:	19540	METER 2 - H: 4543
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/02/2024 12:34:32	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.14	\$16.62	\$0.00	\$0.00	\$16.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$18.09	\$68.21	\$0.00	\$86.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.29	34.71	68.21	5.00	107.92
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/01/2024 07:33:09	04/01/2024 07:42:21	0.15	\$18.09
14-52-021	INSTALL GPS SYSTEM	11074414	04/01/2024 07:24:42	04/01/2024 07:33:09	0.14	\$16.62
LABOR						34.71

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
PARTS						68.21

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50358

## Work Order Notes

(EHANNAH) pm- install GPS

## Job Notes

### 14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240171. SH

### 14-78-044 - INSTALL TOOLBOX ASSY

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50889

USING DEPT NO:	507121	OPENED DATE:	05/20/2024 08:08:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/20/2024 10:38:40	METER 1 - M:	21101	METER 2 - H: 4543
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/20/2024 15:44:12	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	N	N	GARAGE	0.02	\$2.52	\$7.61	\$0.00	\$10.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.02	2.52	7.61	5.00	15.13
--------------	-------------------	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	12395904	05/20/2024 10:12:21	05/20/2024 10:13:38	0.02	\$2.52
					LABOR	2.52

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	58104	1.25 OZ WHEEL WEIGHT	0.63	2	\$1.26
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.73	1	\$2.73
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.62	1	\$3.62
					PARTS	7.61

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 50889

## Work Order Notes

(EHANNAH) perform tire patch on drive rear

## Job Notes

66-17-030 - PERFORM TIRE PATCH

(FCONTRER) Perform patch tire LF - R to

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51078

USING DEPT NO:	507121	OPENED DATE:	06/06/2024 13:53:06	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2024 13:57:19	METER 1 - M:	21543	METER 2 - H:	4543				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2024 15:31:18	IN-SERVICE DATE:	08/21/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-02-074	RECALL WINDOW SWITCH	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51078

## Work Order Notes

(EHANNAH) prep and scheduling- Recall for power window switch

## Job Notes

### **17-02-074 - RECALL WINDOW SWITCH**

(EHANNAH) LL Ford came to our shop for Recall on power window switches.

### **17-GA-005 - RECALL Scheduling and Preparation**

(EHANNAH) prep and scheduling by Denise



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51313

USING DEPT NO:	507121	OPENED DATE:	06/26/2024 08:19:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/27/2024 08:00:02	METER 1 - M:	22390	METER 2 - H: 4842
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/27/2024 08:39:06	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$0.98	\$68.66	\$0.00	\$69.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.01	0.98	68.66	5.00	74.64
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/27/2024 07:46:00	06/27/2024 07:46:30	0.01	\$0.98
LABOR						0.98

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
PARTS						68.66

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51313

## Work Order Notes

(EHANNAH) pm

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

(EKIMBREL) unit is scheduled to be replaced, will let tires go until next pm.

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51597

USING DEPT NO:	507121	OPENED DATE:	07/24/2024 10:57:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/30/2024 09:06:29	METER 1 - M:	22885	METER 2 - H: 4842
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/30/2024 09:06:34	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	N	N	GARAGE	0.00	\$0.00	\$244.23	\$0.00	\$244.23
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$779.48	\$0.00	\$779.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	1,023.71	5.00	1,028.71
--------------	-------------------	------	------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	1.65	1	\$1.65
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	58102	.75 OZ WHEEL WEIGHT	1.65	(1)	(\$1.65)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	1.42	3	\$4.27
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	1.03	3	\$3.10
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	58102	.75 OZ WHEEL WEIGHT	1.65	1	\$1.65
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RAB682614R	REAR ROTORS	86.19	2	\$172.38
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWRZ362231	REAR BRAKE PADS	71.85	1	\$71.85
66-17-028	PERFORM MOUNT AND BALANCE TIRES	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.06	4	\$24.24
66-17-028	PERFORM MOUNT AND BALANCE TIRES	012114	TIRE 255/60R18 FTONE Fhawk PST	186.56	4	\$746.22
					PARTS	1023.71

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51597

## Work Order Notes

(EHANNAH) mount and balance new tires

## Job Notes

### **03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS**

(GARAGE) Replaced rear pads and rotors. Torqued to spec. JAW

### **66-13-130 - PERFORM Burnish Brakes**

(GARAGE) Burnished brakes. JAW

### **66-17-013 - PERFORM ALIGNMENT**

(GARAGE) Performed alignment. Test drove all good. JAW

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) Mounted and Balanced 4 new tires on unit 9692B-GC  
Miles, 23,012

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52202

USING DEPT NO:	507121	OPENED DATE:	09/24/2024 09:05:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/24/2024 15:06:55	METER 1 - M:	25035	METER 2 - H: 4842
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2024 15:06:58	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$67.95	\$0.00	\$67.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.00 0.00 67.95 5.00 72.95

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.81	1	\$12.81
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
PARTS						67.95

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52202

## Work Order Notes

(EHANNAH) pm

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC,CM, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 25,063

Idle Hours, 5,239

Total Hours, 6,572

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53183

USING DEPT NO:	507121	OPENED DATE:	12/17/2024 14:06:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/17/2024 14:39:04	METER 1 - M:	27598	METER 2 - H: 4842
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/17/2024 14:39:10	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 53183

## Work Order Notes

(EHANNAH) no labor- waiting to be sold and remove equipment

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53362

USING DEPT NO:	507121	OPENED DATE:	01/14/2025 09:17:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/16/2025 11:34:31	METER 1 - M:	27938	METER 2 - H: 4842
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/16/2025 13:00:24	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-26	INSPECT TRANSMISSION - MAIN, MANU	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$63.86	\$0.00	\$63.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	63.86	5.00	68.86
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
					PARTS	63.86

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53362

## Work Order Notes

(EHANNAH) SI- inspect transmission- Bostic email and ask for us to look at it, he only stated transmission issues.

## Job Notes

### **06-26 - INSPECT TRANSMISSION - MAIN, MANUAL**

(GARAGE) PULLED UNIT IN SHOP AND HOOKED TO FORD DIAGNOSTIC TOOL , FOUND NO CODES RELATED TO THE TRANSMISSION. INSPECTED FOR TRANS LEAKS AND FOUND NONE. ROAD TESTED WITH DIAGNOSTICS AND DATA LOGGED TRANS SHIFT AND SHIFT COMMAND, FOUND EVERYTHING TO DRIVE AND SHIFT CORRECTY. UNIT STILL HAS BUMPER TO BUMPER WARRANTY TILL AUGUST OF 2025. RETURNED UNIT TO SERVICE. 1 HR DIAGNOSTICS. CQ

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) PERFORMED SI PER SAFETY INSPECTION SHEET. BRONT PADS 5-6MM REAR PADS 10MM EVERYTHING CHECKED OUT OK. RETURNED TO SERVICE. CQ

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) PULLED UNIT ON OIL RACK, DROPPED OIL AND FILTER. INSTALLED NEW FILTER AND FILLED WITH OIL. SET TIRE PRESSURE AND CHECKED ALL FLUID LEAVELS, RETURNED TO SERVICE. CQ

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53422

USING DEPT NO:	507121	OPENED DATE:	01/21/2025 09:36:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/28/2025 09:38:30	METER 1 - M:	27971	METER 2 - H: 4842
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/28/2025 09:38:30	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$74.25	\$0.00	\$74.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	74.25	5.00	79.25
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
06-15	INSPECT STEERING	XL3	LIMITED SLIP ADDITIVE FORD	7.23	1	\$7.23
06-15	INSPECT STEERING	XY75W85QL	GEAR OIL 75W85 SYN FORD	33.51	2	\$67.02
PARTS						74.25

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53422

## Work Order Notes

(EHANNAH) inspect steering- driver reports problems while turning left or right

## Job Notes

### 06-15 - INSPECT STEERING

(GARAGE) DROVE UNIT AND FOUND REAR END WOULD GRAB AND POP IN TIGHT TURNS. PULLED UNIT IN SHOP AND PUT ON LIFT. DRAINED REAR END OIL FOUND OIL HAD A FINE SILVER TENT TO IT. FILLED WITH NEW OIL AND FRICTION MODIFIER. TEST DROVE AND TURNED SHARP BOTH LEFT AND RIGHT AND IN REVERSE COULD NOT GET DIFF TOP GRAB OR POP. RETURNED TO SERVICE. CQ

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 53744

USING DEPT NO:	507121	OPENED DATE:	02/13/2025 07:50:53	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	02/13/2025 15:15:41	METER 1 - M:	28032	METER 2 - H:	4842		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/14/2025 10:49:18	IN-SERVICE DATE:	08/21/2020				
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 3						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53744

## Work Order Notes

(EHANNAH) Check engine light is on- all service lights are on - SI - and check tire pressure

## Job Notes

### **06-17 - INSPECT TIRES, TUBES, LINERS & VALVES**

(GARAGE) FOUND TIRES GOOD, BUID DATES 0824 7/32 TREAD. CQ

### **66-79-002 - PERFORM SERVICE CALL**

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) PERFORMED SAFETY INSPECTION PER SI. FOUND ALL GOOD, 5MM FRONT BRAKES AND 10MM REAR BRAKES. SET TIRE PRESSRE. CQ

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(GARAGE) SCANNED OUT UNIT FOUND FOUND NO CHECK ENGINE LIGHT ON. FOUND CODE NOT ACTIVE U0102 LOST COMMUNICATION WITH TRANSFER CASE, TROUBLESHOT AND PULLED BULLETINS AND FOUND A SOFTWARE UPDATE FOR CODE. UPDATED SOFTWARE PER BULLETIN, TEST DROVE FOUND NO LIGHTS RETURNED TO SERVICE. 1HR SCAN AND UPDATE SOFTWARE. CQ

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54288

USING DEPT NO:	507121	OPENED DATE:	04/02/2025 14:54:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/02/2025 14:56:50	METER 1 - M:	28827	METER 2 - H: 4842
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2025 12:54:36	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.00 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	2714700	176444		\$0.00
COMML					0.00

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI*

**UNIT NO:**                    **243753**                    **2020 FORD INTERCEPTOR EXPLORER**

**WORK ORDER NO:**                    **54288**

---

## Work Order Notes

### Job Notes

17-GA-005 - RECALL Scheduling and Preparation

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) STIVERS PERFORMED RECALL PM

---



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54754

USING DEPT NO:	507121	OPENED DATE:	05/12/2025 14:36:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	COMPLETED	COMPLETED DATE:	05/19/2025 15:08:47	METER 1 - M:	29594	METER 2 - H: 4842
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB4LGC15614	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-33-006	TRANSPORT IGNITION LOCK CYLINDEI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-33-006	REMOVE IGNITION LOCK CYLINDER	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
RY-33-006	REKEY IGNITION LOCK CYLINDER	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$95.22	\$95.22

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	0.00	95.22	95.22
--------------	-------------------	------	------	------	-------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2318907		\$95.22
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2318907		(\$95.22)
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2318907		\$95.22
COMML					95.22

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 08:58:24 By User: GLOBETTI

UNIT NO: 243753 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54754

## Work Order Notes

(EKIMBREL) SURPLUS

## Job Notes

### **16-33-006 - TRANSPORT IGNITION LOCK CYLINDER**

(EKIMBREL) RC/CW TRANSPORTED CYLINDERS TO AND FROM A1 TO BE REKEYED.

### **25-33-006 - REMOVE IGNITION LOCK CYLINDER**

(GARAGE) REMOVED ALL DOOR LOCK CYCLINDERS AND IGNITION CYLINDER TO HAVE REKEYED. HAD TO REMOVE THE POLICE SCANNER CENTER CONSOLE AND THE CENTER DISPLAY OF DASH TO REMOVE THE IGNITION SWITCH.CQ

### **PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) PREPPED FOR SALE PER DECOMMISSION SHEET.CQ

### **RY-33-006 - REKEY IGNITION LOCK CYLINDER**

(EKIMBREL) A-1 LOCKSMITH REKEYED LOCK CYLINDERS

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Tue May 20 2025 08:58:24 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.serial\_no} = '1FM5K8AB4LGC15614') //Q=