

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 37431

USING DEPT NO:	507121	OPENED DATE:	08/25/2020 07:49:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2020 07:50:48	METER 1 - M:	116	METER 2 - H: 1
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2020 09:11:03	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11901357	08/25/2020 07:50:18	08/25/2020 08:20:18	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 37431

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 38827

USING DEPT NO:	507121	OPENED DATE:	01/19/2021 10:31:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2021 10:32:03	METER 1 - M:	651	METER 2 - H: 1
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2021 10:32:04	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 **2020 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 38827

Work Order Notes

(LISAPATE) Opened WO for documentation per Tony J. Unit has not been put in service yet. Being held up due to a strobe light issue

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39137

USING DEPT NO:	507121	OPENED DATE:	02/19/2021 07:23:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/19/2021 11:35:43	METER 1 - M:	1590	METER 2 - H: 1
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/19/2021 14:04:21	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.15	\$135.93	\$34.92	\$0.00	\$170.85

JOB COUNT: 1	WORK ORDER TOTAL:					1.15	135.93	34.92	0.00	170.85
--------------	-------------------	--	--	--	--	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/19/2021 07:29:29	02/19/2021 08:08:53	0.66	\$77.49
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/19/2021 07:32:30	02/19/2021 08:02:13	0.50	\$58.44
					LABOR	135.93

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	34.92

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39137

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG

MILEAGE-1589

Idle hrs-335

Engine hrs-409

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39478

USING DEPT NO:	507121	OPENED DATE:	03/24/2021 07:18:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/29/2021 09:25:45	METER 1 - M:	2446	METER 2 - H: 699
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/29/2021 15:11:46	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.55	\$65.13	\$236.12	\$0.00	\$301.25

JOB COUNT: 1	WORK ORDER TOTAL:	0.55	65.13	236.12	0.00	301.25
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/24/2021 13:40:36	03/24/2021 13:47:52	0.12	\$14.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/24/2021 08:04:24	03/24/2021 08:30:15	0.43	\$50.84
					LABOR	65.13

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	732005563	TIRE 255/60R18 GY ENFORCE 108V	215.19	1	\$215.19
66-17-028	PERFORM MOUNT AND BALANCE TIRES	F2GZ1700E	TPMS KIT	20.00	1	\$20.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.47	2	\$0.93
					PARTS	236.12

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39478

Work Order Notes

(LISAPATE) RR tire has a slow leak

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mileage 2454 Engine hours 699 Idle hours 578. Right rear tiire could not be patched to close to the sidewall. Mounted and balanced 1 tire. SH

66-17-030 - PERFORM TIRE PATCH

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39514

USING DEPT NO:	507121	OPENED DATE:	03/30/2021 07:50:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/01/2021 11:27:36	METER 1 - M:	2629	METER 2 - H: 699
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/06/2021 07:35:12	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.22	\$144.39	\$48.40	\$0.00	\$192.79

JOB COUNT: 1	WORK ORDER TOTAL:	1.22	144.39	48.40	0.00	192.79
--------------	-------------------	------	--------	-------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/30/2021 07:59:05	03/30/2021 08:46:48	0.80	\$93.84
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/30/2021 08:29:16	03/30/2021 08:35:43	0.11	\$12.69
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/30/2021 07:58:54	03/30/2021 08:18:09	0.32	\$37.86
					LABOR	144.39

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	48.40

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 39514

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/SH

MILEAGE-2629

IDLE HRS-630

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39799

USING DEPT NO:	507121	OPENED DATE:	04/26/2021 08:23:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/26/2021 14:26:30	METER 1 - M:	3276	METER 2 - H: 699
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2021 08:43:53	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-02-074	INSPECT WINDOW SWITCH	DON	O	N	GARAGE	0.19	\$22.09	\$0.00	\$0.00	\$22.09

JOB COUNT: 1	WORK ORDER TOTAL:					0.19	22.09	0.00	0.00	22.09
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-02-074	INSPECT WINDOW SWITCH	11213180	04/26/2021 09:20:54	04/26/2021 09:21:30	0.01	\$1.18
06-02-074	INSPECT WINDOW SWITCH	11213180	04/26/2021 08:59:55	04/26/2021 09:10:33	0.18	\$20.91
					LABOR	22.09

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: **243751** **2020 FORD INTERCEPTOR EXPLORER**

WORK ORDER NO: **39799**

Work Order Notes

(LISAPATE) Per Jimmy front windows and mirrors will not work from the switch

Job Notes

06-02-074 - INSPECT WINDOW SWITCH

(MSIDES) All windows and mirrors are working at this time customer will return if issue reoccurs. MS

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39860

USING DEPT NO:	507121	OPENED DATE:	05/04/2021 07:33:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/04/2021 13:35:26	METER 1 - M:	3606	METER 2 - H: 931
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/07/2021 13:18:40	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.23	\$145.24	\$41.84	\$0.00	\$187.08

JOB COUNT: 1	WORK ORDER TOTAL:	1.23	145.24	41.84	0.00	187.08
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/04/2021 07:43:41	05/04/2021 08:23:10	0.66	\$77.65
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/04/2021 07:45:38	05/04/2021 08:20:00	0.57	\$67.59
					LABOR	145.24

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
					PARTS	41.84

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39860

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 3606 Engine hours 1116 Idle hours 931. SH/AMG Performed PM.

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40207

USING DEPT NO:	507121	OPENED DATE:	06/21/2021 07:05:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/23/2021 14:57:19	METER 1 - M:	4714	METER 2 - H: 931
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	06/23/2021 14:57:22	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.26	\$148.98	\$46.94	\$0.00	\$195.92
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.07	\$7.83	\$14.72	\$0.00	\$22.55

JOB COUNT: 2 WORK ORDER TOTAL: 1.33 156.81 61.66 0.00 218.47

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	06/21/2021 15:17:25	06/21/2021 15:21:24	0.07	\$7.83
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/21/2021 08:36:26	06/21/2021 09:25:50	0.82	\$97.15
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/21/2021 08:36:04	06/21/2021 09:02:25	0.44	\$51.82
					LABOR	156.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PF63	FILTER-OIL	9.68	1	\$9.68
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800180C	CABIN FILTER	14.72	1	\$14.72
					PARTS	61.66

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40207

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG

MILEAGE-4770

HRS-1479

IDLE HRS-1242

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40671

USING DEPT NO:	507121	OPENED DATE:	08/09/2021 10:15:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/10/2021 11:36:02	METER 1 - M:	6052	METER 2 - H: 1555
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/11/2021 09:27:58	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.14	\$16.68	\$31.35	\$0.00	\$48.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.74	\$86.83	\$32.39	\$0.00	\$119.22
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.88	103.51	63.74	2.00	169.25
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/09/2021 12:07:23	08/09/2021 12:07:23	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	08/09/2021 10:47:36	08/09/2021 10:56:05	0.14	\$16.68
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/09/2021 10:26:57	08/09/2021 10:51:28	0.41	\$48.22
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/09/2021 10:27:46	08/09/2021 10:47:24	0.33	\$38.61
LABOR						103.51

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	9.72	1	\$9.72
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.84	1	\$5.84
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
PARTS						63.74

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40671

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 6052 idle hours: 1555 hours: 1855 Completed PM topside, Josh was bottomside. Completed checklist. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40999

USING DEPT NO:	507121	OPENED DATE:	09/13/2021 08:21:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/14/2021 10:19:19	METER 1 - M:	7114	METER 2 - H: 1871
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/14/2021 12:54:22	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.34	\$39.69	\$31.77	\$0.00	\$71.46
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.40	\$47.30	\$0.00	\$0.00	\$47.30
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.94	\$111.25	\$42.39	\$0.00	\$153.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.68	198.24	74.16	2.00	274.40
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/13/2021 09:18:42	09/13/2021 09:20:41	0.03	\$3.90
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	09/13/2021 09:11:48	09/13/2021 09:18:26	0.11	\$13.05
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/13/2021 08:57:35	09/13/2021 09:15:00	0.29	\$34.25
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/13/2021 08:51:18	09/13/2021 09:11:29	0.34	\$39.69
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/13/2021 08:26:40	09/13/2021 08:57:22	0.51	\$60.38
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/13/2021 08:27:11	09/13/2021 08:51:04	0.40	\$46.97
				LABOR		198.24

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.14	1	\$10.14
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.13	1	\$5.13
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
					PARTS	74.16

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40999

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. Completed TPMS relearn. AMG SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 7114 hours: 2229 idle hours: 1871 Completed PM topside, Scott was bottomside. Completed checklist. AMG/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41512

USING DEPT NO:	507121	OPENED DATE:	11/04/2021 08:13:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/08/2021 13:55:33	METER 1 - M:	7981	METER 2 - H: 2177
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/09/2021 08:18:25	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.65	\$46.22	\$0.00	\$76.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.26	30.65	46.22	2.00	78.87
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/04/2021 10:57:42	11/04/2021 11:13:17	0.26	\$30.65
LABOR						30.65

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.96	1	\$8.96
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						46.22

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41512

Work Order Notes

(CHANNELL) PM \replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41963

USING DEPT NO:	507121	OPENED DATE:	01/05/2022 07:36:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/06/2022 08:14:13	METER 1 - M:	8831	METER 2 - H: 2177
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/06/2022 11:06:25	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$40.51	\$42.59	\$0.00	\$83.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.34	40.51	42.59	2.00	85.10
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/05/2022 09:25:54	01/05/2022 09:46:30	0.34	\$40.51
LABOR						40.51

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.24	1	\$5.24
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						42.59

Work Order Charge Detail

UNIT NO:	243751	2020 FORD INTERCEPTOR EXPLORER	WORK ORDER NO:	41963
----------	--------	--------------------------------	----------------	-------

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-8831
HRS-2955
IDLE-2503

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42815

USING DEPT NO:	507121	OPENED DATE:	04/04/2022 11:42:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/06/2022 17:04:02	METER 1 - M:	9934	METER 2 - H: 2818
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/18/2022 11:42:18	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.38	\$31.82	\$0.00	\$39.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.88	\$103.51	\$49.30	\$0.00	\$152.81
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.94	110.89	81.12	2.00	194.01
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/04/2022 15:32:34	04/04/2022 15:36:19	0.06	\$7.38
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/04/2022 14:38:41	04/04/2022 15:31:19	0.88	\$103.51
LABOR						110.89

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.39	1	\$5.39
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
PARTS						81.12

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42815

Work Order Notes

(CHANNELL) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-9934

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43884

USING DEPT NO:	507121	OPENED DATE:	07/08/2022 08:20:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/11/2022 14:12:38	METER 1 - M:	11332	METER 2 - H: 3184
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	07/12/2022 07:27:59	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.49	\$57.66	\$46.44	\$0.00	\$104.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.49	57.66	46.44	2.00	106.10
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/08/2022 09:22:11	07/08/2022 09:22:11	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/08/2022 09:30:00	07/08/2022 09:59:19	0.49	\$57.66
LABOR						57.66

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.81	6	\$34.83
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.61	1	\$11.61
PARTS						46.44

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43884

Work Order Notes

(IFALLS) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44270

USING DEPT NO:	507121	OPENED DATE:	08/12/2022 10:06:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/15/2022 14:35:28	METER 1 - M:	12571	METER 2 - H: 3466
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/16/2022 13:13:37	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	1.50	\$177.00	\$146.72	\$0.00	\$323.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00

JOB COUNT: 3	WORK ORDER TOTAL:		2.00	236.00	146.72	2.00	384.72
--------------	-------------------	--	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-00	SCAN OUT COMPLETE VEHICLE	11213180	08/15/2022 08:30:00	08/15/2022 09:00:00	0.50	\$59.00
03-32-002	REPLACE NEW BATTERY	11213180	08/15/2022 07:00:00	08/15/2022 08:30:00	1.50	\$177.00
LABOR						236.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	146.72	1	\$146.72
PARTS						146.72

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44270

Work Order Notes

(LISAPATE) Jumped off twice yesterday. AWD error on display

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Replaced battery and reset BCM (battery relearn procedure) test drove vehicle, operating as designed.

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(LISAPATE) Tried scanning vehicle and scanner would not communicate, checked battery and found battery to have a bad cell with only 9.8 volt total charge.

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44552

USING DEPT NO:	507121	OPENED DATE:	09/02/2022 07:10:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/06/2022 11:01:36	METER 1 - M:	12948	METER 2 - H: 3556
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2022 13:41:51	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$72.24	\$61.31	\$0.00	\$133.55
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$35.40	\$30.95	\$0.00	\$66.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:					1.41	166.64	92.26	5.00	263.90
--------------	-------------------	--	--	--	--	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11915538	09/06/2022 07:00:00	09/06/2022 07:30:00	0.50	\$59.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	09/06/2022 07:00:00	09/06/2022 07:18:00	0.30	\$35.40
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/02/2022 07:29:46	09/02/2022 08:06:30	0.61	\$72.24
LABOR						166.64

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	30.95	1	\$30.95
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.66	1	\$11.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	6	\$36.54
PARTS						92.26

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44552

Work Order Notes

(CWIGLEY) PM

Job Notes

25-53-006 - REMOVE WORDMARKS/IDENTIFIERS

(LISAPATE) Removed wordmarks on both sides of rear bumper

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45181

USING DEPT NO:	507121	OPENED DATE:	11/07/2022 07:16:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/08/2022 07:54:53	METER 1 - M:	14206	METER 2 - H: 3839
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/09/2022 09:08:54	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	O	N	GARAGE	0.19	\$22.45	\$0.00	\$0.00	\$22.45
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.87	\$102.40	\$68.50	\$0.00	\$170.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:		1.06	124.85	68.50	5.00	198.35
--------------	-------------------	--	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/07/2022 08:22:44	11/07/2022 09:10:28	0.80	\$93.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/07/2022 08:14:56	11/07/2022 08:19:16	0.07	\$8.52
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11901357	11/07/2022 08:06:04	11/07/2022 08:17:29	0.19	\$22.45
LABOR						124.85

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	20.78	1	\$20.78
PARTS						68.50

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45181

Work Order Notes

(CWIGLEY) There's a nail in the right rear tire.
(CWIGLEY) PM

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(AGUERRA) Inspected R/R tire, screw did not penetrate tire. All good. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 14206 hours: 4595 idle hours: 3839 Completed PM top and bottom side. Add 1/2 hour for underbody cover. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45743

USING DEPT NO:	507121	OPENED DATE:	01/10/2023 09:50:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/20/2023 10:30:27	METER 1 - M:	14690	METER 2 - H: 3839
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/20/2023 14:22:33	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.25	\$29.53	\$13.73	\$0.00	\$43.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.25 29.53 13.73 5.00 48.26

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	12052187	01/10/2023 14:30:00	01/10/2023 14:35:23	0.09	\$10.59
66-17-030	PERFORM TIRE PATCH	12052187	01/10/2023 14:05:22	01/10/2023 14:15:00	0.16	\$18.95
LABOR						29.54

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.25	1	\$5.25
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	7.59	1	\$7.59
66-17-030	PERFORM TIRE PATCH	58107	WHEEL WEIGHT PFE 2.00	0.89	1	\$0.89
PARTS						13.73

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 45743

Work Order Notes

(EHANNAH) nail in front driver tire. please repair and patch
(LISAPATE)

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-030 - PERFORM TIRE PATCH

(JWRIGHT) Repaired If tire. Aired and balanced. Torqued lug nuts to spec. JAW

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46215

USING DEPT NO:	507121	OPENED DATE:	02/21/2023 10:00:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/22/2023 10:40:37	METER 1 - M:	15151	METER 2 - H: 4122
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2023 11:15:37	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.87	\$56.31	\$0.00	\$101.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.38 44.87 56.31 5.00 106.18

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/21/2023 14:37:16	02/21/2023 15:00:05	0.38	\$44.87
LABOR						44.87

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
PARTS						56.31

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46215

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-15151

ENG-4930

IDLE-4122

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47058

USING DEPT NO:	507121	OPENED DATE:	05/15/2023 12:04:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/16/2023 10:58:24	METER 1 - M:	15677	METER 2 - H: 4499
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/16/2023 13:09:52	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.09	\$10.55	\$34.03	\$0.00	\$44.58
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.33	\$39.01	\$0.00	\$0.00	\$39.01
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$61.16	\$56.31	\$0.00	\$117.47
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.08	\$8.88	\$33.45	\$0.00	\$42.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.01	119.60	123.79	5.00	248.39
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	05/16/2023 07:52:11	05/16/2023 08:12:01	0.33	\$39.01
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/16/2023 07:42:08	05/16/2023 07:47:30	0.09	\$10.55
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/16/2023 07:37:24	05/16/2023 07:41:55	0.08	\$8.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/16/2023 07:06:06	05/16/2023 07:37:12	0.52	\$61.16
					LABOR	119.60

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.73	1	\$10.73
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	33.45	1	\$33.45
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
					PARTS	123.79

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47058

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires relearned the tire positions and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. Add 1/2 hour labor for skid plate removal. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47829

USING DEPT NO:	507121	OPENED DATE:	08/04/2023 10:04:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/09/2023 14:05:20	METER 1 - M:	15993	METER 2 - H: 4603
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/10/2023 07:55:33	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.43	\$34.15	\$0.00	\$38.58
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.29	\$34.25	\$0.00	\$0.00	\$34.25
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	1.50	\$176.74	\$0.00	\$0.00	\$176.74
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	16.21	\$1,912.65	\$779.16	\$0.00	\$2,691.81
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$58.48	\$64.31	\$0.00	\$122.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	18.53	2,186.55	877.62	5.00	3,069.17
--------------	-------------------	-------	----------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	12052187	08/08/2023 14:30:00	08/08/2023 14:44:52	0.25	\$29.24
66-17-013	PERFORM ALIGNMENT	12052187	08/08/2023 13:00:00	08/08/2023 14:15:00	1.25	\$147.50
66-17-013	PERFORM ALIGNMENT	12052187	08/08/2023 12:23:57	08/08/2023 12:23:57	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/08/2023 07:42:27	08/08/2023 07:42:46	0.01	\$0.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/07/2023 14:45:37	08/08/2023 06:57:50	16.20	\$1,912.03
06-15	INSPECT STEERING	11074414	08/04/2023 13:00:00	08/04/2023 13:17:25	0.29	\$34.25
06-15	INSPECT STEERING	11074414	08/04/2023 12:59:06	08/04/2023 12:59:06	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	08/04/2023 12:03:00	08/04/2023 12:03:00	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/04/2023 11:21:55	08/04/2023 11:24:10	0.04	\$4.43
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/04/2023 10:52:11	08/04/2023 11:21:55	0.50	\$58.48
					LABOR	2186.55

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
----------	-----------------	----------	-------------	------------	----------	------------

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	012114	TIRE 255/60R18 FTONE FHAWK PST	186.56	4	\$746.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.90	1	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.66	3	\$1.98
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.63	2	\$1.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.84	4	\$27.36
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.49	1	\$13.49
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	877.62

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47829

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

06-15 - INSPECT STEERING

(GARAGE) Inspected the steering found no issues at this time. SH

66-17-013 - PERFORM ALIGNMENT

(GARAGE) Performed alignment. Found the rear axle was way out of adjustment due to the cam bolts and toe adjustment being loose. Discussed with Lisa and found this to be the unit that had the rear sub frame replaced at dealer. Went ahead and adjusted everything into spec and tightened all bolts to spec. Rechecked all other bolts on rear. Also recalibrated the LDW system. Found no other issues at this time. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and balanced 4 tires and relearned the tire positions. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. The right front has a piece of metal in it at the side wall and cant be fixed. All 4 tires have shoulder wear. Suggest 4 tires. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48145

USING DEPT NO:	507121	OPENED DATE:	09/11/2023 07:35:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/14/2023 10:47:46	METER 1 - M:	16346	METER 2 - H: 4603
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/14/2023 13:32:19	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-22-007	INSPECT ASSEMBLY - REAR AXLE, DRI	DON	O	N	GARAGE	1.85	\$218.10	\$0.00	\$0.00	\$218.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					1.85	218.10	0.00	5.00	223.10
--------------	-------------------	--	--	--	--	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-22-007	INSPECT ASSEMBLY - REAR AXLE, DRIVEN	12052187	09/11/2023 13:21:21	09/11/2023 14:09:48	0.81	\$95.29
06-22-007	INSPECT ASSEMBLY - REAR AXLE, DRIVEN	12052187	09/11/2023 08:23:32	09/11/2023 09:25:59	1.04	\$122.82
LABOR						218.11

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48145

Work Order Notes

(EHANNAH) scan out - driver reports constant vibrating and dragging feeling while driving.

Job Notes

06-22-007 - INSPECT ASSEMBLY - REAR AXLE, DRIVEN

(IFALLS) Inspected everything and checked all bolts. Found rear of skid plate on back side of transmission loose with bolt about to fall out. Removed and found the threads were smooth in the casing. Drilled and installed helicoil and tightened bolt with thread lock tite. Test drove and heard no other issues. JAW. 1hr labor

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48625

USING DEPT NO:	507121	OPENED DATE:	10/19/2023 08:03:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/19/2023 14:24:57	METER 1 - M:	16787	METER 2 - H: 4989
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/20/2023 09:00:07	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	N	N	GARAGE	0.05	\$5.64	\$0.00	\$0.00	\$5.64
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$61.03	\$64.16	\$0.00	\$125.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.57	66.67	64.16	5.00	135.83
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	10/19/2023 10:55:02	10/19/2023 10:57:54	0.05	\$5.64
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	10/19/2023 10:55:02	10/19/2023 10:57:54	(0.05)	(\$5.64)
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	10/19/2023 10:55:02	10/19/2023 10:57:54	0.05	\$5.64
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/19/2023 10:23:48	10/19/2023 10:54:50	0.52	\$61.03
LABOR						66.67

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.83	1	\$10.83
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.83	(1)	(\$10.83)
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
PARTS						64.16

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 48625

Work Order Notes

(EHANNAH) pm- inspect tires DR tire needs air

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(SHARBIN) All 4 tires were 5 to 6 pounds low of air. SH

(LRUSHING) Visit Reason Changed On 10/19/2023 11:20 AM By LRUSHING

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49243

USING DEPT NO:	507121	OPENED DATE:	12/13/2023 07:09:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/04/2024 11:58:31	METER 1 - M:	17510	METER 2 - H: 6266
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/05/2024 08:00:46	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-16-006	REPLACE NEW REAR SHOCK ABSORB	DON	N	N	GARAGE	0.69	\$81.49	\$195.02	\$0.00	\$276.51
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.08	\$9.11	\$0.00	\$0.00	\$9.11
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.31	\$64.16	\$0.00	\$65.47
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.15	\$17.70	\$33.45	\$0.00	\$51.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.93	109.61	292.63	5.00	407.24
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	01/04/2024 07:00:00	01/04/2024 07:09:00	0.15	\$17.70
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	11310047	12/15/2023 14:54:37	12/15/2023 15:36:03	0.69	\$81.49
66-79-003	PERFORM SAFETY INSPECTION	12395904	12/15/2023 15:29:51	12/15/2023 15:34:29	0.08	\$9.11
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/15/2023 15:28:43	12/15/2023 15:29:23	0.01	\$1.31
				LABOR		109.61

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	33.45	1	\$33.45
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	LB5Z18125H	SHOCK	195.02	1	\$195.02
				PARTS		292.63

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49243

Work Order Notes

(EHANNAH) pm- do SI

Job Notes

03-16-006 - REPLACE NEW REAR SHOCK ABSORBER

(EHOWELL) The right rear shock absorber was seeping oil. We ordered two shock absorbers, but one of them was wrong. Replaced the right rear shock absorber and verified that the left rear shock absorber was not leaking. EH

66-79-003 - PERFORM SAFETY INSPECTION

(FCONTRER) perform safety inspection good nid replace 2 shocks Rear FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes FC

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) FC CHANGED CABIN FILTER

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50129

USING DEPT NO:	507121	OPENED DATE:	03/18/2024 07:53:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/20/2024 11:07:22	METER 1 - M:	20756	METER 2 - H: 6266
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/20/2024 11:52:52	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	N	N	GARAGE	0.13	\$15.37	\$0.00	\$0.00	\$15.37
66-17-015	PERFORM TIRE ROTATION	DON	N	N	GARAGE	0.41	\$47.99	\$0.00	\$0.00	\$47.99
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.57	\$67.06	\$60.56	\$0.00	\$127.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.11	130.42	60.56	5.00	195.98
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/18/2024 08:04:49	03/18/2024 08:38:55	0.57	\$67.06
14-52-021	INSTALL GPS SYSTEM	11074414	03/18/2024 08:38:55	03/18/2024 08:46:44	0.13	\$15.37
66-17-015	PERFORM TIRE ROTATION	11074414	03/18/2024 08:46:44	03/18/2024 09:11:08	0.41	\$47.99
				LABOR		130.42

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
				PARTS		60.56

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50129

Work Order Notes

(EHANNAH) PM- tire rotation- install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240066. SH

66-17-015 - PERFORM TIRE ROTATION

(GARAGE) Rotated the tires per customer request. Relearned the tire positions and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51053

USING DEPT NO:	507121	OPENED DATE:	06/05/2024 16:17:18	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2024 08:38:30	METER 1 - M:	22326	METER 2 - H:	6266				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2024 08:57:01	IN-SERVICE DATE:	08/21/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-02-074	RECALL WINDOW SWITCH	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51053

Work Order Notes

(EHANNAH) prep and schedule- RECALL for power window switch

Job Notes

17-02-074 - RECALL WINDOW SWITCH

(EHANNAH) LL Ford came to our shop for Recall for power window switch

17-GA-005 - RECALL Scheduling and Preparation

(EHANNAH) prep and scheduling by Denise

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51562

USING DEPT NO:	507121	OPENED DATE:	07/22/2024 12:31:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/23/2024 08:44:02	METER 1 - M:	23447	METER 2 - H: 6266
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/23/2024 10:15:49	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.08	\$68.66	\$0.00	\$69.74
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.01	1.08	68.66	5.00	74.74
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/22/2024 15:29:21	07/22/2024 15:29:54	0.01	\$1.08
LABOR						1.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
PARTS						68.66

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51562

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51814

USING DEPT NO:	507121	OPENED DATE:	08/14/2024 13:08:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2024 12:13:48	METER 1 - M:	24193	METER 2 - H: 6266
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2024 12:36:16	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
20-00	TOWING COMPLETE VEHICLE	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$94.30	\$94.30
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,300.00	\$2,300.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	0.00	2,399.30	2,399.30
--------------	-------------------	------	------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
24-71	REPAIR BODY	11150605	16979582		\$2,300.00
20-00	TOWING COMPLETE VEHICLE	11076249	2416208		\$94.30
COMML					2399.30

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51814

Work Order Notes

(IFALLS) repair body
hood was unlatched and flew up and damaged windshield, hood, fenders
(EKIMBREL) pm

Job Notes

20-00 - TOWING COMPLETE VEHICLE

(IFALLS) Bamberger towed vehicle to our shop after accident

24-71 - REPAIR BODY

(EKIMBREL) Andrew's performed body repair
(IFALLS) Andrews towed from our shop to there Bodyshop for repairs

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) PERFORMED PM CM 24193 MILES 5939 HOURS, CHECKER, CHECKED ALL FLUIDS, FILTERS, AND TIRES CHECKED OK,

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO:		243751		2020 FORD INTERCEPTOR EXPLORER				WORK ORDER NO:		52682		
USING DEPT NO:		507121		OPENED DATE:		11/04/2024 09:45:19		LOCATION: GARAGE - University Automotive Services				
WO STATUS:		CLOSED		COMPLETED DATE:		11/05/2024 15:12:39		METER 1 - M:		24748 METER 2 - H: 6266		
WO VISIT REASON:		SCHEDULED		CLOSED DATE:		11/05/2024 15:50:20		IN-SERVICE DATE:		08/21/2020		
TECH SPEC NO:		20FORDEXPLINT		2020 Ford Interceptor Explorer				UNIT SERIAL NO:		1FM5K8ABXLGC15617		
JOB CODE		JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-51-046		REMOVE KEY BLANK(S)		DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1				WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52682

Work Order Notes

(EHANNAH) 708 has half a key stuck inside the rear hatch/door which needs removal

Job Notes

25-51-042 - REMOVE KEY FOB BATTERY

(GARAGE) removed broken key from rear hatch door .25 labor cm

25-51-046 - REMOVE KEY BLANK(S)

(EKIMBREL) removed broken key from rear hatch door .25 labor cm

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53254

USING DEPT NO:	507121	OPENED DATE:	01/03/2025 08:04:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/06/2025 09:47:00	METER 1 - M:	25252	METER 2 - H: 6266
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/07/2025 08:08:20	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$225.51	\$0.00	\$225.51
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$71.51	\$0.00	\$71.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	297.02	5.00	302.02
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	225.51	1	\$225.51
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
PARTS						297.02

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53254

Work Order Notes

(EHANNAH) pm- SI

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) JR- replace battery, alternator charging

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) PERFORMED SAFETY INSPECTION PER SI SHEET. EVERYTHING CHECKED OUT IN SPEC. BRAKES 6-7 MM FRONT AND 4-5 MM REAR. RELEARNED BATTERY MONITORING SYSTEM. CQ

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures
25296 miles, 6231 idle hours, 7467 total hours

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54171

USING DEPT NO:	507121	OPENED DATE:	03/26/2025 14:05:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/26/2025 14:08:30	METER 1 - M:	26415	METER 2 - H: 6266
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/27/2025 07:28:41	IN-SERVICE DATE:	08/21/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-GA-005	RECALL Scheduling and Preparation	2714700	176649		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: **243751** **2020 FORD INTERCEPTOR EXPLORER**

WORK ORDER NO: **54171**

Work Order Notes

Job Notes

17-GA-005 - RECALL Scheduling and Preparation

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) STIVERS PERFORMED OIL CHANGE RECALL

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54755

USING DEPT NO:	507121	OPENED DATE:	05/12/2025 14:37:41	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	OPEN	COMPLETED DATE:		METER 1 - M:	26771	METER 2 - H:	6266
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	08/21/2020		
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8ABXLGC15617		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-33-006	TRANSPORT IGNITION LOCK CYLINDEI	WFA	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-33-006	REMOVE IGNITION LOCK CYLINDER	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
RY-33-006	REKEY IGNITION LOCK CYLINDER	WFA	5	N	GARAGE	0.00	\$0.00	\$0.00	\$95.22	\$95.22

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	0.00	95.22	95.22
--------------	-------------------	------	------	------	-------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2318908		\$95.22
				COMML	95.22

Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2025 09:02:45 By User: GLOBETTI

UNIT NO: 243751 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 54755

Work Order Notes

Job Notes

16-33-006 - TRANSPORT IGNITION LOCK CYLINDER

(EKIMBREL) RC/CW TRANSPORTED CYLINDERS TO AND FROM A1

25-33-006 - REMOVE IGNITION LOCK CYLINDER

(GARAGE) REMOVED ALL DOOR LOCK CYLINDERS AND IGNITION CYLINDER TO HAVE REKEYED, HAD TO REMOVED THE POLICE SCANNER CENTER CONSOLE AND THE CENTER DISPLAY OF DASH TO REMOVE IGNITION CYLINDER. CQ

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) PREPPED FOR SALE PER DECOMMISSION SHEET.CQ

RY-33-006 - REKEY IGNITION LOCK CYLINDER

(EKIMBREL) A1 REKEYED LOCK CYLINDERS

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue May 20 2025 09:02:45 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '1FM5K8ABXLGC15617') //Q=