

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 37425

USING DEPT NO:	507121	OPENED DATE:	08/25/2020 07:33:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2020 07:34:46	METER 1 - M:	103	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2020 09:12:33	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 WORK ORDER TOTAL: 0.50 0.00 0.00 0.00 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	12052187	08/25/2020 07:34:16	08/25/2020 08:04:16	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 37425

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 38825

USING DEPT NO:	507121	OPENED DATE:	01/19/2021 10:29:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2021 10:30:23	METER 1 - M:	35770	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2021 10:30:24	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 38825

Work Order Notes

(LISAPATE) Opened WO for documentation per Tony J. Unit has not been put in service yet. Being held up due to a strobe light issue

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39249

USING DEPT NO:	507121	OPENED DATE:	03/01/2021 14:55:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/02/2021 14:14:53	METER 1 - M:	1589	METER 2 - H: 209
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/04/2021 08:10:00	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.28	\$150.78	\$47.75	\$0.00	\$198.53

JOB COUNT: 1	WORK ORDER TOTAL:	1.28	150.78	47.75	0.00	198.53
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/02/2021 08:20:08	03/02/2021 09:36:48	1.28	\$150.78
					LABOR	150.78

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.78	1	\$9.78
66-PM-PMA	PERFORM OIL CHANGE	5066517	WSWF RAIN-X -20DEG DEICER GAL	6.89	1	\$6.89
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	7	\$31.08
					PARTS	47.75

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 39249

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 1589 idle hours: 209 Completed PM, top and bottom side. Completed checklist and vacuumed out vehicle. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40150

USING DEPT NO:	507121	OPENED DATE:	06/11/2021 09:49:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/15/2021 14:15:05	METER 1 - M:	3242	METER 2 - H: 498
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/17/2021 11:27:49	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.71	\$201.81	\$37.69	\$0.00	\$239.50

JOB COUNT: 1	WORK ORDER TOTAL:	1.71	201.81	37.69	0.00	239.50
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/11/2021 10:01:07	06/11/2021 10:56:46	0.93	\$109.45
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/11/2021 10:02:53	06/11/2021 10:49:51	0.78	\$92.37
					LABOR	201.82

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	7	\$30.98
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	(7)	(\$30.98)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					PARTS	37.69

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40150

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40443

USING DEPT NO:	507121	OPENED DATE:	07/15/2021 08:49:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/09/2021 08:31:33	METER 1 - M:	4431	METER 2 - H: 498
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/09/2021 15:11:15	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-02-058	INSPECT DOOR LOCK	DON	O	N	GARAGE	0.30	\$35.17	\$0.00	\$0.00	\$35.17
15-02-055	WARRANTY DOOR LATCH/STRIKER	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.30	153.17	0.00	2.00	155.17
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-02-055	WARRANTY DOOR LATCH/STRIKER	4910000	622146		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11915538	08/09/2021 07:00:00	08/09/2021 08:00:00	1.00	\$118.00
06-02-058	INSPECT DOOR LOCK	11170580	07/15/2021 09:31:58	07/15/2021 09:49:51	0.30	\$35.17
LABOR						153.17

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40443

Work Order Notes

(LISAPATE) Per driver the drivers door locking mechanism is malfunctioning and does not consistently unlock with the key

Job Notes

06-02-058 - INSPECT DOOR LOCK

(ABBLACK) AB verified front door locks do not operate correctly all the time. Needs to go to town and country for warranty work for a SSM on the front door locks.

15-02-055 - WARRANTY DOOR LATCH/STRIKER

(LISAPATE) Town and Country verified failure. Replaced both front door latches

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to T&C by RC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40848

USING DEPT NO:	507121	OPENED DATE:	08/26/2021 08:22:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/09/2021 15:17:08	METER 1 - M:	5112	METER 2 - H: 799
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/10/2021 12:17:07	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.54	\$31.70	\$0.00	\$39.24
06-02-053	INSPECT WINDOW REGULATOR	DON	O	N	GARAGE	0.35	\$40.97	\$0.00	\$0.00	\$40.97
15-78-021	WARRANTY WINDOWS	DON	O	N	GARAGE	0.90	\$106.27	\$0.00	\$0.00	\$106.27
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.15	\$17.96	\$0.00	\$0.00	\$17.96
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.73	\$85.71	\$43.19	\$0.00	\$128.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.19	258.45	74.89	2.00	335.34
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-02-053	INSPECT WINDOW REGULATOR	11170580	09/08/2021 08:01:26	09/08/2021 08:22:16	0.35	\$40.97
15-78-021	WARRANTY WINDOWS	11170580	09/08/2021 09:30:00	09/08/2021 09:31:28	0.02	\$2.88
15-78-021	WARRANTY WINDOWS	11170580	09/08/2021 08:22:26	09/08/2021 09:15:00	0.88	\$103.38
66-79-003	PERFORM SAFETY INSPECTION	12052187	08/27/2021 07:06:34	08/27/2021 07:15:42	0.15	\$17.96
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/26/2021 15:11:15	08/26/2021 15:37:47	0.44	\$52.18
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/26/2021 13:38:01	08/26/2021 13:55:04	0.28	\$33.53
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/26/2021 13:33:59	08/26/2021 13:37:49	0.06	\$7.54
					LABOR	258.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.84	1	\$5.84
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.07	1	\$10.07

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
					PARTS	74.89

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 40848

Work Order Notes

(LISAPATE) PM-replace wipers-Do SI-Driver window is making noise when rolling up and down

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

06-02-053 - INSPECT WINDOW REGULATOR

(ABLACK) AB removed door panel and found the window belt line molding was torn causing window to squeal and bind. Needs a new window belt trim.

(LISAPATE) Trim was broken by Town and Country when doing a window repair recently so they sent us the part at no charge to replace instead of taking the unit all the way back to Birmingham

15-78-021 - WARRANTY WINDOWS

(ABLACK) AB removed the drivers side door trim in order to install the window belt line trim. Rechecked ok.

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed SI. Found no issues. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-5112

IDLE HRS-799

ENG HRS-1068

ADD 1/2 HR LABOR FOR SKID PLATE REMOVAL

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41106

USING DEPT NO:	507121	OPENED DATE:	09/22/2021 15:09:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2021 13:50:08	METER 1 - M:	5537	METER 2 - H: 799
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2021 13:50:11	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-27	WARRANTY TRANSMISSION - MAIN, AL	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-27	TRANSPORT TRANSMISSION - MAIN, A	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
35-27	DIAGNOSE TRANSMISSION - MAIN, AU	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.50	177.00	0.00	2.00	179.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-27	WARRANTY TRANSMISSION - MAIN, AUTOMATIC	11078175	92193		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-27	DIAGNOSE TRANSMISSION - MAIN, AUTOMATIC	11170580	09/28/2021 07:00:00	09/28/2021 08:00:00	1.00	\$118.00
16-27	TRANSPORT TRANSMISSION - MAIN, AUTOMATIC	11915538	09/28/2021 07:00:00	09/28/2021 07:30:00	0.50	\$59.00
LABOR						177.00

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41106

Work Order Notes

(LISAPATE) Per Margaret transmission is shifting hard

Job Notes

15-27 - WARRANTY TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) Per Tuscaloosa Ford verified concern, no DTCs, fluid level and condition ok. Found applicable TSB in Oasis. Performed accelerated main control break in drive cycle. Road tested and verified repair.

16-27 - TRANSPORT TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) Taken to Ford by RC

35-27 - DIAGNOSE TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) Verified concern sent to Fod for warranty repair per TSB 21-2316

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41885

USING DEPT NO:	507121	OPENED DATE:	12/14/2021 12:41:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/15/2021 08:23:49	METER 1 - M:	6926	METER 2 - H: 1098
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/16/2021 08:08:33	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$50.94	\$44.55	\$0.00	\$95.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.43	50.94	44.55	2.00	97.49
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2021 14:59:07	12/14/2021 15:25:01	0.43	\$50.94
LABOR						50.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.20	1	\$7.20
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
PARTS						44.55

Work Order Charge Detail

UNIT NO:	243748	2020 FORD INTERCEPTOR EXPLORER	WORK ORDER NO:	41885
----------	--------	--------------------------------	----------------	-------

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42664

USING DEPT NO:	507121	OPENED DATE:	03/21/2022 08:53:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/22/2022 11:07:27	METER 1 - M:	8137	METER 2 - H: 1098
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/25/2022 07:23:42	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.97	\$31.82	\$0.00	\$37.79
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$70.54	\$49.57	\$0.00	\$120.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:		0.65	76.51	81.39	2.00	159.90
--------------	-------------------	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/21/2022 09:30:00	03/21/2022 09:52:30	0.38	\$44.25
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/21/2022 09:01:38	03/21/2022 09:15:00	0.22	\$26.29
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/21/2022 09:30:00	03/21/2022 09:33:02	0.05	\$5.97
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/21/2022 09:28:35	03/21/2022 09:28:35	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/21/2022 09:17:47	03/21/2022 09:17:47	0.00	\$0.00
LABOR						76.51

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.75	1	\$5.75
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
PARTS						81.39

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42664

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43594

USING DEPT NO:	507121	OPENED DATE:	06/10/2022 07:43:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/10/2022 14:20:19	METER 1 - M:	9625	METER 2 - H: 1722
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/13/2022 09:07:06	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$46.58	\$64.73	\$0.00	\$111.31
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.39	46.58	64.73	2.00	113.31
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/10/2022 09:26:49	06/10/2022 09:45:27	0.31	\$36.65
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/10/2022 08:48:59	06/10/2022 08:54:02	0.08	\$9.93
LABOR						46.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.21	1	\$11.21
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.89	1	\$7.89
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.82	6	\$34.92
PARTS						64.73

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43594

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 9625 hours: 2213 idle hours: 1722 Completed PM top and bottom side. Completed checklist. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44420

USING DEPT NO:	507121	OPENED DATE:	08/23/2022 07:19:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2022 15:04:35	METER 1 - M:	11246	METER 2 - H: 2088
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/24/2022 07:20:10	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$50.15	\$61.08	\$0.00	\$111.23
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.30	\$35.40	\$30.95	\$0.00	\$66.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.73	85.55	92.03	5.00	182.58
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	08/23/2022 08:38:52	08/23/2022 08:56:52	0.30	\$35.40
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/23/2022 08:13:22	08/23/2022 08:38:52	0.43	\$50.15
LABOR						85.55

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.43	1	\$11.43
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	6	\$36.54
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	30.95	1	\$30.95
PARTS						92.03

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44420

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-11246

HRS-2670

IDLE-2088

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Installed new cabin filter

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44639

USING DEPT NO:	507121	OPENED DATE:	09/09/2022 11:38:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/12/2022 10:30:19	METER 1 - M:	11876	METER 2 - H: 2238
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/12/2022 13:08:02	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.60	\$71.29	\$11.26	\$0.00	\$82.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.60	71.29	11.26	5.00	87.55
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11901357	09/09/2022 12:03:18	09/09/2022 12:39:33	0.60	\$71.29
LABOR						71.29

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	4.31	1	\$4.31
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.18	1	\$6.18
66-17-030	PERFORM TIRE PATCH	58101	.50 OZ WHEEL WEIGHT	0.32	1	\$0.32
66-17-030	PERFORM TIRE PATCH	58102	.75 OZ WHEEL WEIGHT	0.45	1	\$0.45
PARTS						11.26

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44639

Work Order Notes

(CHANNELL) nail in driver side front tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) miles: 11876 hours: 2857 idle hours: 2238 Repaired and balanced L/F tire. Rechecked for leak, all good. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44990

USING DEPT NO:	507121	OPENED DATE:	10/17/2022 07:14:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2022 14:39:00	METER 1 - M:	12514	METER 2 - H: 2401
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2022 15:22:32	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.45	\$52.81	\$56.51	\$0.00	\$109.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.45	52.81	56.51	5.00	114.32
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/17/2022 07:33:53	10/17/2022 08:00:44	0.45	\$52.81
					LABOR	52.81

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.96	1	\$5.96
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
					PARTS	56.51

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44990

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. SH/JAW

MILEAGE-12514

IDLE HRS-2401

ENG HRS-3053

(LISAPATE) Removed skid plate

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45292

USING DEPT NO:	507121	OPENED DATE:	11/16/2022 14:16:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/17/2022 13:56:07	METER 1 - M:	12676	METER 2 - H: 2425
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/22/2022 08:10:57	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.58	\$68.37	\$8.36	\$0.00	\$76.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.58	68.37	8.36	5.00	81.73
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11074414	11/17/2022 07:11:10	11/17/2022 07:45:56	0.58	\$68.37
					LABOR	68.37

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	7.59	1	\$7.59
66-17-030	PERFORM TIRE PATCH	58101	.50 OZ WHEEL WEIGHT	0.32	1	\$0.32
66-17-030	PERFORM TIRE PATCH	58102	.75 OZ WHEEL WEIGHT	0.45	1	\$0.45
					PARTS	8.36

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45292

Work Order Notes

(LISAPATE) Nail in RR tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(SHARBIN) Patched the right rear tire. SH

(SHARBIN) Put the tire back on the vehicle and the spare back in the trunk. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45740

USING DEPT NO:	507121	OPENED DATE:	01/10/2023 08:48:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/11/2023 10:28:36	METER 1 - M:	13398	METER 2 - H: 2425
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/17/2023 11:13:50	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.11	\$13.44	\$32.69	\$0.00	\$46.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.65	\$68.60	\$0.00	\$91.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.31	36.09	101.29	5.00	142.38
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	01/10/2023 10:43:55	01/10/2023 10:50:45	0.11	\$13.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/10/2023 10:22:53	01/10/2023 10:34:24	0.19	\$22.65
LABOR						36.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	8.24	6	\$49.41
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.47	1	\$9.47
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.43	1	\$10.43
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.08	1	\$6.08
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
PARTS						101.29

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45740

Work Order Notes

(EHANNAH) pm- replace wipers
(GARAGE) replaced wipers-GC

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46560

USING DEPT NO:	507121	OPENED DATE:	03/30/2023 07:03:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/30/2023 13:47:28	METER 1 - M:	14509	METER 2 - H: 2982
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2023 13:56:00	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.36	\$43.00	\$0.00	\$0.00	\$43.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$6.85	\$56.40	\$0.00	\$63.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.42	49.85	56.40	5.00	111.25
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	03/30/2023 08:47:07	03/30/2023 09:03:03	0.27	\$31.34
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	03/30/2023 08:25:18	03/30/2023 08:31:14	0.10	\$11.67
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/30/2023 08:06:55	03/30/2023 08:10:24	0.06	\$6.85
				LABOR		49.86

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
					PARTS	56.40

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46560

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires relearned the tire positions and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) CW SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47458

USING DEPT NO:	507121	OPENED DATE:	06/28/2023 12:53:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/30/2023 09:29:40	METER 1 - M:	15751	METER 2 - H: 2982
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/05/2023 09:28:34	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.32	\$61.82	\$0.00	\$80.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.16 18.32 61.82 5.00 85.14

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/28/2023 14:05:41	06/28/2023 14:15:00	0.16	\$18.32
LABOR						18.32

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
PARTS						61.82

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47458

Work Order Notes

(EHANNAH) pm- replace wipers
(EKIMBREL) does not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47651

USING DEPT NO:	507121	OPENED DATE:	07/19/2023 14:02:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/19/2023 14:36:01	METER 1 - M:	16045	METER 2 - H: 2982
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/20/2023 08:53:12	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-05-020	RECALL PCM/PROCESSOR ASSEMBLY	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-22	RECALL AXLES - DRIVEN, REAR	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-05-020	RECALL PCM/PROCESSOR ASSEMBLY	11099772	100610658		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47651

Work Order Notes

(LISAPATE) Long Lewis came to the shop to completed recalls. MV99pm and 22S27.

Job Notes

17-05-020 - RECALL PCM/PROCESSOR ASSEMBLY

(LISAPATE) Reprogrammed PCM

17-22 - RECALL AXLES - DRIVEN, REAR

(LISAPATE) Replaced subframe bushing

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48260

USING DEPT NO:	507121	OPENED DATE:	09/20/2023 07:25:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2023 13:57:48	METER 1 - M:	17247	METER 2 - H: 3685
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2023 09:39:22	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.75	\$64.34	\$0.00	\$87.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.19	22.75	64.34	5.00	92.09
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/20/2023 08:21:13	09/20/2023 08:32:47	0.19	\$22.75
					LABOR	22.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
					PARTS	64.34

Work Order Charge Detail

UNIT NO:

243748

2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO:

48260

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48941

USING DEPT NO:	507121	OPENED DATE:	11/13/2023 09:09:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/15/2023 11:28:11	METER 1 - M:	18286	METER 2 - H: 3894
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/15/2023 13:19:29	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	P	N	GARAGE	0.07	\$8.00	\$221.08	\$0.00	\$229.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.43	\$81.62	\$0.00	\$111.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	O	N	GARAGE	0.06	\$7.21	\$0.00	\$0.00	\$7.21

JOB COUNT: 4	WORK ORDER TOTAL:	0.38	44.64	302.70	5.00	352.34
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
	COMML				5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/13/2023 10:02:46	11/13/2023 10:17:44	0.25	\$29.43
03-32-002	REPLACE NEW BATTERY	11074414	11/13/2023 09:58:27	11/13/2023 10:02:31	0.07	\$8.00
03-32-002	REPLACE NEW BATTERY	11074414	11/13/2023 09:58:27	11/13/2023 10:02:31	(0.07)	(\$8.00)
03-32-002	REPLACE NEW BATTERY	11074414	11/13/2023 09:58:27	11/13/2023 10:02:31	0.07	\$8.00
SO-00	SCAN OUT COMPLETE VEHICLE	11074414	11/13/2023 09:54:34	11/13/2023 09:58:14	0.06	\$7.21
	LABOR					44.64

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	9.17	6	\$54.99
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	221.08	1	\$221.08
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	221.08	(1)	(\$221.08)
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	221.08	1	\$221.08
	PARTS					302.70

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48941

Work Order Notes

(EHANNAH) dash states " Falt service Required.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Installed a new battery. ALT Charging at 14.10 volts. No messages on dash. SH
(IFALLS) Visit Reason Changed On 11/15/2023 1:19 PM By IFALLS

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(SHARBIN) Battery only had 9 volts in it. SH
(IFALLS) used to reset charging pids

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48970

USING DEPT NO:	507121	OPENED DATE:	11/16/2023 07:40:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/16/2023 14:16:18	METER 1 - M:	18331	METER 2 - H: 3906
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/16/2023 15:42:03	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.16	\$19.34	\$0.00	\$0.00	\$19.34
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.16	19.34	0.00	5.00	24.34
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-021	INSTALL GPS SYSTEM	11074414	11/16/2023 08:05:28	11/16/2023 08:15:18	0.16	\$19.34
LABOR						19.34

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48970

Work Order Notes

(EHANNAH) install GPS- 87X032360251

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(SHARBIN) Installed GPS# 87X032360251 SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49547

USING DEPT NO:	507121	OPENED DATE:	01/24/2024 07:17:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2024 15:00:31	METER 1 - M:	19931	METER 2 - H: 4201
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/25/2024 07:36:21	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$75.88	\$60.56	\$0.00	\$136.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.64	75.88	60.56	5.00	141.44
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/24/2024 08:23:58	01/24/2024 09:02:33	0.64	\$75.88
					LABOR	75.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
					PARTS	60.56

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49547

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 he for skid pan.

Miles, 19,931

Idle Hours, 4,201

Total Hours, 5,229

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50163

USING DEPT NO:	507121	OPENED DATE:	03/20/2024 07:15:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/04/2024 15:41:54	METER 1 - M:	21643	METER 2 - H: 4201
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/05/2024 07:23:21	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	N	N	GARAGE	1.91	\$225.87	\$359.19	\$0.00	\$585.06
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.41	\$48.64	\$0.00	\$0.00	\$48.64
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	1.02	\$120.39	\$0.00	\$0.00	\$120.39
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.62	\$190.93	\$948.58	\$0.00	\$1,139.51
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.05	\$5.57	\$60.56	\$0.00	\$66.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	5.01	591.40	1,368.33	5.00	1,964.73
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	12052187	03/26/2024 08:01:36	03/26/2024 09:02:49	1.02	\$120.39
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/01/2024 09:12:10	04/01/2024 09:15:00	0.05	\$5.57
66-13-130	PERFORM Burnish Brakes	12052187	03/26/2024 13:27:09	03/26/2024 13:51:53	0.41	\$48.64
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	12052187	03/26/2024 10:00:07	03/26/2024 10:49:56	0.83	\$97.97
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12395904	03/25/2024 10:07:20	03/25/2024 11:31:56	1.41	\$166.38
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12395904	03/22/2024 09:02:31	03/22/2024 09:15:00	0.21	\$24.55
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	12052187	03/26/2024 12:18:20	03/26/2024 13:23:22	1.08	\$127.90
				LABOR		591.40

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWRZ362231	REAR BRAKE PADS	71.85	1	\$71.85

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	L1MZ2C026C	REAR ROTORS	143.67	2	\$287.34
66-17-028	PERFORM MOUNT AND BALANCE TIRES	0450555	TIRE 255/60R18 GEN GMAXPURSUIT	231.62	4	\$926.46
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.56	(1)	(\$3.56)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.56	4	\$14.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	1.22	1	\$1.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.10	3	\$3.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.78	1	\$0.78
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.56	1	\$3.56
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	1.34	1	\$1.34
					PARTS	1368.33

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50163

Work Order Notes

(EHANNAH) perform mount an balance- pm

Job Notes

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(JWRIGHT) Replaced rear brakes and rotors. JAW

66-13-130 - PERFORM Burnish Brakes

(JWRIGHT) burnished brakes. JAW

66-17-013 - PERFORM ALIGNMENT

(JWRIGHT) Performed alignment. Adjusted rear and front toe. Recalibrated the LDW system. Test drove and found no other issues. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(FCONTRER) Mounted 4 tires and balanced 58105 - 3- 58103- 1- 58107- 1- 58102- 2- 58100- 1 - 58106 -1 - 21060- 4 FC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50575

USING DEPT NO:	507121	OPENED DATE:	04/15/2024 12:34:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/16/2024 13:53:17	METER 1 - M:	22078	METER 2 - H: 4556
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/17/2024 08:50:15	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$60.65	\$0.00	\$60.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.00 0.00 60.65 5.00 65.65

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.67	6	\$34.02
PARTS						60.65

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50575

Work Order Notes

(EHANNAH) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51173

USING DEPT NO:	507121	OPENED DATE:	06/13/2024 07:14:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/13/2024 09:05:08	METER 1 - M:	24404	METER 2 - H: 4884
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/13/2024 10:11:44	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$106.16	\$0.00	\$106.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.00 0.00 106.16 5.00 111.16

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	FP100	CABIN FILTER	37.50	1	\$37.50
PARTS						106.16

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51173

Work Order Notes

(LRUSHING) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC,FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 24,404

Idle Hours, 4,884

Total Hours, 6,142

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51654

USING DEPT NO:	507121	OPENED DATE:	07/31/2024 07:41:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/01/2024 16:18:43	METER 1 - M:	25438	METER 2 - H: 4884
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/05/2024 08:19:16	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.00	\$0.00	\$7.99	\$0.00	\$7.99
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	7.99	5.00	12.99
--------------	-------------------	--	--	--	--	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.62	1	\$3.62
66-17-030	PERFORM TIRE PATCH	58101	.50 OZ WHEEL WEIGHT	1.04	1	\$1.04
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.33	1	\$3.33
PARTS						7.99

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51654

Work Order Notes

(EHANNAH) inspect tire - PSI 19 - PS

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) Found small nail in rr tire. Repaired tire, aired to spec and balanced. Replaced valve stem. JAW

66-17-030 - PERFORM TIRE PATCH

(EKIMBREL) Found small nail in rr tire. Repaired tire, aired to spec and balanced. Replaced valve stem. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51751

USING DEPT NO:	507121	OPENED DATE:	08/09/2024 08:21:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/15/2024 17:19:21	METER 1 - M:	26353	METER 2 - H: 5233
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/16/2024 07:37:11	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$68.66	\$0.00	\$68.66
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.00	0.00	68.66	5.00	73.66
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
PARTS						68.66

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51751

Work Order Notes

(EHANNAH) pm- SI

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed SI. Brake pads are 8mm all around. Found no issues. JAW

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed pm service. JAW,GC/GC

Mileage-26353

Idle-5233

Eng=6600

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52225

USING DEPT NO:	507121	OPENED DATE:	09/25/2024 09:58:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2024 10:52:12	METER 1 - M:	27337	METER 2 - H: 5233
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2024 11:09:44	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.00	\$0.00	\$24.48	\$0.00	\$24.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	24.48	5.00	29.48
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	XC21	21" WIPER	11.25	1	\$11.25
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
PARTS						24.48

Work Order Charge Detail

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52225

Work Order Notes

(EHANNAH) wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) installed new blades cm

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52509

USING DEPT NO:	507121	OPENED DATE:	10/17/2024 10:59:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2024 09:04:09	METER 1 - M:	28269	METER 2 - H: 5233
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2024 10:10:34	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-015	PERFORM TIRE ROTATION	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$82.85	\$0.00	\$82.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	82.85	5.00	87.85
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	9.57	6	\$57.42
PARTS						82.85

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52509

Work Order Notes

(CWIGLEY) PM

Job Notes

66-17-015 - PERFORM TIRE ROTATION

(GARAGE) performed tire rotation, tires had edge wear-GC
Miles, 28,269

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm-CM

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52922

USING DEPT NO:	507121	OPENED DATE:	11/27/2024 07:18:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/27/2024 08:42:26	METER 1 - M:	29871	METER 2 - H: 5991
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/27/2024 09:08:42	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$78.71	\$0.00	\$78.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.00 0.00 78.71 5.00 83.71

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	8.88	6	\$53.28
PARTS						78.71

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52922

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC-topside, checked fluids, checked air filters, checked tires and tire pressures

JR-pit, changed oil and filter

29871 miles, 5991 idle hours, 7573 total hours

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53075

USING DEPT NO:	507121	OPENED DATE:	12/11/2024 07:47:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/20/2024 07:47:56	METER 1 - M:	30184	METER 2 - H: 5991
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/20/2024 08:57:23	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-52-024	REPLACE NEW BACK UP CAMERA	DON	N	N	GARAGE	0.00	\$0.00	\$58.41	\$0.00	\$58.41
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$37.50	\$0.00	\$37.50
CH-32-002	CHARGE BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	95.91	5.00	100.91
--------------	-------------------	------	------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP100	CABIN FILTER	37.50	1	\$37.50
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP100	CABIN FILTER	37.50	(1)	(\$37.50)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP100	CABIN FILTER	37.50	1	\$37.50
03-52-024	REPLACE NEW BACK UP CAMERA	LB5Z19G490E	BACK UP CAMERA	58.41	1	\$58.41
PARTS						95.91

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53075

Work Order Notes

(EHANNAH) screen is working for a few seconds and then goes out and keeps doing this.

Job Notes

03-52-024 - REPLACE NEW BACK UP CAMERA

(GARAGE) installed the new back up camera on unit 8202B-GC, CQ removed trim pieces to get to the back up camera, new camera came in today 12-19-24, Ethan had GC install new back up camera and put trim pieces back on.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) replaced cabin air filter on unit 8202B-GC ,CQ had removed the glove box to put in a new cabin filter, CQ was off today so GC also installed the new cabin filter (EHOWELL) Visit Reason Changed On 12/20/2024 7:46 AM By EHOWELL

CH-32-002 - CHARGE BATTERY

(GARAGE) CQ removed battery to charge, GC went and inspected battery and battery was fully charged, tested battery and battery tested good, installed battery back into unit 8202B, tested battery volts and volts were 14.08-GC

(EHOWELL) The vehicle was brought in for a screen display issue, not a battery concern. No charge because we may have left the radio on and ran the battery down.

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

SO-52-003 - SCAN OUT RADIO

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53549

USING DEPT NO:	507121	OPENED DATE:	01/30/2025 11:00:16	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	02/05/2025 07:25:31	METER 1 - M:	31128	METER 2 - H:	6369				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/05/2025 10:30:05	IN-SERVICE DATE:	08/20/2020						
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$757.86	\$0.00	\$757.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$70.59	\$0.00	\$70.59
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	828.45	5.00	833.45
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	F012114	TIRE 255/60R18 FSTONE PURSUIT	186.56	4	\$746.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.91	4	\$11.64
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.40	1	\$11.40
PARTS						828.45

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53549

Work Order Notes

(EHANNAH) pm

Job Notes

06-15 - INSPECT STEERING

(EKIMBREL) CM JR CHECKED STEERING CHECKED OK,.25 LABOR

66-17-013 - PERFORM ALIGNMENT

(GARAGE) performed alignment cm test drove checked ok, 31128 miles,

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) PULLED IN SHOP AND ON LIFT, REMOVED TIRES. MOUNT AND BALANCED 4 NEW TIRES AND INSTALLED ON INTERCEPTOR. SET TIRE PRESSURE AND RELEARNED TMS SENSORS. CQ

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR-topside

FJ- pit
perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
31128 miles, 6369 idle hours, 8027 total hours

quoting a full set of tires

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO:		243748		2020 FORD INTERCEPTOR EXPLORER				WORK ORDER NO:		53973		
USING DEPT NO:		507121		OPENED DATE:		03/05/2025 07:32:54		LOCATION: GARAGE - University Automotive Services				
WO STATUS:		CLOSED		COMPLETED DATE:		03/07/2025 14:20:53		METER 1 - M:		31336 METER 2 - H: 6369		
WO VISIT REASON:		SCHEDULED		CLOSED DATE:		03/17/2025 09:22:42		IN-SERVICE DATE:		08/20/2020		
TECH SPEC NO:		20FORDEXPLINT		2020 Ford Interceptor Explorer				UNIT SERIAL NO:		1FM5K8AB9LGC15611		
JOB CODE		JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-71-032		INSPECT WATER LEAK INTERIOR/EXTE		DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1				WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: **243748** **2020 FORD INTERCEPTOR EXPLORER**

WORK ORDER NO: **53973**

Work Order Notes

(EHANNAH) takening on water Pass. side window

Job Notes

06-71-032 - INSPECT WATER LEAK INTERIOR/EXTERIOR

(GARAGE) CHECKED FOR WATER LEAK ON PASSENGER SIDE WINDOW, DID NOT FIND ANY LEAK. CQ

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54146

USING DEPT NO:	507121	OPENED DATE:	03/25/2025 11:35:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2025 15:51:51	METER 1 - M:	31378	METER 2 - H: 6369
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/26/2025 08:08:40	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-40-433	INSPECT OIL LEAK	DON	N	N	GARAGE	0.00	\$0.00	\$20.43	\$0.00	\$20.43
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	20.43	5.00	25.43
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
06-40-433	INSPECT OIL LEAK	5W30BT	5W30 BULK	6.39	2	\$12.78
06-40-433	INSPECT OIL LEAK	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
PARTS						20.43

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54146

Work Order Notes

(EHANNAH) officer states there is an oil leak

(EHOWELL) This vehicle was included in the recall group that Stivers came to headquarters over spring break. See attachment in M5.

Job Notes

06-40-433 - INSPECT OIL LEAK

(GARAGE) PULLED UNIT IN SHOP AND CHECKED FOR OIL LEAK. REMOVED SKID PAN AND FOUND FILTER WAS LOOSE. TIGHTENED FILTER AND CLEANED OIL FROM UNIT. TOPPED OFF WITH OIL, OIL WAS 1.92 QUARTS LOW. RAN TO TEST AFTER AND FOUND NOTHING LEAKING. INSTALLED SKID PLATE AND RETURNED TO SERVICE CQ 1HR

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54192

USING DEPT NO:	507121	OPENED DATE:	03/27/2025 15:21:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/27/2025 15:24:52	METER 1 - M:	31378	METER 2 - H: 6369
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/28/2025 07:57:29	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	2714700	176835		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 54192

Work Order Notes

Job Notes

17-GA-005 - RECALL Scheduling and Preparation

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) STIVERS PERFORMED RECALL PM

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54282

USING DEPT NO:	507121	OPENED DATE:	04/02/2025 14:28:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/02/2025 14:30:10	METER 1 - M:	31441	METER 2 - H: 6369
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2025 12:59:27	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.00 0.00 0.00 0.00 0.00

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	2714700	176457		\$0.00
66-PM-PMA	PERFORM OIL CHANGE	2714700	176457		\$0.00
66-PM-PMA	PERFORM OIL CHANGE	2714700	176467		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54282

Work Order Notes

Job Notes

17-GA-005 - RECALL Scheduling and Preparation

(EHOWELL) Automotive Services opened a work order and documented repairs performed by Stivers Ford.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) STIVERS PERFORMED RECALL PM

(EHOWELL) They left the drain plug loose and a bunch of oil leaked out. We had to add 3 quarts of oil to the vehicle. They sent us an oil filter and six quarts of oil for us to use the next time this vehicle comes in for a PM.

Invoice # 180334

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54596

USING DEPT NO:	507121	OPENED DATE:	04/25/2025 07:21:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/28/2025 09:16:45	METER 1 - M:	31507	METER 2 - H: 6369
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/28/2025 13:08:17	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-02-065	INSPECT WINDOW SEAL STRIP	DON	N	N	GARAGE	0.00	\$0.00	\$9.12	\$0.00	\$9.12
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	N	N	GARAGE	0.00	\$0.00	\$26.60	\$0.00	\$26.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	35.72	5.00	40.72
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	8.87	3	\$26.60
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	8.87	(4)	(\$35.46)
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	8.87	4	\$35.46
06-02-065	INSPECT WINDOW SEAL STRIP	82180	ULTRA BLACK RTV	9.12	1	\$9.12
PARTS						35.72

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54596

Work Order Notes

(EHANNAH) pass side window is leaking- driver stated there was a puddle

Job Notes

06-02-065 - INSPECT WINDOW SEAL STRIP

(GARAGE) INSPECTED FOR CUSTOMER COMPLAINT OF WATER LEAKING IN THE CAB FROM THE PASSENGER SIDE WINDOW AREA. SPRAYED WITH WATER AND FOI WATER DRIPPING IN PASSENGER SIDE FLOOR WELL FROM THE GLOVE BOX. REMOVED PASSENGER SIDE WINDOW TRIM AND MOLDING AND PULLED DOWN HEAD LINER, FOUND WATER ENTERING FROM A PLASTIC GROMMET UNDER BLACK RAIL ON TOP OF THE VEHICLE. CLEANED AREA AND APPLIED BLACK RTV SILICONE AN LET DRY OVER THE WEEKEND. FIRST THING MONDAY MORNING SPRAYED WATER TO LEAKING AREA AND FOUND NO LEAK, INSTALLED ALL THAT WAS REMOVED AI RETURNED TO SERVICE. 2 HR CQ

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

(GARAGE) FOUND PUDDLE OF OIL UNDER VEHICLE WHEN MOVING VEHICLE. PULLED ON DRIVE ON RAMP AND CHECKED FOR OIL LEAK, FOUND OIL DRAIN PLUG WAS BACKED OUT WITH ONLY TWO THREADS HOLDING IT IN. CHECKED SEAL ON PLUG AND FOUND WAS GOOD, RAN PLUG UP FLUSH AND TORQUED PLUG TO 20 I LBS PER PRO DEMAND TORQUE SPECS. TOPPED OFF OIL AND FOUND IT TOOK THREE QUARTS. RAN AND FOUND NO OTHER LEAKS AT THIS TIME. RETURNED TO SERVICE. CQ

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54884

USING DEPT NO:	507121	OPENED DATE:	05/23/2025 12:51:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/30/2025 16:01:45	METER 1 - M:	31641	METER 2 - H: 6369
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/04/2025 08:58:26	IN-SERVICE DATE:	08/20/2020	
TECH SPEC NO:	20FORDEXPLINT	2020 Ford Interceptor Explorer		UNIT SERIAL NO:	1FM5K8AB9LGC15611	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-33-006	TRANSPORT IGNITION LOCK CYLINDEI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-33-006	REMOVE IGNITION LOCK CYLINDER	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$40.92	\$0.00	\$40.92
RY-33-006	REKEY IGNITION LOCK CYLINDER	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$119.03	\$119.03

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	40.92	124.03	164.95
--------------	-------------------	------	------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2319111		\$118.50
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2319111		(\$118.50)
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2319111		\$119.03
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2319111		(\$119.03)
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2319111		\$119.03
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					124.03

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	08984	ADHESIVE REMOVER	40.65	1	\$40.65
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	08984	ADHESIVE REMOVER	40.65	(1)	(\$40.65)
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	08984	ADHESIVE REMOVER	40.65	1	\$40.65
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.14	2	\$0.27
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.14	(2)	(\$0.27)
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.14	2	\$0.27
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.15	(1)	(\$0.15)
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.15	1	\$0.15
PARTS						40.92

Work Order Charge Detail

The University of Alabama

Report Printed: 07/07/2025 07:56:42 By User: GLOBETTI

UNIT NO: 243748 2020 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54884

Work Order Notes

(CWIGLEY) Prep For Sale.

Job Notes

16-33-006 - TRANSPORT IGNITION LOCK CYLINDER

(EKIMBREL) driver transported lock cylinders to vendor to be rekeyed.

25-33-006 - REMOVE IGNITION LOCK CYLINDER

(EHOWELL) tech removed lock cylinders to be rekeyed

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) CW PERFORMED PREP FOR SALE

RY-33-006 - REKEY IGNITION LOCK CYLINDER

(EHOWELL) A1 REKEYED LOCKS

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Jul 07 2025 07:56:42 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243748') //Q=