

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 34550

USING DEPT NO:	507121	OPENED DATE:	10/22/2019 11:31:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2019 15:30:09	METER 1 - M:	98	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2019 15:30:10	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-13	TRANSPORT BRAKES	DON	O	N	GARAGE	0.93	\$0.00	\$0.00	\$0.00	\$0.00
17-02-028	RECALL SEAT ADJUSTER	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-13-033	RECALL ABS MODULATOR	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.93	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
17-02-028	RECALL SEAT ADJUSTER	4910000	588552		\$0.00
				COMML	0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-13	TRANSPORT BRAKES	10208562	10/23/2019 07:34:35	10/23/2019 08:30:07	0.93	\$0.00
					LABOR	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 34550

## Work Order Notes

(LISAPATE) Take to Town and Country to complete Recalls for Anti lock brakes system module software update and mechanical seat recliner

## Job Notes

### **16-13 - TRANSPORT BRAKES**

(LISAPATE) Take to Town and Country by EK

### **17-02-028 - RECALL SEAT ADJUSTER**

(LISAPATE) Town and Country Performed recall 19C07. Vehicle is upfitted for police and has divider between front and rear seats. Removed divider to access front seats. Using force meter inspected front seats in directed positions. Both front seats pass inspection

### **17-13-033 - RECALL ABS MODULATOR**

(LISAPATE) Town and Country Performed campaign 19B12 Reprogrammed ABS module to latest calibration

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 35157

USING DEPT NO:	507121	OPENED DATE:	12/12/2019 07:13:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/17/2019 13:57:40	METER 1 - M:	1959	METER 2 - H: 370
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	12/17/2019 13:57:42	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.46	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$0.00	\$22.31	\$0.00	\$22.31

JOB COUNT: 2	WORK ORDER TOTAL:					0.86	0.00	22.31	0.00	22.31
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	12/12/2019 11:06:42	12/12/2019 11:34:11	0.46	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/12/2019 08:49:30	12/12/2019 09:13:30	0.40	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.88	6	\$17.28
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					PARTS	22.31

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 35157

## Work Order Notes

(LISAPATE) PM-Rotate tires

## Job Notes

### **31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LISAPATE) Rotated tires and relearned tire positions

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by JW

Coolant -34'

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 35449

USING DEPT NO:	507121	OPENED DATE:	01/21/2020 07:16:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/31/2020 08:41:34	METER 1 - M:	2989	METER 2 - H: 579
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	01/31/2020 08:41:35	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.58	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.84	\$0.00	\$22.73	\$0.00	\$22.73
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.92	0.00	22.73	0.00	22.73
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	01/21/2020 10:52:41	01/21/2020 11:27:29	0.58	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/21/2020 10:03:49	01/21/2020 10:28:17	0.41	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/21/2020 09:52:53	01/21/2020 10:19:00	0.44	\$0.00
CH-32-002	CHARGE BATTERY	10208562	01/22/2020 07:00:00	01/22/2020 07:30:00	0.50	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	22.73

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 35449

## Work Order Notes

(LISAPATE) PM-rotate tires

## Job Notes

### **31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LISAPATE) Rotated tires and relearned tire positions

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by JW/SH

Coolant -10'

### **CH-32-002 - CHARGE BATTERY**

(LISAPATE) Charged battery. Rechecked ok

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 35564

USING DEPT NO:	507121	OPENED DATE:	02/04/2020 07:30:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/06/2020 13:41:41	METER 1 - M:	3221	METER 2 - H: 622
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	02/06/2020 13:41:43	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$98.65	\$0.00	\$98.65
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.50	0.00	98.65	0.00	98.65
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11074414	02/05/2020 06:00:00	02/05/2020 06:30:00	0.50	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	97.81	1	\$97.81
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.42	2	\$0.84
					PARTS	98.65

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 35564

## Work Order Notes

(GARAGE) Battery dead. radio wont cut off

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) Installed new battery checked charging ok at 14.5 volts. SH  
Advised UAPD police radio is staying on causing battery to run down  
AB reset charging monitor

### **CH-32-002 - CHARGE BATTERY**

(LISAPATE) Charged battery still failed.



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 36007

USING DEPT NO:	507121	OPENED DATE:	03/12/2020 10:04:08	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	04/02/2020 14:41:31	METER 1 - M:	3221	METER 2 - H:	622				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2020 13:58:16	IN-SERVICE DATE:	03/01/2019						
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor			UNIT SERIAL NO:	1FM5K8AR5KGB28056					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$27.02	\$0.00	\$27.02

JOB COUNT: 3	WORK ORDER TOTAL:	1.31	0.00	27.02	0.00	27.02
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	168938		\$0.00
COMML					0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	10208562	04/02/2020 07:00:00	04/02/2020 08:00:00	1.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/03/2020 07:00:00	04/03/2020 07:18:36	0.31	\$0.00
LABOR						0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
PARTS						27.02

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 36007

## Work Order Notes

(LISAPATE) Take to Andrews to repair rear end damage. To be paid direct to Andrews by Safeway Insurance  
(IFALLS) PM

## Job Notes

### **16-71 - TRANSPORT BODY**

(IFALLS) EK performed transport

### **24-71 - REPAIR BODY**

(IFALLS) Safeway Auto Insurance paid Andrews Body Shop in full.

### **66-PM-PMA - PERFORM OIL CHANGE**

(IFALLS) AG performed pm

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 36685

USING DEPT NO:	507121	OPENED DATE:	06/03/2020 11:42:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/05/2020 09:48:33	METER 1 - M:	4005	METER 2 - H: 758
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/05/2020 10:32:02	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.22	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$0.00	\$22.73	\$0.00	\$22.73
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.11	\$0.00	\$3.55	\$0.00	\$3.55
PR-01	PROGRAM AIR CONDITIONING, HEAT, \	DON	O	N	GARAGE	0.71	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.23	0.00	26.28	0.00	26.28
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11901357	06/05/2020 09:01:33	06/05/2020 09:15:00	0.22	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	06/05/2020 08:20:55	06/05/2020 08:27:32	0.11	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/05/2020 08:10:07	06/05/2020 08:20:55	0.18	\$0.00
PR-01	PROGRAM AIR CONDITIONING, HEAT, VENT	11170580	06/04/2020 07:44:41	06/04/2020 08:27:25	0.71	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4068	FILTER- CABIN AIR	3.55	1	\$3.55
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	6	\$17.70
					PARTS	26.28

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 36685

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### **31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(EKIMBREL) AG rotated tires and relearned TPMS.

### **66-PM-PMA - PERFORM OIL CHANGE**

(EKIMBREL) JW/AG performed pm. Coolant -35

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(EKIMBREL) AG replaced cabin filter.

### **PR-01 - PROGRAM AIR CONDITIONING, HEAT, VENT**

(ABLACK) AB re programmed PCM, BCM, HVAC modules in order to activate coronavirus disinfectant mode.

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 37016

USING DEPT NO:	507121	OPENED DATE:	07/06/2020 07:33:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/07/2020 14:07:35	METER 1 - M:	4007	METER 2 - H: 758
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	07/08/2020 07:48:20	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.25	\$0.00	\$0.00	\$0.00	\$0.00
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.75	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
CH-32-002	CHARGE BATTERY	11074414	07/07/2020 06:00:00	07/07/2020 06:30:00	0.50	\$0.00
66-79-002	PERFORM SERVICE CALL	10208562	07/06/2020 14:02:15	07/06/2020 14:17:06	0.25	\$0.00
					LABOR	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 37016

## Work Order Notes

(LISAPATE) Service call to UAPD for a dead battery

## Job Notes

### **66-79-002 - PERFORM SERVICE CALL**

(LISAPATE) RC/EK completed service call jumped off and brought to the shop

### **CH-32-002 - CHARGE BATTERY**

(LISAPATE) SH Charged the battery rechecked ok  
Advised Capt Nabors radio does not cut off

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 37252

USING DEPT NO:	507121	OPENED DATE:	08/04/2020 14:41:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/05/2020 13:41:05	METER 1 - M:	4575	METER 2 - H: 863
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/06/2020 07:21:08	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-02-010	ADJUST MIRRORS	DON	O	N	GARAGE	0.20	\$0.00	\$0.00	\$0.00	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.89	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.09	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
01-02-010	ADJUST MIRRORS	11074414	08/05/2020 06:00:00	08/05/2020 06:12:00	0.20	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/04/2020 14:57:12	08/04/2020 15:50:49	0.89	\$0.00
					<b>LABOR</b>	<b>0.00</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	(1)	(\$5.03)
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	5.03	1	\$5.03
					<b>PARTS</b>	<b>0.00</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 37252

## Work Order Notes

(LISAPATE) PM-Rotate tires-Driver mirror assy is loose

## Job Notes

### **01-02-010 - ADJUST MIRRORS**

(LISAPATE) Adjusted and tightened driver side mirror assy

### **31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LISAPATE) Tire rotation was not needed at this time. AG

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) Did not drop oil at this time. Checked fluids, battery and tire pressures. Updated sticker

Coolant -35'

AG



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 37854

USING DEPT NO:	507121	OPENED DATE:	10/05/2020 07:32:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/05/2020 12:31:43	METER 1 - M:	5655	METER 2 - H: 1147
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/06/2020 07:20:41	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$100.33	\$41.72	\$0.00	\$142.05

JOB COUNT: 1	WORK ORDER TOTAL:	0.85	100.33	41.72	0.00	142.05
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/05/2020 07:37:34	10/05/2020 07:55:34	0.30	\$35.40
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/05/2020 07:37:34	10/05/2020 08:44:23	(1.11)	(\$131.41)
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/05/2020 07:37:34	10/05/2020 08:44:23	1.11	\$131.41
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/05/2020 07:38:27	10/05/2020 07:55:40	0.29	\$33.86
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/05/2020 07:37:16	10/05/2020 07:53:04	0.26	\$31.07
					<b>LABOR</b>	<b>100.33</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.83	1	\$6.83
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.34	1	\$8.34
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					<b>PARTS</b>	<b>41.72</b>

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI*

**UNIT NO:**                    **243198**                    **2019 FORD INTERCEPTOR**

**WORK ORDER NO:**                    **37854**

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(EKIMBREL) SH JW/AMG Performed PM. Coolant -34

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 38808

USING DEPT NO:	507121	OPENED DATE:	01/15/2021 15:36:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2021 13:54:48	METER 1 - M:	5655	METER 2 - H: 1147
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/20/2021 07:22:52	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.09	\$10.49	\$148.66	\$0.00	\$159.15
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:					1.09	128.49	148.66	0.00	277.15
--------------	-------------------	--	--	--	--	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11310047	01/15/2021 15:47:07	01/15/2021 15:52:27	0.09	\$10.49
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	01/19/2021 07:00:00	01/19/2021 08:00:00	1.00	\$118.00
					LABOR	128.49

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	01253	BATT TERM PROTECTOR, PAIR PK	1.94	1	\$1.94
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	146.72	1	\$146.72
					PARTS	148.66

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 38808

## Work Order Notes

(LISAPATE) Per driver battery keeps going dead

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) Battery tested bad. Alternator is charging. EH replaced battery.

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) AB reset battery monitoring system with scan too

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 38844

USING DEPT NO:	507121	OPENED DATE:	01/20/2021 10:41:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/21/2021 07:46:54	METER 1 - M:	6960	METER 2 - H: 1496
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/21/2021 12:53:23	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$47.20	\$34.92	\$0.00	\$82.12

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.40</b>	<b>47.20</b>	<b>34.92</b>	<b>0.00</b>	<b>82.12</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/20/2021 12:46:41	01/20/2021 13:10:41	0.40	\$47.20
					<b>LABOR</b>	<b>47.20</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
					<b>PARTS</b>	<b>34.92</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 38844

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/JAW

MILEAGE-6960

IDLE HRS-1496

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 39791

USING DEPT NO:	507121	OPENED DATE:	04/23/2021 12:28:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/26/2021 14:39:02	METER 1 - M:	9015	METER 2 - H: 1777
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2021 08:42:15	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$8.92	\$31.13	\$0.00	\$40.05

JOB COUNT: 1	WORK ORDER TOTAL:	0.08	8.92	31.13	0.00	40.05
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/23/2021 14:03:19	04/23/2021 14:07:51	0.08	\$8.92
					LABOR	8.92

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.58	1	\$4.58
					PARTS	31.13

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 39791

---

## Work Order Notes

(EKIMBREL) pm

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/EH

MILEAGE-9015

ENG HRS-2263

IDLE HRS-1777

---



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 40496

USING DEPT NO:	507121	OPENED DATE:	07/21/2021 10:13:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2021 10:00:02	METER 1 - M:	9917	METER 2 - H: 1897
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/22/2021 14:18:34	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$30.65	\$0.00	\$42.45
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$14.26	\$10.71	\$0.00	\$24.97

JOB COUNT: 2	WORK ORDER TOTAL:	0.22	26.06	41.36	0.00	67.42
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/21/2021 13:15:29	07/21/2021 13:15:45	0.00	(\$0.52)
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/21/2021 13:15:29	07/21/2021 13:15:45	0.00	\$0.52
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/21/2021 13:15:29	07/21/2021 13:21:29	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/21/2021 12:51:08	07/21/2021 12:58:23	0.12	\$14.26
					LABOR	26.06

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	11.97	1	\$11.97
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	8.85	1	\$8.85
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	9.83	1	\$9.83
					PARTS	41.36

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 40496

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has 2098 miles and 180hrs left before being due. Changed sticker. Checked fluids and tires. Coolant -34°. JAW  
MILEAGE-9917  
IDLE HRS-1897

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 41468

USING DEPT NO:	507121	OPENED DATE:	11/01/2021 08:42:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2021 08:14:45	METER 1 - M:	9917	METER 2 - H: 1897
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/04/2021 08:14:48	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.47	\$31.82	\$0.00	\$37.29
15-32-002	WARRANTY BATTERY	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.35	\$41.69	\$0.00	\$0.00	\$41.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.66	\$77.95	\$46.13	\$0.00	\$124.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.06	125.11	77.95	2.00	205.06
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-32-002	WARRANTY BATTERY	3307676	0840		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
15-32-002	WARRANTY BATTERY	11074414	11/04/2021 07:00:00	11/04/2021 07:12:00	(0.20)	(\$23.60)
15-32-002	WARRANTY BATTERY	11074414	11/04/2021 07:00:00	11/04/2021 07:12:00	0.20	\$23.60
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	11/01/2021 11:27:39	11/01/2021 11:48:51	0.35	\$41.69
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/01/2021 11:20:15	11/01/2021 11:23:02	0.05	\$5.47
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/01/2021 10:40:25	11/01/2021 11:20:03	0.66	\$77.95
LABOR						125.11

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.87	1	\$8.87
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19

# Work Order Charge Detail

PARTS	77.95
-------	-------

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 41468

## Work Order Notes

(CHANNELL) PM\ replace wipers

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

### **15-32-002 - WARRANTY BATTERY**

(EHOWELL) SH INSTALLED WARRANTY BATTERY. EH reset Battery Monitoring System using Ford scan tool.

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(SHARBIN) Rotated tires relearned tire positions and inspected brakes. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH Performed PM. Battery test shows a bad cell will need a battery.

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 42416

USING DEPT NO:	507121	OPENED DATE:	02/21/2022 07:51:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/21/2022 14:07:34	METER 1 - M:	12909	METER 2 - H: 2413
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2022 07:06:36	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.13	\$15.44	\$31.82	\$0.00	\$47.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.70	\$82.50	\$46.37	\$0.00	\$128.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.83	97.94	78.19	2.00	178.13
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11901357	02/21/2022 10:03:43	02/21/2022 10:11:34	0.13	\$15.44
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/21/2022 09:41:14	02/21/2022 10:03:27	0.37	\$43.69
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/21/2022 09:36:01	02/21/2022 09:55:45	0.33	\$38.81
LABOR						97.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	9.11	1	\$9.11
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
PARTS						78.19

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 42416

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) replaced front and rear wipers. AMG

### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 12909 hours: 3137 idle hours: 2413 Completed PM topside, Scott was bottomside. Completed checklist. AMG/SH

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 43352

USING DEPT NO:	507121	OPENED DATE:	05/23/2022 10:21:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/24/2022 08:57:41	METER 1 - M:	14181	METER 2 - H: 2622
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/25/2022 13:35:39	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$78.99	\$55.02	\$0.00	\$134.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.67	78.99	55.02	2.00	136.01
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/23/2022 15:13:26	05/23/2022 15:51:32	0.64	\$74.93
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/23/2022 15:23:17	05/23/2022 15:25:21	0.03	\$4.06
				LABOR		78.99

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.64	6	\$33.84
				PARTS		55.02



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 43352

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG

MILEAGE-14181

ENG HRS-3435

IDLE HRS-2622

### CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 44467

USING DEPT NO:	507121	OPENED DATE:	08/25/2022 14:05:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/26/2022 09:40:48	METER 1 - M:	15722	METER 2 - H: 2743
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/26/2022 13:52:36	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.44	\$32.39	\$0.00	\$37.83
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.38	44.38	32.39	5.00	81.77
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/25/2022 14:19:19	08/25/2022 14:39:07	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/25/2022 14:19:19	08/25/2022 14:19:19	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/25/2022 14:19:19	08/25/2022 14:19:19	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/25/2022 14:29:09	08/25/2022 14:29:09	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/25/2022 14:30:00	08/25/2022 14:32:46	0.05	\$5.44
LABOR						44.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
PARTS						32.39

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 44467

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1541 miles and has 121 hours on it. Checked fluids battery tire pressure and updated the oil change sticker. SH AMG JW

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 45109

USING DEPT NO:	507121	OPENED DATE:	10/28/2022 09:30:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/28/2022 15:19:53	METER 1 - M:	16306	METER 2 - H: 2829
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/31/2022 08:28:27	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-02-013	ADJUST FLOOR COVERINGS	DON	O	N	GARAGE	0.60	\$70.24	\$0.00	\$0.00	\$70.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.60	70.24	0.00	5.00	75.24
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
01-02-013	ADJUST FLOOR COVERINGS	11901357	10/28/2022 12:44:14	10/28/2022 13:19:57	0.60	\$70.24
LABOR						70.24

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 45109

## Work Order Notes

(LISAPATE) Passenger floor plastic floor covering is coming out was not reinstalled properly when light were put in

## Job Notes

### 01-02-013 - ADJUST FLOOR COVERINGS

(AGUERRA) miles: 16306 hours: 3735 idle hours: 2829 Adjusted floor covering, passenger side. AMG (1 hour)

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 45282

USING DEPT NO:	507121	OPENED DATE:	11/16/2022 09:29:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/18/2022 11:31:27	METER 1 - M:	16349	METER 2 - H: 2840
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/22/2022 08:17:15	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.37	\$66.77	\$0.00	\$82.14
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.02	\$2.56	\$30.32	\$0.00	\$32.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.15	17.93	97.09	5.00	120.02
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	11/17/2022 09:30:21	11/17/2022 09:31:39	0.02	\$2.56
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/17/2022 09:07:11	11/17/2022 09:15:00	0.13	\$15.37
				LABOR		17.93

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.36	1	\$8.36
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP68	CABIN FILTER	30.32	1	\$30.32
				PARTS		97.09

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 45282

---

## Work Order Notes

(LRUSHING) PM

---

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/GC Performed PM.

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(SHARBIN) Replaced the cabin air filter. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 46378

USING DEPT NO:	507121	OPENED DATE:	03/06/2023 10:56:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/07/2023 11:51:21	METER 1 - M:	19150	METER 2 - H: 2911
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/07/2023 13:19:20	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$46.68	\$79.11	\$0.00	\$125.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.40	46.68	79.11	5.00	130.79
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/06/2023 13:43:34	03/06/2023 14:07:18	0.40	\$46.68
					LABOR	46.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	3.66	1	\$3.66
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	19.05	1	\$19.05
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
					PARTS	79.11



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 46378

---

## Work Order Notes

(EHANNAH) pm- replace wipers

---

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 46763

USING DEPT NO:	507121	OPENED DATE:	04/19/2023 08:28:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/25/2023 07:52:57	METER 1 - M:	22284	METER 2 - H: 2911
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/26/2023 08:50:56	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
09-15	ALIGN STEERING	DON	O	N	GARAGE	2.05	\$242.00	\$0.00	\$0.00	\$242.00
10-22-003	SERVICE DIFFERENTIAL CARRIER	DON	O	N	GARAGE	0.54	\$64.28	\$0.00	\$0.00	\$64.28
10-27	SERVICE TRANSMISSION - MAIN, AUTC	DON	O	N	GARAGE	0.06	\$6.69	\$45.90	\$0.00	\$52.59
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.11	\$13.24	\$781.01	\$0.00	\$794.25
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.16	\$18.85	\$0.00	\$0.00	\$18.85
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.63	\$60.08	\$0.00	\$111.71
66-PM-PTU	PERFORM Power Transfer Unit Service	DON	P	N	GARAGE	1.79	\$211.38	\$32.11	\$0.00	\$243.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 8	WORK ORDER TOTAL:	5.15	608.07	919.10	5.00	1,532.17
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	04/24/2023 13:15:26	04/24/2023 13:22:10	0.11	\$13.24
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	04/24/2023 12:05:55	04/24/2023 12:05:55	0.00	\$0.00
09-15	ALIGN STEERING	11310047	04/21/2023 12:00:00	04/21/2023 13:44:14	1.74	\$204.99
09-15	ALIGN STEERING	11310047	04/21/2023 10:41:11	04/21/2023 11:00:00	0.31	\$37.01
66-79-003	PERFORM SAFETY INSPECTION	12052187	04/21/2023 08:14:23	04/21/2023 08:23:58	0.16	\$18.85
10-27	SERVICE TRANSMISSION - MAIN, AUTOMATIC	12052187	04/21/2023 08:10:46	04/21/2023 08:14:10	0.06	\$6.69
66-PM-PTU	PERFORM Power Transfer Unit Service	11310047	04/21/2023 07:01:10	04/21/2023 07:25:34	0.41	\$47.99
66-PM-PTU	PERFORM Power Transfer Unit Service	11310047	04/20/2023 15:32:46	04/20/2023 15:46:10	0.22	\$26.35
10-22-003	SERVICE DIFFERENTIAL CARRIER	11310047	04/20/2023 15:00:05	04/20/2023 15:32:46	0.54	\$64.28
66-PM-PTU	PERFORM Power Transfer Unit Service	11310047	04/20/2023 14:30:00	04/20/2023 15:00:05	0.50	\$59.16

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PTU	PERFORM Power Transfer Unit Service	11310047	04/20/2023 14:26:53	04/20/2023 14:26:53	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	04/19/2023 14:23:22	04/19/2023 14:23:22	0.00	\$0.00
66-PM-PTU	PERFORM Power Transfer Unit Service	11310047	04/19/2023 13:34:14	04/19/2023 14:03:00	0.48	\$56.57
66-PM-PTU	PERFORM Power Transfer Unit Service	11310047	04/19/2023 13:05:35	04/19/2023 13:16:25	0.18	\$21.31
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/19/2023 09:37:09	04/19/2023 10:03:24	0.44	\$51.63
					<b>LABOR</b>	<b>608.07</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	9.53	1	\$9.53
66-PM-PTU	PERFORM Power Transfer Unit Service	VV324	TRANS FLUID QT	7.63	7	\$53.44
66-PM-PTU	PERFORM Power Transfer Unit Service	VV831	HP 80W90 GEAR OIL GL5 QT	9.20	1	\$9.20
66-PM-PTU	PERFORM Power Transfer Unit Service	VV982	75W-140 LS SYN GEAR OIL QT	15.68	1	\$15.68
66-PM-PTU	PERFORM Power Transfer Unit Service	XL3	LIMITED SLIP ADDITIVE FORD	7.23	1	\$7.23
66-PM-PTU	PERFORM Power Transfer Unit Service	VV324	TRANS FLUID QT	7.63	(7)	(\$53.44)
66-PM-PTU	PERFORM Power Transfer Unit Service	VV324	TRANS FLUID QT	7.65	6	\$45.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.50	4	\$13.98
66-PM-PTU	PERFORM Power Transfer Unit Service	VV324	TRANS FLUID QT	7.65	(6)	(\$45.90)
10-27	SERVICE TRANSMISSION - MAIN, AUTOMATIC	VV324	TRANS FLUID QT	7.65	6	\$45.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.66	1	\$0.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.75	3	\$2.25
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	3	\$3.02
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000702	TIRE 245/55R18 FSTONE PURSUIT	190.28	4	\$761.10
					<b>PARTS</b>	<b>919.10</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 46763

## Work Order Notes

(EHANNAH) pm- replace wiper-do SI- power trans- 4 tires

## Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

03-51-038 - REPLACE NEW WIPER BLADES

09-15 - ALIGN STEERING

(EHOWELL) Performed 4 wheel alignment. EH

10-22-003 - SERVICE DIFFERENTIAL CARRIER

(EHOWELL) Extracted fluid from rear differential using the trans flush machine. Filled differential with fluid and additive. EH/JAW .7 HR

10-27 - SERVICE TRANSMISSION - MAIN, AUTOMATIC

(JWRIGHT) Serviced transmission. Filled with 5.5qts of fluid. Drove and got temp up to 186° and checked. Fluid is full. JAW,EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GRCOOK) Mounted and balanced all 4 new tires,-GC

Miles, 22,284

Idle Hours, 2,996

(GRCOOK) Performed mount and balance all 4 new tires-GC

Miles 22,284

Idle hours, 2,996

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. Tires worn below spec and got replaced. Brake pads 8mm all around. No other issues found. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/GC

MILEAGE-46763

66-PM-PTU - PERFORM Power Transfer Unit Service

(EHOWELL) Drained fluid from front differential. Removed vent tube on front differential and filled will fluid to spec. EH 1.5 HRS

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 47609

USING DEPT NO:	507121	OPENED DATE:	07/17/2023 07:15:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/20/2023 10:56:16	METER 1 - M:	25546	METER 2 - H: 2911
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/20/2023 13:18:17	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$9.01	\$61.82	\$0.00	\$70.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.08	9.01	61.82	5.00	75.83
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/17/2023 07:20:46	07/17/2023 07:25:21	0.08	\$9.01
					LABOR	9.01

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
					PARTS	61.82

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 47609

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM-GC&JW, SH on bottom, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

Miles, 25,546

Engine Hrs, 4,295

Idle Hrs, 3,142

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 48077

USING DEPT NO:	507121	OPENED DATE:	09/05/2023 07:07:00	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	09/05/2023 15:38:14	METER 1 - M:	28817	METER 2 - H:	3393				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2023 11:45:36	IN-SERVICE DATE:	03/01/2019						
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.05	\$5.31	\$34.15	\$0.00	\$39.46
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.37	\$64.34	\$0.00	\$87.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.24	28.68	98.49	5.00	132.17
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	09/05/2023 07:26:48	09/05/2023 07:29:30	0.05	\$5.31
66-PM-PMA	PERFORM OIL CHANGE	12201267	09/05/2023 07:14:55	09/05/2023 07:26:48	0.20	\$23.37
LABOR						28.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
PARTS						98.49

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 48077

## Work Order Notes

(EHANNAH) pm- driver request wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC,FC

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC&FC,SH,- Changed oil and oil filter, checked fluids, filters good, tires and tire and tire pressure.

Miles, 28,817

Idle Hrs, 3,393

Total Hrs, 4,637

### CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 48665

USING DEPT NO:	507121	OPENED DATE:	10/23/2023 07:09:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2023 14:47:01	METER 1 - M:	31967	METER 2 - H: 4958
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2023 07:14:15	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$33.79	\$64.16	\$0.00	\$97.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.29	33.79	64.16	5.00	102.95
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/23/2023 07:19:08	10/23/2023 07:36:19	0.29	\$33.79
					LABOR	33.79

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
					PARTS	64.16

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 48665

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 49228

USING DEPT NO:	507121	OPENED DATE:	12/12/2023 07:09:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/12/2023 14:56:50	METER 1 - M:	34936	METER 2 - H: 4958
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2023 09:32:27	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.32	\$37.40	\$221.08	\$0.00	\$258.48
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$12.06	\$64.16	\$0.00	\$76.22
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.42	49.46	285.24	5.00	339.70
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11310047	12/12/2023 07:57:54	12/12/2023 08:16:55	0.32	\$37.40
66-PM-PMA	PERFORM OIL CHANGE	11310047	12/12/2023 07:51:46	12/12/2023 07:57:54	0.10	\$12.06
LABOR						49.46

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	221.08	1	\$221.08
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
PARTS						285.24

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 49228

---

## Work Order Notes

(EHANNAH) pm

---

## Job Notes

### 03-32-002 - REPLACE NEW BATTERY

(EHOWELL) Installed a new battery and reset Battery Monitoring System. EH

### 66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) Top-EH/SH  
Bottom-FC

### CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 49602

USING DEPT NO:	507121	OPENED DATE:	01/29/2024 07:05:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/29/2024 11:48:36	METER 1 - M:	38061	METER 2 - H: 4958
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/05/2024 08:36:38	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.88	\$60.56	\$0.00	\$89.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.24	28.88	60.56	5.00	94.44
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/29/2024 07:25:35	01/29/2024 07:40:16	0.24	\$28.88
					LABOR	28.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
					PARTS	60.56

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 49602

## Work Order Notes

(EHANNAH) pm

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JW/SH Performed PM. SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 50043

USING DEPT NO:	507121	OPENED DATE:	03/04/2024 08:58:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/05/2024 07:46:18	METER 1 - M:	39724	METER 2 - H: 4958
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/05/2024 10:48:54	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.06	\$6.88	\$0.00	\$0.00	\$6.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.06	6.88	0.00	5.00	11.88
--------------	-------------------	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-021	INSTALL GPS SYSTEM	12201267	03/04/2024 09:36:37	03/04/2024 09:40:07	0.06	\$6.88
					LABOR	6.88

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 50043

## Work Order Notes

(EHANNAH) install GPS

## Job Notes

### 14-52-021 - INSTALL GPS SYSTEM

(GRCOOK) Installed GPS SN: 87U030240070 in unit 2475C-GC

CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 50668

USING DEPT NO:	507121	OPENED DATE:	04/24/2024 07:45:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/25/2024 11:49:49	METER 1 - M:	41139	METER 2 - H: 5969
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/29/2024 10:06:40	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$6.59	\$60.65	\$0.00	\$67.24
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.01	\$1.08	\$32.21	\$0.00	\$33.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.07	7.67	92.86	5.00	105.53
--------------	-------------------	------	------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	04/24/2024 09:33:52	04/24/2024 09:34:25	0.01	\$1.08
66-PM-PMA	PERFORM OIL CHANGE	12395904	04/24/2024 09:30:00	04/24/2024 09:33:21	0.06	\$6.59
66-PM-PMA	PERFORM OIL CHANGE	12395904	04/24/2024 09:17:46	04/24/2024 09:17:46	0.00	\$0.00
LABOR					7.67	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.67	6	\$34.02
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP68	CABIN FILTER	32.21	1	\$32.21
PARTS					92.86	

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 50668

---

## Work Order Notes

(EHANNAH) pm

---

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Perform oil changes FC

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(FCONTRER) replaced new cabin filter

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 51554

USING DEPT NO:	507121	OPENED DATE:	07/22/2024 08:09:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/23/2024 08:53:30	METER 1 - M:	45202	METER 2 - H: 5969
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/23/2024 10:13:41	IN-SERVICE DATE:	03/01/2019	
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.41	\$68.66	\$0.00	\$70.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.01	1.41	68.66	5.00	75.07
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/22/2024 15:20:48	07/22/2024 15:21:31	0.01	\$1.41
					LABOR	1.41

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
					PARTS	68.66

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 51554

## Work Order Notes

(EHANNAH) pm

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed FC

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 52770

USING DEPT NO:	507121	OPENED DATE:	11/11/2024 07:28:05	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	11/18/2024 09:34:09	METER 1 - M:	48672	METER 2 - H:	5969		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/18/2024 10:41:33	IN-SERVICE DATE:	03/01/2019				
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-010	REPLACE NEW TAG LIGHT	DON	P	N	GARAGE	0.00	\$0.00	\$0.39	\$0.00	\$0.39
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$34.15	\$0.00	\$34.15
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$813.72	\$0.00	\$813.72
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$63.86	\$0.00	\$63.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7	WORK ORDER TOTAL:	0.00	0.00	912.12	5.00	917.12
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000702	TIRE 245/55R18 FSTONE PURSUIT	200.09	4	\$800.34
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.35	4	\$13.38
03-34-010	REPLACE NEW TAG LIGHT	194	BULB-TAG/MARKER	0.39	1	\$0.39
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
					PARTS	912.12

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 52770

## Work Order Notes

(EHANNAH) pm- SI

## Job Notes

### **03-34-010 - REPLACE NEW TAG LIGHT**

(GARAGE) JR- replaced passenger side tag light

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) JR- replaced wiper blades

### **66-17-013 - PERFORM ALIGNMENT**

(GARAGE) performed alignment checked ok, cm 47160 miles

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) JR-mounted and balanced tires

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) JR-performed SI, 4 new tires

(GARAGE) performed

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures  
47160 miles 4857 idle hours, 6888 total hours

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 53887

USING DEPT NO:	507121	OPENED DATE:	02/26/2025 08:38:50	LOCATION:	GARAGE - University Automotive Services					
WO STATUS:	CLOSED	COMPLETED DATE:	03/19/2025 07:01:36	METER 1 - M:	48413	METER 2 - H:	5969			
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/19/2025 07:01:36	IN-SERVICE DATE:	03/01/2019					
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor			UNIT SERIAL NO:	1FM5K8AR5KGB28056				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI*

**UNIT NO:**                    **243198**                    **2019 FORD INTERCEPTOR**

**WORK ORDER NO:**                    **53887**

---

## Work Order Notes

(CWIGLEY) PM

(EHOWELL) This vehicle was supposed to be service over Spring Break by Stiver's Ford.

---

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

---



# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 54285

<b>USING DEPT NO:</b>	507121	<b>OPENED DATE:</b>	04/02/2025 14:40:14	<b>LOCATION:</b>	GARAGE - University Automotive Services					
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	04/02/2025 14:49:01	<b>METER 1 - M:</b>	48413	<b>METER 2 - H:</b>	5969			
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	04/03/2025 12:57:45	<b>IN-SERVICE DATE:</b>	03/01/2019					
<b>TECH SPEC NO:</b>	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		<b>UNIT SERIAL NO:</b>	1FM5K8AR5KGB28056					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 2</b>	<b>WORK ORDER TOTAL:</b>					<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	2714700	176443		\$0.00
<b>COMML</b>					<b>0.00</b>

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI*

**UNIT NO:**                243198                2019 FORD INTERCEPTOR

**WORK ORDER NO:**        54285

---

## Work Order Notes

### Job Notes

17-GA-005 - RECALL Scheduling and Preparation

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) STIVERS PERFORMED RECALL PM

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 56133

USING DEPT NO:	507121	OPENED DATE:	08/28/2025 11:29:49	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	09/04/2025 15:51:46	METER 1 - M:	48488	METER 2 - H:	5969		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/05/2025 08:28:18	IN-SERVICE DATE:	03/01/2019				
TECH SPEC NO:	19FORDEXPINTR	2019 Ford Explorer Police Interceptor		UNIT SERIAL NO:	1FM5K8AR5KGB28056				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-44-042	REPLACE NEW FUEL INJECTOR PIGTA	DON	N	N	GARAGE	0.00	\$0.00	\$7.44	\$0.00	\$7.44
16-33-006	TRANSPORT IGNITION LOCK CYLINDEI	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
24-33-012	REPAIR WIRING HARNESS	DON	N	N	GARAGE	0.00	\$0.00	\$62.30	\$0.00	\$62.30
25-33-006	REMOVE IGNITION LOCK CYLINDER	DON	5	N	GARAGE	2.53	\$315.94	\$0.00	\$0.00	\$315.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.37	\$45.97	\$0.00	\$0.00	\$45.97
RY-33-006	REKEY IGNITION LOCK CYLINDER	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$122.59	\$122.59
SO-00	SCAN OUT COMPLETE VEHICLE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 8	WORK ORDER TOTAL:	2.90	361.91	69.74	127.59	559.24
--------------	-------------------	------	--------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2321097		\$122.59
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2321097		(\$122.59)
RY-33-006	REKEY IGNITION LOCK CYLINDER	11111231	2321097		\$122.59
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					127.59

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12051004	08/29/2025 10:11:47	08/29/2025 10:33:10	0.36	\$44.55
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12051004	08/29/2025 11:20:32	08/29/2025 11:21:13	0.01	\$1.42
25-33-006	REMOVE IGNITION LOCK CYLINDER	12051004	08/29/2025 11:21:13	08/29/2025 12:00:00	(0.65)	(\$80.80)
25-33-006	REMOVE IGNITION LOCK CYLINDER	12051004	08/29/2025 11:21:13	08/29/2025 12:00:00	0.65	\$80.80
25-33-006	REMOVE IGNITION LOCK CYLINDER	12051004	08/29/2025 11:21:13	08/29/2025 12:00:00	0.65	\$80.80
25-33-006	REMOVE IGNITION LOCK CYLINDER	12051004	09/02/2025 07:03:14	09/02/2025 08:56:06	(1.88)	(\$235.14)
25-33-006	REMOVE IGNITION LOCK CYLINDER	12051004	09/02/2025 07:03:14	09/02/2025 08:56:06	1.88	\$235.14
25-33-006	REMOVE IGNITION LOCK CYLINDER	12051004	09/02/2025 07:03:14	09/02/2025 08:56:06	1.88	\$235.14

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
					<b>LABOR</b>	<b>361.91</b>
<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-44-042	REPLACE NEW FUEL INJECTOR PIGTAILS	PIC5714PT	FUEL INJECTOR PIGTAIL	7.44	1	\$7.44
24-33-012	REPAIR WIRING HARNESS	STIS2820	COIL PIGTAIL	62.30	1	\$62.30
					<b>PARTS</b>	<b>69.74</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 09/15/2025 09:01:40 By User: GLOBETTI

UNIT NO: 243198 2019 FORD INTERCEPTOR

WORK ORDER NO: 56133

## Work Order Notes

(CWIGLEY) PM. SI Inspection

## Job Notes

### **03-44-042 - REPLACE NEW FUEL INJECTOR PIGTAILS**

(GARAGE) replaced damaged fuel injector pigtail cm .25 labor,

### **16-33-006 - TRANSPORT IGNITION LOCK CYLINDER**

(EHOWELL) RC & CW- took lock cylinders to get rekeyed

We're only charging .25 hours for the transport because another set of UAPD lock cylinders was taken with these. (Work order #56144)

### **24-33-012 - REPAIR WIRING HARNESS**

(GARAGE) repaired damaged wiring harness going to cylinders 4 and 5, replaced pigtail going to cylinder 6 test ran unit checked ok, rescan unit faults were inactive cm unit checked ok, .75 labor

### **25-33-006 - REMOVE IGNITION LOCK CYLINDER**

(EHOWELL) JR- removed both door locks, the truck lock, and the ignition lock cylinders, ready to be taken to get re-keyed

The lock cylinders were installed after they were rekeyed.

### **25-52-021 - REMOVE GPS SYSTEM**

### **66-79-003 - PERFORM SAFETY INSPECTION**

### **66-PM-PMA - PERFORM OIL CHANGE**

### **CH-SP - CHARGE Shop Supplies**

### **PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) JR- prepped vehicle for sale, no gps

### **RY-33-006 - REKEY IGNITION LOCK CYLINDER**

(GARAGE) A-1 rekeyed lock cylinders

### **SO-00 - SCAN OUT COMPLETE VEHICLE**

(GARAGE) cm scan out vehicle unit had faults for open coil circuits, and cylinder miss fire, further checks found rat had damaged wiring harness going too 3 different coils and fuel injector

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Mon Sep 15 2025 09:01:40 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '243198') //Q=