

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 40462

USING DEPT NO:	507121	OPENED DATE:	07/16/2021 11:07:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/16/2021 11:09:31	METER 1 - M:	163	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/19/2021 13:27:01	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	118.00	0.00	0.00	118.00
--------------	-------------------	------	--------	------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	12052187	07/16/2021 11:09:12	07/16/2021 12:09:12	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 40462

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) JW completed PDI

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 40794

USING DEPT NO:	507121	OPENED DATE:	08/20/2021 08:46:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/24/2021 08:00:04	METER 1 - M:	164	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/24/2021 08:00:08	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$115.00	\$115.00
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	115.00	174.00
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
14-78-028	INSTALL WINDOW TINT	8616313	1241		\$115.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					115.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	11915538	08/23/2021 07:00:00	08/23/2021 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 40794

Work Order Notes

(LISAPATE) Per Rusty Romine tint both front windows to match the rear

Job Notes

14-78-028 - INSTALL WINDOW TINT

(LISAPATE) Custom Films tinted both front windows and did a windshield strip . Pd by CC

16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(LISAPATE) Taken to Custom Films by RC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 41962

USING DEPT NO:	507121	OPENED DATE:	01/05/2022 07:24:45	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	02/22/2022 07:30:34	METER 1 - M:	3275	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2022 07:30:37	IN-SERVICE DATE:	07/16/2021						
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4									
			UNIT SERIAL NO:	1GNSKNKD0MR337048							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-02-016	WARRANTY TAIL&LIFT GATE	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
15-05	WARRANTY ELECTRONIC ENGINE EEC	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-05	TRANSPORT ELECTRONIC ENGINE EE	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.00	236.00	0.00	2.00	238.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-02-016	WARRANTY TAIL&LIFT GATE	4244121	179147		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	02/22/2022 07:00:00	02/22/2022 08:00:00	1.00	\$118.00
16-05	TRANSPORT ELECTRONIC ENGINE EEC SYSTEM	11915538	02/21/2022 07:00:00	02/21/2022 08:00:00	1.00	\$118.00
LABOR						236.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 41962

Work Order Notes

(LISAPATE) Per Kirsch there is a message on display says Service safety restraint system and power liftgate is not working

Job Notes

15-02-016 - WARRANTY TAIL&LIFT GATE

(LISAPATE) This repair was fixed when roof console was replaced

15-05 - WARRANTY ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Premiere installed new roof console

(IFALLS) Part was delayed for 6-8 weeks and had to come from the manufacture.

16-05 - TRANSPORT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Taken to Premiere by RC/CW

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) EH scanned out before sending unit to the dealer

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 42469

USING DEPT NO:	507121	OPENED DATE:	02/24/2022 14:13:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/25/2022 13:38:22	METER 1 - M:	3413	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/28/2022 08:33:02	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$39.89	\$44.36	\$0.00	\$84.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.34	39.89	44.36	2.00	86.25
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/24/2022 14:30:00	02/24/2022 14:35:17	0.09	\$10.39
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/24/2022 14:21:22	02/24/2022 14:36:22	0.25	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/24/2022 14:21:22	02/24/2022 14:21:22	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/24/2022 14:21:22	02/24/2022 14:21:22	0.00	\$0.00
				LABOR		39.89

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.48	1	\$8.48
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	8	\$35.88
				PARTS		44.36

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 42469

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG

MILEAGE-3413

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 44061

USING DEPT NO:	507121	OPENED DATE:	07/25/2022 12:04:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/27/2022 10:04:28	METER 1 - M:	6068	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/27/2022 13:13:34	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$47.54	\$0.00	\$86.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.33	38.94	47.54	2.00	88.48
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/25/2022 12:15:48	07/25/2022 12:15:48	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/25/2022 12:15:48	07/25/2022 12:15:48	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/25/2022 12:15:48	07/25/2022 12:35:36	0.33	\$38.94
				LABOR		38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.66	1	\$11.66
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	8	\$35.88
					PARTS	47.54

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 44061

Work Order Notes

(EKIMBREL) PM
(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. SH/JAW
MILEAGE-6068

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 44970

USING DEPT NO:	507121	OPENED DATE:	10/13/2022 07:25:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/14/2022 14:06:18	METER 1 - M:	10263	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2022 08:23:20	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.35	\$54.06	\$0.00	\$92.41
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.33	38.35	54.06	5.00	97.41
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/13/2022 13:12:05	10/13/2022 13:30:12	0.30	\$35.63
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/13/2022 11:17:48	10/13/2022 11:19:11	0.02	\$2.72
				LABOR		38.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	8	\$46.20
					PARTS	54.06

Work Order Charge Detail

UNIT NO:	244118	2021 CHEVROLET TAHOE	WORK ORDER NO:	44970
----------	--------	----------------------	----------------	-------

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 46600

USING DEPT NO:	507121	OPENED DATE:	04/04/2023 07:16:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/07/2023 07:43:23	METER 1 - M:	13666	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/07/2023 14:38:39	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$29.12	\$0.00	\$52.72
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$55.80	\$0.00	\$94.74
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.53	62.54	84.92	5.00	152.46
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
	COMML				5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12052187	04/04/2023 12:40:39	04/04/2023 12:40:39	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/04/2023 12:37:30	04/04/2023 12:49:30	0.20	\$23.60
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/04/2023 12:37:30	04/04/2023 12:37:30	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/04/2023 12:37:30	04/04/2023 12:37:30	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/04/2023 12:27:12	04/04/2023 12:47:00	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/04/2023 12:27:12	04/04/2023 12:27:12	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/04/2023 12:27:12	04/04/2023 12:27:12	0.00	\$0.00
	LABOR					62.54

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.65	2	\$21.30
03-51-038	REPLACE NEW WIPER BLADES	11-1	11" WIPER	7.82	1	\$7.82
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	8	\$50.04
	PARTS					84.92

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 46600

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,CW/GC
MILEAGE-13666

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(JWRIGHT) Do not wash UAPD

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 48033

USING DEPT NO:	507121	OPENED DATE:	08/29/2023 13:21:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/31/2023 07:59:38	METER 1 - M:	17589	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/31/2023 09:51:02	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$76.79	\$0.00	\$115.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.33	38.94	76.79	5.00	120.73
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	08/31/2023 07:00:00	08/31/2023 07:19:48	0.33	\$38.94
					LABOR	38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	8	\$50.16
					PARTS	76.79

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 48033

Work Order Notes

(LRUSHING) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 49576

USING DEPT NO:	507121	OPENED DATE:	01/25/2024 08:27:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/29/2024 09:30:15	METER 1 - M:	18832	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/29/2024 11:34:41	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.39	\$0.00	\$0.00	\$28.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.24	28.39	0.00	5.00	33.39
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/25/2024 15:00:26	01/25/2024 15:14:52	0.24	\$28.39
					LABOR	28.39

Work Order Charge Detail

UNIT NO:	244118	2021 CHEVROLET TAHOE	WORK ORDER NO:	49576
----------	--------	----------------------	----------------	-------

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 50383

USING DEPT NO:	507121	OPENED DATE:	04/02/2024 08:45:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/03/2024 10:57:26	METER 1 - M:	18902	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2024 11:38:07	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.37	\$43.20	\$0.00	\$0.00	\$43.20
CH-SP	CHARGE Shop Supplies	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.37	43.20	0.00	5.00	48.20
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-021	INSTALL GPS SYSTEM	12201267	04/02/2024 09:48:59	04/02/2024 10:10:57	0.37	\$43.20
LABOR						43.20

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 50383

Work Order Notes

(EHANNAH) install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GRCOOK) Installed GPS SN: 87U030240172 in unit 9644B -GC

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 4/29/2024 10:21 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 51319

USING DEPT NO:	507121	OPENED DATE:	06/26/2024 10:55:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/27/2024 08:03:06	METER 1 - M:	19513	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/27/2024 08:38:37	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$22.50	\$0.00	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$0.98	\$69.32	\$0.00	\$70.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$0.82	\$0.00	\$0.00	\$0.82

JOB COUNT: 4	WORK ORDER TOTAL:	0.02	1.80	91.82	5.00	98.62
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	06/27/2024 07:51:06	06/27/2024 07:51:31	0.01	\$0.82
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/27/2024 07:27:22	06/27/2024 07:27:52	0.01	\$0.98
				LABOR		1.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	XC22	22" WIPER	11.25	2	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	8	\$55.80
				PARTS		91.82

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 51319

Work Order Notes

(EHANNAH) pm- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) sh replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 51870

USING DEPT NO:	507121	OPENED DATE:	08/19/2024 13:38:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/26/2024 14:24:58	METER 1 - M:	19806	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/26/2024 15:36:16	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$822.25	\$822.25
16-71	TRANSPORT BODY	DON	A	N	GARAGE	0.02	\$2.72	\$0.00	\$0.00	\$2.72
CH-SP	CHARGE Shop Supplies	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.02	2.72	0.00	827.25	829.97
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	2-121018		\$822.25
03-02-061	REPLACE NEW WINDSHIELD	11078716	2-121018		(\$822.25)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2-1211018		(\$822.25)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2-1211018		\$822.25
03-02-061	REPLACE NEW WINDSHIELD	11078716	2-1211018		(\$563.50)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2-1211018		\$563.50
03-02-061	REPLACE NEW WINDSHIELD	11078716	2-121018		\$822.25
					COMML
					827.25

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11399745	08/22/2024 10:25:33	08/22/2024 10:26:56	0.02	\$2.72
16-71	TRANSPORT BODY	11399745	08/22/2024 10:25:33	08/22/2024 10:26:56	(0.02)	(\$2.72)
16-71	TRANSPORT BODY	11399745	08/22/2024 10:25:33	08/22/2024 10:26:56	0.02	\$2.72
					LABOR	2.72

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 51870

Work Order Notes

(EHANNAH) transport to Glass Dr for replacement of the windshield

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(EKIMBREL) GLASS DR REPLACED WINDSHIELD

(LRUSHING) Visit Reason Changed On 8/27/2024 8:58 AM By LRUSHING

16-71 - TRANSPORT BODY

(GARAGE) Transported vehicle to Glass Doctor. CW/RC

(LRUSHING) Visit Reason Changed On 8/27/2024 8:58 AM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 8/27/2024 8:58 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 52916

USING DEPT NO:	507121	OPENED DATE:	11/26/2024 10:40:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/27/2024 09:26:00	METER 1 - M:	21087	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/27/2024 10:27:51	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$21.69	\$0.00	\$21.69
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$5.72	\$0.00	\$5.72
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$38.64	\$0.00	\$38.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	66.05	5.00	71.05
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	(1)	(\$12.32)
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	9.12	8	\$72.96
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC4211C	CABIN FILTER	38.64	1	\$38.64
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL QT	9.12	(8)	(\$72.96)
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2450	KEY FOB BATTERY	5.72	1	\$5.72
					PARTS	66.05

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 52916

Work Order Notes

(EHANNAH) PM- SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wipers-GC

03-51-042 - REPLACE NEW KEY FOB BATTERY

(EHOWELL) replaced key fob battery-GC

The battery was for our master key.

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) JR & GC- perform SI per SI sheet

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ-fluid check only, checked air filters, checked tires and tire pressures

21087 miles

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) JR- replaced cabin air filter

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 54372

USING DEPT NO:	507121	OPENED DATE:	04/07/2025 11:35:27	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	04/07/2025 11:41:08	METER 1 - M:	22471	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/09/2025 07:48:59	IN-SERVICE DATE:	07/16/2021						
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4									
				UNIT SERIAL NO:	1GNSKNKD0MR337048						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-79-009	INSPECT SEAT BELT(S)	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
06-79-009	INSPECT SEAT BELT(S)	2734953	6131634		\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 54372

Work Order Notes

Job Notes

06-79-009 - INSPECT SEAT BELT(S)

(EHOWELL) Donohoo Chevrolet came to the UA campus and performed recall #N222372380. They inspected both the left and right side third row seatbelt buckle assemblies.

17-GA-005 - RECALL Scheduling and Preparation

(EHOWELL) Automotive Services scheduled the recall and documented the performed repair.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 54573

USING DEPT NO:	507121	OPENED DATE:	04/23/2025 10:58:41	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	04/23/2025 15:11:06	METER 1 - M:	24098	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2025 07:19:33	IN-SERVICE DATE:	07/16/2021						
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4									
				UNIT SERIAL NO:	1GNSKNKD0MR337048						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-40	INSPECT ENGINE / MOTOR SYSTEMS	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$63.39	\$0.00	\$63.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	63.39	5.00	68.39
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	8	\$51.36
66-PM-PMA	PERFORM OIL CHANGE	PF63	FILTER-OIL	12.03	1	\$12.03
PARTS						63.39

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 54573

Work Order Notes

(EHANNAH) pm- inspect engine for jerking while going.

Job Notes

06-40 - INSPECT ENGINE / MOTOR SYSTEMS

(EKIMBREL) cm 24106 miles, checked over vehicle, test drove vehicle checked ok, test drove checked ok,

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC- top side, checked fluids, filters good, tires and tire pressure, filled with oil, reset oil life and installed oil change sticker.

FJ- drained oil and changed oil filter.

Miles, 24,098

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(EKIMBREL) scan out vehicle, vehicle had no active faults, and no stored faults, vehicle checked ok. CQ

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 54621

USING DEPT NO:	507121	OPENED DATE:	04/29/2025 07:58:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/29/2025 13:03:21	METER 1 - M:	24698	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/29/2025 13:24:04	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$12.93	\$0.00	\$12.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	12.93	5.00	17.93
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	SF16	SEA FOAM 16OZ	12.93	1	\$12.93
					PARTS	12.93

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 54621

Work Order Notes

(EHANNAH) Scan out- SI
(IFALLS) customer said vehicle surges at low speed

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) PERFORMED SI PER SAFETY INSPECTION SHEET, FOUND ALL TO CHECK OUT OK AT THIS TIME. BRAKE PADS 9MM ALL AROUND. CQ

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(GARAGE) PULLED VEHICLE IN SHOP AND CONNECTED TO SCAN TOOL, FOUND COE P0011 FOR INTAKE CAM POSITION PERFORMANCE. LOOKED UP BULLITENS FC CODES AND DRIVING SYMPTOMS, FOUND ALL IN SERVICE BULLITEN TO CHECK CHECKED OK. ROAD TESTED AND VEHICLE DROVE AND SHIFTED FINE, AND PASSE ALL MODULE SELF TESTS. ADDED ONE BOTTLE OF SEA FOAM TO GAS TANK. RETURNED TO SERVICE. 1HR SCAN , 0.5 HR ROAD TEST. CQ

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 55340

USING DEPT NO:	507121	OPENED DATE:	07/09/2025 13:57:46	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	07/11/2025 14:12:51	METER 1 - M:	24981	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2025 14:40:17	IN-SERVICE DATE:	07/16/2021						
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-02-053	INSPECT WINDOW REGULATOR	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
06-16	INSPECT SUSPENSION	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 55340

Work Order Notes

(EHANNAH) PF window is rolling down by itself- and there is a vibrating while driving

Job Notes

06-02-053 - INSPECT WINDOW REGULATOR

(GARAGE) hooked scan tool to vehicle found no codes related to the window regulator, could not get window to roll down by itself, test drove window never rolled down, cq 0.5 hr

06-16 - INSPECT SUSPENSION

(GARAGE) test drove vehicle and found no vibration, tahoe drove smooth, pulled in shop and checked suspension and found all to check in spec. cq 0.5 hr

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 55571

USING DEPT NO:	507121	OPENED DATE:	07/23/2025 11:25:30	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	08/11/2025 08:08:14	METER 1 - M:	25283	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/12/2025 07:27:19	IN-SERVICE DATE:	07/16/2021						
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4									
				UNIT SERIAL NO:	1GNSKNKD0MR337048						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CB-02-052	COME BACK WINDOW MOTOR	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PR-07	PROGRAM BODY CONTROL MODULE (DON	N	N	GARAGE	0.00	\$0.00	\$67.50	\$0.00	\$67.50

JOB COUNT: 3	WORK ORDER TOTAL:					0.00	0.00	67.50	5.00	72.50
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PR-07	PROGRAM BODY CONTROL MODULE (BCM)	VEHICLE PROGRAMMING S	A/C DELCO VEHICLE SOFTWARE	67.50	1	\$67.50
					PARTS	67.50

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 55571

Work Order Notes

(EHANNAH) Come back for Pass. window is rolling down on it's own.

Job Notes

06-02-052 - INSPECT WINDOW MOTOR

CB-02-052 - COME BACK WINDOW MOTOR

(GARAGE) customer complaint of passenger window rolling down. updated bcm software and using vehicle as a chase vehicle at the moment. cq 1.hr

CH-SP - CHARGE Shop Supplies

PR-07 - PROGRAM BODY CONTROL MODULE (BCM)

(EHOWELL) EH/CQ programmed the body control module. We verified the module calibrations, and there were later and greater calibrations available.

(EHOWELL) Someone came and picked up the vehicle from our facility without us knowing about it.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 56515

USING DEPT NO:	507121	OPENED DATE:	09/23/2025 15:23:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/24/2025 09:16:06	METER 1 - M:	25873	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2025 14:37:49	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$210.00	\$0.00	\$210.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	210.00	5.00	215.00
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	94RH7	BATTERY BCI 94R DIN H7 800 CCA	210.00	1	\$210.00
					PARTS	210.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 56515

Work Order Notes

(CWIGLEY) Officer said the vehicle will not do anything when he tries to start it. He even said that he tried to jump the vehicle off and still couldn't get it to start.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) FJ- Replaced battery
25,873 miles

66-79-002 - PERFORM SERVICE CALL

(GARAGE) FJ- Performed service call to customer's address for dead battery concern
25,873 miles

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 56730

USING DEPT NO:	507121	OPENED DATE:	10/08/2025 15:24:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/08/2025 15:37:15	METER 1 - M:	25924	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/09/2025 07:39:14	IN-SERVICE DATE:	07/16/2021	
TECH SPEC NO:	21CHEVTAHO4X4	2021 Chevrolet Tahoe 4X4		UNIT SERIAL NO:	1GNSKNKD0MR337048	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.50	\$75.00	\$0.00	\$0.00	\$75.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.50	75.00	0.00	5.00	80.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	10/08/2025 15:32:49	10/08/2025 15:36:20	0.06	\$8.79
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	10/08/2025 15:32:49	10/08/2025 15:36:20	(0.06)	(\$8.79)
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	10/08/2025 15:32:49	10/08/2025 16:02:49	0.50	\$75.00
				LABOR		75.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/10/2025 07:45:14 By User: GLOBETTI

UNIT NO: 244118 2021 CHEVROLET TAHOE

WORK ORDER NO: 56730

Work Order Notes

(EKIMBREL) PREP FOR SALE

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed tag \RC

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Oct 10 2025 07:45:14 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244118') //Q=