

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 41569

USING DEPT NO:	507121	OPENED DATE:	11/09/2021 15:34:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/09/2021 15:35:38	METER 1 - M:	115	METER 2 - H: 3
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/10/2021 07:53:37	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2 WORK ORDER TOTAL: 1.00 118.00 0.00 2.00 120.00

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	11/09/2021 15:35:14	11/09/2021 16:35:14	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 41569

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42422

USING DEPT NO:	507121	OPENED DATE:	02/21/2022 08:42:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/21/2022 14:04:15	METER 1 - M:	188	METER 2 - H: 3
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2022 07:09:04	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-02-013	INSTALL FLOOR COVERINGS	DON	O	N	GARAGE	0.15	\$17.70	\$178.76	\$0.00	\$196.46
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.22	\$0.00	\$0.00	\$22.22
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:		0.34	39.92	178.76	2.00	220.68
--------------	-------------------	--	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-02-013	INSTALL FLOOR COVERINGS	11399745	02/21/2022 12:32:15	02/21/2022 12:32:15	0.00	\$0.00
14-02-013	INSTALL FLOOR COVERINGS	11399745	02/21/2022 12:32:15	02/21/2022 12:32:15	0.00	\$0.00
14-02-013	INSTALL FLOOR COVERINGS	11399745	02/21/2022 12:32:15	02/21/2022 12:41:15	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/21/2022 11:08:08	02/21/2022 11:19:26	0.19	\$22.22
LABOR						39.92

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-02-013	INSTALL FLOOR COVERINGS	4415751	2021 FORD EXP FRONT FLOOR MATS	178.76	1	\$178.76
PARTS						178.76

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 42422

Work Order Notes

(LISAPATE) PM

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

(GARAGE) installed floormats. cw

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 188 miles and has 11 idle hours. Checked fluids battery tire pressure and updated oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43125

USING DEPT NO:	507121	OPENED DATE:	05/03/2022 14:42:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/05/2022 09:50:42	METER 1 - M:	199	METER 2 - H: 3
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/05/2022 12:54:39	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-02-027	REMOVE SEAT FRAMES & SPRINGS	DON	O	N	GARAGE	0.67	\$78.99	\$0.00	\$0.00	\$78.99
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.67	78.99	0.00	2.00	80.99
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
25-02-027	REMOVE SEAT FRAMES & SPRINGS	11074414	05/04/2022 13:00:58	05/04/2022 13:01:17	0.01	\$0.62
25-02-027	REMOVE SEAT FRAMES & SPRINGS	11074414	05/04/2022 10:48:35	05/04/2022 11:28:26	0.66	\$78.37
LABOR						78.99

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: **244401** **2021 FORD INTERCEPTOR EXPLORER**

WORK ORDER NO: **43125**

Work Order Notes

(LISAPATE) Remove rear seat assy. Per Kevin B

Job Notes

25-02-027 - REMOVE SEAT FRAMES & SPRINGS

(HHARBIN) SH JW Removed rear seats.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43382

USING DEPT NO:	507121	OPENED DATE:	05/24/2022 13:44:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/26/2022 10:51:51	METER 1 - M:	203	METER 2 - H: 12
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/27/2022 15:00:54	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$68.08	\$52.20	\$0.00	\$120.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.58 68.08 52.20 2.00 122.28

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/25/2022 09:01:34	05/25/2022 09:02:36	0.02	\$2.03
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/25/2022 08:52:50	05/25/2022 09:05:19	0.21	\$24.55
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/25/2022 09:03:21	05/25/2022 09:05:32	0.04	\$4.29
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/25/2022 08:21:36	05/25/2022 08:40:31	0.32	\$37.20
LABOR						68.07

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.89	1	\$7.89
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.64	6	\$33.84
PARTS						52.20

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43382

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 203 hours: 20 idle hours: 12

(AGUERRA) Completed PM topside, Scott was bottomside. Completed checklist. AMG/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43458

USING DEPT NO:	507121	OPENED DATE:	06/01/2022 08:29:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2022 11:05:49	METER 1 - M:	374	METER 2 - H: 12
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/03/2022 12:56:28	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$115.00	\$115.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	0.00	117.00	117.00
--------------	-------------------	--	--	--	--	------	------	------	--------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
14-78-028	INSTALL WINDOW TINT	8616313	1597		\$115.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					117.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 43458

Work Order Notes

(LISAPATE) Barrett will take his K-9 unit to Custom Films to have 2 front windows and a windshield strip installed while waiting.

Job Notes

14-78-028 - INSTALL WINDOW TINT

(LISAPATE) Custom Films completed tint on both front windows and a windshield strip. Pd by CC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44079

USING DEPT NO:	507121	OPENED DATE:	07/26/2022 14:41:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/28/2022 15:37:51	METER 1 - M:	3405	METER 2 - H: 316
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/29/2022 09:18:09	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.98	\$115.35	\$46.58	\$0.00	\$161.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.98	115.35	46.58	2.00	163.93
--------------	-------------------	--	--	--	--	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/26/2022 14:51:03	07/26/2022 15:34:40	0.73	\$85.78
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/26/2022 14:52:41	07/26/2022 15:07:43	0.25	\$29.57
LABOR						115.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.66	1	\$11.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.82	6	\$34.92
PARTS						46.58

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 44079

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH/JW Performed PM.

(LISAPATE) removed skid plate

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45011

USING DEPT NO:	507121	OPENED DATE:	10/17/2022 14:17:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/19/2022 07:31:08	METER 1 - M:	5731	METER 2 - H: 633
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/19/2022 09:51:36	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	0.10	\$11.57	\$0.00	\$0.00	\$11.57
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.32	\$43.40	\$0.00	\$71.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.34	39.89	43.40	5.00	88.29
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11915538	10/17/2022 15:35:36	10/17/2022 15:41:29	0.10	\$11.57
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/17/2022 14:30:00	10/17/2022 14:44:24	0.24	\$28.32
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/17/2022 14:25:41	10/17/2022 14:25:41	0.00	\$0.00
LABOR						39.89

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.96	1	\$5.96
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
PARTS						43.40

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45011

Work Order Notes

(LISAPATE) PM-remove wordmarks from both sides of rear bumper

Job Notes

25-53-006 - REMOVE WORDMARKS/IDENTIFIERS

(CHANNELL) removed identifiers RC
JAW

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 5731 hours: 780 idle hours: 633 Completed PM topside, Scott was bottomside. AMG/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45820

USING DEPT NO:	507121	OPENED DATE:	01/18/2023 09:42:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2023 11:02:32	METER 1 - M:	7978	METER 2 - H: 932
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2023 15:38:54	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.83	\$32.73	\$0.00	\$44.56
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$38.12	\$56.72	\$0.00	\$94.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.42	49.95	89.45	5.00	144.40
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/18/2023 10:20:15	01/18/2023 10:39:38	0.32	\$38.12
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/18/2023 10:13:53	01/18/2023 10:19:54	0.10	\$11.83
LABOR						49.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	6.08	1	\$6.08
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.47	1	\$9.47
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
PARTS						89.45

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 45820

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 7978 hours: 1142 idle hours: 932 Completed PM topside, Josh was bottomside. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46585

USING DEPT NO:	507121	OPENED DATE:	04/03/2023 08:47:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/03/2023 15:43:25	METER 1 - M:	10636	METER 2 - H: 1302
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/04/2023 07:18:55	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$31.50	\$56.40	\$0.00	\$87.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.27	31.50	56.40	5.00	92.90
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/03/2023 08:56:28	04/03/2023 09:12:29	0.27	\$31.50
LABOR						31.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
PARTS						56.40

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 46585

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47556

USING DEPT NO:	507121	OPENED DATE:	07/10/2023 08:39:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/11/2023 09:09:21	METER 1 - M:	13498	METER 2 - H: 1668
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2023 10:49:17	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$61.91	\$0.00	\$100.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.33	38.94	61.91	5.00	105.85
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/10/2023 09:15:38	07/10/2023 09:15:38	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/10/2023 09:15:38	07/10/2023 09:15:38	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/10/2023 09:15:38	07/10/2023 09:35:26	0.33	\$38.94
LABOR						38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
PARTS						61.91

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 47556

Work Order Notes

(EHANNAH) pm- replace wiper - wash
(EKIMBREL) DID NOT NEED WIPERS YET

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM- CW,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 13,498
Engine Hrs, 2,040
Idle Hrs, 1,668

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48701

USING DEPT NO:	507121	OPENED DATE:	10/25/2023 07:44:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/26/2023 09:45:58	METER 1 - M:	15961	METER 2 - H: 2063
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/26/2023 13:27:43	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$31.57	\$64.16	\$0.00	\$95.73
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.27	31.57	64.16	5.00	100.73
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/25/2023 07:55:33	10/25/2023 08:11:36	0.27	\$31.57
					LABOR	31.57

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
					PARTS	64.16

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 48701

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Washed SH

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 49492

USING DEPT NO:	507121	OPENED DATE:	01/18/2024 12:56:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/22/2024 15:07:01	METER 1 - M:	18688	METER 2 - H: 2416
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/23/2024 07:52:39	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$31.20	\$60.56	\$0.00	\$91.76
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.26	31.20	60.56	5.00	96.76
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/18/2024 13:28:07	01/18/2024 13:43:59	0.26	\$31.20
LABOR						31.20

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
PARTS						60.56

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 49492

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes FC - sh

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50332

USING DEPT NO:	507121	OPENED DATE:	03/28/2024 07:29:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/29/2024 08:52:19	METER 1 - M:	20876	METER 2 - H: 2724
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/29/2024 10:02:24	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.12	\$13.70	\$34.15	\$0.00	\$47.85
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.37	\$43.92	\$0.00	\$0.00	\$43.92
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$41.23	\$52.80	\$0.00	\$94.03
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.84	98.85	86.95	5.00	190.80
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	03/28/2024 08:26:01	03/28/2024 08:32:59	0.12	\$13.70
14-52-021	INSTALL GPS SYSTEM	12201267	03/28/2024 08:03:29	03/28/2024 08:25:49	0.37	\$43.92
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/28/2024 07:42:18	03/28/2024 08:03:16	0.35	\$41.23
				LABOR		98.85

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
				PARTS		86.95

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50332

Work Order Notes

(EHANNAH) pm- wipers- install GPS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

14-52-021 - INSTALL GPS SYSTEM

(GRCOOK) Installed GPS SN: 87U030240067 in unit 3876C -GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC,SH, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

(GARAGE) Miles, 20,876

Idle Hours, 2,724

Total Hours, 3,311

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 50444

USING DEPT NO:	507121	OPENED DATE:	04/05/2024 11:10:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/05/2024 13:31:50	METER 1 - M:	21180	METER 2 - H: 2759
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/05/2024 14:20:45	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-78-038	INSPECT UNDER CARRIAGE SKID PLAT	DON	N	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.15	17.70	0.00	5.00	22.70
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-78-038	INSPECT UNDER CARRIAGE SKID PLATES	11074414	04/05/2024 11:18:01	04/05/2024 11:27:01	0.15	\$17.70
LABOR						17.70

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 50444

Work Order Notes

(LRUSHING) inspect skid plate it is dragging

Job Notes

06-78-038 - INSPECT UNDER CARRIAGE SKID PLATES

(GARAGE) Officer had to go off the road at the Arboretum while meeting a vehicle and tore the plastic skid plate loose. Added some washers to the screws and secured the skid plate. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51038

USING DEPT NO:	507121	OPENED DATE:	06/05/2024 12:56:26	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2024 10:42:49	METER 1 - M:	22994	METER 2 - H:	2759				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2024 11:15:59	IN-SERVICE DATE:	11/09/2021						
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-GA-005	RECALL Scheduling and Preparation	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
24-22-014	REPAIR REAR AXLE BEARING	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER

WORK ORDER NO: 51038

Work Order Notes

(EHANNAH) prep and schedule- RECALL for rear axle bolt

Job Notes

17-GA-005 - RECALL Scheduling and Preparation

(EHANNAH) prep and scheduling by Denise.

24-22-014 - REPAIR REAR AXLE BEARING

(EHANNAH) LL Ford came to our shop for Recall for rear axle bolt.

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51101

USING DEPT NO:	507121	OPENED DATE:	06/10/2024 07:56:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/10/2024 09:00:09	METER 1 - M:	23633	METER 2 - H: 3028
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/10/2024 10:11:35	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$2.92	\$76.31	\$0.00	\$79.23
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.02	2.92	76.31	5.00	84.23
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	06/10/2024 08:51:04	06/10/2024 08:52:33	0.02	\$2.92
LABOR						2.92

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
PARTS						76.31

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51101

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC,FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure, add 1/2 hour for skid pan.

Miles, 23,633

Idle Hours, 3,028

Total Hours, 3,697

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51954

USING DEPT NO:	507121	OPENED DATE:	08/28/2024 07:51:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/28/2024 15:06:57	METER 1 - M:	25812	METER 2 - H: 3255
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/29/2024 08:43:44	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$68.75	\$0.00	\$68.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	68.75	5.00	73.75
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.02	6	\$42.12
PARTS						68.75

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 51954

Work Order Notes

(LRUSHING) Pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) PERFORMED PM CM CHANGED MOTOR OIL AND FILTER, CHECKED ALL FLUIDS CHECKED OKK

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52393

USING DEPT NO:	507121	OPENED DATE:	10/07/2024 07:48:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/07/2024 15:28:21	METER 1 - M:	27431	METER 2 - H: 3255
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/14/2024 10:36:12	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-42-006	INSPECT THERMOSTATS	DON	N	N	GARAGE	0.00	\$0.00	\$25.26	\$0.00	\$25.26
15-42-004	WARRANTY WATER PUMP	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42-004	TRANSPORT WATER PUMP	DON	W	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	25.26	5.00	30.26
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
15-42-004	WARRANTY WATER PUMP	11078175	131030		\$0.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
06-42-006	INSPECT THERMOSTATS	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	25.26	1	\$25.26
PARTS						25.26

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52393

Work Order Notes

(EHANNAH) inspect thermostat

Job Notes

06-42-006 - INSPECT THERMOSTATS

(GARAGE) CHECKED OVER VEHICLE, FOUND COOLANT WAS LOW ADDED COOLANT CHECKED OK CHECKED OVER VEHICLE COULD NOT SEE ANY LEAKS UNDER VEHICLE, UNDER HOOD OR WHERE VEHICLE WAS PARKED CHECKED OK, CM .25

(EHOWELL) Chase spoke with the customer and they were complaining that the heater would not work unless the engine was revved up. Chase added coolant and verified heater operation afterwards.

(EHOWELL) EH raised vehicle on the rack and removed the skid plate. Pressure tested the cooling system and found coolant behind the water pump pulley.

15-42-004 - WARRANTY WATER PUMP

(EHOWELL) Tuscaloosa Ford replaced the water pump under warranty.

16-42-004 - TRANSPORT WATER PUMP

(EHOWELL) The vehicle was driven to and from Tuscaloosa Ford for a warranty repair.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52771

USING DEPT NO:	507121	OPENED DATE:	11/11/2024 07:45:15	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	11/11/2024 13:50:22	METER 1 - M:	28694	METER 2 - H:	3643				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/11/2024 15:43:38	IN-SERVICE DATE:	11/09/2021						
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$759.60	\$0.00	\$759.60
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$63.86	\$0.00	\$63.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	823.46	5.00	828.46
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	F012114	TIRE 255/60R18 FSTONE PURSUIT	186.56	4	\$746.22
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	12.32	1	\$12.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.35	4	\$13.38
PARTS						823.46

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52771

Work Order Notes

(EHANNAH) pm- SI

Job Notes

66-17-013 - PERFORM ALIGNMENT

(GARAGE) EH/CM- Performed alignment.

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) FJ- Mounted & balanced 4 tires.

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) FJ- Performed SI. Mounted & balanced 4 tires.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- Top

JR- Bottom

FJ- Topped off fluids, and added new engine oil.

JR- Drained oil and installed new oil filter.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52849

USING DEPT NO:	507121	OPENED DATE:	11/19/2024 07:51:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/19/2024 08:16:56	METER 1 - M:	29044	METER 2 - H: 3643
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/19/2024 10:59:57	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	N	N	GARAGE	0.00	\$0.00	\$3.35	\$0.00	\$3.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$3.35	\$3.35

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	3.35	3.35	6.70
--------------	-------------------	--	--	--	--	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$3.35
COMML					3.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.35	1	\$3.35
PARTS						3.35

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 52849

Work Order Notes

(CWIGLEY) LF Tire Patch

Job Notes

66-17-030 - PERFORM TIRE PATCH

(GARAGE) GC- & JR- patch tire

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53576

USING DEPT NO:	507121	OPENED DATE:	02/03/2025 07:59:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/03/2025 10:56:18	METER 1 - M:	32300	METER 2 - H: 3643
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/03/2025 13:57:49	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$62.94	\$0.00	\$62.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.00 0.00 62.94 5.00 67.94

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	11.40	1	\$11.40
PARTS						62.94

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 53576

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- filled and checked oil, checked fluids, filled up washer fluid, changed sticker
GC- changed oil and filter, checked tires and tire pressures, reset oil light, checked air filters,
31690 miles, 3969 idle hours, 4879 total hours
waiter

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54820

USING DEPT NO:	507121	OPENED DATE:	05/19/2025 11:44:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/19/2025 12:15:12	METER 1 - M:	35569	METER 2 - H: 4397
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/19/2025 15:07:14	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$63.20	\$0.00	\$63.20
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.00 0.00 63.20 5.00 68.20

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.96	1	\$11.96
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	12.81	1	\$12.81
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	6.41	6	\$38.43
PARTS						63.20

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 54820

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) CM- topside

JR- pit

perform PM, changed oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
35569 miles, 5436 total hours, 4397 idle hours

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 55766

USING DEPT NO:	507121	OPENED DATE:	08/06/2025 07:26:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/06/2025 09:12:18	METER 1 - M:	37764	METER 2 - H: 4622
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/06/2025 15:24:47	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$90.00	\$0.00	\$90.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	90.00	5.00	95.00
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SFFL500S	FL500S OIL FILTER - STIVERS	12.39	1	\$12.39
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	12.81	1	\$12.81
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL	9.53	6	\$57.15
PARTS						90.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 55766

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) perform PM, changed oil and filter

JR- checked tread depths and date codes

GC- checked fluids, checked air filters, checked tire pressures, changed sticker, reset oil light, filled up washer fluid

FJ-pit

37764 miles, 4622 idle hours, 5730 total hours

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 56409

USING DEPT NO:	507121	OPENED DATE:	09/16/2025 11:05:52	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	09/19/2025 08:43:30	METER 1 - M:	49469	METER 2 - H:	4857				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/19/2025 15:58:57	IN-SERVICE DATE:	11/09/2021						
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor			UNIT SERIAL NO:	1FM5K8AB4MGB96662					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15-003	INSPECT STEERING GEAR	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$83.96	\$0.00	\$83.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	83.96	5.00	88.96
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	12.81	1	\$12.81
66-PM-PMA	PERFORM OIL CHANGE	SFFL500S	FL500S OIL FILTER - STIVERS	12.39	1	\$12.39
66-PM-PMA	PERFORM OIL CHANGE	SF5W30BT	5W30BT OIL - STIVERS	5.87	6	\$35.19
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	23.57	1	\$23.57
PARTS						83.96

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 56409

Work Order Notes

(EHOWELL) pm- inspect tires replace if needed- rotate and balace- inspecet ball joints
The vehicle is making a clicking noise

Job Notes

06-15-003 - INSPECT STEERING GEAR

(EHOWELL) Removed tie rod boots and inspected inner tie rods. Tightened up sway bar link bolts and checked for other loose bolts. Inspected rear of vehicle for any loose items that could be causing the noise that the customer was complaining about. A road test was performed. The noise was coming from the rack and pinion.

06-15-010 - INSPECT BALL JOINT

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) GC,JR- inspected tires, front tires are almost to the wear bar and the rear are at the wear bar and the unit needs a new set of tires. Issac found 3 BFG Elite Enforcer tires up stairs and Ethan was going to order 1 more tire to make a set.

66-17-029 - PERFORM ROTATE AND BALANCE TIRES

66-79-003 - PERFORM SAFETY INSPECTION

(EKIMBREL) CQ PERFORMED SI. VEHICLE HAD MANY ISSUES. NNEDED BREAR BRAKES/ROTORS, RACK AND PINION, TIRES. UAPD TO SURPLUS VEHICLE.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC- top side, checked fluids, filters good, tires need to be replaced, reset oil life and changed oil stickers, filled with oil and checked oil level.

JR- bottom side, unit was missing skid pan, drained oil and changed oil filter,

JR- added seafoam to fuel

Miles, 39,539

Idle Hours, 4,857

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 56530

USING DEPT NO:	507121	OPENED DATE:	09/24/2025 12:50:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/29/2025 15:58:54	METER 1 - M:	49469	METER 2 - H: 4857
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/29/2025 16:38:17	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 **2021 FORD INTERCEPTOR EXPLORER** **WORK ORDER NO:** 56530

Work Order Notes

(EHANNAH) prep for sale - Unit 742 K9 is ready to be picked up at UAPD. The vehicle will be in the rear of the parking lot near the Radio Shop.

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) PREPPED VEHICLE , NO GPS. PER JR
(EKIMBREL) LOCKS ARE SENT TO A1 TO BE REKEYED

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 56612

USING DEPT NO:	507121	OPENED DATE:	09/30/2025 12:24:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/30/2025 13:14:45	METER 1 - M:	49469	METER 2 - H: 4857
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/30/2025 14:36:15	IN-SERVICE DATE:	11/09/2021	
TECH SPEC NO:	21FORDEXPLINT	2021 Ford Explorer Interceptor		UNIT SERIAL NO:	1FM5K8AB4MGB96662	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-33-001	INSTALL IGNITION SWITCH	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-33-001	TRANSPORT IGNITION SWITCH	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-33-001	REMOVE IGNITION SWITCH	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
RY-33-001	REKEY IGNITION SWITCH	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$122.60	\$122.60

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	0.00	127.60	127.60
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
RY-33-001	REKEY IGNITION SWITCH	11111231	2321626		\$122.60
COMML					127.60

Work Order Charge Detail

The University of Alabama

Report Printed: 10/02/2025 11:08:48 By User: GLOBETTI

UNIT NO: 244401 2021 FORD INTERCEPTOR EXPLORER WORK ORDER NO: 56612

Work Order Notes

Job Notes

14-33-001 - INSTALL IGNITION SWITCH

(IFALLS) JR installed new lock cylinders into vehicle, checked all lock cylinders with new key, all worked with new key after installing 1.5 hours labor

16-33-001 - TRANSPORT IGNITION SWITCH

(GARAGE) RC- took lock cylinders to A1
CW- picked up lock cylinders from A1

25-33-001 - REMOVE IGNITION SWITCH

(IFALLS) JR- removed ignition lock cylinder, trunk lock cylinder, and 2 front door lock cylinders to be rekeyed.
1.5 hours labor

CH-SP - CHARGE Shop Supplies

RY-33-001 - REKEY IGNITION SWITCH

(GARAGE) JR- A1 rekeyed 4 lock cylinders

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Oct 02 2025 11:08:48 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244401') //Q=